

15/5/2019

INS CASE OWNER:

Jaclyn

CC6/AIG18000219 1 W/CS35

LKK:

IDAC:

ASSIGNMENT

Surveyor:

Wilson

DOI:

22/12/17

Date / Time:

29/12/17

Registered in Merimen:

04/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 8151K

Name of Insured:

RHINO TECH PTE LTD

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

22/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: CHIA KWANG MENG

Driver Tel No.: 9696 4801

(V/L: YES / NO)

Claim No.:

819027416656

Policy No.:

5098609700

Make / Model:

NISSAN URVAN PANEL LWB 3.0

Place of Accident:

50R LAT PAS AIRBAG

ANG MO KEO AVE 1

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLM 535M



INSRS:

WSP: 1st Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLM 535M - X ; GBB 8151K

STAGE

DATE / PIC

02/01/18 (own)

COPIED TO OI (Mr Chia) confirmed accident details and OI re-confirmed TP. OI will send additional photos via email. Informed about claim, aware of ISO issue and agree to settle. Send letter to OI.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

7 601395

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

26/01/18

File pass to Wilson to finalize.

COR: 3,514.74

05/02/18

File pass to Shirley to close.

LOR: 2 x 100

(w/last): 214.00

* Policy number please refer to the merimen.

Total: 3,728.74

06/02/18 (ypist)

RECEIVED 0 0 FEB 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Ronnie

Email ☐ Call ☐

Final Liability:

%

00

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

3,514.74

Loss of Rental (LOR):

SS

214.00

(2 days) x \$100.00

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3,728.74

Global Sum \$S:

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with: Ronnie

Payee 1:

SS

3,728.74

Name 1:

1st Autoworks Pte Ltd

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

COPY SENT

06/02/18

Front: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/INV

To inspect Vehicle No. SLM 535 Mat Workshop m/s 1st Auto Workof 23 Kato, Bulat Ave 4 #04

Insured

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Van: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

JDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM 535 M Yr Regn: 14/3/2017Type: (M) Car / PM Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet Cruze cc 1362Colour: Dark Grey A: Insured / Std / NI / NASp. Reading: 8833 T Radio: Insured / Std / NI / NA

Eng No: _____

C/No: KLITA6984GK353962Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size F: 205/60 R16R: 205/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook (F) / (R)

Front

Rear

R/Bal: 4 mm R/Bal: 4 mmL/Bal: 4 mm L/Bal: 4 mmD.O.A: 22/12/2017 D.O.I: 29/12/2017Survey held at: As AboveDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

e. Quotation Given(P/P: 13,284.80 / Red: 116,148.00 / 83%.)

Date/Time File Pass to:

☐

: Preli. Report

1.

☐

: Final Report

Date/Time File Return to:

2.

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transporter

1. S - R

2. Photos

3. Smart

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18000219/Wks3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-01-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 8151K	Veh. Inspected	SLM 535M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/12/2017	Inspection Date	29/12/2017	
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way

#07-16, Singapore 079120

GST Ref. No: 20-0000274-Z

Vehicle No: SLM 535M

Invoice No:

Chassis No : KL1JA6989GK353962

Engine No: B14NET162850044

Invoice Date:

DESCRIPTION

AMOUNT
SGD

Parts

No.	Qty.	Description	Price (SGD)
1	1	Rear bumper	1391.00
2	1	Centre Bumper Guide	75.00
3	1	RHRC Bumper Guide	50.00
4	1	LHRC Bumper Guide	50.00
5	1	RHR Bumper Guide	60.00
6	1	LHR Bumper Guide	60.00
7	1	Rear bumper reinforcement	736.00

Total: 2422.00

Less 10%: 242.20

Parts Total : 2179.80

Labour

Labour Description

Price (SGD)

Rear		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2200.00 x 350
2	Carry out spray painting on accident affected area	1800.00 x 450
3	To remove and refix reverse sensor and conduct test	60.00 x 30

Labour Total : 4060.00 1030

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Other

No.	Other Description	Price (SGD)
-----	-------------------	-------------

Rear Portion

1	1	Rear Number plate & bracket	45.00	✓
2	10	Rear bumper clip (set)	30.00	✓

Other Total : 75.00

Total : \$6,314.80
GST (7%) \$442.04
Grand Total: \$6,756.84

Handwritten: \$3284.80
\$229.94
\$3514.74

Yours Faithfully,



Ronnie Tan

Service Advisor

Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FIRST AUTOWORKS

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 27/12/2017

Reference: SLM 535M

To Whom It May Concern

Make: Chevrolet Cruze

Dear Sir,

RE: VEHICLE.: SLM 535M

CHASSIS NO.: KL1JA6989GK353962

ENGINE NO.: B14NET162850044

Name of insured . Chan Kok Kai

Date of accident.: 22/12/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Boot lid	\$ 1,701.00
2	1	Boot lid Emblem	\$ 71.00
3	1	Boot lid lettering 'CHEVROLET'	\$ 65.00
4	1	Boot lid lettering 'CRUZE'	\$ 45.00
5	1	Boot lid Lettering 'LS'	\$ 25.00
6	1	Boot lid lettering 'Turbo'	\$ 52.00
7	1	RHR Bootlid Lamp	\$ 399.00
8	1	LHR Bootlid Lamp	\$ 399.00
9	1	Rear Bootlid Handle (plastic)	\$ 343.00
10	1	Bootlid outer switch assy	\$ 235.00
11	2	Number plate lamp	\$ 167.00
12	1	LH Bootlid Hinge	\$ 75.00
13	1	RH Bootlid hinge	\$ 75.00
14	1	Rear Bootlid Inner Trim	\$ 250.00
15	1	Boot lid lock mechanism	\$ 310.00
16	1	Boot lid striker	\$ 42.00
17	1	Boot lid weatherstrip	\$ 189.00
18	1	RHR Tail lamp	\$ 706.00
19	1	RHR Tail lamp Panel	\$ 271.00
20	1	LHR Tail lamp	\$ 706.00
21	1	LHR Tail lamp Panel	\$ 271.00
22	1	Rear bumper	\$ 1,391.00
23	1	Rear bumper tow hook cover	\$ 30.00
24	1	Centre Bumper Guide (riveting)	\$ 75.00
25	1	RHRC Bumper Guide (riveting)	\$ 50.00
26	1	LHRC Bumper Guide (riveting)	\$ 50.00
27	1	RHR Bumper Guide (riveting)	\$ 60.00
28	1	LHR Bumper Guide (riveting)	\$ 60.00
29	1	Rear bumper reinforcement	\$ 736.00
30	1	Rear end panel	\$ 906.00
31	1	Rear end panel trim	\$ 139.00
32	1	Rear spare tyre panel top board	\$ 325.00
33	1	Rear Spare Tyre Panel	\$ 1,383.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

34	1	Rear Exhaust with exhaust muffler	\$ 1,700.00	X
----	---	-----------------------------------	-------------	---

Parts Total: \$ 13,302.00

Less 10%: \$ 1,330.20

Total: \$ 11,971.80

Labour

No.	Labour Description	Price (SGD)	
	<u>Rear portion</u>		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,800.00 350	
2	Carry out spray painting on accident affected area	\$ 2,200.00 450	
3	To conduct anti rust of under carriage tuff coat	\$ 250.00	X
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	X
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	X
6	To remove and refix reverse sensor and conduct test	\$ 80.00	X 30
7	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	X
8	Transfer of internal mechanism from old door panel to new door panel	\$ 70.00	X
9	To remove and replace exhaust pipe	\$ 80.00	X
10	To conduct water leakage test after repairs of vehicle	\$ 80.00	X
11	Remove and replace reverse camera (Labour)	\$ 80.00	X
12	Remove and replace reverse sensor (Labour)	\$ 80.00	X

Labour Total: \$ 6,130.00

Others

No.	Qty	Other Description	Price (SGD)
		<u>Rear Portion</u>	
1	10	Rear Number plate & bracket	\$ 45.00
2	6	Rear bumper clip (set)	\$ 65.00
3	4	Tail lamp clip (set)	\$ 39.00
4	8	Rear Bootlid Handle clips	\$ 26.00
5	11	Rear Exhaust mounting	\$ 180.00
6	12	Inner bootlid Trim Clips	\$ 71.50
7	1	Rear end panel top granish clip (set)	\$ 32.50
8	1	Reverse camera	\$ 280.00
9	1	Reverse sensor(1 set)	\$ 592.00

Other Total: \$ 1,331.00

Total : \$ 19,432.80
Gst 7%: \$ 1,360.30
GRAND TOTAL: \$ 20,793.10

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Executive
Ronnie Tan
HP : 8298 8933 Fax: 6844 5185

LKK Auto Consultants hence notify
the Repairer of the following:
☒ To resurvey before/after spray painting
☒ To display damaged part(s) during resurvey
☒ Parts prices are subject to confirmation
☒ Third party survey is on a "Without Prejudice" basis
☒ No illegal modification(s) is allowed
☒ Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts By Part
Part Price Subject Confirmation
Resurvey Before Paint
Without Prejudice
2 Days Repair

Wilson, LKK

29/12/2017

E-mail: Wilson@lkkauto.com

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date: 27/12/2017

Reference: SLM 535M

Make: Chevrolet Cruze

To Whom It May Concern

Dear Sir,

RE: VEHICLE.: SLM 535M

CHASSIS NO.: KL1JA6989GK353962

ENGINE NO.: B14NET162850044

Name of insured: Chan Kok Kai

Date of accident: 22/12/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts No.	Qty	Part Description	Price (SGD)
1	1	Boot lid	\$ 1,701.00
2	1	Boot lid Emblem	\$ 71.00
3	1	Boot lid lettering 'CHEVROLET'	\$ 65.00
4	1	Boot lid lettering 'CRUZE'	\$ 45.00
5	1	Boot lid Lettering 'LS'	\$ 25.00
6	1	Boot lid lettering 'Turbo'	\$ 52.00
7	1	RHR Bootlid Lamp	\$ 399.00
8	1	LHR Bootlid Lamp	\$ 399.00
9	1	Rear Bootlid Handle (plastic)	\$ 343.00
10	1	Bootlid outer switch assy	\$ 235.00
11	2	Number plate lamp	\$ 167.00
12	1	LH Bootlid Hinge	\$ 75.00
13	1	RH Bootlid hinge	\$ 75.00
14	1	Rear Bootlid Inner Trim	\$ 250.00
15	1	Boot lid lock mechanism	\$ 310.00
16	1	Boot lid striker	\$ 42.00
17	1	Boot lid weatherstrip	\$ 189.00
18	1	RHR Tail lamp	\$ 706.00
19	1	RHR Tail lamp Panel	\$ 271.00
20	1	LHR Tail lamp	\$ 706.00
21	1	LHR Tail lamp Panel	\$ 271.00
22	1	Rear bumper	\$ 1,391.00
23	1	Rear bumper tow hook cover	\$ 30.00
24	1	Centre Bumper Guide (riveting)	\$ 75.00
25	1	RHRC Bumper Guide (riveting)	\$ 50.00
26	1	LHRC Bumper Guide (riveting)	\$ 50.00
27	1	RHR Bumper Guide (riveting)	\$ 60.00
28	1	LHR Bumper Guide (riveting)	\$ 60.00
29	1	Rear bumper reinforcement	\$ 736.00
30	1	Rear end panel	\$ 906.00
31	1	Rear end panel trim	\$ 139.00
32	1	Rear spare tyre panel top board	\$ 325.00
33	1	Rear Spare Tyre Panel	\$ 1,383.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel: 6844 1985 Fax: 6844 5185

34	1	Rear Exhaust with exhaust muffler	X NN	\$ 1,700.00	X
----	---	-----------------------------------	------	-------------	---

Parts Total: \$ 13,302.00

Less 10%: \$ 1,330.20

Total: \$ 11,971.80

Labour

No.	Labour Description	Price (SGD)	
	Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,800.00	530
2	Carry out spray painting on accident affected area	\$ 2,200.00	450
3	To conduct anti rust of under carriage tuff coat	\$ 250.00	X
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	X
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	X
6	To remove and refix reverse sensor and conduct test	\$ 80.00	X30
7	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	X
8	Transfer of internal mechanism from old door panel to new door panel	\$ 70.00	X
9	To remove and replace exhaust pipe	\$ 80.00	X
10	To conduct water leakage test after repairs of vehicle	\$ 80.00	X
11	Remove and replace reverse camera (Labour)	\$ 80.00	X
12	Remove and replace reverse sensor (Labour)	\$ 80.00	X

Labour Total: \$ 6,130.00

Others

No.	Qty	Other Description	Price (SGD)	
		Rear Portion		
1	10	Rear Number plate & bracket	\$ 45.00	✓ CRD / AD
2	6	Rear bumper clip (set)	\$ 65.00	✓ NEC
3	4	Tail lamp clip (set)	\$ 39.00	X NN
4	8	Rear Bootlid Handle clips	\$ 26.00	X NN
5	11	Rear Exhaust mounting	\$ 180.00	X NN
6	12	Inner bootlid Trim Clips	\$ 71.50	X NN
7	1	Rear end panel top granish clip (set)	\$ 32.50	X NN
8	1	Reverse camera	\$ 280.00	X NN
9	1	Reverse sensor (1 set)	\$ 592.00	X NN

Other Total: \$ 1,331.00

Total : \$ 19,432.80
Gst 7%: \$ 1,360.30
GRAND TOTAL: \$ 20,793.10

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Executive
Ronnie Tan
HP : 8298 8933 Fax: 6844 5185

LKK Auto Consultants hence notify
the Repairer of the following:

- ☒ To resurvey before/after spray painting
- ☒ To display damaged part(s) during resurvey
- ☒ Parts prices are subject to confirmation
- ☒ Third party survey is on a "Without Prejudice" basis
- ☒ No illegal modification(s) is allowed
- ☒ Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
26/1/18

Parts By Part
Part Price Subject To Confirmation
Resurvey Before Paint
Without Prejudice
2 Days Repair
Wilson, LKK
29/12/2017
E-mail: Wilson@lkkauto.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Dec 2017 Edit Reg		29 Dec 2017 00:00 Edit Adj Rpt	S\$3,284.80 Edit Estimates	S\$3,284.80 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Rhino Tech Pte Ltd, Co. Reg. No.: 199508645E		
Main Claimant:	CHAN KOK KAI, ID: S7407405G		
Vehicle Reg. No.:	SLM535M	Date of Loss:	22/12/2017 20:00 - :59
Claim Type:	TP / 8190274166SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	GBB8151K	Policy No. (Claimant):	5088609700
		Excess:	
Repairer:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 15/01/2018]		
Driver/Custodian (Insured):	CHIA KWANG MENG (), NRIC: S7102094J		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLM535M (8190274166SG)**
[GBB8151K]
TP
CHAN KOK KAI
Dec 22 2017 8:00PM
[Rhino Tech Pte Ltd]
1st Autoworks Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit		
															1 per page			☒		
Assessment Reports															1 per page			☒		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	05/01/18 10:33		Accident Statement From: SC - Reg. No: GBB8151K, Claimant: RHINO TECH PTE LTD												1			Load HTM		
															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	30/01/18 14:48		Odometer Reading												1			Load JPG		
2	30/01/18 14:48		General View												1			Load JPG		
3	30/01/18 14:48		General View												1			Load JPG		
4	30/01/18 14:48		Chassis Number												1			Load JPG		
5	30/01/18 14:48		General View												1			Load JPG		
6	30/01/18 14:48		General View												1			Load JPG		
7	30/01/18 14:48		General View												1			Load JPG		
8	30/01/18 14:48		General View												1			Load JPG		
9	30/01/18 14:48		General View												1			Load JPG		
10	30/01/18 14:48		General View												1			Load JPG		
11	30/01/18 14:48		General View												1			Load JPG		
12	30/01/18 14:48		General View												1			Load JPG		
13	30/01/18 14:48		General View												1			Load JPG		
14	30/01/18 14:48		General View												1			Load JPG		
15	30/01/18 14:48		General View												1			Load JPG		
16	30/01/18 14:48		General View												1			Load JPG		
17	30/01/18 14:48		General View												1			Load JPG		
18	30/01/18 14:48		General View												1			Load JPG		
19	30/01/18 14:48		General View												1			Load JPG		
20	30/01/18 14:48		General View												1			Load JPG		
21	30/01/18 14:48		General View												1			Load JPG		
22	30/01/18 14:48		General View												1			Load JPG		
23	30/01/18 14:48		General View												1			Load JPG		
24	30/01/18 14:48		General View												1			Load JPG		
25	30/01/18 14:48		General View												1			Load JPG		
26	30/01/18 14:48		General View												1			Load JPG		
27	30/01/18 14:48		General View															Load JPG		

			i		✓
28	30/01/18 14:48	General View	i	Load JPG	✓
29	30/01/18 14:48	General View	i	Load JPG	✓
30	30/01/18 14:48	General View	i	Load JPG	✓
31	30/01/18 14:48	General View	i	Load JPG	✓
32	30/01/18 14:48	General View	i	Load JPG	✓
33	30/01/18 14:49	Reinspection Photo	i	Load JPG	✓
34	30/01/18 14:49	Reinspection Photo	i	Load JPG	✓
35	30/01/18 14:49	Reinspection Photo	i	Load JPG	✓
36	30/01/18 14:49	Reinspection Photo	i	Load JPG	✓
Documentation				1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/01/18 14:04	TP GIA REPORT	i	Load PDF	
2	04/01/18 14:04	TP ESTIMATE- MARKED	i	Load PDF	
3	12/02/18 11:15	AUTHORISATION TO ACT	i	Load PDF	
4	12/02/18 11:15	LETTER TO OI	i	Load PDF	
5	12/02/18 11:15	RELEASE VOUCHER	i	Load PDF	
6	12/02/18 11:15	RENTAL RECEIPT	i	Load PDF	
7	12/02/18 11:15	WORKSHOP INVOICE	i	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBB8151K (Insd veh)	Model:	CHEVROLET CRUZE NB 1.4 D 6
	SLM535M (TP veh)		(A)
Date of Accident:	22/12/2017		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		20,793.10
Final Repair Cost	:	\$		3,514.74
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		214.00 2 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$		3,728.74

Is Third Party Workshop GIA Registered?	[] YES	[X] NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability _____ 100 _____ (%)		
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)		
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>			
Remarks _____			

Payment Instruction: Payee's Breakdown

1)	1st Autoworks Pte Ltd	:	\$	3,728.74
2)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

12 Feb

2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18000219/WKS3S2
Date: 12/02/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No: SLM535M Insured Vehicle No: GBB8151K
Date of Loss: 22/12/2017 Nature of Claim: TP Claim No: 8190274166SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM535M
Make & Model: CHEVROLET CRUZE NB, 1.4 D 6 (A) Engine No: B14NET162850044
Reg. Date: 14/03/2017 (Man. Year: 2016) Chassis No: KL1JA6989GK353962
Colour: Dark Grey Odometer: 8833 km
Engine Capacity: 1362 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Hankook 4 mm Rear Left Side: Hankook 4 mm
Front Right Side: Hankook 4 mm Rear Right Side: Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,302.80	2,254.80	11,048.00	83.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,130.00	1,030.00	5,100.00	83.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,432.80	3,284.80	16,148.00	83.10
+ GST 7.00/7.00% (S\$)	1,360.30	229.94	1,130.36	83.10
Nett Amount (S\$)	20,793.10	3,514.74	17,278.36	83.10
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
Nett Liability (S\$)		3,728.74		

INSPECTION

Date of Assignment: 29/12/2017
Date Inspected: 29/12/2017 Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933
Estimated Period of Repair: 2.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Zaini Bin Kusaini

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but
https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printpt&caseid=671742&extid=261010&CFID=28443628&C... 1/4

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Not Necessary	1,701.00 FL	*- FL
2	1		*BOOT LID EMBLEM	Not Necessary	71.00 FL	*- FL
3	1		*BOOT LID LETTERING CHEVROLET	Not Necessary	65.00 FL	*- FL
4	1		*BOOT LID LETTERING CRUZE	Not Necessary	45.00 FL	*- FL
5	1		*BOOT LID LETTERING LS	Not Necessary	25.00 FL	*- FL
6	1		*BOOT LID LETTERING TURBO	Not Necessary	52.00 FL	*- FL
7	1		*RHR BOOTLID LAMP	Not Necessary	399.00 FL	*- FL
8	1		*LHR BOOTLID LAMP	Not Necessary	399.00 FL	*- FL
9	1		*REAR BOOTLID HANDLE (PLASTIC)	Not Necessary	343.00 FL	*- FL
10	1		*BOOTLID OUTER SWITCH ASSY	Not Necessary	235.00 FL	*- FL
11	2		*NUMBER PLATE LAMP	Not Necessary	167.00 FL	*- FL
12	1		*LH BOOTLID HINGE	Not Necessary	75.00 FL	*- FL
13	1		*RH BOOTLID HINGE	Not Necessary	75.00 FL	*- FL
14	1		*REAR BOOTLID INNER TRIM	Not Necessary	250.00 FL	*- FL
15	1		*BOOT LID LOCK MECHANISM	Not Necessary	310.00 FL	*- FL
16	1		*BOOT LID STICKER	Not Necessary	42.00 FL	*- FL
17	1		*BOOT LID WEATHERSTRIP	Not Necessary	189.00 FL	*- FL
18	1		*RHR TAIL LAMP	Not Necessary	706.00 FL	*- FL
19	1		*RHR TAIL LAMP PANEL	Not Necessary	271.00 FL	*- FL
20	1		*LHR TAIL LAMP	Not Necessary	706.00 FL	*- FL
21	1		*LHR TAIL LAMP PANEL	Not Necessary	271.00 FL	*- FL
22	1		*REAR BUMPER	Dented / Scratched	1,391.00 FL	*1,391.00 FL
23	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	30.00 FL	*- FL
24	1		*CENTRE BUMPER GUIDE (RIVETING)	Necessary	75.00 FL	*75.00 FL
25	1		*RHRC BUMPER GUIDE (RIVETING)	Necessary	50.00 FL	*50.00 FL
26	1		*LHRC BUMPER GUIDE (RIVETING)	Necessary	50.00 FL	*50.00 FL
27	1		*RHR BUMPER GUIDE (RIVETING)	Necessary	60.00 FL	*60.00 FL
28	1		*LHR BUMPER GUIDE (RIVETING)	Necessary	60.00 FL	*60.00 FL
29	1		*REAR BUMPER REINFORCEMENT	Bent	736.00 FL	*736.00 FL
30	1		*REAR END PANEL	Not Necessary	906.00 FL	*- FL
31	1		*REAR END PANEL TRIM	Not Necessary	139.00 FL	*- FL
32	1		*REAR SPARE TYRE PANEL TOP BOARD	Not Necessary	325.00 FL	*- FL
33	1		*REAR SPARE TYRE PANEL	Not Necessary	1,383.00 FL	*- FL
34	1		*REAR EXHAUST WITH EXHAUST MUFFLER	Not Necessary	1,700.00 FL	*- FL
35	10		*REAR NUMBER PLATE & BRACKET	Cracked / Dented	45.00 FS	*45.00 FS
36	6		*SET REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
37	4		*SET TAIL LAMP CLIP	Not Necessary	39.00 FS	*- FS
38	8		*REAR BOOTLID HANDLE CLIPS	Not Necessary	26.00 FS	*- FS
39	11		*REAR EXHAUST MOUNTING	Not Necessary	180.00 FS	*- FS
40	12		*INNER BOOTLID TRIM CLIPS	Not Necessary	71.50 FS	*- FS
41	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	32.50 FS	*- FS
42	1		*REVERSE CAMERA	Not Necessary	280.00 FS	*- FS
43	1		*SET REVERSE SENSOR	Not Necessary	592.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	14,633.00	2,497.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,330.20	242.20
Total Parts (S\$)	13,302.80	2,254.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	New	2,800.00	550.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.	New	2,200.00	450.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.	New	250.00	0.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.	New	80.00	0.00
5	REMOVE AND REFIX SEAT CUSHION / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.	New	250.00	0.00
6	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.	New	80.00	30.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID.	New	80.00	0.00
8	TRANSFER OF INTERNAL MECHANISM FROM OLD DOOR PANEL TO NEW DOOR PANEL.	New	70.00	0.00
9	TO REMOVE AND REPLACE EXHAUST PIPE.	New	80.00	0.00
10	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	New	80.00	0.00
11	REMOVE AND REPLACE REVERSE CAMERA (LABOUR)	New	80.00	0.00
12	REMOVE AND REPLACE REVERSE SENSOR (LABOUR)	New	80.00	0.00

Gross Labour Cost (\$\$)

6,130.00

1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >