

FIRST AUTOWORKS

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 27/12/2017

Reference: SLM 535M

Make: Chevrolet Cruze

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLM 535M
CHASSIS NO.: KL1JA6989GK353962
ENGINE NO.: B14NET162850044

Name of insured : Chan Kok Kai
Date of accident.: 22/12/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts		Part Description	Price (SGD)
No.	Qty		
1	1	Boot lid	\$ 1,701.00
2	1	Boot lid Emblem	\$ 71.00
3	1	Boot lid lettering 'CHEVROLET'	\$ 65.00
4	1	Boot lid lettering 'CRUZE'	\$ 45.00
5	1	Boot lid Lettering 'LS'	\$ 25.00
6	1	Boot lid lettering 'Turbo'	\$ 52.00
7	1	RHR Bootlid Lamp	\$ 399.00
8	1	LHR Bootlid Lamp	\$ 399.00
9	1	Rear Bootlid Handle (plastic)	\$ 343.00
10	1	Bootlid outer switch assy	\$ 235.00
11	2	Number plate lamp	\$ 167.00
12	1	LH Bootlid Hinge	\$ 75.00
13	1	RH Bootlid hinge	\$ 75.00
14	1	Rear Bootlid Inner Trim	\$ 250.00
15	1	Boot lid lock mechanism	\$ 310.00
16	1	Boot lid striker	\$ 42.00
17	1	Boot lid weatherstrip	\$ 189.00
18	1	RHR Tail lamp	\$ 706.00
19	1	RHR Tail lamp Panel	\$ 271.00
20	1	LHR Tail lamp	\$ 706.00
21	1	LHR Tail lamp Panel	\$ 271.00
22	1	Rear bumper	\$ 1,391.00
23	1	Rear bumper tow hook cover	\$ 30.00
24	1	Centre Bumper Guide (floating) * / NEC	\$ 75.00
25	1	RHRC Bumper Guide (floating) * / NEC	\$ 50.00
26	1	LHRC Bumper Guide (floating) * / NEC	\$ 50.00
27	1	RHR Bumper Guide (floating) * / NEC	\$ 60.00
28	1	LHR Bumper Guide (floating) * / NEC	\$ 60.00
29	1	Rear bumper reinforcement	\$ 736.00
30	1	Rear end panel	\$ 906.00
31	1	Rear end panel trim	\$ 139.00
32	1	Rear spare tyre panel top board	\$ 325.00
33	1	Rear Spare Tyre Panel	\$ 1,383.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

34	1	Rear Exhaust with exhaust muffler	\$ 1,700.00	X
----	---	-----------------------------------	-------------	---

Parts Total: \$ 13,302.00
Less 10%: \$ 1,330.20
Total : \$ 11,971.80

Labour

No.	Labour Description	Price (SGD)	
	<u>Rear portion</u>		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,800.00 550	
2	Carry out spray painting on accident affected area	\$ 2,200.00 450	
3	To conduct anti rust of under carriage tuff coat	\$ 250.00	X
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 80.00	X
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	X
6	To remove and refix reverse sensor and conduct test	\$ 80.00	X 30
7	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	X
8	Transfer of internal mechanism from old door panel to new door panel	\$ 70.00	X
9	To remove and replace exhaust pipe	\$ 80.00	X
10	To conduct water leakage test after repairs of vehicle	\$ 80.00	X
11	Remove and replace reverse camera (Labour)	\$ 80.00	X
12	Remove and replace reverse sensor (Labour)	\$ 80.00	X

Labour Total : \$ 6,130.00

Others

No.	Qty	Other Description	Price (SGD)
		<u>Rear Portion</u>	
1	10	Rear Number plate & bracket	\$ 45.00
2	6	Rear bumper clip (set)	\$ 65.00
3	4	Tail lamp clip (set)	\$ 39.00
4	8	Rear Bootlid Handle clips	\$ 26.00
5	11	Rear Exhaust mounting	\$ 180.00
6	12	Inner bootlid Trim Clips	\$ 71.50
7	1	Rear end panel top granish clip (set)	\$ 32.50
8	1	Reverse camera	\$ 280.00
9	1	Reverse sensor(1 set)	\$ 592.00

Other Total: \$ 1,331.00

Total : \$ 19,432.80
Gst 7%: \$ 1,360.30
GRAND TOTAL: \$ 20,793.10

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Executive
Ronnie Tan
HP : 8298 8933 Fax: 6844 5185

Parts By Part
Part Price Subject Confirmation
Resurvey Before Paint
Without Prejudice
2 Days Repair
Wilson, LKK
29/12/2017
E-mail: Wilson@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- ✓ To resurvey before/after spray painting
- ✓ To display damaged part(s) during resurvey
- ✓ Parts prices are subject to confirmation
- ✓ Third party survey is on a "Without Prejudice" basis
- ✓ No illegal modification(s) is allowed
- ✓ Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: