



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: FY17/18/0052
Our Ref: CC2/MIDA18000220 /j

22 May 2019

HQ-Transport Command
Kranji Camp 3
151 Chua Chu Kang Way
Singapore 688248

ATTENTION : 1WO RAVEEN/CAPT. MERLIN

Dear Sirs,

ACCIDENT INVOLVING MID 33943 & YN 9516A ON 10/10/2017

We refer to the above matter. Based on our report, we are involved in chain collision whereby we are NOT at fault.

We are to submit for recovery claim (our final bill for recovery is at \$12,892.80) However, as our contract has ended, we are unable to continue and hold the claim file indefinitely to process for recovery. As such, we seek your approval to close file at our end for your further endorsement or turn over to the new adjusters for further handling.

For your approval.

Thank you.

Yours faithfully,

Joy Irene Bascao
Claims Section
DID: 6749 5792
Fax: 6741 4108
E-mail: joyirene@lkkauto.com


APPROVED
S1842144E
1WO RAVEENDRAN
TA INVESTIGATION WO
HQ TRANSPORT

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Monday, 22 April 2019 10:31 AM
To: HQ TPT Safety Branch
Cc: Hsiao Tong (LKKAuto); Olivia Lau (LKKAuto)
Subject: ARMY : 1WO RAVEEN/ PTE JEREMY / CAPT KOH (FY 17/18/0052) MID 33943 ON 10.10.2017

Dear Sirs,

We would like to request for the coloured photographs for our recovery claim.

Kindly send us copies.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

10, DEC. 2017 10:59

KAS B VEHICLE

NO. 402 P. 1

KAS B VEHICLE



ST Kinetics

A company of ST Engineering

Singapore Technologies
Kinetics Ltd
249 Jalan Boon Lay
Singapore 619523
Tel: (65) 6660 3711
Fax: (65) 6318 5371

Reference :
Date : 18-Dec-17

3AMB/33FMD JURONG
CAMP APN 1016, 102
UPPER JURONG RD #01-
02 JURONG CAMP 1

Dear Sir

ACCIDENT REPAIRS (DRAFT COPY)

Job No :
Vehicle No : MID33943
Model : OUV
Contract Ref No : 8017100888

We hereby submit the quote for the repair of the above vehicle/component in accordance to the job description.

Accident Repairs

Accident Labour Cost	: \$ 5,301.91 @ \$72.98 / Mhr
Non-Accident labour	\$ 2,043.44
Total Labour Cost	: \$ 7,345.35
Accident Spare Cost	\$ 2,306.77
Non-Accident Spares	\$ 1,814.26
Total Spare Cost	\$ 4,121.03
Assessment Cost	\$ 583.85
Towing Services	: \$ 242.56
Grand Total Cost	: \$ 12,892.80

Delivery Period : 7 week(s) from date of PO received.

Validity Period : 30 days from date of Quotation

Spares purchased by ST Kinetics are subjected to mark-up for both local and overseas items based on CIF price. The grand total repair cost of labour and spares / materials used are subjected to Goods & Services Tax.

Yours faithfully
SINGAPORE TECHNOLOGIES KINETICS LTD

Tay Boon Kiat
Manager
Kinetics Automotive Services

QA177508
MID33943
PASIR LABA CAMP

Task S/No	Task Summary	Task Type	Labor Code	Man Hours
	10 ACCIDENT REPAIR			0
1	20 Tailgate damaged and unable to open	RPL	BMR-SS	1.6
	30 1.1) Renew "Only 1 person allowed" sticker	RPL		0
	40 1.2) Renew "Maximum load" sticker	RPL		0
	50 1.3) Rear ladder damaged	RPL		0
	60 1.4) Remove and refit tailgate glass to new tailgate	REP	BMR-SS	8.5
	70 1.5) Renew glass adhesives	RPL		0
2	80 Rear bumper damaged	RPL	BMR-SS	1.2
	90 2.1) LH rear corner garnish torn	RPL		0
3	110 Body LH rear fender panel dented	REP	BMR-SS	2.4
	120 3.1) Renew "Do Not Pull" sticker	RPL		0
	130 3.2) LH rear combination lamp damaged	RPL		0
	140 3.3) LH rear combination lamp guard damaged	REP		0
	141 3.4) LH rear fender glass smashed	RPL	BMR-SS	8.5
	142 3.5) Renew glass adhesives	RPL		0
	143 3.6) Remove cooling unit to assist in repair and to p-up gas after repaired	RPL & REP		0
4	144 LH rear door wheel arch ripped off	RPL	BMR-SS	0.5
5	150 Spray paint on all above accident repaired areas	RPL & REP	BMR-SS	10
	160			0
	170 NON-ACCIDENT REPAIR JOB			0
1	171 ABS warning light always ON	REP	BMR-SS	2.8
	172 1.1) ABS hydraulic unit assembly faulty	RPL		0
	173 1.2) Renew both front wheel ABS sensors	RPL		0
	174 1.3) Renew both rear wheel ABS sensors	RPL		0
	175 1.4) Renew ABS G-sensor	RPL		0
	176 1.5) Top-up and bleed brake system after above repaired	RPL & REP		0
	177 1.6) Erase all error codes after above repaired	REP		0
	178			0
1	180 ASSESSMENT COST			0
	190			0
	200 TOWING SERVICES			0
1	210 Collect vehicle from Pasir Laba camp, return to same location			0
	220 POC - ME3 Nara 90084485			0
	230			0
	240 REMARKS (INFO)			0
	250 ERP IU present			0

Task	Part No	Description	Quantity	Unit Price	Line Price
	Accident Spares				
	20 UA6G-62-020	TAILGATE	1	0	434.15
	30 OUV-01PA	STICKER, ONLY 1 PERSON ALLOWED	1	0	19.62
	40 OUV-MAXLOAD	STICKER, MAX LOAD	1	0	19.88
	50 B7A10259A	LADDER	1	0	300
	70 NIV	ACTIVATOR FOR GLASS	1	4.5	4.5
	70 NIV	GLASS PRIMER	1	4.5	4.5
	70 NIV	WINDSCREEN ADHESIVE	1	25	25
	80 B7A10242A	REAR BUMPER	1	0	980
	90 UBYK-50-241B	REAR CORNER GARNISH LH	1	0	60.15
	120 OUV-DNPS	DO NOT PULL STICKER	1	0	7
	130 UA6G-51-160	LAMP, LH REAR COMB. LAMP	1	0	61
	140 UA6G-51-160-GD	GUARD LIGHT, REAR LH	1	0	124.05
	141 UA6G-63-950A	SIDE GLASS, LH FENDER	1	0	55
	142 NIV	WINDSCREEN ADHESIVE	1	25	25
	142 NIV	GLASS PRIMER	1	4.5	4.5
	142 NIV	ACTIVATOR FOR GLASS	1	4.5	4.5
	143 NIV	REFRIGERANT R134a	1	50	50
	144 UA6G-51-RFOA04	WHEEL ARCH, LH REAR DOOR	1	0	85.95
	150 NIV	PAINT	3	14	42
		Total			2306.77
	Non-Accident spares				
	172 UV6C-43-7A0	UNIT, HYDRAULIC ABS	1	0	1235.25
	173 UMS3-43-70XA	ABS SENSOR, FRONT RH	1	0	101.06
	173 UMS3-43-73XA	ABS SENSOR, FRONT LH	1	0	100
	174 UMS3-43-71YA	SENSOR, REAR RH ABS	1	0	66.12
	174 UMS3-43-72YA	SENSOR, REAR LH ABS	1	0	68.41
	175 LB96-43-7G0A	SENSOR, ABS	1	0	331.43
	176 C9008	BRAXE OIL	1	11.99	11.99
		Total			1914.26

10. DEC. 2017 10.00
10. DEC. 2017 10.00

KAS B VEHICLE
KAS B VEHICLE

NO. 400000 P. 13

260 LH blindspot mirror not present
270 Fire extinguisher not present
280 Rifle rack present
290 Spare wheel present
300 Rear ladder present
310 Engine able to start
320 PDB present x02
330 PDB batteries present x02
340 Rear signaller backrest cushion not present
350

0
0
0
0
0
0
0
0
0
0
0



**SINGAPORE
POLICE FORCE**



T/20171010/2033

2 of 3

Report No. T/20171010/2033

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

CONTINUATION OF REPORT

Name	LING BOCK HENG		ID No.	S8726132H
Related Vehicle	33943MID (ARMY OUV)		Contact No.	96443633
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Name	MURUGESAN		ID No.	036128216
Related Vehicle	YN9516A (Lorry)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 10/10/2017 at about 6.20 am, I was driving my army vehicle bearing registration plate no. 33943MID and travelling along TPE towards SLE near to Jalan Kayu exit when the vehicle in front of mine suddenly jammed brake. As such, I also jammed brake and managed to stop in time to avoid collision with the front vehicle.

All of a sudden, I heard a bang sound coming from the rear of my vehicle and felt some impact. I alighted from my vehicle and discovered that one lorry bearing registration plate no. YN9516A had collided onto the rear left portion of my vehicle. My vehicle's left rear side window was shattered, the small ladder was dislodged, the left rear portion was dented and my rear door unable to open. My passenger and I were not injured. The lorry was ferrying about 5 other passengers and I believed one of them was injured as ambulance was at scene and conveyed one subject to hospital.

Subsequently, Traffic Police Officers arrived at scene vide F/20171010/0074 and I was advised to lodge a Police report.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545026
Tel No: 1800-343 8999



T/20171010/2033

3 of 3

Report No. T/20171010/2033

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F/
Staff Sgt LEE SHAO WEI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / AEIT /
SSI 2 YEO GEAK ENG CECILIA
Contact No.: 65476404

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
10/10/2017 10:07

Classification Of Case:

SN 006



Signature:

Singapore Police Force



SINGAPORE POLICE FORCE



T/20171010/2033

1 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20171010/2033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/10/2017 10:07		Vide Report No.: F/20171010/0074		Station Diary No.: 20	
Name of Informant: LING BOCK HENG		Address: APT BLK 211B COMPASSVALE LANE #05-212 SINGAPORE 542211			
ID Type / ID No.: NRIC NO / S8726132H		Contact No.: Home/Office:		Mobile: 96443633	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 30	Date of Birth: 25/08/1987	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: SAF Regular		Driving Licence Information: Class:		Date of Expiry:	

Type of Accident:	Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 10/10/2017 08:20	Type of Location: Straight Road
Location: Along Road 1 TAMPINES EXPRESSWAY				
TPE towards SLE near to Jalan Kayu exit				
Weather: Heavy rain		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

33943MID	ARMY OUV	FORD		Green	Seriously Damaged	1
YN9516A	Lorry	MITSUBISHI		White	Seriously Damaged	5

Any Pedestrian Involved: No	
No. of Pedestrians Injured: Nil	Use of Pedestrian Crossing: NA

RESTRICTED

GOM NO 301-03

STATEMENT OF SERVICEMEN

SINGAPORE ARMED FORCES

STATEMENT OF DRIVER

STATEMENT OF	MSG LING BOCK HENG						ALIASES	N/A		
NRIC NO	S8726132H	AGE	30				MALE/FEMALE	MALE		
EMPLOYMENT	REGULAR	DRIVING LICENCE NO					NATIONALITY	SINGAPOREAN		
DIALECT		LANGUAGE SPOKEN	ENGLISH				TEL NO	96443633		
ADDRESS										
INTERPRETED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.	
RECORDED BY	NA	RANK	NA	TIME	NA	DATE	NA	SIGN	NA	
<p>I, S8726132H, MSG LING BOCK HENG, on 101017, at about 0620, was driving an OUV (MID 33943) along TPR towards SLE near to Jalan Kayu exit when the OUV (MID 33866) in front of mine suddenly jammed brake. As such, I also jammed brake and manage to stop in time to avoid collision with the front vehicle.</p> <p>All of a sudden, I heard a bang sound coming from the rear of my vehicle and felt some impact. I alighted from my vehicle and discovered that one lorry bearing registration plate no. YN9516A had collided onto the rear left portion of my vehicle. My vehicle's left rear side window was shattered, the small ladder was dislodged, the left rear portion was dented and my rear door unable to open. My passenger and I were not injured. The lorry was ferrying about 5 other passengers and I believed one of them was injured as an ambulance was at the scene and conveyed one subject to the hospital.</p> <p>Subsequently, Traffic Police Officers arrived at scene vide F/20171010/0074 and I was advised to lodge a Police report.</p>										
DATE	100817		SIGNATURE OF DRIVER/WITNESS				<Sent via Email>			

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.



SINGAPORE POLICE FORCE



T/20171010/2033

1 of 3

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

Report No. T/20171010/2033

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/10/2017 10:07		Vide Report No.: F/20171010/0074		Station Diary No.: 20	
Name of Informant: LING BOCK HENG			Address: APT BLK 211B COMPASSVALE LANE #05-212 SINGAPORE 542211		
ID Type / ID No.: NRIC NO / S8726132H			Contact No.: Home/Office:		Mobile: 96443633
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 30	Date of Birth: 25/08/1987	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: SAF Regular			Driving Licence Information: Class:		Date of Expiry:

Type of Accident:	Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 10/10/2017 06:20	Type of Location: Straight Road
Location: Along Road 1 TAMPINES EXPRESSWAY				
TPE towards SLE near to Jalan Kayu exit				
Weather: Heavy rain		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Vehicle No.	Vehicle Type	Make	Color	Damage	Count
33943MID	ARMY OUV	FORD	Green	Seriously Damaged	1
YN9516A	Lorry	MITSUBISHI	White	Seriously Damaged	5

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: Nil			



**SINGAPORE
POLICE FORCE**



T/20171010/2033

2 of 3

Police Station Of Origin:

Sengkang N.P.C

2 Sengkang Square #01-02 SINGAPORE

545025

Tel No: 1800-343 8999

Report No. T/20171010/2033

CONTINUATION OF REPORT

Name	LING BOCK HENG		ID No.	S8726132H
Related Vehicle	33943MID (ARMY OUV)		Contact No.	96443633
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Name	MURUGESAN		ID No.	036128216
Related Vehicle	YN9516A (Lorry)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 10/10/2017 at about 6.20 am, I was driving my army vehicle bearing registration plate no. 33943MID and travelling along TPE towards SLE near to Jalan Kayu exit when the vehicle in front of mine suddenly jammed brake. As such, I also jammed brake and managed to stop in time to avoid collision with the front vehicle.

All of a sudden, I heard a bang sound coming from the rear of my vehicle and felt some impact. I alighted from my vehicle and discovered that one lorry bearing registration plate no. YN9516A had collided onto the rear left portion of my vehicle. My vehicle's left rear side window was shattered, the small ladder was dislodged, the left rear portion was dented and my rear door unable to open. My passenger and I were not injured. The lorry was ferrying about 5 other passengers and I believed one of them was injured as ambulance was at scene and conveyed one subject to hospital.

Subsequently, Traffic Police Officers arrived at scene vide F/20171010/0074 and I was advised to lodge a Police report.



**SINGAPORE
POLICE FORCE**



T/20171010/2033

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No. T/20171010/2033

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /
Staff Sgt LEE SHAO WEI

Signature Of Informant:

Signature Of Interpreter:
Not applicable


Date/Time:
10/10/2017 10:07

Officer In Charge Of Case:
TP / AEIT /
SSI 2 YEO GEAK ENG CECILIA
Contact No.: 65476404

Classification Of Case:

SN 036

Authentication Stamp
NP168



RESTRICTED

GOM NO 301-03

STATEMENT OF SERVICEMEN

SINGAPORE ARMED FORCES

STATEMENT OF DRIVER

STATEMENT OF	MSG LING BOCK HENG						ALIASES	N/A	
NRIC NO	S8726132H	AGE	30				MALE/FEMALE	MALE	
EMPLOYMENT	REGULAR	DRIVING LICENCE NO					NATIONALITY	SINGAPOREAN	
DIALECT		LANGUAGE SPOKEN	ENGLISH				TEL NO	96443633	
ADDRESS									
INTERPRETED BY	N.A.	RANK	N.A.	TIME	N.A.	DATE	N.A.	SIGN	N.A.
RECORDED BY	NA	RANK	NA	TIME	NA	DATE	NA	SIGN	NA
<p>I, S8726132H, MSG LING BOCK HENG, on 101017, at about 0620, was driving an OUV (MID 33943) along TPR towards SLE near to Jalan Kayu exit when the OUV (MID 33886) in front of mine suddenly jammed brake. As such, I also jammed brake and manage to stop in time to avoid collision with the front vehicle.</p> <p>All of a sudden, I heard a bang sound coming from the rear of my vehicle and felt some impact. I alighted from my vehicle and discovered that one lorry bearing registration plate no. YN9516A had collided onto the rear left portion of my vehicle. My vehicle's left rear side window was shattered, the small ladder was dislodged, the left rear portion was dented and my rear door unable to open. My passenger and I were not injured. The lorry was ferrying about 5 other passengers and I believed one of them was injured as an ambulance was at the scene and conveyed one subject to the hospital.</p> <p>Subsequently, Traffic Police Officers arrived at scene vide F/20171010/0074 and I was advised to lodge a Police report.</p>									
DATE	100817		SIGNATURE OF DRIVER/WITNESS				<u><Sent via Email></u>		

SAF 1201/91

All statements and further statements are to be timed and dated. Witness will be re-warned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter.

A-11
RESTRICTED