

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 396S**AAD1801-025**

Not Authorized
640g &
Passing B4 point

Vehicle No.:

SHD 396S

Chassis No.:

VF1ABL15AUC283253

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

30.12.2017

Third Party Insurer :

III

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Br</i> 1,108.46 —
2	1 BUMPER LOWER REAR	\$	<i>nd</i> 768.84 —
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	225.95 7
12	1 BUMPER BEAM BRACKET RH REAR	\$	225.95 7
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
19	1 BOOT BADGE	\$	<i>Sn</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
30	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45

Trans-cab Auto Services Pte Ltd**AAD1801-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 396S

31	1 FENDER PANEL REAR LH	\$	R 3,299.13	}	X
32	1 WHEELARCH REAR LH	\$	SL 543.47		
33	1 FENDER PANEL INNER TRIM REAR RH	\$	SL 671.45		
34	1 FENDER PANEL REAR RH	\$	R 3,299.13		
35	1 WHEELARCH REAR RH	\$	SL 543.47		
36	1 TAILLAMP RH	\$	SL 552.55		
37	1 TAILLAMP PANEL RH	\$	R 986.70		
38	1 TAILLAMP LH	\$	SL 552.55		
39	1 TAILLAMP PANEL LH	\$	R 986.70		
40	1 OUTER PANEL REAR (End Panel)	\$	R 1,471.77		
41	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL 404.56		
42	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88		
43	1 SPARE WHEEL PANEL TRIM	\$	SL 612.21		
44	1 EXHAUST REAR	\$	R 7,489.05		
45	1 EXHAUST CAP REAR	\$	R 230.49		

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET PARKING AID	\$	SL 700.00	X
2	1SET REAR BUMPER CLIP	\$	na 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	—
4	1SET BUMPR BRACKET SIDE CLIP RH RR	\$	na 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	—
10	1 EXHAUST MOUNTING REAR	\$	SL 17.82	} X
11	1SET BOOT FINISHER CLIP	\$	na 24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na 30.00	
13	1 BOOT STICKER "6555-3333"	\$	na 30.00	
14	1 BOOT INNER TRIM CLIP	\$	na 45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na 28.00	

Trans-cab Auto Services Pte Ltd**AAD1801-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 396S

18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00	} X
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00	
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00	
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00	
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>nn</i> 385.00	
25	1 SPARE TYRE	\$	<i>nn</i> 330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 34,507.07****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>2200</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>2000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X

\$ 380.00 X

\$ 22 380.00 X

\$ 170.00 X

\$ 220.00 X

Over All Total	\$	45,667.07
-----------------------	-----------	------------------

Repair Days

~~15 Days~~

2 days

• P
 • T
 • N
 • S
 • R