COMFORTDELGRO ENGINEERING

45 Pandan Road S (609286)

ACCIDENT REPAIR ESTIMATES

Our Ref:			
Type of Claim : Own Damag	re	Vehicle No.	SLA871E
X 3rd Party		Make & Model	: KIA / FORTE K3
Windscreen		Year of Manufacture	: 2015
		Chassis No.	: KNAFZ411MF5538437
Ins Company : AIG	NS	Engine No.	: G4FGFH601010
Excess :		Policy No.	
Date of Accident : 01.01.	2018	Time of Accident	: 13.40 P.M
Suggested Days of Repair :	8 DAY	In-house Vehicle Asse	ssor
Repair Estimates		Name	: Wong Chee Wei
Parts (a) Cost / List Price Items	\$2,632.60	Signature	
Plus/Less 10 %	\$(263.26)	Contact No	: 68676919 HP: 97239882
1103/2635 10 /0	ψ(203.20)	LKK Auto Cons	sultants hence notify
(b) Nett Price Items		the Repairer of	the following:
Less %			re/after spray painting ged part(s) during resurvey
		Parts prices are:	subject to confirmation
(c) Special Nett Items			ry is on a "Without Prejudice" basis cation(s) is allowed
Total Parts Cost (Appendix A)	\$2,369.34	Supplementary in	teni(s) must be resurveyed and
Labour (Appendix B)	\$1,660.00	is subject to final	approval from Insurance Company
Total Repair Cost	\$4,029.34	Acknowledged by	Repairer
The above total will be subjected to 7%	G.S.T.	Signature: Date:	
Name of Surveyor		Tauphh 97	195749
Company	:	Cll.	
Survey conducted on	: 3/1	(<u>8</u> at	1730
Remarks By Surveyor			1
(a) The repair of this vehicle is author	orized / is not authoriz	zed until further notice.	WM
(b) Recommended Days of Repair	: 4	day(s)	()
(c) Resurvey	: Required / Not F		bythe part
(d) Excess	:\$_	gui	C Mulantown.
(e) Signature of surveyor	: July	Date:	341 18
ACCIDENT REPAIR ESTIMATESIF3			

COMFORTDELGRO ENGINEERING PTE LTD

Appendix B

45 Pandan Road S (609386) Tel: 68676919 Fax: 62626950,68676903

L	a	h	O		r
_	ч	~	·	ч	

Vehicle No.	:	SLA871E	Submit By	:	:_	Wong Chee Wei	
Make & Model	:	KIA	Year of Manufac	Year of Manufacture:			

viake	& Model : KIA Year of Manufacture	2015		
S/No	Labour Description	Esimated Price	Adjusted Price	
1	TO REMOVE / REPLACE /PANEL BEAT, RE ALIGN : DOOR RHF			
	DAMAGED AREA.	\$800.00	500.	
2	TO PUTTY,RESPRAY :DOOR RHF & RHR	\$600.00	400-	
3	TO CHECK WIRE	\$60.00	30.	
4	TO REMOVE /TRANSFER / RE FIT :FROM OLD DOOR PARTS			
	TO NEW DOOR PARTS	\$200.00	60	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

Appendix A

45 Pandna Road S (609286) Tel: 68676919 Fax: 62626950

Spare Parts

Vehicle No. :	S	LA871E	Submit By :	Wong Chee Wei
Make & Model :	KIA	FORTE K3 1.6A SX	Year Manufacture :	2015
Chassis No. :	KNAFZ	Z411MF5538437	_ Engine No. :	G4FGFH601010

TP

S/No	Part Description	Qty	Cost	Nett	List	S- Nett	Diposition By
			Price	Price	Price	Price	Surveyor
1	DOOR RHF	1			\$836.00		ht-
2	DOOR LOCK RHF	1			\$252.40		?
3	DOOR TAPE TOP RHF	1			\$12.00		ne (-
4	DOOR TAPE RR RHF	1			\$12.00		all
5	DOOR WEATHERSTRIP RHF	1			\$93.00		74
6	DOOR RHR	1			\$996.00		RY
7	DOOR LOCK RHR	1			\$309.20		\times
8	DOOR TAPE TOP RHR	1			\$9.00		×
9	DOOR TAPE FR RHR	1			\$10.00		Χ.
10	DOOR WEATHERSTRIP RHR	1			\$103.00		×
11		1					
12		1					
13		1					
14		1					
15		1					
16		1					
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.