

SEE REF BY:

REF:

CS/CT18000227/KHbz

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTL

Date/Time

04/01/2018 9:11am

Estimated Cost:

Bill to:

011/TP/WS/TP RES/OD RES/EVA/ENV/MV/CS

To Inspect Vehicle No:

SKD 81430M

Insured:

at Workshop m/s

Cheng Hise Motor

Tel:

6755 6142

of

Blk 109 Yishun Ind Park A #01-374

Policy No:

DMPCSN3062961700

Claim No:

SM18000045L01

Sum Insured:

Excess:

waived

Make of Veh:

(Client's Record)

D.O.A.

01-01-2018

CA / REV / KEP / REV 24 HRS

Date/Time:

04/01/2018 10:05am

Person Contacted:

Wei Ling

R.O.D. Endorsement

Vehicle IN/OUT


Date/Time	Action/Instruction
	SKD 81430M - 004 / 104 / 16032155 / m1043g2
5/1-	Revert via m1043g2
8/1-	authorise repair by Susan Foo
8/1-	* email June authorise repair excs \$0/- P/P.

2913 82624.20 Cabernet & Sdp

Insurer

ASSIGNMENT

From: _____ Date: **04-01-2018**
 Estimated Cost: _____
 () TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SKD 8430M**
 at Workshop in: **Cheng Hoe motor.**
 of: **Blk 1019 Yishun Ind Park A #01-374**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **Waived**
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value: **77K**
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **03** days Res.: Yes or No
 Lump Sum: **1 B.1** % 3 Val: Yes or No
 CA / **REP.** / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Vehicle: **SKD 8430M** Reg: **01 12**
 Type: **Car** / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or
 Make: **Mercedes**
 Colour: **White** A.O. Insured: Std / Nil / NA
 So. Reading: **115540** T. Radio Insured: Std / Nil / NA
 Eng. No: _____
 C. No: **WDD 2040452A 641885**
 Gen. Cond: **Fair** / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brakes: **In order** / Jammed / Leaked / Burnt or
 Mod: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **225/45R17**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R. Bal: **6** mm R. Bal: **7** mm
 L. Bal: **6** mm L. Bal: **7** mm
 D.O.A: **17/11/18** D.O.I: **4/1/18**
 Survey held at: **✓**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
015 141
 The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction
3/1 File pass to Cot home

2/4- refinalized with eleda. \$2603.41 3days (Red: 181.40 6%)
2/4

RECEIVED 2 APR 2018

Date Time File Pass to: ☐ Prelim. Report
2/4 Typist ☒ Final Report
 Date Time File Return to: _____

Days Of Repair: **3**
 Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp: \$
☐ Repairs: \$
☐ Test: \$
☐ Rep. And: \$

Survey Fee: **220**
 Transportation: _____
 Other: _____
220


Report Format: _____
 Lump Sum: **2603.41**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18000227/Ktb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 04-01-2018	
		Code : CTI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKD 8430M
Policy No.	DMPCSN3062961700	Coverage (\$)	0.00
Claim No.	SNM18D00045C01	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	04/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/01/2018	Inspection Date	04/01/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 4511A

Vehicle Details

Vehicle No.: SKD8430M

Vehicle to be Exported: Yes

Intended De-registration
Date: 02 Jan 2018

Vehicle Make: MERCEDES BENZ

Vehicle Model: C 180 KOMPRESSOR

Primary Colour: Grey

Manufacturing Year: 2011

Engine No.: 27191031350442

Chassis No.: WDD2040452A641885

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$31,076.00

Original Registration Date: 12 Jan 2012

First Registration Date: 12 Jan 2012

Transfer Count: 1

Actual ARF Paid: \$31,076.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 11 Jan 2022

PARF Rebate Amount: \$21,753.00

Intended COE Rebate Details

COE Expiry Date: 11 Jan 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$54,887.00

COE Rebate Amount: \$22,087.00

Total Rebate Amount: \$43,840.00

The information contained herein is correct as at 02 Jan 2018

OK

View Received Message

This mail is associated with :

SKD8430M (SNM18D00045C01)

OD

Jan 1 2018 1:00PM

[LIM SHU JIN]

Cheng Hoe Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 08/01/2018 13:03 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2679.01) - SKD8430M - Claim Handler: Jowyn Tay

Approved:2679.01.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 8 January, 2018 3:21 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Cc: SUR
Subject: SKD8430M CHINA TAIPING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKD 8430M (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Cheong Towing Services

Blk 251 Yishun Ring Road #03-1061 Singapore 760251
Co. Reg. No.: 53170956J

HotLine : 9183 3558

CASH SALES / WORK ORDER

- | | |
|--|---|
| <input type="checkbox"/> Jump Start | <input type="checkbox"/> Transport Charge |
| <input type="checkbox"/> Tyre Replacement | <input type="checkbox"/> Low Body Kit |
| <input type="checkbox"/> Accident / Breakdown | <input type="checkbox"/> Door Opening Service |
| <input type="checkbox"/> Multi / Basement | <input type="checkbox"/> Crane Up / Winch out |
| <input type="checkbox"/> With Load / Cargo Box | <input type="checkbox"/> Collect Doc / Key |
| <input type="checkbox"/> King Dolly | |

No. 6495

Date: 2/1/18

Messrs: Cheong Hoi

Vehicle No: SKD 8430 W. Model No: C100

From: Yishun. To: Yishun.

Time (day/night):

Others:

CASH \$: 50 CHEQUE:

Authorised by: Received by:

注意：本公司对所拖之车辆，在进行中如有任何损失或破坏，一概由车主自行负责。
NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being towed.



SINGAPORE POLICE FORCE



T/20180101/2074

1 of 3

Police Station Of Origin:
Chong Pang NPP
141 Yishun Ring Road SINGAPORE 760141
Tel No: 1800-7529999

Report No. T/20180101/2074

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/01/2018 17:16	Vide Report No.:	Station Diary No.: 38
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LIM SHU JIN			Address: APT BLK 130 YISHUN STREET 11 #03-255 SINGAPORE 760130		
ID Type / ID No.: NRIC NO / S8224511A			Contact No.: Home/Office: Mobile: 93380988		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 07/08/1982	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: INSURANCE AGENT			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 01/01/2018 13:10	Type of Location: Car Park
Location: Along Road 1 YISHUN STREET 22				
Open Car Park				
Weather: Cloudy		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JHG4681	Lorry					1
SKD8430M	Car	MERCEDES BENZ	C 180 KOMPRESS OR	White	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180101/2074

2 of 3

Report No. T/20180101/2074

Police Station Of Origin:
Chong Pang NPP
141 Yishun Ring Road SINGAPORE 760141
Tel No: 1800-7529999

CONTINUATION OF REPORT

Vehicle Owner			
Name	LIM SHU JIN	ID No.	S8224511A
Related Vehicle	NIL	Contact No.	93380988
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

1. On 01/01/2019 at about 1310hrs, I parked my vehicle (SKD8430M) at Yishun Street 22 Open Car Park near blk 291.


2. At about 1357hrs, there's a vehicle (JHG4681) was tried to park beside my vehicle at the parking lot on the right, I noticed that the parking lot is too small for the vehicle (JHG4681) as such the driver of (JHG4681) maneuver a few times trying to reverse the vehicle (JHG4681) into the parking lot but ended up damaged my vehicle (S KD8430M) resulting of a bend on the driver door, shattered windscreen and right wing mirror was damaged. As such the vehicle (JHG4681) gave up parking the loading / unloading bay and went to park on another parking lot. As such my mum went up to confront the driver of (JHG4681) but the driver refused to cooperate with us and drove off without leaving his particulars.

I wish to state that there's a vehicle camera installed inside my vehicle but was did not manage to record the accident. There's no injuries on anyone and Traffic Police was called to the scene. I was informed by the fruits store owner at blk 291 Yishun. He informed me that the vehicle (JHG4681) was hired by him to unload the fruits and deliver to his store. As such he said that he have the driver (JHG4681) particulars and wanted me to claim insurance for the damaged of my car.

I was instructed by Traffic Police to make a Traffic Report : F/20180101/0227 - IO Philip / 6547 6960

Mum : Ng Lay Hoon / 9757 5259
Witness 1 : Sherlin / 84480886
Witness 2 : Kelvin / 91915544
Fruits store owner : 8510 8358

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls refer Police Report attach

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

G:\ARMC SketchPlanForm_V5

(X) Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSN3062961700	Date of Loss:	01/01/2018
Vehicle Reg. No.:	SKD8430M	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	THIRD PARTY
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM SHU JIN		
Driver:	LIM SHU JIN		
Make/Model:	MERCEDES-BENZ C180, 1.8 KOMPRESSOR (A)	Vehicle Reg. Date:	12/01/2012
Vehicle Colour:	GREY		
Engine No:	27191031350442	Chassis No:	WDD2040452A641885
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	PLS REFER POLICE REPORT ATTACH		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS	Amount
Parts	1,923.60
Miscellaneous Items	192.00
Labour	669.21
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,784.81
+ GST 7.00% (\$\$)	194.94
Nett Amount (\$\$)	2,979.75

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 03 Jan 2018)**Parts:** 143 MERCEDES-BENZ C180 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SKD8430M/03/01/2018 11:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*R/DOOR MIRROR GLASS	0.00	0.00	cra *708.00 F
2	1	NA	*R/DOOR MIRROR HSG	0.00	0.00	cra *187.00 F
3	1	NA	*R/F DOOR SEAL	0.00	0.00	cut ✓150.00 F
4	1	NA	*R/F DOOR WINDOW	0.00	0.00	cra ✓98.00 F
5	1	NA	*R/F OUT WINDOW SEAL	0.00	0.00	new *75.00 F
6	1	NA	*R/F WINDOW CHANNEL	0.00	0.00	svc x*72.00 F
7	1	NA	*R/LWR D/MIRROR COVER	0.00	0.00	Delet ✓47.00 F
8	1	NA	*R/MIRROR BASE	0.00	0.00	Delet *495.00 F

F=Franchise part.

Sub Total (S\$) 1,832.00

+ Margin on L,N Items 5.00% (S\$) 91.60

Total Parts (S\$) 1,923.60

Cheng Hoe Motor Pte Ltd/SKD8430M/03/01/2018 11:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	SPECIALIST AUDATEX FEE	42.00
2	1	SPECIALIST RESET FRT DOOR SYS	50.00
3	1	SUNDRY PARTS NA	100.00
Sub Total (S\$)			192.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New	271.40
2	Total Paint Materials	New	71.21
3	Total Panel/Mechanical Labour	New	326.60
Gross Labour Cost (S\$)			669.21

Cheng Hoe Motor Pte Ltd/SKD8430M/03/01/2018 11:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761**

SKD8430M
03/01/2018

Claim Reference:
Assessment Number: CSKD8430
Version: CHENGHOE/1
Date Calculated: 03/01/2018 01:50

Full Report - V1
Registration: SKD8430M
Printed: 03/01/2018 11:06

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	01/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	8 day(s) 3 days
Policy Number:	DMPCSN3062961700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	C Class
Sub Model:	C 180 KOMPR BE
Model Sheet Number:	3AL 27
Registration:	SKD8430M
Registration Month:	January
Registration Year:	2012
VIN Number:	WDD2040452A641885
Manufacture Year:	2011
Odometer:	Not Known
Colour:	White
Engine Number:	
Fuel Level:	%

Model Specs

FROM A620/F788/R191.	MODEL 2012
RAIN SENSOR	LED DAYT RUN LAMPS
MEDIA INTERFACE	MIRROR PACKAGE
NAVIG SYSTEM COMAND	GRILLE WITH STAR
STORAGE PACKAGE	LEATHER UPHOLSTERY
ALU DESIGN PARTS	TRIM AVANTGARDE
CUP HOLDER	STRG WHEEL LEATHER
H/DUTY ALTERNATOR	FUEL TANK 66L
ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
PARAMETER STEERING	CRUISE CONTROL
WHEELS 7.5J X 17 ALU	SPARE WHEEL
TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD	TYRES 225/45 YR 17

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	03/01/2018
Pre-Accident Damage:	
Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:
Tread Depth LHR:	Tread Depth RHR:
Damage Areas:	Direction of Impact:

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSKD8430



Version: CHENGHOE/1

Date Calculated: 03/01/2018 01:50

Full Report - V1

Registration: SKD8430M

Printed: 03/01/2018 11:06



Addresses

Repairer

Name : CHENG HOE MOTOR PTE LTD

Address :

BLK 1019, YISHUN IND PK A

01-374/382

Post Code : 768761

Cost Summary

Total Labour	\$598.00
Total Paint/Material	\$71.21
Total Parts	\$2,023.60
Total of Additional Costs	\$92.00
Excess:	TBA
Grand Total Exc GST:	\$2,784.81
7 % GST:	\$194.94
Grand Total Inc GST:	\$2,979.75

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
88-3230 01	R + R RIGHT MIRROR	3.0	13.80
88-3232 01)	RENEW R/DOOR MIRROR (REMOVED)	3.0	13.80
72-5851 01	R + R R/F DOOR MODULE (DOOR TRIM REMOVED)	9.0	41.40
72-6405 01	R + R RIGHT FRONT DOOR TRIM	4.0	18.40
72-5174 01)	R + R R/CRANK WINDOW SEALING	1.0	4.60
72-8442 01	R + R RIGHT FRONT DOOR LWR SEALING RAIL	3.0	13.80
72-8469 01)	RENEW R/F DOOR SEAL	8.0	36.80
72-6666 01	R + R R/F WINDOW FRAME TRIM	2.0	9.20
0250	VEHICLE TRANSPORT	13.0*	59.80
1406	REMOVE GLASS SPLINTER	15.25*	115.00

LABOUR COST

Total Work Units	71.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	7.1HRS	\$326.60
Paint Labour	5.9HRS	\$271.40
Total Labour	13.0HRS	\$598.00

PAINT WORK

Guide Number Description

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

Audatex System Using Manufacturer's Times

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSKD8430

Version: CHENGHOE/1

Date Calculated: 03/01/2018 01:50

Full Report - V1

Registration: SKD8430M

Printed: 03/01/2018 11:06

	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1740	R/DOOR MIRROR HSG NEW PART PAINT K1R	3.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	23.0	
1564	R/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	29.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	59.0	
	Total Paintwork Labour	5.9HRS	\$271.40
MATERIAL COST - PAINT			
	Cost Price		
	New Part Painting - Plastic K1R		\$2.46
	Material-Constant Main Work Metal		\$28.60
	Surface Paint Plastic		\$0.73
	Repair Painting		\$30.42
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$71.21
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$71.21

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1510	1	R/F DOOR SEAL	204 727 1187		0% <i>CM</i> 150.00* ✓
1520	1	R/F DOOR WINDOW	204 725 0800		0% <i>CM</i> 98.00* ✓
1598	1	R/F WINDOW CHANNEL	204 725 1625		0% <i>SM</i> 72.00* X
1662	1	R/F OUT WINDOW SEAL	204 725 1665		0% <i>SM</i> 75.00* ✓
1740	1	R/DOOR MIRROR HSG	212 810 6000 9040		0% <i>CM</i> 187.00* ✓
1742	1	R/LWR D/MIRROR COVER	204 810 0215	<i>Null CM</i>	0% 47.00* ✓
1744	1	R/DOOR MIRROR GLASS	212 810 2621		0% <i>CM</i> 708.00* ✓
1746	1	R/MIRROR BASE	204 810 3076		0% <i>Null CM</i> 495.00* ✓
f: OEM Parts			Sub Total		\$1,832.00
g: Original			Mark Up From Cost	(5 %)	\$91.60
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$2,023.60
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE SPECIALIST	0%	\$42.00 ✓
RESET FRT DOOR SPECIALIST		\$50.00 ✓
SYS		
Total Extras		\$92.00

Final Calculation

Total Parts	\$2,023.60
Labour	
Total Panel/Mechanical	\$326.60
Total Paintwork	\$271.40
Total Labour	\$598.00
Additional Costs	
Corr Prot Materials External	\$0.00

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER**

079909

**Claim Reference: SNM18D00045C01
Assessment Number: CSKD8430
Version: CHINATAI/2
Date Calculated: 05/01/2018 01:29**

**Full Report - V1
Registration: SKD8430M
Printed: 05/01/2018 09:30**

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	01/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM18D00045C01	Estimated Repair Time:	5 day(s)
Policy Number:	DMPCSN3062961700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	C Class
Sub Model:	C 180 KOMPR BE
Model Sheet Number:	3AL 27
Registration:	SKD8430M
Registration Month:	January
Registration Year:	2012
VIN Number:	WDD2040452A641885
Manufacture Year:	2011
Odometer:	Not Known
Colour:	White
Engine Number:	
Fuel Level:	%



Model Specs

FROM A620/F788/R191.	MODEL 2012
RAIN SENSOR	LED DAYT RUN LAMPS
MEDIA INTERFACE	MIRROR PACKAGE
NAVIG SYSTEM COMAND	GRILLE WITH STAR
STORAGE PACKAGE	LEATHER UPHOLSTERY
ALU DESIGN PARTS	TRIM AVANTGARDE
CUP HOLDER	STRG WHEEL LEATHER
H/DUTY ALTERNATOR	FUEL TANK 66L
ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
PARAMETER STEERING	CRUISE CONTROL
WHEELS 7.5J X 17 ALU	SPARE WHEEL
TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD	TYRES 225/45 YR 17

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	03/01/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: SNM18D00045C01****Assessment Number: CSKD8430****Version: CHINATAI/2****Date Calculated: 05/01/2018 01:29****Full Report - V1****Registration: SKD8430M****Printed: 05/01/2018 09:30****Addresses****Repairer**

Name : CHENG HOE MOTOR PTE LTD

Address :

BLK 1019, YISHUN IND PK A

01-374/382

Post Code : 768761

Cost Summary

Total Labour	\$492.20
Total Paint/Material	\$71.21
Total Parts	\$2,023.60
Total of Additional Costs	\$92.00
Excess:	- \$0.00
Grand Total Exc GST:	\$2,679.01
7 % GST:	\$187.53
Grand Total Inc GST:	\$2,866.54

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR****Price/Dent = \$46.00/HR****Repair /**

Guide Number	Repair Details	WU	Cost Price (\$)
88-3230 01	R + R RIGHT MIRROR	3.0	13.80
88-3232 01)	RENEW R/DOOR MIRROR (REMOVED)	3.0	13.80
72-5851 01	R + R R/F DOOR MODULE (DOOR TRIM REMOVED)	9.0	41.40
72-6405 01	R + R RIGHT FRONT DOOR TRIM	4.0	18.40
72-5174 01)	R + R R/CRANK WINDOW SEALING	1.0	4.60
72-8442 01	R + R RIGHT FRONT DOOR LWR SEALING RAIL	3.0	13.80
72-8469 01)	RENEW R/F DOOR SEAL	8.0	36.80
72-6666 01	R + R R/F WINDOW FRAME TRIM	2.0	9.20
1406	REMOVE GLASS SPLINTER	15.0*	69.00

LABOUR COST

Total Work Units	48.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	4.8HRS	\$220.80
Paint Labour	5.9HRS	\$271.40
Total Labour	10.7HRS	\$492.20

PAINT WORK**Time Basis 10 WU = 1 HR. Price = \$46.00/HR**

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference: SNM18D00045C01

Assessment Number: CSKD8430

Version: CHINATAI/2

Date Calculated: 05/01/2018 01:29

Full Report - V1

Registration: SKD8430M

Printed: 05/01/2018 09:30

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1740	R/DOOR MIRROR HSG NEW PART PAINT K1R	3.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	23.0	
1564	R/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	29.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	59.0	
	Total Paintwork Labour	5.9HRS	\$271.40
MATERIAL COST - PAINT			
	Cost Price		
	New Part Painting - Plastic K1R		\$2.46
	Material-Constant Main Work Metal		\$28.60
	Surface Paint Plastic		\$0.73
	Repair Painting		\$30.42
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$71.21
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$71.21

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1510	1	R/F DOOR SEAL	204 727 1187		0% 150.00*
1520	1	R/F DOOR WINDOW	204 725 0800		0% 98.00*
1598	1	R/F WINDOW CHANNEL	204 725 1625		0% 72.00*
1662	1	R/F OUT WINDOW SEAL	204 725 1665		0% 75.00*
1740	1	R/DOOR MIRROR HSG	212 810 6000 9040		0% 187.00*
1742	1	R/LWR D/MIRROR COVER	204 810 0215		0% 47.00*
1744	1	R/DOOR MIRROR GLASS	212 810 2621		0% 708.00*
1746	1	R/MIRROR BASE	204 810 3076		0% 495.00*
f: OEM Parts			Sub Total		\$1,832.00
g: Original			Mark Up From Cost	(5 %)	\$91.60
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$2,023.60
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	SPECIALIST 0%	\$42.00
RESET FRT DOOR	SPECIALIST	\$50.00
SYS		
Total Extras		\$92.00

Final Calculation

Total Parts		\$2,023.60
Labour		
Total Panel/Mechanical	\$220.80	
Total Paintwork	\$271.40	
Total Labour		\$492.20
Additional Costs		

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference: SNM18D00045C01****Full Report - V1****Assessment Number: CSKD8430****Registration: SKD8430M****Version: CHINATAI/2****Printed: 05/01/2018 09:30****Date Calculated: 05/01/2018 01:29**

Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$92.00	
Total of Additional Costs		\$92.00
Total Paint/Material Costs		\$71.21
Grand Total Excludes GST		<u>\$2,679.01</u>
GST @ 7 %		\$187.53
Grand Total Includes GST		<u>\$2,866.54</u>

Assessment Notes

CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761

SKD8430M
OD/CA/NA

Claim Reference:
Assessment Number: CSKD8430
Version: CHENGHOE/1
Date Calculated: 03/01/2018 01:50

Full Report - V1
Registration: SKD8430M
Printed: 03/01/2018 11:06

01/01/18 Not Authored
1-1-1
Assessing B4 claim

Summary Information



Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	01/01/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	5 day(s) 3 days
Policy Number:	DMPCSN3062961700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	MERCEDES	FROM A620/F788/R191.	MODEL 2012
Model:	C Class	RAIN SENSOR	LED DAYT RUN LAMPS
Sub Model:	C 180 KOMPR BE	MEDIA INTERFACE	MIRROR PACKAGE
Model Sheet Number:	3AL 27	NAVIG SYSTEM COMAND	GRILLE WITH STAR
Registration:	SKD8430M	STORAGE PACKAGE	LEATHER UPHOLSTERY
Registration Month:	January	ALU DESIGN PARTS	TRIM AVANTGARDE
Registration Year:	2012	CUP HOLDER	STRG WHEEL LEATHER
VIN Number:	WDD2040452A641885	H/DUTY ALTERNATOR	FUEL TANK 66L
Manufacture Year:	2011	ENGINE PROTECTION	AUTO GEARBOX 5 SPEED
Odometer:	Not Known	PARAMETER STEERING	CRUISE CONTROL
Colour:	White	WHEELS 7.5J X 17 ALU	SPARE WHEEL
Engine Number:		TWO COAT METALLIC	PREPARE OFF VEHICLE
Fuel Level:	%	CLEAR COAT HARD	TYRES 225/45 YR 17

Vehicle Condition

Vehicle Status			
Pre-Accident Condition:		Severity of Impact:	
Steering:		Vehicle Status on Inspection:	
Brakes Pedal Travel:		Date of Inspection:	03/01/2018
Place of Inspection:			
Pre-Accident Damage:			
Tyres Condition:			
Tread Depth LHF:		Tread Depth RHF:	
Tread Depth LHR:		Tread Depth RHR:	
Damage Areas:		Direction of Impact:	

CHENG HOE MOTOR PTE LTD**Claim Reference:****Assessment Number: CSKD8430****Version: CHENGHOE/1****Date Calculated: 03/01/2018 01:50****Full Report - V1****Registration: SKD8430M****Printed: 03/01/2018 11:06****Addresses****Repairer**

Name : CHENG HOE MOTOR PTE LTD

Address :

BLK 1019, YISHUN IND PK A

01-374/382

Post Code : 768761

Cost Summary

Total Labour	\$598.00
Total Paint/Material	\$71.21
Total Parts	\$2,023.60
Total of Additional Costs	\$92.00
Excess:	TBA
Grand Total Exc GST:	\$2,784.81
7 % GST:	\$194.94
Grand Total Inc GST:	\$2,979.75

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR

Price/Dent = \$46.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
88-3230 01	R + R RIGHT MIRROR	3.0	13.80
88-3232 01)	RENEW R/DOOR MIRROR (REMOVED)	3.0	13.80
72-5851 01	R + R R/F DOOR MODULE (DOOR TRIM REMOVED)	9.0	41.40
72-6405 01	R + R RIGHT FRONT DOOR TRIM	4.0	18.40
72-5174 01)	R + R R/CRANK WINDOW SEALING	1.0	4.60
72-8442 01	R + R RIGHT FRONT DOOR LWR SEALING RAIL	3.0	13.80
72-8469 01)	RENEW R/F DOOR SEAL	8.0	36.80
72-6666 01	R + R R/F WINDOW FRAME TRIM	2.0	9.20
0250	VEHICLE TRANSPORT	<i>11</i> 13.0*	59.80 X
1406	REMOVE GLASS SPLINTER	<i>15</i> 25.0*	<i>#69</i> 115.00 <i>220</i>
LABOUR COST			
Total Work Units		71.0	
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		7.1HRS	\$326.60
Paint Labour		5.9HRS	\$271.40
Total Labour		13.0HRS	\$598.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number Description

WU Cost Price (\$)

Att: Kenneth *OK*
CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSKD8430

Version: CHENGHOE/1

Date Calculated: 03/01/2018 01:50

Full Report - V1

Registration: SKD8430M

Printed: 03/01/2018 11:06

	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
1740	R/DOOR MIRROR HSG NEW PART PAINT K1R	3.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	23.0	
1564	R/F DOOR OUT HANDLE SURFACE PAINT PLAST.	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	29.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	59.0	
	Total Paintwork Labour	5.9HRS	\$271.40
MATERIAL COST - PAINT			
			Cost Price
	New Part Painting - Plastic K1R		\$2.46
	Material-Constant Main Work Metal		\$28.60
	Surface Paint Plastic		\$0.73
	Repair Painting		\$30.42
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$71.21
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$71.21

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1510	1	R/F DOOR SEAL	204 727 1187		0% <i>CM</i> ✓ 150.00* ✓
1520	1	R/F DOOR WINDOW	204 725 0800		0% <i>CM</i> ✓ 98.00* ✓
1598	1	R/F WINDOW CHANNEL	204 725 1625		0% <i>CM</i> ✓ 72.00* ?X
1662	1	R/F OUT WINDOW SEAL	204 725 1665		0% <i>CM</i> ✓ 75.00* ✓
1740	1	R/DOOR MIRROR HSG	212 810 6000 9040		0% <i>CM</i> ✓ 187.00* ✓
1742	1	R/LWR D/MIRROR COVER	204 810 0215	<i>Del/CM</i>	0% ✓ 47.00* ✓
1744	1	R/DOOR MIRROR GLASS	212 810 2621		0% <i>CM</i> ✓ 708.00* ✓
1746	1	R/MIRROR BASE	204 810 3076		0% <i>Del/CM</i> ✓ 495.00* ✓
f: OEM Parts			Sub Total		\$1,832.00
g: Original			Mark Up From Cost	(5 %)	\$91.60
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$2,023.60
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
AUDATEX FEE	0%	\$42.00 ✓
RESET FRT DOOR SYS	SPECIALIST SPECIALIST	\$50.00 ✓
Total Extras		\$92.00

Final Calculation

Total Parts	\$2,023.60
Labour	
Total Panel/Mechanical	\$326.60
Total Paintwork	\$271.40
Total Labour	\$598.00
Additional Costs	
Corr Prot Materials External	\$0.00

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSKD8430

Version: CHENGHOE/1

Date Calculated: 03/01/2018 01:50

Full Report - V1

Registration: SKD8430M

Printed: 03/01/2018 11:06

Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$92.00	
Total of Additional Costs		\$92.00
Total Paint/Material Costs		\$71.21
Grand Total Excludes GST		\$2,784.81
GST @ 7 %		\$194.94
Grand Total Includes GST		\$2,979.75

Assessment Notes

Parts \$1760
 Add sp \$88
 Add Sundry \$100
 Add specialist \$92
 Add Labour \$492.20
 Materials \$92

 Total \$2624.20



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

TAX INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 338564.
Tel: 6298 3888 Fax: 6297 0863 (Accounts)
E-mail : info@minghee.com
Website : http://www.minghee.com

INV NO : 80933485

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

CO REG NO. 198905613E

ACCOUNT NUMBER: CHEONGH2 TIME: 09:41

CHEONG HOE MOTOR PTE LTD
BLK 1019, YISHUN INDUSTRIAL
PARK 1, #01-374/382,
SINGAPORE 768761

Telephone No : 67556142

768761

ROUTE
SK2

DELIVER TO:

CHEONG HOE MOTOR PTE LTD
BLK 1019, YISHUN INDUSTRIAL
PARK 1, #01-374/382,
SINGAPORE 768761



DATE	09/01/2018	PAID	1
TERM	30 Days Net	SALES TAX	Ong Hai Choon
CUSTOMER	SKD8430M	QUANTITY	64864

PART NO	PARTICULARS	LOG	QUANTITY	UNIT PRICE	AMOUNT
1-000-000-00	ENGINE BLDG RM	SK	1 PC	98.00	98.00
1-000-000-00	ENGINE BLDG RM	SK	1 PC	75.00	75.00
1-000-000-00	ENGINE BLDG RM	SK	1 PC	150.00	150.00
1-000-000-00	ENGINE BLDG RM	SK	1 PC	495.00	495.00
1-000-000-00	ENGINE BLDG RM	SK	1 PC	187.00	187.00
1-000-000-00	ENGINE BLDG RM	SK	1 PC	47.00	47.00
1-000-000-00	ENGINE BLDG RM	SK	1 PC	708.00	708.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

GOODS SOLD ARE NOT RETURNABLE.
OVERDUE ACCOUNTS SHALL
BEAR INTEREST AT UOB'S PREVAILING
LENDING RATE

CASH INVOICE MUST BE
PAID WITHIN 7 DAYS
FROM DATE OF INVOICE

Exclusive Distributor
HDK
C.V. JOINT
MADE IN JAPAN
Stockists

TOTAL
ADD GST
AMOUNT DUE
SIN
78
SIN

SIGN & COMPANY'S STAMP

Signature

DATE
ALL CHECKS MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.



For MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jan 2018 Sendback Est	03 Jan 2018 11:15 S\$2,784.81	04 Jan 2018 09:11 Edit Adj Rpt	S\$2,603.41 Edit Estimates	S\$2,603.41 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LIM SHU JIN, ID: S8224511A								
Vehicle Reg. No.:	SKD8430M	Date of Loss:	01/01/2018 13:00 - :59 [71 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D00045C01	Policy/Cover Note No.:	DMPCSN3062961700 (Comprehensive) Coverage: 07/08/2017 - 06/08/2018						
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/01/2018]								
Driver/Custodian:	LIM SHU JIN (/ Male), NRIC: S8224511A								
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY AND REVERT. EXCESS WAIVED FOR THIS ACCIDENT.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA TAIPING (08/01/2018): Alert - Adj Mandate Approved (S\$2679.01) - SKD8430M - Claim Handler: Jowyn Tay 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKD8430M (SNM18D00045C01)

OD

Jan 1 2018 1:00PM

[LIM SHU JIN]

Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter		View View in Browser	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail Print
1	03/01/18 11:15	Repairer Estimates	<input checked="" type="checkbox"/> Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	05/01/18 09:47	Adjuster Immediate Advice	<input checked="" type="checkbox"/> Load HTM
2	08/01/18 15:01	Rpt-for-Repairer (Pre-Auth)	<input checked="" type="checkbox"/> Load HTM
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	05/01/18 09:51	PHOTO	<input checked="" type="checkbox"/> Load PDF
2	02/04/18 14:53	RESURVEY	<input checked="" type="checkbox"/> Load PDF
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail Print
1	03/01/18 11:15	E-filed GIA report	<input checked="" type="checkbox"/> Load PDF
2	03/01/18 11:15	Driver's Driving License	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	05/01/18 09:51	ESTIMATE	<input checked="" type="checkbox"/> Load PDF
2	04/04/18 09:26	Parts Invoice	<input checked="" type="checkbox"/> Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>		
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118000227/KTBE2

Date: 04/04/2018

REFERENCE

Insured/Claimant: LIM SHU JIN Policy No: DMPCSN3062961700
Date of Loss: 01/01/2018 Nature of Claim: OD Claim No: SNM18D00045C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKD8430M**
Make & Model: MERCEDES-BENZ C180, 1.8 Kompressor (A) Engine No: 27191031350442
Reg. Date: 12/01/2012 (Man. Year: 2011) Chassis No: WDD2040452A641885
Colour: White Odometer: 115540 km
Engine Capacity: 1597 cc
Market Value/New Car Price: S\$77,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,923.60	1,848.00	75.60	3.93
Miscellaneous Items	192.00	192.00	0.00	0.00
Labour	669.21	563.41	105.80	15.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,784.81	2,603.41	181.40	6.51
+ GST 7.00/7.00% (S\$)	194.94	182.24	12.70	6.51
Nett Amount (S\$)	2,979.75	2,785.65	194.10	6.51

INSPECTION

Date of Assignment: 04/01/2018 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 04/01/2018 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2018)
Parts: 143 MERCEDES-BENZ C180 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKD8430M)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*R/DOOR MIRROR GLASS (WCP)	Cracked	708.00 F	*708.00 F
2	1	NA	*R/DOOR MIRROR HSG (WCP)	Cracked	187.00 F	*187.00 F
3	1	NA	*R/F DOOR SEAL (WCP)	Cut	150.00 F	*150.00 F
4	1	NA	*R/F DOOR WINDOW (WCP)	Cracked	98.00 F	*98.00 F
5	1	NA	*R/F OUT WINDOW SEAL (WCP)	Necessary	75.00 F	*75.00 F
6	1	NA	*R/F WINDOW CHANNEL (WCP)	Serviceable	72.00 F	*- F
7	1	NA	*R/LWR D/MIRROR COVER (WCP)	Dented / Cut	47.00 F	*47.00 F
8	1	NA	*R/MIRROR BASE (WCP)	Dented / Cut	495.00 F	*495.00 F

F=Franchise part.

Sub Total (\$\$)	1,832.00	1,760.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	91.60	88.00
Total Parts (\$\$)	1,923.60	1,848.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SPECIALIST AUDATEX FEE	42.00	42.00
2	1	SPECIALIST RESET FRT DOOR SYS	50.00	50.00
3	1	SUNDRY PARTS NA (NECESSARY)	100.00	100.00
Sub Total (S\$)			192.00	192.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	271.40	271.40
2	Total Paint Materials	New	71.21	71.21
3	Total Panel/Mechanical Labour	New	326.60	220.80
Gross Labour Cost (S\$)			669.21	563.41

Report was unsubmitted during this print-out.

< END OF ESTIMATES >