


SMRT Accident Vehicle Repair Estimates

A/C

G/H

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4436P
 Ref. No : TAX/01/18/2003
 Reg. Date : 13/01/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : WONG LEE SENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 01/01/2018 05:00:00 PM
 Accident Reported Date / Time : 02/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093893
 Special Instruction to ARC, if any :
 SLG5264T
 Prepared Date : 02/01/2018 04:55:45 PM



Sebastian.
3/1/18.

- Lump Sum Repair.
- Question Mark Item Photo.
- Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary repair(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U50-5722234

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges | : 338.00 | 0.00 |
| Total Spray Painting Charges | : 558.00 | 0.00 |
| Total Material Charges | : 927.44 | 946.37 |
| Other Charges | : 360.00 | 0.00 |
| TOTAL | : 2,183.44 | 0.00 |
| Lum Sum Total | : 2,200.00 | 0.00 |
| No. of Repair Days | : 3.00 | 0.00 |
| Prepared / Adjusted By | : | 2 days. |
| Arc / Surveyor Sign Off Date | : 03/01/2018 01:08:57 PM | 01/01/1900 12:00:00 AM |



Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/01/2018 01:08:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

| | |
|------------------|-----------------|
| Quotation No : | Invoice No : |
| Quotation Date : | Invoice Date : |
| Invoice Amount : | Prepared Date : |

Section D - Details of Repair Estimates**Part 1 - Labour Works**

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------|--------------------|-------------------------------------|
| TO REPAIR RH REAR PORTION | 338.00 | 0.00 200 |
| Total Labour | 338.00 | 0.00 |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO REPSRAY REAR BUMPER | 378.00 | 0.00 200 |
| TO RESPRAY BUMPER BEAM | 180.00 ? | 0.00 |
| Total Spray Painting & Panel Beating | 558.00 | 0.00 |

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION | 80.00 | 0.00 X |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | 120.00 | 0.00 30 |
| TO REPLACE SUNDRY PARTS | 100.00 | 0.00 20 |
| TO WASH AND VACUUM | 60.00 | 0.00 X |
| Total Other Costs | 360.00 | 0.00 |

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|------------------------------------|---------|----------|----------------------------|-----|-----------------|--------------|------------------|--------------------|---|-----------------|
| 52159-47905 | | 6505548 | BUMPER REAR | 1 | 458.60 | 25.00 | 343.95 | Replace | Replace <input checked="" type="checkbox"/> | No |
| 52023-12240 | | 6505547 | BUMPER REINFORCEMENT REAR | 1 | 205.70 | 25.00 | 154.27 | Replace | Replace <input type="checkbox"/> | No |
| 52015-47050 | | | ARM SUB-ASSY, RR BUMPER RH | 1 | 139.60 | 25.00 | 104.70 | Replace | Replace <input type="checkbox"/> | No |
| | | | SENSOR REVERSE | 1 | 180.00 | 0.00 | 180.00 | Replace | Replace <input type="checkbox"/> | No |
| | | | PIXEL STICKER | 2 | 60.00 | 0.00 | 120.00 | Replace | Replace <input checked="" type="checkbox"/> | No |
| 76087-47020 | | 6505618 | BUMPER LIP COVER RR/RH | 1 | 118.10 | 25.00 | 88.57 | Replace | Replace <input checked="" type="checkbox"/> | No |
| 52591-47021 | | | BUMPER SEAL, RR RH | 1 | 65.70 | 25.00 | 49.27 | Replace | Replace <input checked="" type="checkbox"/> | No |
| 52575-47020 | | 6505549 | BUMPER SIDE RETAINER RR/RH | 1 | 94.80 | 25.00 | 71.10 | Replace | Replace <input type="checkbox"/> | No |
| TOTAL MATERIALS | | | | | | | | 1,111.88 | 1,111.86 | |
| TOTAL MATERIALS(Discounted) | | | | | | | 927.44 | 946.37 | | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|--------------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | | |