



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLH 7035 U

Parts	(a) Cost / List Price Items	\$	5,117.30
	Plus/Less 25%	\$	1,279.33
	Total of Cost / List	\$	3,837.98
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	3,837.98
Labour		\$	1,300.00
Total		\$	5,137.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 19/1/18 at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$

(e) Signature of surveyor : *Le*

Date: 19/1/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLH 7035 U
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU603537436

Submit By : Carmen Lim
Year Manufacture : 2016
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH	1	\$2,631.70		✓
2	Front bumper <i>Bm</i>	1	\$470.80		✓
3	Front bumper clip <i>mc</i>	10	\$40.00		✓
4	Front bumper reinforcement <i>R</i>	1	\$721.40		X
5	Front bumper side retainer RH <i>DHP</i>	1	\$92.30		✓
6	Front bumper bracket RH <i>R</i>	1	\$124.70		X
7	Front bumper sponge <i>in</i>	1	\$125.70		X
8	Fog lamp RH <i>CR</i>	1	\$910.70		✓
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLH 7035 U**

Submit By : Carmen Lim

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2016

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.