

卓亚水喷漆公司

TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

BUSINESS REG. NO: 09935300L

GST REG. NO: 09-935300-L

03/01/2018

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING

78 SHENTON WAY #07-16

SINGAPORE 079120

ATTN : MOTOR CLAIMS DEPT.

ESTIMATED REPAIR BILL

YOUR REF : GBF4069X
 TYPE OF CLAIM : THIRD PARTY CLAIM
 CLAIMANT : TAN WAI MUN
 VEHICLE NO. : SJU5140S
 MAKE/ MODEL : HONDA FREED
 ACCIDENT DATE : 02/01/2018

MATERIAL COST

1PC	BOOTLID ✓ DT	\$	1,720.00
1PC	BOOTLID LOCK ✗	\$	227.00
1PC	BOOTLID RUBBER ✓	\$	114.00
1PC	BOOTLID OUTER HANDLE ✓ CRK.	\$	345.00
1PC	BOOTLID INNER TRIM BOARD ✓ CRK.	\$	248.00
1PC	REAR BUMPER R	\$	588.00
1PC	REAR LAMP RH ✗	\$	483.00
1PC	REAR LAMP LH ✗	\$	483.00
1PC	END INNER PANEL GARNISH ✓ Reform.	\$	96.00
		\$	4,304.00
	LESS : DISCOUNT 20%	\$	(860.80)
		\$	3,443.20

MATERIAL COST - SPECIAL NETT

1PC	"H" LOGO ✓ NEC	\$	30.00
1PC	"FREED" EMBLEM ✓ NEC	\$	50.00
1PC	CAR NUMBER PLATE ✗	\$	35.00
1SET	REVERSE SENSOR ?	\$	200 280.00
		\$	3,838.20

卓亚水喷漆公司

TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

BUSINESS REG. NO: 09935300L

GST REG. NO: 09-935300-L

4 days

03/01/2018

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING

78 SHENTON WAY #07-16

SINGAPORE 079120

ATTN: MOTOR CLAIMS DEPT.

Substation.

4/1/18.

- Lump Sum Repair.

- Question mark Item

Photo.

- Photo After Paint

90036121

sebastian.yeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED REPAIR BILL

YOUR REF : GBF4069X
 TYPE OF CLAIM : THIRD PARTY CLAIM
 CLAIMANT : TAN WAI MUN
 VEHICLE NO. : SJU5140S
 MAKE/ MODEL : **HONDA FREED**
 ACCIDENT DATE : 02/01/2018

BALANCE B/D \$ 3,838.20

LABOUR CHARGE

TO REMOVE & REFIX REAR WINDSCREEN \$ 120.00 ✓

TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING. \$ 30 120.00

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS. INCLUDING REMOVE & REFIX TAIL GATE. \$ 600 800.00

PUTTY AND SPRAY PAINTING ON ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS \$ 600 1,000.00

ADD : GST 7%

TOTAL :

\$ 5,878.20

\$ 411.47

\$ 6,289.67

SINGAPORE DOLLARS : SIX THOUSAND TWO HUNDRED EIGHTY NINE AND CENTS SIXTY SEVEN ONLY

NOTE: THE ESTIMATED PERIOD OF REPAIRS IS SIX (6) DAYS

TOH AH SWEE SPRAY PAINTING CO.

SALLY ANG (TEL : 63660286)