


SMRT Accident Vehicle Repair Estimates

China Taping

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6359K
 Ref. No : TAX/01/18/2002
 Reg. Date : 28/06/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TAN KIAT KIAT (CHEN JIJI)
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 01/01/2018 09:20:00 AM
 Accident Reported Date / Time : 02/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093872
 Special Instruction to ARC, if any :
 DROVE IN / SJH9467S
 Prepared Date : 02/01/2018 10:29:50 AM



Sebastian.
3/1/2018.
 - Part by part repair.
 - Question Mark Item
 Photo
 - Photo Before Paint

LRK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205768247

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	676.00	0.00
Total Spray Painting Charges :	738.00	0.00
Total Material Charges :	4,242.65	4,242.65
Other Charges :	240.00	0.00
TOTAL :	5,896.65	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sign Off Date :	03/01/2018 09:22:26 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 03/01/2018 09:22:26 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	0.00 400
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0.00 100
TO REPRAY LOWER RADIATOR SUPPORT	180.00 ?	0.00
Total Spray Painting & Panel Beating	738.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20 20
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	240.00	0.00

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>Deform</i>	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace <i>NEC</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace ?	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ?	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ?	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace ?	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace <i>✓</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>✓ cut</i>	No
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	Replace	Replace <i>✓ ns</i>	No
51220-42230		6505438	FOG LAMP LH	1	280.10	10.00	252.09	Replace	Replace <i>✓ cut</i>	No
51521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace ?	No
5310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace <i>✓ NEC</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace ?	No
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace ?	No
56851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace <i>✓ cut</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.22	Replace	Replace ?	No
51170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>✓ CRK</i>	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>✓ TN</i>	No
51410-42105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace ?	No
TOTAL MATERIALS								4,242.69	4,242.65	
TOTAL MATERIALS(Discounted)							4,242.65	4,242.65		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									