

12/01/2018

ASS. RE. BY:

REF: CS/EG18000246/Atton2

Special Instructions:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EG1

Date/Time:

04/01/2018 11:47am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 7110A

Insured:

GBB 9477P

at Workshop m/s

TC Autoclinic

Tel:

9645 0098

of

23 Long Kee Rd

Policy No:

Claim No:

GBB9477P / SE / pi

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

02/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

05-01-2018 @ 11am

H.O.D. Endorsement:

Date/Time:

04/01/2018 12:08pm

Person Contacted:

Kevin

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBD 7110A - X
	GBB 9477P - X
	Part by Part \$6122.38 ; 8 days (Red: 2872.72 : 31%)

Rajan

REF: EGI

3272R

ASSIGNMENT

From: Date: 05/01/2018

Veh No: GBD 7110A Yr Regd: 2015 F6B

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: GBD 7110A

Make: NISSAN NV350 2.5 cc 2488

at Workshop n/s TC Autoclinic

Colour: GREY A/C: Insured / Std / NI / NA

of 25 Leng Kee Rd

Sp. Reading: 67783 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: JN1MC2E2620003345

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

11 am

Brakes: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size: F: 195R13C

R: -

Bal. or Market Value:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

IDAC Accident Rpt: Consistent? : Yes or No

Front R/Bal. 6 mm Rear R/Bal. 6 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 6 mm

Est. Repairs: days Res: Yes or No

D.O.A. 02/01/18 D.O.I. 05/01/18

Lum Sum: % 3 Val: Yes or No

Survey held at TC AUTOCLINIC

CA / REV / REP. / 24 HRS 'up'

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 FEB 2018

Date/Time File Pass to?

: Preli. Report

Days Of Repair: 8

7/2 Typist

: Final Report

Resurvey No. of Trip: 1

Survey Fee

Date/Time File Return to?

Transportation

0

Add Fee: Site Insp \$

0-PS \$

Interview \$

Photo

Tech. Insp \$

Diagn

Weekend \$

Report Format :

Lump Sum / I.B.I: 6122.38

Box containing the number 250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18000246/R1tb	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 04-01-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 9477P	Veh. Inspected	GBD 7110A
Policy No.		Coverage (\$)	0.00
Claim No.	GBB9477/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	04/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/01/2018	Inspection Date	05/01/2018
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 4 January, 2018 11:47 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB9477P / TP : GBD7110A/LKK / DOA : 02/01/2018
Attachments: GBD7110A - SAS (TO AMEND ON DOA).pdf; GBD7110A - PRS FORM.pdf; GBD7110A - ESTIMATE.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **TC AUTOCLINIC PTE LTD**,

ADDRESS : 25 LENG KENG ROAD
SINGAPORE 159097

PERSON TO CONTACT : KELVIN HENG @ 9645 0098

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimates and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Date: 04.01.2018
 Our Reference: GBB 9477P/SE/pl
 Your Reference: GBD 7110A
 To: TC AUTOCLINIC PTE LTD

Sent via Fax
 or
 Email kelvinheng@tanchong.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBD 7110A
 Insured's Vehicle: GBB 9477P
 Date Of Accident: 02.01.2018


We acknowledge receipt of your request for PRS on: 03.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd *
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
 - Your request for inspection does not have your client's GIA report, kindly forward a copy.
 - We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
 - Our Insured's driver has not reported the accident to us to date.
 - Others: **We are therefore not in a position to discuss on liability at this juncture.**
- OFFICER-IN-CHARGE STEVE LIM - steve.lim@ergo.com.sg, 6829 9197**

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:
 Assignment Date: _____
 Assignment Time: _____

Workshop use only:
Assessor attended workshop on:
 Date: _____
 Time: _____
 Inspector: _____

Remarks:

Vehicle not available at the appointed date and time.
 Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.
 Note: Our Inspection is on a without admission to liability basis.

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 003/IC/TCAC/CCR/2018
DATE : 02-JAN-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : M/S NEDCOM SERVICES PTE LTD
ADDRESS : 51 TANNERY LANE
#08-02 SHARELY WAREHOUSE
S(347798)
TELEPHONE NO : 85910096/91994227

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : NTUC INCOME AGAINST ERGO
VEHICLE NO : GBD7110A
MODEL CODE : MVL2RDRE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25356985A
CHASSIS NO : JN1MC2E26Z0003345
MILEAGE : 1 KM
DATE IN : 02/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 02/01/2017

Fr: Kelvin Heng
96450098

kelvinheng@teuchong.com

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO GBD7110A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
3	ZZ/001	RENEW REAR BUMPER ASSY, END PANEL, BACKDOOR ASSY, BACKDOOR EMBLEMS, ETC, PANEL AND REPAIRS	2348.00 1560	✓
4	ZZ/002	RESRPAY REAR BUMPER ASSY, END PANEL, BACKDOOR ASSY, FLOOR PANEL.	1500.00 1000	✓
5	ZZ/003	TRANSFER BACKDOOR MECHANISM TO FACILITATES REPAIRS	240.00	✓
6	ZZ/004	REMOVE AND INSTALL BACKDOOR GLASS TO FACILITATES REPAIRS	180.00	✓
7	ZZ/005	CONSULT CHECK AND RETUNE ENGINE (INSURANCE CLAIM)		
8	ZZ/006	TO SUPPLY GPS BRACKET (BROKEN IN THE ACCIDENT)	20.00	X
		TOTAL LABOUR CHARGES	4455.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD7110A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	REAR BUMPER ASSEMBLY	85022-3XA0A	600.50	DE ✓	
2	SENSOR-REVERSE	SENSOR			✓ 200.00 NW ✓
3	MBR-CROSS, TAIL, OUTER	75615-3XA0A			✓ 138.50 BT ✓
4	MEMBER ASSY-CROSS, TAIL INNER	75614-3XA0A	411.80	BT ✓	
5	PLATE-CARPET, RR	74990-3XA0A	55.30	? X SW	
6	REAR BUMPER CENTRE FINISHER	85040-VZ00A	153.60	? ✓ HW ✓	
7	LAMP COMB RR, RH	26550-3XA0B	209.80	? X SW	
8	LAMP COMB RR, LH	26555-3XA0B	209.80	? X SW	
9	LAMP ASSY-LICENCE @ \$71.30 X 2	26510-9Y00A	142.60	? X SW	
10	URVAN EMBLEM	90892-3XY0A	✓ 59.70	NW ✓	
11	NISSAN EMBLEM	90890-JX00A	✓ 59.70	NW ✓	
12	WEATHER STRIP	90830-3XA0A	✓ 127.50	NW ✓	
13	DOOR BACK	K010M-3XBAA	✓ 1742.00	SW ✓	
14	FINISHER ASSY-BACK DOOR	90810-3XU1A	511.40	? X SW	
15	GLASS-TAIL GATE	90300-3XA0A	837.00	X X SW	
SUB TOTAL			5120.70	0.00	338.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1024.14	0.00	0.00
GRAND TOTAL			4096.56	0.00	338.50
OVERALL TOTAL			4435.06		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO G807110A

TOTAL LABOUR CHARGES	4455.00
TOTAL SPARE PARTS CHARGES	4435.06
GRAND TOTAL	8890.06 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Repair - HP 900 10068
05/01/18 @ 1140

8 days

Resin & 4 paint


10/1/2018

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8995-1

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 003/IC/TCAC/CCR/2018
DATE : 02-JAN-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : M/S NEDCOM SERVICES PTE LTD
ADDRESS : 51 TANNERY LANE
#08-02 SHARELY WAREHOUSE
S(347798)
TELEPHONE NO : 85910096/91994227

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5069701574-02
VEHICLE NO : GB07110A
MODEL CODE : MVL2RDRE26KW3GBR-D
MODEL/YEAR : NISSAN NV350 PANEL VAN MT EURO 5
ENGINE NO : YD25356985A
CHASSIS NO : JN1MC2E26Z0003345
MILEAGE : 1 KM
DATE IN : 02/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 02/01/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO G8D7110A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	55.00
3	ZZ/001	RENEW REAR BUMPER ASSY, END PANEL, BACKDOOR ASSY, BACKDOOR EMBLEMS, ETC, PANEL AND REPAIRS	2340.00	1560.00
4	ZZ/002	RESRPAY REAR BUMPER ASSY, END PANEL, BACKDOOR ASSY, FLOOR PANEL.	1500.00	1000.00
5	ZZ/003	TRANSFER BACKDOOR MECHANISM TO FACILITATES REPAIRS	240.00	240.00
6	ZZ/004	REMOVE AND INSTALL BACKDOOR GLASS TO FACILITATE REPAIRS	180.00	180.00
7	ZZ/005	CONSULT CHECK AND RETUNE ENGINE (INSURANCE CLAIM)		
8	ZZ/006	TO SUPPLY GPS BRACKET (BROKEN IN THE ACCIDENT)	20.00	.00
		TOTAL LABOUR CHARGES	4455.00	3155.00

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO GBD7110A

NETT ITEM	3286.10
LESS 20.00%)	-657.22
NETT AMOUNT	2628.88
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	338.50
LESS .00%)	0.00
SPECIAL NETT AMOUNT	338.50
TOTAL LABOUR CHARGES	3155.00
TOTAL SPARE PARTS CHARGES	2967.38
TOTAL CHARGES	6122.38
ADD 7 % GST	428.57
GRAND TOTAL	6550.95

TC AUTOCLINIC PTE LTD
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO GBD7110A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 NV350 EMBLEM (SUPPLEMENTARY)	90890-3XY0A	101.30	(CA) <i>neu</i>		OK
2 BACK DOOR LOCK COVER (SUPPLEMENTARY)	90542-VW000	30.00	(CA) <i>DE</i>		OK
3 MBR-CROSS, TAIL, OUTER	75615-3XA0A			138.50	OK
4 MEMBER ASSY-CROSS, TAIL INNER	75614-3XA0A	411.80			OK
5 PLATE-CARPET, RR	74990-3XA0A	55.30			X
6 REAR BUMPER CENTRE FINISHER (SUPPLEMENTARY)	85040-VZ00A	153.60			OK
7 LAMP COMB RR, RH	26550-3XA0B	209.80			X
8 REAR BUMPER ASSEMBLY	85022-3XA0A	600.50			OK
9 SENSOR-REVERSE	SENSOR			200.00	OK
10 LAMP COMB RR, LH	26555-3XA0B	209.80			X
11 LAMP ASSY-LICENCE @ \$71.30 X 2	26510-9Y00A	142.60			X
12 URVAN EMBLEM	90892-3XY0A	59.70			OK
13 NISSAN EMBLEM	90890-JX00A	59.70			OK
14 WEATHER STRIP	90830-3XA0A	127.50			OK
15 DOOR BACK	K010M-3XBAA	1742.00			OK
16 FINISHER ASSY-BACK DOOR	90810-3XU1A	511.40			X
17 GLASS-TAIL GATE	90300-3XA0A	837.00			X
SUB TOTAL		3286.10	0.00	338.50	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		657.22	0.00	0.00	
GRAND TOTAL		2628.88	0.00	338.50	
OVERALL TOTAL		2967.38			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18000246/R11bn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 08-02-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 9477P	Veh. Inspected	GBD 7110A
Policy No.		Coverage (\$)	0.00
Claim No.	GBB9477P/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	04/01/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV350 2.5	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1MC2E26Z0003345	Colour	GREY
Odometer	67783	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R13C	DUNLOP	6 mm
L/H Front Tyre	195 R13C	DUNLOP	6 mm
R/H Rear Tyre	195 R13C	DUNLOP	6 mm
L/H Rear Tyre	195 R13C	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/01/2018	Inspection Date	05/01/2018
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7110A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER ASSEMBLY (N)	DEFORMED	600.50	600.50
1	MEMBER ASSY-CROSS, TAIL INNER (N)	BENT	411.80	411.80
1	PLATE-CARPET, RR (N)	SERVICEABLE	55.30	-
1	REAR BUMPER CENTRE FINISHER (N)	BENT	153.60	153.60
1	LAMP COMB RR, RH (N)	SERVICEABLE	209.80	-
1	LAMP COMB RR, LH (N)	SERVICEABLE	209.80	-
2	LAMP ASSY-LICENCE @\$71.30 (N)	SERVICEABLE	142.60	-
1	URVAN EMBLEM (N)	NECESSARY	59.70	59.70
1	NISSAN EMBLEM (N)	NECESSARY	59.70	59.70
1	WEATHER STRIP (N)	NECESSARY	127.50	127.50
1	DOOR BACK (N)	BUCKLED	1,742.00	1,742.00
1	FINISHER ASSY-BACK DOOR (N)	SERVICEABLE	511.40	-
1	GLASS-TAIL GATE (N)	SERVICEABLE	837.00	-
1	NV350 EMBLEM (ADDITIONAL)(N)	NECESSARY	101.30	101.30
1	BACK DOOR LOCK COVER (ADDITIONAL)(N)	DEFORMED	30.00	30.00
	LESS 20% DISCOUNT		-1,050.40	-657.22
			4,201.60	2,628.88
<u>SPECIAL NETT ITEMS</u>				
1	SENSOR-REVERSE (SN)	NOT WORKING	200.00	200.00
1	MBR-CROSS, TAIL, OUTER (SN)	BENT	138.50	138.50
			338.50	338.50
<u>LABOUR</u>				
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	120.00
	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.		55.00	55.00
	RENEW REAR BUMPER ASSY, END PANEL, BACKDOOR ASSY, BACKDOOR EMBLEMS, ETC, PANEL AND REPAIRS.		2,340.00	1,560.00
	RESPRAY REAR BUMPER ASSY, END PANEL, BACKDOOR ASSY, FLOOR PANEL.		1,500.00	1,000.00
	TRANSFER BACKDOOR MECHANISM TO FACILITATES REPAIRS.		240.00	240.00

Report Ref No. CS/EGI18000246/R1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND INSTALL BACKDOOR GLASS TO FACILITATES REPAIRS.		180.00	180.00
	TO SUPPLY GPS BRACKET (BROKEN IN THE ACCIDENT).	NOT NECESSARY	20.00	-
			4,455.00	3,155.00
	GRAND TOTAL		8,995.10	6,122.38
RECOMMENDED COST OF REPAIRS				6,122.38

Report Ref No. CS/EG118000246/R1tbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.