

INS. CASE OWNER:

ONG LI LI

CC4/LPC18000251

IT/hg32

LKK:

IDAC:

Surveyor:

TANPILAH

DOI:

ASSIGNMENT

05/01/18

Date / Time:

04/01/18

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.:

SIL 3126U

Claim No.:

17/18/18/UP05/020316

Name of Insured:

TAN WEI MENG GEC

Policy No.:

217UP0506584

Insured Tel No.:

HP: 9322 3938

Make / Model:

MITSUBISHI COLT PLUS - 1.5 (A)

Excess Sec II :\$S

D.O.A: 01/01/18

Place of Accident:

ALONG GEYLANG LORONG 5

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLB 4660R

INSRS:

WSP: Autotrance

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

08/01/18 (UIC)

SLB 4660R -X ; SIL 3126U -X

STAGE

DATE / PIC

10/01/18

16/01/18 @

P2N

TP CON POSTAGE IN Y PAKING VIC SUB AGENT

TRAFFIC LIGHT ON TPB PASSAGE

FORWARDING TP CON TO LPC (UIC)

CALL OI. NO RESPONSE.

OI CALLED BACK. CONFIRMED ACCIDENT

DETAILS. INFORMED TP CLAIM & ACD

19/01/18. OI CONFIRMED NO ALCOHOL &

IMPLICATION TAKEN PRIOR TO RECOVERY.

REQUESTED TO GETLE & ACD & ACD

19/01/18.

BULK CLAIMS CLEAR

@ 12:05A

OPPOSE TO UIC (LPC), NO FINE. REPTD

VLS.

PINKETED.

26/01/18

TYPE REPORT WHILE FORWARDING TO LOD.

REPORT DONE

IN LOW IMP BY EVIDENCE 26 MAR 2018

20/01/18

RECEIVED WARRANTS TO LPC BY BULK.

LPC APPROVED WARRANTS.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

ELIMINARY ADVICE

Date/Time:

15/06/18

Sent By:

SS

04/07/18 - 954450. AL VICE IN ORDER.

Confirm by:

Email

Call

Email

Call

If NO or B 28, Ass. Lia:

COI 28/28/18 (UIC)

ORIGINAL LOD & POC

WITH LPC

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 150.00

Global Sum \$S:

25,695.07

Date/Time:

Confirm with:

Email

Call

Name 1:

Name 2:

Name 3:

Name 4:

Name 5:

Name 6:

Name 7:

Name 8:

Name 9:

Name 10:

Name 11:

Name 12:

Name 13:

Name 14:

Name 15:

Name 16:

Name 17:

Name 18:

Name 19:

Name 20:

Name 21:

Name 22:

Name 23:

Name 24:

Name 25:

Name 26:

Name 27:

Name 28:

Name 29:

Name 30:

Name 31:

Name 32:

Name 33:

Name 34:

Name 35:

Name 36:

Name 37:

Name 38:

Name 39:

Name 40:

Name 41:

Name 42:

Name 43:

Name 44:

Name 45:

Name 46:

Name 47:

Name 48:

Name 49:

Name 50:

Name 51:

Name 52:

Name 53:

Name 54:

Name 55:

Name 56:

Name 57:

Name 58:

Name 59:

Name 60:

Name 61:

Name 62:

Name 63:

Name 64:

Name 65:

Name 66:

Name 67:

Name 68:

Name 69:

Name 70:

Name 71:

Name 72:

Name 73:

Name 74:

Name 75:

Name 76:

Name 77:

Name 78:

Name 79:

Name 80:

Name 81:

Name 82:

Name 83:

Name 84:

Name 85:

Name 86:

Name 87:

Name 88:

Name 89:

Name 90:

Name 91:

Name 92:

Name 93:

Name 94:

Name 95:

Name 96:

Name 97:

Name 98:

Name 99:

Name 100:

RECEIVED 05 JUL 2018

10/2/2018

Tanjil

REF: IPC

Ref: 024/LPC 1300025/11h55

ASSIGNMENT

2016 April

From: _____ Date: 05/01/2018
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLB 4660R
at Workshop m/s: Autofrance
of 30B Alexandra Rd
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 12 days Res.: Yes or No
Lum Sum: - % 3 Val: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLB 4660R Vt Regn: _____
Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
Truck / Trailer or: _____
Make: Peugeot 3008 C/C 1580
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 034520 T/Radio: Insured / Std / NI / NA
Eng. No: _____
C/No: VF 3049HD 8 F S24 5155
Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or
Tyre Size: F: 225/50K17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: _____ D.O.I: 5/1/18 @ 1700
Survey held at: Autofrance
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rear & u/c.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
1.A. [Expense \$14,000.00, week 6,766.80] 15/2/18.
P/P \$23,115.02
CR00: 5,461.58 (19%)

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report
1) _____
Date/Time, File Return to? _____
2) _____
Report Format: _____
Lump Sum / I.B.I: (\$ _____)
Days Of Repair: _____
Resurvey No. of Trip: _____
Survey Fee: _____
Transportation: _____
Add Fee: ☐ : Site Insp (\$ _____) ☐ : S-PS (\$ _____)
☐ : Interview (\$ _____) ☐ : Photos
☐ : Tech. Invs (\$ _____) ☐ : Other
☐ : Weekend (\$ _____)
TOTAL: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18000251/T1hs3		
300 BEACH ROAD		Date : 04-01-2018		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 3126U	Veh. Inspected	SLB 4660R	
Policy No.	Z17VP05016584	Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020316	Excess (\$)	0.00	
Assign From		Assign Date	04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/01/2018	Inspection Date	05/01/2018	
Survey held at	AUTOFRANCE 305, ALEXANDRA ROAD SINGAPORE 159942.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3493
Date Estimated : 03/01/2018
Prepared By : Wong Guo Xiang

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Chen Si Xuan
85 Anchorvale Crescent
#09-30

Singapore 544627

- ACCOUNT - 2000

CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB4660R	VF30U9HD8FS245955	08/04/2016	3008 1.6 ETG	0

DESCRIPTION

VALUE

SUNDRIES

hec 500 150.00

REPLACE/REPAIR REAR BUMPER, REAR LHS FENDER, REAR END PANEL 600

2400 3,600.00

RESPRAY REAR BUMPER, REAR LHS FENDER, REAR END PANEL 600

1800 2,400.00

WIRING CONNECTION & CHECK (NETT)

✓ 150.00

REMOVE & REFIX REVERSE SENSOR (NETT)

✓ 150.00

REMOVE & REFIX REAR LIGHTING SYSTEM (NETT)

? ✓ 150.00

REMOVE & REFIX REAR BOOT COMPARTMENT INNER TRIM & GARNISH (NETT)

✓ 300.00

REMOVE & REPLACE ROOF LINING (NETT)

✓ 600.00

REMOVE & REPLACE LHS SIDE AIRBAG, LHS SEAT AIRBAG (NETT)

2400 600.00

REMOVE & REPLACE FRT SEATS BELT (NETT)

my ? X 600.00

REMOVE, REPLACE, RECALIBRATE AIRBAG MODULE (NETT)

✓ 600.00

REMOVE & REPLACE REAR LHS QUARTER GLASS (NETT)

✓ 300.00

INNER SEAL FOR REAR LHS QUARTER GLASS (NETT)

hec ✓ 60.00

SEALANT FOR REAR LHS QUARTER GLASS (NETT)

hec ✓ 50.00

TO SUPPLY & INSTALL REAR LHS QUARTER GLASS 3M SOLAR FILM (NETT)

hec ✓ 250.00

WHEEL ALIGNMENT (NETT)

✓ 600.00

REMOVE & REPLACE REAR SUSPENSION SYSTEM (NETT)

2500 1,500.00

WHEEL BALANCING @ \$60 PER UNIT

60 120.00

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3493
Date Estimated : 03/01/2018
Prepared By : Wong Guo Xiang

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB4660R	VF30U9HD8FS245955	08/04/2016	3008 1.6 ETG	0

DESCRIPTION

TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR
FAULT CODES (NETT)

VALUE

600.00

Total Labour 1: 12,780.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
00007410JP	REAR BUMPER	1	950.00	10.00	855.00
00007416P9	RR BUMPER END BRACKET SET - P3008	1	108.00	10.00	97.20
00007416Q0	RR BUMPER SIDE BRACKET SET - P3008	1	80.00	10.00	72.00
00007452ZC	RR BUMPER FINISHER SET - P3008	1	135.00	10.00	121.50
00007452ZE	RR BUMPER LWR PROTECTOR	1	380.00	10.00	342.00
1613431980	RR LWR PAN FIXING KIT	1	98.00	10.00	88.20
00008569XE	RR QUARTER GLASS LH - P3008/5008	1	322.00	0.00	322.00
00008525YY	REAR FENDER LH - P3008	1	1,100.00	0.00	1,100.00
00008533J2	RR MUDGUARD LH	1	112.00	10.00	100.80
00008338TX	ROOF HEADLINING	1	1,100.00	10.00	990.00
98019799XX	PIROTECHNIC SAFETY BELT LH	1	690.00	10.00	621.00
98019797XX	PIROTECHNIC SAFETY BELT RH	1	690.00	10.00	621.00
98019826XT	SEAT BELT PRETENSIONER ATTACH	2	285.00	10.00	513.00
00008976Q8	FRT SEAT BELT BUCKLE - P3008	2	185.00	10.00	333.00
00008977C4	SAFETY-BELT RETURN ADJUSTMENT	2	91.00	10.00	163.80
9805511380	TAILGATE LIGHT LH	1	186.00	10.00	167.40
00006350HG	RR BUMPER FOG LAMP LH	1	90.00	10.00	81.00
00008216XV	PYRO AIR BAG <i>Rouk</i>	1	1.00	0.00	1.00
9801663080	AIRBAG <i>sent</i>	1	1.00	0.00	1.00
0000424946	RR HUB DISC (1PC) - P3008,B9	1	226.00	10.00	203.40
0000374894	HUB BEARING	1	212.00	10.00	190.80
0000517645	LHR WHEEL SWIVEL	1	130.00	10.00	117.00
00005148W4	RR SUSPENSION X-MEMBER	1	2,098.00	10.00	1,888.20
0000516530	UPPER CUP	1	10.00	10.00	9.00
0000516436	CUP	1	25.00	10.00	22.50
9811521080	RR SHOCK-ABSORB	1	140.00	10.00	126.00
00006546CG	AIR BAG ECU	1	650.00	10.00	585.00
00008216XR	ABL SENSOR	2	100.00	10.00	180.00
9811536380	EMITTER MODULE, TYRE SENSOR	1	94.00	10.00	84.60
98024623ZV	ALLOY WHEEL (OSIRIS J17)	1	780.00	10.00	702.00

Total Parts : 10,699.40

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3493
Date Estimated : 03/01/2018
Prepared By : Wong Guo Xiang

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB4660R	VF30U9HD8FS245955	08/04/2016	3008 1.6 ETG	0

Tanpin 97495749
- WP
05/01/18 @ 1700.
10-12 days
* Resurvey before paint
sur@lkkands.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

24771.60

Labour 1	:	12,780.00
Parts	:	10,699.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,643.56
Grand Total	:	25,122.96

Customer Service Officer

Contact

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

28546.60

855.00	97.20		50.00	100.00
342.00	72.00		2400.00	1200.00
88.20	121.50		1800.00	600.00
322.00	621.00		150.00	150.00
1100.00	621.00		150.00	600.00
100.80	513.00		300.00	1500.00
990.00	333.00		600.00	60.00
81.00	163.80		600.00	
1.00	167.40		600.00	
1.00	203.40		300.00	
585.00	190.80		60.00	
180.00	117.00		50.00	
84.60	1888.20		250.00	
702.00	9.00	0.00	600.00	
	22.50		60.00	
	126.00		600.00	
		0.00	8570.00	4210.00
	5266.80			

5432.60

10699.40	0.00	12780.00
5432.60	0.00	8570.00
5266.80	0.00	4210.00

0.00

0.00

0.00

5432.60

8570.00

14002.60

97.20
72.00
121.50
621.00
621.00
513.00
333.00
163.80
167.40
203.40
190.80
117.00
1888.20
9.00
22.50
126.00
150.00
600.00
750.00
6766.80

}

CHECK ITEM

✓
6/3/18



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/18/18/VP05/020316
Our ref: CC4/LPC18000251/T1hs3

Date: 15/03/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLB 4660R


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.01.2018 at the M/s Autofrance (Alexandra) have the following to report:-

Workshop Estimate Amount	: S\$	23,479.40
Revised Estimate Amount	: S\$	14,002.60
"Check" Items Amount	: S\$	6,766.80
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion & UC



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 - 12.0 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

3275

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. 52907220C GST Regs. No. M2-0000551-1

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Service Booking: 6477 7377

Parts: 6477 7420

Vantage 24-Hour Assist: 6473 8588

Fax: 6477 7300

**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. bp 114110	Date IN 16/01/2018 Payment Term 30 Days From Invoice Customer Service Advisor Wong Guo Xiang	Invoice Number Invoice Date Invoice By Wong Guo Xiang	Page No. 1 of 2
CUSTOMER INFORMATION Qairul Fahmi Bin Sapari Blk 528A Pasir Ris Street 51 #05-669 Singapore 511528		INVOICE TO 14805 Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555	
REGISTRATION No. SLB4660R	CHASSIS No. VF30U9HD8FS245955	STOCK No. 209044	REGISTRATION DATE 08/04/2016
MODEL 3008 1.6 ETG		MILEAGE 0	

CODE	DESCRIPTION	UNITS	DISC %	NETT
	SUNDRIES	1	0.00	50.00
	REPLACE/REPAIR REAR BUMPER, REAR LHS FENDER, REAR END PANEL	1	0.00	2,400.00
	RESPRAY REAR BUMPER, REAR LHS FENDER, REAR END PANEL	1	0.00	1,800.00
	WIRING CONNECTION & CHECK (NETT)	1	0.00	150.00
	REMOVE & REFIX REVERSE SENSOR (NETT)	1	0.00	150.00
	REMOVE & REFIX REAR LIGHTING SYSTEM (NETT)	1	0.00	150.00
	REMOVE & REFIX REAR BOOT COMPARTMENT INNER TRIM & GARNISH (NETT)	1	0.00	300.00
	REMOVE & REPLACE ROOF LINING (NETT)	1	0.00	600.00
	REMOVE & REPLACE LHS SIDE AIRBAG, LHS SEAT AIRBAG (NETT)	1	0.00	600.00
	REMOVE, REPLACE, RECALIBRATE AIRBAG MODULE (NETT)	1	0.00	600.00
	REMOVE & REPLACE REAR LHS QUARTER GLASS (NETT)	1	0.00	300.00
	INNER SEAL FOR REAR LHS QUARTER GLASS (NETT)	1	0.00	60.00
	SEALANT FOR REAR LHS QUARTER GLASS (NETT)	1	0.00	50.00
	TO SUPPLY & INSTALL REAR LHS QUARTER GLASS 3M SOLAR FILM (NETT)	1	0.00	250.00
	WHEEL ALIGNMENT (NETT)	1	0.00	600.00
	REMOVE & REPLACE REAR SUSPENSION SYSTEM (NETT)	1	0.00	1,500.00
	WHEEL BALANCING @ \$60 PER UNIT	1	0.00	60.00
	TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR FAULT CODES (NETT)	1	0.00	600.00
	VEHICLE TOWED TO VAL DUE TO ACCIDENT	1	0.00	150.00 (H)
	TO REWRAP FRT PASSENGER LEATHER SEAT COVER	1	0.00	300.00 (H)
	TO CONDUCT CAR O LINER CHASSIS ALIGNMENT & MEASUREMENT	1	0.00	1,680.00 (H)
	TO REPAIR REAR RHS FENDER	1	0.00	600.00 (H)
	TO RESPRAY REAR RHS FENDER	1	0.00	600.00 (H)
Sub-Total :				13,550.00

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Co. Regs. No. S2907220C GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942Service Booking: 6477 7377
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300**PEUGEOT****SERVICE TAX INVOICE**

RE-PRINT

REPAIR ORDER NO. bp 114110	Date IN 16/01/2018	Invoice Number	Page No. 2 of 2
	Payment Term 30 Days From Invoice	Invoice Date	
	Customer Service Advisor Wong Guo Xiang	Invoice By Wong Guo Xiang	

CODE	DESCRIPTION	UNITS	DISC %	NETT
000074522E	RR BUMPER LWR PROTECTOR	1	10.00	342.00
1613431980	RR LWR PAN FIXING KIT	1	10.00	88.20
00006350HG	RR BUMPER FOG LAMP LH	1	10.00	81.00
0000424946	RR HUB DISC (1PC) - P3008,B9	1	10.00	162.72
0000374894	HUB BEARING	1	10.00	190.80
9811521080	RR SHOCK-ABSORB	1	10.00	126.00
9811536380	EMITTER MODULE,TYRE SENSOR	1	10.00	84.60
98024623ZV	ALLOY WHEEL (OSIRIS J17)	1	10.00	702.00
0000517645	LHR WHEEL SWIVEL	1	10.00	117.00
00006546CG	AIR BAG ECU	1	10.00	585.00
00008216XR	ABL SENSOR	2	10.00	180.00
00005148W4	RR SUSPENSION X-MEMBER	1	10.00	1,888.20
00007410JP	REAR BUMPER	1	10.00	855.00
00008338TX	ROOF HEADLINING	1	10.00	990.00
00008525YY	REAR FENDER LH - P3008	1	10.00	990.00
00008533J2	RR MUDGUARD LH	1	10.00	100.80
00008569XE	RR QUARTZ GLASS LH - P3008/5008	1	10.00	289.80
9801663080	AIRBAG	1	10.00	647.10
00007203P0	RR BUMPER REINFORCEMENT - P3008	1	10.00	400.50
00008216XW	PYRO AIR BAG	1	10.00	647.10
00007416P9	RR BUMPER END BRACKET SET - P3008	1	10.00	97.20
Sub-Total :				9,565.02

Attending CSO : Wong

Should you require further explanation, please reach me at 64777409

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$ 23,115.02
Labour Charges	13,550.00	Less Insurance Excess	S\$ 0.00
Parts Charges	9,565.02	GST @ 7%	S\$ 1,618.05
Lubricant/Misc	0.00	Invoice Total Amounts	S\$ 24,733.07
		Less Deposit/Voucher	S\$ 0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$ 24,733.07

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.

Catherine Chong (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Thursday, 4 January, 2018 11:51 AM
To: natarajan.k.rajan@simedarby.com.sg; assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/18/18/VP05/020316 VANTAGE// REQ FOR DIRECT SETTLEMENT- SLB4660R AND SJL3126U ON 01/01/2018 (Car In Work Shop)
Attachments: estimate - slb4660r.pdf; GIA - SLB4660R.PDF

Dear Kavidha,

Please note that we will be appointing Mohammed Rasul from LKK Auto Consultants Pte Ltd for survey.

Kindly liaise with our surveyor for direct settlement and liability status.

Dear Catherine,

FYA.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

04012018 @ 12.13pm
Guo Xiang veh in
Taufik.

From: Natarajan Kavidha Rajan [<mailto:natarajan.k.rajan@simedarby.com.sg>]
Sent: Thursday, 4 January, 2018 10:43 AM
To: GERALD POH WEE BIN
Cc: CHEW BENG KEE; Mohamed Shabir Abdul Hamid; Wong Guo Xiang
Subject: VANTAGE// REQ FOR DIRECT SETTLEMENT- SLB4660R AND SJL3126U ON 01/01/2018 (Car In Work Shop)

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU/rental.

***KINDLY ARRANGE FOR SURVEY, TOMORROW(05/01/18), AS THE CAR IS IN THE WORKSHOP**

Warmest Regards,
Kavidha Rajan (Kavi)
Assistant Executive for Accident & Insurance Claims

Tel : +65 64777364

Fax : +65 64777398

Email : natarajan.k.rajan@simedarby.com.sg

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

AutoFrance

A division of Vantage Automotive Limited
 BUSINESS REGN. NO. 52907220C
 305 Alexandra Road
 Singapore 159942
 Tel (65) 6376 2288
 Fax (65) 6477 7373
Sales
 Tel (65) 6376 2288
 Fax (65) 6477 7373
Service/Parts
 Tel (65) 6477 7377/420
 Fax (65) 6477 7398
24-hr Roadside Assistance
 Tel (65) 6473 8588
www.peugeot.com.sg

SATISFACTION CUM DISCHARGE VOUCHER

Date: _____

To: Longce Insurance Bhd

MOTOR VEHICLE CLAIM

Vehicle Owner's Name: Qaisul Fahmi Bin Sapari

Vehicle Registration No.: SLB 4660 R

Make / Model: Peugeot 3008

Motor Policy Number: GA309939/1


Date of Accident: 01/01/2018

Owner's Excess: Nil

Repairs Cost: _____

I/We certify that the repairs to my/our vehicle number SLB4660R have been completed by AutoFrance, a division of Vantage Automotive Limited, of 305 Alexandra Road, Singapore 159942, to my/our entire satisfaction. Payment of the repair charges that are claimable under the Policy will be deemed and settled by me/us.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Owner/Insured Signature: 

Date: 14/02/18

Job No.: BP 114110



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18000251/T1hb3s2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 05-07-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 3126U	Veh. Inspected	SLB 4660R
Policy No.	Z17VP05016584	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020316	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	PEUGEOT 3008	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF30U9HD8FS245955	Colour	BLUE
Odometer	034520	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R17	MICHELIN	6 mm
L/H Front Tyre	225/50R17	MICHELIN	6 mm
R/H Rear Tyre	225/50R17	MICHELIN	6 mm
L/H Rear Tyre	225/50R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/01/2018	Inspection Date	05/01/2018
Survey held at	AUTOFRANCE 305, ALEXANDRA ROAD SINGAPORE 159942.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 4660R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (SN)	DEFORMED	855.00	855.00
1	RR BUMPER END BRACKET SET - P3008 (SN)	NECESSARY	97.20	97.20
1	RR BUMPER SIDE BRACKET SET - P3008 (SN)	NOT NECESSARY	72.00	-
1	RR BUMPER FINISHER SET - P3008 (SN)	NOT NECESSARY	121.50	-
1	RR BUMPER LWR PROTECTOR (SN)	DEFORMED	342.00	342.00
1	RR LWR PAN FIXING KIT (SN)	NECESSARY	88.20	88.20
1	RR QUARTR GLASS LH - P3008/5008 (SN)	NECESSARY	322.00	289.80
1	REAR FENDER LH - P3008 (SN)	BENT	1,100.00	990.00
1	RR MUDGUARD LH (SN)	DEFORMED	100.80	100.80
1	ROOF HEADLINING (SN)	DEFORMED	990.00	990.00
1	PIROTECHNIC SAFETY BELT LH (SN)	NOT NECESSARY	621.00	-
1	PIROTECHNIC SAFETY BELT RH (SN)	NOT NECESSARY	621.00	-
2	SEAT BELT PRETENTIONER ATTACH (SN)	NOT NECESSARY	513.00	-
2	FRT SEAT BELT BUCKLE - P3008 (SN)	NOT NECESSARY	333.00	-
2	SAFETY-BELT RETURN ADJUSTMENT (SN)	NOT NECESSARY	163.80	-
1	TAILGATE LIGHT LH (SN)	NOT NECESSARY	167.40	-
1	RR BUMPER FOG LAMP LH (SN)	MISSING	81.00	81.00
1	PYRO AIR BAG ROOF (SN)	ACTIVATED	647.10	647.10
1	AIRBAG (SN)	ACTIVATED	647.10	647.10
1	RR HUB DISC (1PC) - P3008, B9 (SN)	BENT	203.40	162.72
1	HUB BEARING (SN)	BENT	190.80	190.80
1	LHR WHEEL SWIVEL (SN)	BENT	117.00	117.00
1	RR SUSPENSION X-MEMBER (SN)	BENT	1,888.20	1,888.20
1	UPPER CUP (SN)	NOT NECESSARY	9.00	-
1	CUP (SN)	NOT NECESSARY	22.50	-
1	RR SHOCK-ABSORB (SN)	DISTORTED	126.00	126.00
1	AIR BAG ECU (SN)	ACTIVATED	585.00	585.00
2	ABL SENSOR (SN)	ACTIVATED	180.00	180.00
1	EMITTER MODULE, TYRE SENSOR (SN)	NECESSARY	84.60	84.60
1	ALLOY WHEEL (OSIRIS J17) (SN)	CUT	702.00	702.00
1	SUNDRIES (SN)	NECESSARY	150.00	50.00

Report Ref No. CC4/LPC18000251/T1hb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	INNER SEAL FOR REAR LHS QUARTER GLASS (SN)	NECESSARY	60.00	60.00
1	SEALANT FOR REAR LHS QUARTER GLASS (SN)	NECESSARY	50.00	50.00
1	REAR LHS QUARTER GLASS 3M SOLAR FILM (SN)	NECESSARY	250.00	250.00
1	RR BUMPER REINFORCEMENT - P3008 (SN) (ADDITIONAL)	BENT	445.00	400.50
1	FRT PASSENGER LEATHER SEAT COVER (SN) (ADDITIONAL)	TORN	300.00	300.00
			13,246.60	10,275.02
	LABOUR			
	REPLACE / REPAIR REAR BUMPER, REAR LHS FENDER, REAR END PANEL.		3,600.00	2,400.00
	RESPRAY REAR BUMPER, REAR LHS FENDER, REAR END PANEL.		2,400.00	1,800.00
	WIRING CONNECTION & CHECK.		150.00	150.00
	REMOVE & REFIX REVERSE SENSOR.		150.00	150.00
	REMOVE & REFIX REAR LIGHTING SYSTEM.		150.00	150.00
	REMOVE & REFIX REAR BOOT COMPARTMENT INNER TRIM & GARNISH.		300.00	300.00
	REMOVE & REPLACE ROOF LINING.		600.00	600.00
	REMOVE & REPLACE LHS SIDE AIRBAG, LHS SEAT AIRBAG.		600.00	600.00
	REMOVE & REPLACE FRT SEATS BELT.	NOT NECESSARY	600.00	-
	REMOVE, REPLACE, RECALIBRATE AIRBAG MODULE.		600.00	600.00
	REMOVE & REPLACE REAR LHS QUARTER GLASS.		300.00	300.00
	WHEEL ALIGNMENT.		600.00	600.00
	REMOVE & REPLACE REAR SUSPENSION SYSTEM.		1,500.00	1,500.00
	WHEEL BALANCING.		120.00	60.00
	TO CONDUCT ECU COMPUTER INCLUDING CLEAR FAULT CODES.		600.00	600.00
	TO CONDUCT CAR O LINER CHASSIS ALIGNMENT & MEASUREMENT.		1,680.00	1,680.00
	TO REPAIR REAR RHS FENDER.		600.00	600.00
	TO RESPRAY REAR RHS FENDER.		600.00	600.00
	VEHICLE TOWED TO VAL DUE TO ACCIDENT.		150.00	150.00
			15,300.00	12,840.00

Report Ref No. CC4/LPC18000251/T1hb3s2



GRAND TOTAL		28,546.60	23,115.02
RECOMMENDED COST OF REPAIRS			23,115.02

Report Ref No. CC4/LPC18000251/T1hb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.