

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3493
Date Estimated : 03/01/2018
Prepared By : Wong Guo Xiang

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Chen Si Xuan
85 Anchorvale Crescent
#09-30

Singapore 544627

- ACCOUNT - 2000
CASH - Sale service

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB4660R	VF30U9HD8FS245955	08/04/2016	3008 1.6 ETG	0

DESCRIPTION

SUNDRIES

VALUE

	50	150.00
REPLACE/REPAIR REAR BUMPER, REAR LHS FENDER, REAR END PANEL	600	2400 3,600.00
RESpray REAR BUMPER, REAR LHS FENDER, REAR END PANEL	600	1800 2,400.00
WIRING CONNECTION & CHECK (NETT)	✓	150.00
REMOVE & REFIX REVERSE SENSOR (NETT)	✓	150.00
REMOVE & REFIX REAR LIGHTING SYSTEM (NETT)	?	150.00
REMOVE & REFIX REAR BOOT COMPARTMENT INNER TRIM & GARNISH (NETT)	✓	300.00
REMOVE & REPLACE ROOF LINING (NETT)	✓	600.00
REMOVE & REPLACE LHS SIDE AIRBAG, LHS SEAT AIRBAG (NETT)	800 ✓	600.00
REMOVE & REPLACE FRT SEATS BELT (NETT)	?	600.00
REMOVE, REPLACE, RECALIBRATE AIRBAG MODULE (NETT)	✓	600.00
REMOVE & REPLACE REAR LHS QUARTER GLASS (NETT)	✓	300.00
INNER SEAL FOR REAR LHS QUARTER GLASS (NETT)	✓	60.00
SEALANT FOR REAR LHS QUARTER GLASS (NETT)	✓	50.00
TO SUPPLY & INSTALL REAR LHS QUARTER GLASS 3M SOLAR FILM (NETT)	✓	250.00
WHEEL ALIGNMENT (NETT)	✓	600.00
REMOVE & REPLACE REAR SUSPENSION SYSTEM (NETT)	750?	1,500.00
WHEEL BALANCING @ \$60 PER UNIT	60	120.00

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

169842, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BP 3493
Date Estimated : 03/01/2018
Prepared By : Wong Guo Xiang

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB4660R	VF30U9HD8FS245955	08/04/2016	3008 1.6 ETG	0

DESCRIPTION

TO CONDUCT ECU COMPUTER DIAGNOSTIC INCLUDING CLEAR
FAULT CODES (NETT)

VALUE

✓ 600.00

Total Labour 1: 12,780.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
00007410JP	REAR BUMPER	1	950.00	10.00	de ✓ 855.00
00007416P9	RR BUMPER END BRACKET SET - P3008	1	188.00	10.00	de ✓ 97.20
00007416Q0	RR BUMPER SIDE BRACKET SET - P3008	1	80.00	10.00	de ✓ 72.00
00007452ZC	RR BUMPER FINISHER SET - P3008	1	135.00	10.00	de ✓ 121.50
00007452ZE	RR BUMPER LWR PROTECTOR	1	380.00	10.00	de ✓ 342.00
1613431980	RR LWR PAN FIXING KIT	1	98.00	10.00	de ✓ 88.20
00008569XE	RR QUARTZ GLASS LH - P3008/5008	1	322.00	0.00	de ✓ 322.00
00008525YY	REAR FENDER LH - P3008	1	1,100.00	0.00	de ✓ 1,100.00
00008533J2	RR MUDGUARD LH	1	112.00	10.00	de ✓ 100.80
00008338TX	ROOF HEADLINING	1	1,100.00	10.00	de ✓ 990.00
98019799XX	PIROTECHNIC SAFETY BELT LH	1	690.00	10.00	de ✓ 621.00
98019797XX	PIROTECHNIC SAFETY BELT RH	1	690.00	10.00	de ✓ 621.00
98019826XT	SEAT BELT PRETENTIONER ATTACH	2	285.00	10.00	de ✓ 513.00
00008976Q8	FRT SEAT BELT BUCKLE - P3008	2	185.00	10.00	de ✓ 333.00
00008977C4	SAFETY-BELT RETURN ADJUSTMENT	2	91.00	10.00	de ✓ 163.80
9805511380	TAILGATE LIGHT LH	1	186.00	10.00	de ✓ 167.40
00006350HG	RR BUMPER FOG LAMP LH	1	90.00	10.00	de ✓ 81.00
00008216XW	PYRO AIR BAG <i>Roof</i>	1	1.00	0.00	act ✓ 1.00
9801663080	AIRBAG <i>seat</i>	1	1.00	0.00	act ✓ 1.00
0000424946	RR HUB DISC (1PC) - P3008, B9	1	226.00	10.00	de ✓ 203.40
0000374894	HUB BEARING	1	212.00	10.00	de ✓ 190.80
0000517645	LHR WHEEL SWIVEL	1	130.00	10.00	de ✓ 117.00
00005148W4	RR SUSPENSION X-MEMBER	1	2,098.00	10.00	de ✓ 1,888.20
0000516530	UPPER CUP	1	10.00	10.00	de ✓ 9.00
0000516436	CUP	1	25.00	10.00	de ✓ 22.50
9811521080	RR SHOCK-ABSORB	1	140.00	10.00	de ✓ 126.00
00006546CG	AIR BAG ECU	1	650.00	10.00	act ✓ 585.00
00008216XR	ABL SENSOR	2	100.00	10.00	act ✓ 180.00
9811536380	EMITTER MODULE, TYRE SENSOR	1	94.00	10.00	act ✓ 84.60
98024623ZV	ALLOY WHEEL (OSIRIS J17)	1	780.00	10.00	act ✓ 702.00
Total Parts :					10,699.40

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No.	:	BP 3493	Page No. :	3 of 3
Date Estimated	:	03/01/2018		
Prepared By	:	Wong Guo Xiang		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLB4660R	VF30U9HD8FS245955	08/04/2016	3008 1.6 ETG	0

Tanpin 97495749
- WP
05/01/18 @ 1700.
10-12 days
* Resurvey before paint
sur @ lkkando.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

		Labour 1	:	12,780.00
		Parts	:	10,699.40
		Labour 2	:	0.00
		Excess	:	0.00
		Total GST @ 7%	:	1,643.56
Customer Service Officer	Contact	Grand Total	:	25,122.96

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.