

ASS. REC. BY:

REF: CS/SMD18000258/Tlgbnz Special Instruction:

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMD

Date/Time

04/01/2018 9:16am

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 2963M

Insured:

SJX 7324A

at Workshop m/s

Yermogen

Tel:

6704 4586

of

6 Bandi Sector

Policy No:

Claim No:

CMTD1800062 / AGC

Sum Insured:

Excess:

Make of Veh:

D.O.A:

29122017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi

H.O.D. Endorsement:

Date/Time:

04/01/2018 10:15am

Person Contacted:

Pila

Vehicle: ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 2963M - X

SJX 7324A - X

08/1/18 @ 12pm raised to Agnes Chan by email.

14/5/18 @ 11.57am confirmed with Paula LS \$6600, 3 days by email.

Cled \$9784.03, 86%)

Sanitizer

Tanglin

REF:

SMO

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLJ2963M

Yr Regn:

2016 / Dec.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Handy Grace

C.C.

1496

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

81853

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GM 41105450

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

0

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

04/01/18 04pm

Survey held at

Vermogen 6 Rawi Sector

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

1) 24/5/18

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

7P

1600

350

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18000258/T1qb		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 04-01-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJX 7324A	Veh. Inspected	SLJ 2963M	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800062/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/12/2017	Inspection Date	04/01/2018	
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1800062/AGC

Date: 08th January 2018

Our Ref: CS/SMO18000258/T1qb

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLJ 2963M .


We thank you for the instruction on 04/01/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/01/2018 at the premises of M/s VERMOGEN and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,639.28</u> .
Revised Estimate Amount	: S\$ <u>1,818.40</u> .
"Check" Items Amount	: S\$ <u>300.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorized repair.

Yours faithfully

Taufikh
Automobile Assessor

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 4 January, 2018 9:26 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: pila.vermogenace@gmail.com; edmondvermogenace@gmail.com;
minokovermogenace@gmail.com; paulovermogenace@gmail.com;
ezelvermogenace@gmail.com; vermogenace@gmail.com;
vmg.vermogenace@gmail.com; Chan, Shu Hui Agnes; Henry, Irene James
Subject: CMTD1800062/AGC - ACCIDENT INVOLVING SJX7324A & SLJ2963M ON 29.12.2017
Attachments: SLJ2963M 20171229 TP ADDENDUM ADDED.PDF

Our Reference : CMTD1800062/AGC

Dear LKK AUTO/ Mohd Taufikh,

Please make arrangement to conduct the survey for SLJ2963M.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: pila.vermogenace@gmail.com [mailto:pila.vermogenace@gmail.com]
Sent: Thursday, January 04, 2018 9:20 AM
To: Teo, Grace; edmondvermogenace@gmail.com
Cc: minokovermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com;
vermogenace@gmail.com; vmg.vermogenace@gmail.com; Chan, Shu Hui Agnes; Henry, Irene James
Subject: RE: CMTD1800062/AGC - ACCIDENT INVOLVING SJX7324A & SLJ2963M ON 29.12.2017

Dear Grace,

Kindly arrange LKK Auto Consultants - Mohd Taufikh (West area).

Thanks & regards,

Pila
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Thursday, January 4, 2018 9:15 AM
To: 'edmondvermogenace@gmail.com' <edmondvermogenace@gmail.com>
Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vermogenace@gmail.com; vmg.vermogenace@gmail.com; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1800062/AGC - ACCIDENT INVOLVING SJX7324A & SLJ2963M ON 29.12.2017

Our Reference : CMTD1800062/AGC
Your Reference: SLJ2963M

Without Prejudice

Date: 4TH January 2018

Attention:
M/S VERMOGEN ACE PTE LTD

ACCIDENT INVOLVING SJX7324A & SLJ2963M ON 29.12.2017

Dear Edmond,

We refer to your Notice of Accident dated 03/01/2018.

Please be informed that Agnes Chan the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	

		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Wong, Shi Yi Shery

Sent: Wednesday, January 03, 2018 4:46 PM

To: 'edmondvermogenace@gmail.com'; Claims - Motor Survey

Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vermogenace@gmail.com; vmg.vermogenace@gmail.com

Subject: FW: PLEASE ARRANGE TP SURVEY (OUR REF:SLJ2963M) YR REF:SJX7324A DOA:29/12/2017

Hi,

Kindly re-direct your future motor claims request to motorsurvey@sompo.com.sg

Thank you.

Dear Colleagues,

Kindly assist on the request.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: edmondvermogenace@gmail.com [mailto:edmondvermogenace@gmail.com]

Sent: Wednesday, January 03, 2018 4:41 PM

To: Wong, Shi Yi Shery

Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vermogenace@gmail.com; vmg.vermogenace@gmail.com

Subject: PLEASE ARRANGE TP SURVEY (OUR REF:SLJ2963M) YR REF:SJX7324A DOA:29/12/2017

Dear Arrange survey dept

Kindly arrange TP survey on 04/01/2018 (THURSDAY) following detail & attach here GIA report:

Survey before repair

Your Vehicle: SJX7324A

Our Vehicle: SLJ2963M

DOA : 29/12/2017

AOL : SERANGOON AVE 2 (TOWARDS ANG MO KIO AVE 1)

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank you

Best Regards,

Edmond Lim
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 24 May 2018 1:57 PM
To: Baldoz Juan Paulo Bongon; Guo Qiang (LKKAUTO); Taufikh (LKKAUTO); Rasul (LKKAUTO); SUR
Cc: Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Minoko Chan; Pila Ng; Edmond Lim; Quantum Risk; Lina Rosli; Luis Tan; Paul Tan
Subject: RE: THIRTY PARTY FOR FINALISE (LKK)

Dear Paulo,

SLJ 2963M – Confirm Lump Sum \$1,600.00 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAUTO)

Sent: Thursday, 19 April 2018 12:34 PM

To: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>

Cc: Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Quantum Risk <Info@quantum-risk.com.sg>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>

Subject: RE: THIRTY PARTY FOR FINALISE (LKK)

Hi Paulo,

We acknowledge your email below.

Hi All,

Please kindly assist.

SLR9578D DOA: 25/07/2017 (LONPAC TP)

Our Ref: CC4/LPC17018727/T1pb3 – Hsiao Tong

SLC4445R DOA: 18/11/2017 (AXA TP)

Our ref: [CC4/ASM17022226/T1ea3](#) - Asher

SLF2640R DOA: 23/12/2017 (CHINA TAIPING TP)

Our Ref: CS/CTI17024676/Gtb - Denise

SLD4407X DOA: 21/12/2017 (LONPAC TP)

Our ref: [CC4/LPC17024358/T1pb3](#) – Hsiao Tong

SLJ2963M DOA: 29/12/2017 (SOMPO TP)

Our ref: [CS/SMO18000258/T1qb](#) – Shiau Chan

SLC2397J DOA: 03/01/2018 (ECICS TP)

Our Ref: CC4/ICS18000322/R1eb3 - Finalize L/S \$2,850 (5days)

SKW6819P DOA: 02/01/2018 (SOMPO TP)

Our ref: [CS/SMO18000260/T1vb](#) - Veron

Celine Fong (LKKAUTO)

From: juan paulo baldoz <paulovermogenace@gmail.com>
Sent: Saturday, 3 February 2018 12:21 PM
To: Taufikh (LKKAUTO); Zaini (LKK Auto); SUR
Cc: vmg.vermogenace; Eric Glorioso; ezel tejano; Minoko; pila.vermogenace; Luis Tan; Paul
Subject: SLJ2963M DOA: 29/12/2017 TO FINALISE (SOMPO TP)
Attachments: 06aedc4f-a0d5-4453-ac42-edc85f1ec0d3.jpg; 7ad29a59-fa67-47e3-9365-a8d43d7c2ac8.jpg;
74ca9a32-2e04-4632-8b17-497bfaf23f6.jpg; bce0a7fd-6244-4bca-8a58-dfe28ae97c61.jpg;
c92a82ac-2d6a-42f4-b6cb-a280a49a45d7.jpg; daabc7e8-d41b-4fce-9f72-a2580a5ac492.jpg;
f6bb894c-5214-4fd8-9b71-466d927783f4.jpg; SLJ2963M FINALISE.pdf

Hi Taufikh,

Please check and confirm finalise COR @ **\$1600** bef gst (lump sum) 3 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,



Paulo Baldoz
Vermogen Ace Pte Ltd
6358 3031

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 8 January, 2018 12:00 PM
To: 'Teo, Grace'; assignments; 'Chan, Shu Hui Agnes'
Cc: 'Henry, Irene James'; SUR
Subject: RE: CMTD1800062/AGC - ACCIDENT INVOLVING SJX7324A & SLJ2963M ON 29.12.2017
Attachments: CSSMO18000258T1qb.pdf

Dear Agnes,

Enclosed herewith preliminary advice of SLJ 2963M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Thursday, 4 January, 2018 10:21 AM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: CMTD1800062/AGC - ACCIDENT INVOLVING SJX7324A & SLJ2963M ON 29.12.2017

Dear Grace,

Thank you for the assignment.

"Wishes you a Happy New Year 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Thursday, 4 January, 2018 9:26 AM

To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: pila.vermogenace@gmail.com; edmondvermogenace@gmail.com; minokovermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vermogenace@gmail.com; vmg.vermogenace@gmail.com; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1800062/AGC - ACCIDENT INVOLVING SJX7324A & SLJ2963M ON 29.12.2017

Our Reference : CMTD1800062/AGC

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 18:40
Date Of Accident	29/12/2017 17:55
Exact Location Of Accident	SERANGOON AVE 2 (TOWARDS ANG MO KIO AVE 1)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ2963M
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	GRACE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995170
Cover Note Number	

Driver

Name of Driver	YAP LING JING
NRIC No	S1612312I
Date Of Birth	03/02/1963
Occupation	OUTDOOR
Date Of Driving Pass	10/09/1987
Driving Experience	30 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 628 YISHUN STREET 61 #12-141
Postcode	760628
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
---	----

Number of Passengers (Including Driver)	3
---	---

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS. THANK YOU.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX7324A
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



Car A: SLJ2963m

Car B: SJX7324A

Location:

Serangoon Ave 2
(Towards Ang Mo Kio Ave 1)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/12/17 At 17:55pm, my vehicle A was stationary along Serangoon Ave 2 (Towards Ang Mo Kio Ave 1) slip road waiting for the major road vehicles to be cleared. While my vehicle A was still stationary, suddenly I felt a impact. I then went down and assess the accident scene and realise vehicle B has collided onto my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NIKO

Identification Card

REPUBLIC OF SINGAPORE DRIVING LICENCE

816123121

YAP LING JING

16 Feb 1945

21 Nov 2018

VMG USE ONLY



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. 816123121

YAP LING JING

葉齡晶

16 Feb 1945

21 Nov 2018

VMG USE ONLY



YOU WILL BE REQUIRED TO CONTINUE TO USE THE FOLLOWING ID CARD

DATE OF BIRTH: 16 Feb 1945

DATE OF EXPIRATION: 21 Nov 2018

VMG USE ONLY



YOU WILL BE REQUIRED TO CONTINUE TO USE THE FOLLOWING ID CARD

DATE OF BIRTH: 16 Feb 1945

DATE OF EXPIRATION: 21 Nov 2018

VMG USE ONLY





SLJ2963M

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 29/12/2017

Vehicle Reg. No. : SLJ2963M
Vehicle Reg. Date: 2-Dec-2016
Make / Model : GRACE HYBRID 1.5DX A
Engine No. : LEB5255465
Chassis No. : GM41105450

COST OF CLAIMS

Parts Cost / List Items :	\$	8,839.10
Plus/Less <u>20%</u>	\$	1,767.82
Total Cost / List :	\$	7,071.28
Special Nett Items :	\$	218.00
Total Parts Amount :	\$	7,289.28
Total Labour Amount :	\$	3,350.00
Gross Total :	\$	10,639.28
GST % : <u>7%</u>	\$	744.75
Nett Amount :	\$	11,384.03

Surveyor Name and Company :

Tan Jiah 97495749
Date of survey : 4/1/18 @ 3pm
Part by Part / Lump Sum : 3 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur @ lkkauto.com
Fax No : _____
HP No : _____

This claim is handled by : Edmond

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLJ2963M**
 Vehicle Reg. Date: **2/12/2016**
 Make / Model : **GRACE HYBRID 1.5DX A**
 Engine No. : **LEB5255465**
 Chassis No. : **GM41105450**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	de✓	\$ 837.00	✓	
2	1	REAR BUMPER CLIP - SET	new✓	\$ 50.00	✓	
3	2	REAR BUMPER SIDE RETAINER	new✓	\$ 60.00	✓	
4	1	REAR BUMPER REINFORCEMENT	X	\$ 400.00		
5	2	REAR BUMPER REINFORCEMENT BRACKET	X	\$ 68.00		
6	2	REAR BUMPER REFLECTOR	X	\$ 180.00		
7	1	REAR BUMPER ANTENNA SENSOR	X	\$ 90.00		
8	1	REAR BUMPER LOWER COVER	X	\$ 155.00		
9	1	REAR BUMPER TOW HOOK	X	\$ 135.00		
10	2	REAR FENDER INNER SHIELD	X	\$ 130.00	X	
11	2	REAR FENDER INNER SHIELD CLIP - SET	X	\$ 120.00	hw	
12	2	REAR FENDER INNER TRIM	X	\$ 340.00		
13	2	REAR FENDER INNER TRIM CLIP - SET	X	\$ 80.00		
14	1	REAR END PANEL	X	\$ 450.00		
15	1	REAR END PANEL TOP GARNISH	X	\$ 180.00		
16	1	REAR END PANEL TOP GARNISH CLIP - SET	X	\$ 50.00		
17	1	SPARE TYRE PANEL TOOL TRAY	X	\$ 200.00		
18	1	SPARE TYRE PANEL TOP BOARD	X	\$ 160.00		
19	1	REAR BOOT	Rp	\$ 650.00		
20	2	REAR BOOT HINGE	X	\$ 190.00		
21	1	REAR BOOT LOCK	X	\$ 180.00		
22	1	REAR BOOT LOCK CATCH	X	\$ 30.00		
23	1	REAR BOOT INNER TRIM	X	\$ 100.00	X	
24	1	REAR BOOT INNER TRIM CLIP - SET	X	\$ 40.00	hw	
25	1	REAR BOOT CHROME GARNISH	X	\$ 190.00		
26	2	REAR BOOT LAMP	X	\$ 360.00		
27	1	REAR BOOT LOGO	new✓	\$ 60.00	✓	
28	1	REAR BOOT EMBLEM - GRACE	new✓	\$ 56.00	✓	
29	1	REAR BOOT EMBLEM - HYBRID	new✓	\$ 60.00	✓	
30	1	REAR BOOT SPOILER	X	\$ 490.80		
31	1	REAR BOOT HANDLE SWITCH	X	\$ 295.30		
32	1	REAR BOOT OPEN SMART SENSOR	X	\$ 105.00		
33	1	REAR BOOT WIRE HARNESS	X	\$ 1,025.00		
34	1	REAR BOOT WEATHERSTRIP	X	\$ 125.00	hw	
35	2	REAR NUMBER PLATE LAMP	X	\$ 112.00		
36	2	TAILLAMP LH/RH	X	\$ 560.00		
37	2	REAR AIR DUCT LH/RH	X	\$ 150.00		
38	2	TAILLAMP CLIP	X	\$ 40.00		
39	1	REVERSE SENSOR	? 200	\$ 300.00	hw✓	
40	1	REAR NUMBER PLATE	X	\$ 35.00	hw	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLJ2963M**Vehicle Reg. Date: **2/12/2016**Make / Model : **GRACE HYBRID 1.5DX A**Engine No. : **LEB5255465**Chassis No. : **GM41105450**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR NUMBER PLATE CASING	X	}	\$ 35.00	
42	1	REAR BOOT SEALANT	X		\$ 80.00	
43	1	REAR END PANEL SEALANT	X		\$ 80.00	
44	2	REAR BUMPER EXTENSION GROMMET SCREW	X		\$ 8.00	
45	2	REAR BYMPER EXTENSION FASTENER	X		\$ 7.00	
46	0	REAR BUMPER FASTENER	X		\$ 8.00	
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SLJ2963M

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 29/12/2017

Vehicle Reg. No. : SLJ2963M
Vehicle Reg. Date: 2-Dec-2016
Make / Model : GRACE HYBRID 1.5DX A
Engine No. : LEB5255465
Chassis No. : GM41105450

COST OF CLAIMS

Parts Cost / List Items :	\$	8,839.10
Plus/Less <u>20%</u>	\$	1,767.82
Total Cost / List :	\$	7,071.28
Special Nett Items :	\$	218.00
Total Parts Amount :	\$	7,289.28
Total Labour Amount :	\$	3,350.00
Gross Total :	\$	10,639.28
GST % : <u>7%</u>	\$	744.75
Nett Amount :	\$	11,384.03

Surveyor Name and Company :

Tan Jiah 97495749

Date of survey : 4/1/18 @ 3pm.

Part by Part / Lump Sum : 3 days

Resurvey Before Paint / After Paint 0

Authorize/Not Authorize/Without Prejudice 0

Email : sur @ (klean) .com

Fax No : _____

HP No : _____

This claim is handled by : Edmond

P = 1123
- 20%
898.40
SN = 200
L = 920
2018.40
- 20%
1614.72

L/S = 1600

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLJ2963M
 Vehicle Reg. Date: 2/12/2016
 Make / Model : GRACE HYBRID 1.5DX A
 Engine No. : LEB5255465
 Chassis No. : GM41105450

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	de✓	\$ 837.00		
2	1	REAR BUMPER CLIP - SET	new✓	\$ 50.00		
3	2	REAR BUMPER SIDE RETAINER	new✓	\$ 60.00		
4	1	REAR BUMPER REINFORCEMENT	X	\$ 400.00		
5	2	REAR BUMPER REINFORCEMENT BRACKET	X	\$ 68.00		
6	2	REAR BUMPER REFLECTOR	X	\$ 180.00		
7	1	REAR BUMPER ANTENNA SENSOR	X	\$ 90.00		
8	1	REAR BUMPER LOWER COVER	X	\$ 155.00		
9	1	REAR BUMPER TOW HOOK	X	\$ 135.00		
10	2	REAR FENDER INNER SHIELD	X	\$ 130.00		
11	2	REAR FENDER INNER SHIELD CLIP - SET	X	\$ 120.00		
12	2	REAR FENDER INNER TRIM	X	\$ 340.00		
13	2	REAR FENDER INNER TRIM CLIP - SET	X	\$ 80.00		
14	1	REAR END PANEL	X	\$ 450.00		
15	1	REAR END PANEL TOP GARNISH	X	\$ 180.00		
16	1	REAR END PANEL TOP GARNISH CLIP - SET	X	\$ 50.00		
17	1	SPARE TYRE PANEL TOOL TRAY	X	\$ 200.00		
18	1	SPARE TYRE PANEL TOP BOARD	X	\$ 160.00		
19	1	REAR BOOT	Rp	\$ 650.00		
20	2	REAR BOOT HINGE	X	\$ 190.00		
21	1	REAR BOOT LOCK	X	\$ 180.00		
22	1	REAR BOOT LOCK CATCH	X	\$ 30.00		
23	1	REAR BOOT INNER TRIM	X	\$ 100.00		
24	1	REAR BOOT INNER TRIM CLIP - SET	X	\$ 40.00		
25	1	REAR BOOT CHROME GARNISH	X	\$ 190.00		
26	2	REAR BOOT LAMP	X	\$ 360.00		
27	1	REAR BOOT LOGO	new✓	\$ 60.00		
28	1	REAR BOOT EMBLEM - GRACE	new✓	\$ 56.00		
29	1	REAR BOOT EMBLEM - HYBRID	new✓	\$ 60.00		
30	1	REAR BOOT SPOILER	X	\$ 490.80		
31	1	REAR BOOT HANDLE SWITCH	X	\$ 295.30		
32	1	REAR BOOT OPEN SMART SENSOR	X	\$ 105.00		
33	1	REAR BOOT WIRE HARNESS	X	\$ 1,025.00		
34	1	REAR BOOT WEATHERSTRIP	X	\$ 125.00		
35	2	REAR NUMBER PLATE LAMP	X	\$ 112.00		
36	2	TAILLAMP LH/RH	X	\$ 560.00		
37	2	REAR AIR DUCT LH/RH	X	\$ 150.00		
38	2	TAILLAMP CLIP	X	\$ 40.00		
39	1	REVERSE SENSOR	200	\$ 300.00	— SM	
40	1	REAR NUMBER PLATE	X	\$ 35.00		

P = 1123

SN = 200

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLJ2963M

Vehicle Reg. Date: 2/12/2016

Make / Model : GRACE HYBRID 1.5DX A

Engine No. : LEB5255465

Chassis No. : GM41105450

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR NUMBER PLATE CASING	X		\$ 35.00	
42	1	REAR BOOT SEALANT	X		\$ 80.00	
43	1	REAR END PANEL SEALANT	X		\$ 80.00	
44	2	REAR BUMPER EXTENSION GROMMET SCREW	X		\$ 8.00	
45	2	REAR BYMPER EXTENSION FASTENER	X		\$ 7.00	
46	0	REAR BUMPER FASTENER	X		\$ 8.00	
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]
$$L = 920$$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18000258/T1qbn2

50 RAFFLES PLACE
#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 28-05-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 7324A	Veh. Inspected	SLJ 2963M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800062/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA GRACE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	GM41105450	Colour	SILVER
Odometer	81853	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	ACHILLES	6 mm
L/H Front Tyre	185/60 R15	ACHILLES	6 mm
R/H Rear Tyre	185/60 R15	ACHILLES	6 mm
L/H Rear Tyre	185/60 R15	ACHILLES	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/12/2017	Inspection Date	04/01/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 2963M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	837.00	837.00
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER	NECESSARY	60.00	60.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	400.00	-
2	REAR BUMPER REINFORCEMENT BRACKET	NOT NECESSARY	68.00	-
2	REAR BUMPER REFLECTOR	NOT NECESSARY	180.00	-
1	REAR BUMPER ANTENNA SENSOR	NOT NECESSARY	90.00	-
1	REAR BUMPER LOWER COVER	NOT NECESSARY	155.00	-
1	REAR BUMPER TOW HOOK	NOT NECESSARY	135.00	-
2	REAR FENDER INNER SHIELD	NOT NECESSARY	130.00	-
2	SET REAR FENDER INNER SHIELD CLIP	NOT NECESSARY	120.00	-
2	REAR FENDER INNER TRIM	NOT NECESSARY	340.00	-
2	SET REAR FENDER INNER TRIM CLIP	NOT NECESSARY	80.00	-
1	REAR END PANEL	NOT NECESSARY	450.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	180.00	-
1	SET REAR END PANEL TOP GARNISH CLIP	NOT NECESSARY	50.00	-
1	SPARE TYRE PANEL TOOL TRAY	NOT NECESSARY	200.00	-
1	SPARE TYRE PANEL TOP BOARD	NOT NECESSARY	160.00	-
1	REAR BOOT	TO REPAIR SEE LABOUR	650.00	-
2	REAR BOOT HINGE	NOT NECESSARY	190.00	-
1	REAR BOOT LOCK	NOT NECESSARY	180.00	-
1	REAR BOOT LOCK CATCH	NOT NECESSARY	30.00	-
1	REAR BOOT INNER TRIM	NOT NECESSARY	100.00	-
1	SET REAR BOOT INNER TRIM CLIP	NOT NECESSARY	40.00	-
1	REAR BOOT CHROME GARNISH	NOT NECESSARY	190.00	-
2	REAR BOOT LAMP	NOT NECESSARY	360.00	-
1	REAR BOOT LOGO	NECESSARY	60.00	60.00
1	REAR BOOT EMBLEM-GRACE	NECESSARY	56.00	56.00
1	REAR BOOT EMBLEM-HYBRID	NECESSARY	60.00	60.00
1	REAR BOOT SPOILER	NOT NECESSARY	490.80	-
1	REAR BOOT HANDLE SWITCH	NOT NECESSARY	295.30	-
1	REAR BOOT OPEN SMART SENSOR	NOT NECESSARY	105.00	-
1	REAR BOOT WIRE HARNESS	NOT NECESSARY	1,025.00	-

Report Ref No. CS/SMO18000258/T1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT WEATHERSTRIP	NOT NECESSARY	125.00	-
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	112.00	-
2	TAILLAMP LH/RH	NOT NECESSARY	560.00	-
2	REAR AIR DUCT LH/RH	NOT NECESSARY	150.00	-
2	TAILLAMP CLIP	NOT NECESSARY	40.00	-
1	REAR NUMBER PLATE	NOT NECESSARY	35.00	-
	LESS 20% DISCOUNT		-1,707.82	-224.60
			6,831.28	898.40
1	REVERSE SENSOR (SN)	NOT WORKING	300.00	200.00
	LESS 20% DISCOUNT		-60.00	-
			240.00	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE CASING (SN)	NOT NECESSARY	35.00	-
1	REAR BOOT SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
2	REAR BUMPER EXTENSION GROMMET SCREW (SN)	NOT NECESSARY	8.00	-
2	REAR BUMPER EXTENSION FASTENER (SN)	NOT NECESSARY	7.00	-
1	REAR BUMPER FASTENER (SN)	NOT NECESSARY	8.00	-
			218.00	-
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA.TO REMOVE AND REPLACE DAMAGED PARTS.TO CUT/WELD REPLACED PANELS.INCLUSIVE OF THE REPAIR OF REAR BOOT.		1,200.00	400.00
	TO PUTTY,SPRAY PAINTING AND POLISH ACCIDENT AFFECTED AREAS.REAR PORTION.		1,400.00	400.00
	TO RUST PROOF AFFECTED REAR AREAS.		200.00	20.00
	TO REMOVE AND TRANSFER BOOT COMPONENTS.	NOT NECESSARY	150.00	-
	TO CHECK AND RECTIFY WIRING.		100.00	30.00
	TO REMOVE & REPLACE INTERIOR & UPHOLSTERY.		150.00	40.00
	TO REMOVE & REPLACE REVERSE SENSOR.		150.00	30.00
			3,350.00	920.00
	GRAND TOTAL		10,639.28	2,018.40

Report Ref No. CS/SMO18000258/T1qbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	----------

Report Ref No. CS/SMO18000258/T1qbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.