

ASS. REC. BY:

REF:

CS/SMO18000260/Tlvb 22

Special Instruction:

SUBJECT:

Taufkh.

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMO

Date/Time:

04-01-2018 9:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 6819P

Insured:

SIL 1914A

at Workshop no/s

Vermogen

Tel:

6904 4596.

of

6 Bendu Sector

Policy No:

Claim No:

OMTD 1800057 / GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03-01-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

04-01-2018 10:15am

Person Contacted:

Pila /i

Vehicle: (X) OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 6819P: DOA / AXA 16000975 / Ahwq?

DOA: B11215

SIL 1914A - X

5/1/18

Email preli. revised to Grace Teo

30/1/18

@533pm Pila will email finalise

15/5/18


LS \$ 4850 confirmed by email (Red 7455.36, 60%)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKW 6819P Yr Regn: 2009 Nov.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Vios C.C. 1497
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 268679 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MK053HY9325/33692
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 07/01/1801545
 Survey held at Vermogen 66awi Sector
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 MAY 2012

Date/Time. File Pass to? ☐ : Preli. Report
☐ : Final Report

Date/Time. File Return to?

2) 15/5- typist

Report Format : TP
 Lump Sum / I.B.I: (\$) 4850

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$) ☐
☐ : Interview (\$) ☐
☐ : Tech. Ins (\$) ☐
☐ : Weekend (\$) ☐

Survey Fee: 390
 Transportation: _____
) S + RS (\$) _____
) Photos _____
) Others _____

TOTAL

390

Survey Department Check List (Case Handler)

Reference No. : CS| SMO|8000 260| Tivb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

✓			
✓			
✓			

(4) System - (Views/Merimen)

✓			
---	--	--	--

Check By: Veron 15/5/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMQ18000260/T1vb	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623		Date : 04-01-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJL 1914A	Veh. Inspected	SKW 6819P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800057/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/01/2018	Inspection Date	04/01/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 5 January, 2018 1:04 PM
To: 'Teo, Grace'
Cc: 'Gnoh, Pau Loong'; 'Henry, Irene James'; SUR
Subject: RE: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018
Attachments: SKW 6819P PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SKW 6819P
Date of survey: 4/1/2018
Number of days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 4 January, 2018 10:24 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Dear Grace,

Thank you for the assignment.

"WISHES YOU A HAPPY NEW YEAR 2018"

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Thursday, 4 January, 2018 9:24 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com

Cc: pila.vermogenace@gmail.com; edmondvermogenace@gmail.com; minokovermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Our Reference : CMTD1800057/GPL

Dear LKK AUTO/ Mohd Taufikh,

Please make arrangement to conduct the survey for SKW6819P.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: pila.vermogenace@gmail.com [<mailto:pila.vermogenace@gmail.com>]

Sent: Thursday, January 04, 2018 9:19 AM

To: Teo, Grace; edmondvermogenace@gmail.com

Cc: minokovermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com; Gnoh, Pau Loong; Henry, Irene James

Subject: RE: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Dear Grace,

Kindly arrange LKK Auto Consultants - Mohd Taufikh (West area).

Thanks & regards,

Pila

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Thursday, January 4, 2018 9:14 AM

To: 'edmondvermogenace@gmail.com' <edmondvermogenace@gmail.com>

Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Our Reference : CMTD1800057/GPL

Your Reference: SKW6819P

Without Prejudice

Date: 4th January 2018

Attention:

M/S VERMOGEN ACE PTE LTD

ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Dear Edmond,

We refer to your Notice of Accident dated 03/01/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Wong, Shi Yi Shery

Sent: Wednesday, January 03, 2018 4:47 PM

To: 'edmondvermogenace@gmail.com'; Claims - Motor Survey

Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com

Subject: FW: PLEASE ARRANGE TP SURVEY (OUR REF:SKW6819P) YR REF:SJL1914A DOA:02/01/2017

Hi,

Kindly re-direct your future motor claims request to motorsurvey@sompo.com.sg

Thank you.

Dear Colleagues,

Kindly assist on the request.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or

legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: edmondvermogenace@gmail.com [<mailto:edmondvermogenace@gmail.com>]

Sent: Wednesday, January 03, 2018 4:44 PM

To: Wong, Shi Yi Shery

Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com

Subject: PLEASE ARRANGE TP SURVEY (OUR REF:SKW6819P) YR REF:SJL1914A DOA:02/01/2017

Dear Arrange survey dept

Kindly arrange TP survey on **04/01/2018 (THURSDAY)** following detail & attach here GIA report:

Survey before repair

Your Vehicle: SJL1914A

Our Vehicle: SKW6819P

DOA : 02/01/2018

AOL : TAMPINES AVE 1

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank you

Best Regards,

Edmond Lim
Vermogen Ace Pte Ltd

1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1800057/GPL

Our ref: CS/SMO18000260/T1vb

Date :5/1/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKW 6819P


We thank you for your instruction on 4/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/1/2018 at the premises of M/s VERMOGEN ACE PTE LTD and have the following to report:-

Workshop Estimate Amount	:S\$12,305.36
Revised Estimate Amount	:S\$5,298.68
"Check" Items Amount	:S\$782.43
Market Value	:S\$
LTA Reimbursement Value	:S\$
Nett Value	:S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 4 January, 2018 9:24 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: pila.vermogenace@gmail.com; edmondvermogenace@gmail.com; minokovermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com; Gnoh, Pau Loong; Henry, Irene James
Subject: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018
Attachments: SKW6819P 02JAN2018 TP.PDF

Our Reference : CMTD1800057/GPL

Dear LKK AUTO/ Mohd Taufikh,

Please make arrangement to conduct the survey for SKW6819P.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: pila.vermogenace@gmail.com [mailto:pila.vermogenace@gmail.com]

Sent: Thursday, January 04, 2018 9:19 AM

To: Teo, Grace; edmondvermogenace@gmail.com

Cc: minokovermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com; Gnoh, Pau Loong; Henry, Irene James

Subject: RE: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Dear Grace,

Kindly arrange LKK Auto Consultants - Mohd Taufikh (West area).

Thanks & regards,

Pila
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Thursday, January 4, 2018 9:14 AM
To: 'edmondvermogenace@gmail.com' <edmondvermogenace@gmail.com>
Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1800057/GPL - ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Our Reference : CMTD1800057/GPL
Your Reference: SKW6819P

Without Prejudice

Date: 4th January 2018

Attention:
M/S VERMOGEN ACE PTE LTD

ACCIDENT INVOLVING SJL1914A & SKW6819P ON 02.01.2018

Dear Edmond,

We refer to your Notice of Accident dated 03/01/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	

		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Wong, Shi Yi Shery

Sent: Wednesday, January 03, 2018 4:47 PM

To: 'edmondvermogenace@gmail.com'; Claims - Motor Survey

Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com

Subject: FW: PLEASE ARRANGE TP SURVEY (OUR REF:SKW6819P) YR REF:SJL1914A DOA:02/01/2017

Hi,

Kindly re-direct your future motor claims request to motorsurvey@sompo.com.sg

Thank you.

Dear Colleagues,

Kindly assist on the request.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: edmondvermogenace@gmail.com [<mailto:edmondvermogenace@gmail.com>]

Sent: Wednesday, January 03, 2018 4:44 PM

To: Wong, Shi Yi Shery

Cc: minokovermogenace@gmail.com; pila.vermogenace@gmail.com; paulovermogenace@gmail.com; ezelvermogenace@gmail.com; vmg.vermogenace@gmail.com; vermogenace@gmail.com

Subject: PLEASE ARRANGE TP SURVEY (OUR REF:SKW6819P) YR REF:SJL1914A DOA:02/01/2017

Dear Arrange survey dept

Kindly arrange TP survey on **04/01/2018 (THURSDAY)** following detail & attach here GIA report:

Survey before repair

Your Vehicle: SJL1914A

Our Vehicle: SKW6819P

DOA : 02/01/2018

AOL : TAMPINES AVE 1

Vehicle Location: 6 BENOI SECTOR SINGAPORE 629904

Thank you

Best Regards,

Edmond Lim
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	4597K

Vehicle Details

Vehicle No.:	SKW6819P
Vehicle to be Exported:	No
Intended De-registration Date:	05 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOSE AUTO
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	1NZX983081
Chassis No.:	MR053HY9305133692
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,717.00
Original Registration Date:	24 Nov 2009
First Registration Date:	24 Nov 2009
Transfer Count:	2
Actual ARF Paid:	\$12,717.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Nov 2019
PARF Rebate Amount:	\$6,994.00

Intended COE Rebate Details

COE Expiry Date:	23 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,527.00
COE Rebate Amount:	\$3,237.00
Total Rebate Amount:	\$10,231.00

The information contained herein is correct as at 05 Jan 2018

OK



SKW6819P

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 2/1/2018

Vehicle Reg. No. : SKW6819P
Vehicle Reg. Date: 24-Nov-2009
Make / Model : TOYOTA VIOS E AUTO
Engine No. : 1NZX983081
Chassis No. : MR053HY9305133692

COST OF CLAIMS

Parts Cost / List Items : \$ 9,887.14
Plus/Less 25% \$ 2,471.79
Total Cost / List : \$ 7,415.36
Special Nett Items : \$ 510.00
Total Parts Amount : \$ 7,925.36
Total Labour Amount : \$ 4,380.00
Gross Total : \$ 12,305.36
GST % : 7% \$ 861.37
Nett Amount : \$ 13,166.73

Surveyor Name and Company :

Tanjah 97495744

Date of survey : 4/1/18 @ 1545

Part by Part / Lump Sum : 6 days

Resurvey Before Paint / After Paint After Paint

Authorize/Not Authorize/Without Prejudice Without Prejudice

Email : sur@lkkauto.com

Fax No : _____

HP No : _____

This claim is handled by : Edmond

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SKW6819P**

Vehicle Reg. Date: **24/11/2009**

Make / Model : **TOYOTA VIOS E AUTO**

Engine No. : **1NZX983081**

Chassis No. : **MR053HY9305133692**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	2	Rear No.plate lamp LH/RH @ \$102.30	X <i>nm</i>	\$ 204.60		
2	1	Rear bumper	de <i>nm</i>	\$ 521.80		
3	1set	Rear bumper clip	nei <i>nm</i>	\$ 50.00		
4	2	Rear bumper side retainer LH/RH @ \$93.80	nei <i>nm</i>	\$ 187.60		
5	2	Rear bumper side retainer no. 2 LH/RH @ \$93.80	nei <i>nm</i>	\$ 187.60		
6	2	Rear bumper impact bracket LH/RH @ \$110.50	<i>nm</i>	\$ 221.00	✓	
7	2	Rear bumper reflector LH/RH @ \$115.40	cut <i>nm</i>	\$ 230.80		
8	2	Rear bumper watershield LH/RH @ \$168.00	X <i>nm</i>	\$ 336.00		
9	1	Bootlid	bt <i>nm</i>	\$ 933.30		
10	1	Bootlid lock	dis <i>nm</i>	\$ 92.60		
11	1	Bootlid lock cable	X <i>nm</i>	\$ 88.30		
12	1	Bootlid lock catch	bt <i>nm</i>	\$ 75.30		
13	2	Bootlid hinge LH/RH @ \$157.60	Ry <i>nm</i>	\$ 315.20		
14	1	Bootlid logo	nei <i>nm</i>	\$ 104.20		
15	1	Bootlid emblem 'VIOS'	nei <i>nm</i>	\$ 93.80		
16	1	Bootlid emblem 'E'	nei <i>nm</i>	\$ 75.80		
17	1	Boot weatherstrip	tn <i>nm</i>	\$ 102.00		
18	1	Bootlid chrome outer garnish	X <i>nm</i>	\$ 627.20		
19	1	Rear end panel	bt <i>nm</i>	\$ 627.20		
20	1	Rear end panel garnish	de <i>nm</i>	\$ 200.30		
21	1	Rear end panel garnish clip - set	nei <i>nm</i>	\$ 50.00		
22	2	Rear fender inner trim LH/RH @ \$457.60	X <i>nm</i>	\$ 915.20		
23	1set	Rear fender inner trim clip - set	X <i>nm</i>	\$ 80.00		
24	2	Rear fender air duct	X <i>nm</i>	\$ 158.00		
25	2	Tail lamp LH/RH @ \$296.30	nei <i>nm</i>	\$ 592.60		
26	1set	Tail lamp clip - set	nei <i>nm</i>	\$ 40.00		
27	1	Spare tyre panel	Ry <i>nm</i>	\$ 845.90		
28	1	Spare tyr top board	X <i>nm</i>	\$ 415.80		
29	2	Spare tyre panel sponge LH/RH @ \$216.92	? de <i>nm</i>	\$ 433.84	✓	
30	1	Spare tyre panel sponge centre	? de <i>nm</i>	\$ 388.40	✓	
31	1	Exhaust muffler	Ry <i>nm</i>	\$ 617.20		
32	1	Exhaust muffler mounting	X <i>nm</i>	\$ 75.60		
33	2	Rear number plate	bt <i>nm</i>	45 \$ 50.00		
34	2	Rear end panel selant	nei <i>nm</i>	40 \$ 80.00		
35	2	Tail lamp pad	X <i>nm</i>	\$ 80.00		
36	1	Reverse sensor	nei <i>nm</i>	200 \$ 300.00		
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SKW6819P

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 2/1/2018

Vehicle Reg. No. : SKW6819P
Vehicle Reg. Date: 24-Nov-2009
Make / Model : TOYOTA VIOS E AUTO
Engine No. : 1NZX983081
Chassis No. : MR053HY9305133692

COST OF CLAIMS

Parts Cost / List Items : \$ 9,887.14
Plus/Less 25% \$ 2,471.79
Total Cost / List : \$ 7,415.36
Special Nett Items : \$ 510.00
Total Parts Amount : \$ 7,925.36
Total Labour Amount : \$ 4,380.00
Gross Total : \$ 12,305.36
GST % : 7% \$ 861.37
Nett Amount : \$ 13,166.73

Surveyor Name and Company :

Tanjich 97495744

Date of survey : 4/1/18 R 1545

Part by Part / Lump Sum : 6 days

Resurvey Before Paint / After Paint Q

Authorize/Not Authorize/Without Prejudice Q

Email : sur@lkhaut.com

Fax No : _____

HP No : _____

This claim is handled by : Edmond

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SKW6819P**

Vehicle Reg. Date: **24/11/2009**

Make / Model : **TOYOTA VIOS E AUTO**

Engine No. : **1NZX983081**

Chassis No. : **MR053HY9305133692**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	2	Rear No.plate lamp LH/RH @ \$102.30	X	\$ 204.60		
2	1	Rear bumper	de	\$ 521.80		
3	1set	Rear bumper clip	rel	\$ 50.00		
4	2	Rear bumper side retainer LH/RH @ \$93.80	rel	\$ 187.60		
5	2	Rear bumper side retainer no. 2 LH/RH @ \$93.80	rel	\$ 187.60		
6	2	Rear bumper impact bracket LH/RH @ \$110.50	?	\$ 221.00		
7	2	Rear bumper reflector LH/RH @ \$115.40	out	\$ 230.80		
8	2	Rear bumper watershield LH/RH @ \$168.00	X	\$ 336.00		
9	1	Bootlid	bt	\$ 933.30		
10	1	Bootlid lock	dis	\$ 92.60		
11	1	Bootlid lock cable	X	\$ 88.30		
12	1	Bootlid lock catch	bt	\$ 75.30		
13	2	Bootlid hinge LH/RH @ \$157.60	Ry	\$ 315.20		
14	1	Bootlid logo	rel	\$ 104.20		
15	1	Bootlid emblem 'VIOS'	rel	\$ 93.80		
16	1	Bootlid emblem 'E'	rel	\$ 75.80		
17	1	Boot weatherstrip	in	\$ 102.00		
18	1	Bootlid chrome outer garnish	X	\$ 627.20		
19	1	Rear end panel	bt	\$ 627.20		
20	1	Rear end panel garnish	de	\$ 200.30		
21	1	Rear end panel garnish clip - set	rel	\$ 50.00		
22	2	Rear fender inner trim LH/RH @ \$457.60	X	\$ 915.20		
23	1set	Rear fender inner trim clip - set	X	\$ 80.00		
24	2	Rear fender air duct	X	\$ 158.00		
25	2	Tail lamp LH/RH @ \$296.30	rel	\$ 592.60		
26	1set	Tail lamp clip - set	rel	\$ 40.00		
27	1	Spare tyre panel	Ry	\$ 845.90		
28	1	Spare tyr top board	X	\$ 415.80		
29	2	Spare tyre panel sponge LH/RH @ \$216.92	?	\$ 433.84		
30	1	Spare tyre panel sponge centre	?	\$ 388.40		
31	1	Exhaust muffler	Ry	\$ 617.20		
32	1	Exhaust muffler mounting	X	\$ 75.60		
33	2	Rear number plate	bt	45	\$ 50.00	
34	2	Rear end panel selant	rel	40	\$ 80.00	
35	2	Tail lamp pad	X		\$ 80.00	
36	1	Reverse sensor	rel	200	\$ 300.00	
37	0	0				
38	0	0				
39	0	0				
40	0	0				

$$5208.14 - 25\% = 3906.11$$

$$84 = 285$$

Tel : 6358 3031 | Fax No : 6694 4929

SKW6819P

24/11/2009

TOYOTA VIOS E AUTO

1NZX983081

MR053HY9305133692

Estimates on Labour

[illegible]

$$P = 4191.11$$

$$L = 1890$$

$$6081.11 \cdot 20\% = 4864.89$$

4/5 = \$ 4850/-

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 15 May 2018 9:48 AM
To: Taufikh (LKKAUTO); 'ezel tejano'; 'pila@vermogen-group.com'
Cc: SUR
Subject: RE: FINALISE (TP) SKW6819P DOA: 02/01/2018

Dear Ezel,

WITHOUT PREJUDICE

Confirm finalise Lump Sum @\$4,850.00 before 7% gst in **6 working days**.

Final invoice and all supporting documents sent over to SOMPO INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 14 May 2018 12:58 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; 'ezel tejano' <ezelvermogenace@gmail.com>; 'pila@vermogen-group.com' <pila@vermogen-group.com>
Subject: RE: FINALISE (TP) SKW6819P DOA: 02/01/2018

Dear Ezel/Pila,

WITHOUT PREJUDICE

Can we close at Lump Sum \$4,200/- (before GST), since no photos to the 3 items.

No of days: 6 working days for repairs.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 20 April 2018 3:59 PM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; 'ezel tejano' <ezelvermogenace@gmail.com>

Subject: RE: FINALISE (TP) SKW6819P DOA: 02/01/2018

Hi Ezel,

Can forward the check items photo? rear bumper impact bracket , spare tyre panel sponge lh , rh and centre.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Taufikh (LKKAUTO)

Sent: Wednesday, 14 February 2018 9:37 AM

To: 'ezel tejano' <ezelvermogenace@gmail.com>

Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Subject: RE: FINALISE (TP) SKW6819P DOA: 02/01/2018

Hi Ezel,

Can forward the check items photo? rear bumper impact bracket , spare tyre panel sponge lh , rh and centre.

Regards

Taufikh

Lkk Auto

From: ezel tejano [mailto:ezelvermogenace@gmail.com]

Sent: Tuesday, 13 February 2018 1:52 PM

To: Taufikh (LKKAUTO); SUR

Cc: Eric Glorioso; Edmond Lim jian zhi; juan paulo baldoz; pila.vermogenace; Minoko; Luis Tan; vmg.vermogenace

Subject: FINALISE (TP) SKW6819P DOA: 02/01/2018

Dear Taufikh,

Please check and confirm finalise COR @ **\$4,850.00** before 7% gst (lump sum) in **6 working days**.

Thank you.

Best Regards,

Ezel Tejano

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6358 3031

Fax: 6694 4929



P1020848.JPG



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18000260/T1vbe2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 18-05-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 1914A	Veh. Inspected	SKW 6819P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800057/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/01/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305133692	Colour	BLUE
Odometer	268679	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/01/2018	Inspection Date	04/01/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 6819P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	REAR NO PLATE LAMP LH/RH @\$102.30	NOT NECESSARY	204.60	-
1	REAR BUMPER	DEFORMED	521.80	521.80
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER LH/RH @\$93.80	NECESSARY	187.60	187.60
2	REAR BUMPER SIDE RETAINER NO.2 LH/RH @\$93.80	NECESSARY	187.60	187.60
2	REAR BUMPER IMPACT BRACKET LH/RH @\$110.50	BENT	221.00	221.00
2	REAR BUMPER REFLECTOR LH/RH @\$115.40	CUT	230.80	230.80
2	REAR BUMPER WATERSHIELD LH/RH @\$168.00	NOT NECESSARY	336.00	-
1	BOOTLID	BENT	933.30	933.30
1	BOOTLID LOCK	DISTORTED	92.60	92.60
1	BOOTLID LOCK CABLE	NOT NECESSARY	88.30	-
1	BOOTLID LOCK CATCH	BENT	75.30	75.30
2	BOOTLID HINGE LH/RH @\$157.60	TO REPAIR SEE LABOUR	315.20	-
1	BOOTLID LOGO	NECESSARY	104.20	104.20
1	BOOTLID EMBLEM "VIOS"	NECESSARY	93.80	93.80
1	BOOTLID EMBLEM "E"	NECESSARY	75.80	75.80
1	BOOT WEATHERSTRIP	TORN	102.00	102.00
1	BOOTLID CHROME OUTER GARNISH	NOT NECESSARY	627.20	-
1	REAR END PANEL	BENT	627.20	627.20
1	REAR END PANEL GARNISH	DEFORMED	200.30	200.30
1	SET REAR END PANEL GARNISH CLIP	NECESSARY	50.00	50.00
2	REAR FENDER INNER TRIM LH/RH @\$457.60	NOT NECESSARY	915.20	-
1	SET REAR FENDER INNER TRIM CLIP	NOT NECESSARY	80.00	-
2	REAR FENDER AIR DUCT	NOT NECESSARY	158.00	-
2	TAIL LAMP LH/RH @\$296.30	CRACKED	592.60	592.60
1	SET TAIL LAMP CLIP	NECESSARY	40.00	40.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	845.90	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	415.80	-
2	SPARE TYRE PANEL SPONGE LH/RH @\$216.92	DEFORMED	433.84	433.84
1	SPARE TYRE PANEL SPONGE CENTRE	DEFORMED	388.40	388.40
1	EXHAUST MUFFLER	TO REPAIR SEE LABOUR	617.20	-
1	EXHAUST MUFFLER MOUNTING	NOT NECESSARY	75.60	-

Report Ref No. CS/SMO18000260/T1vbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,471.79	-1,302.04
			7,415.35	3,906.10
	<u>SPECIAL NETT ITEMS</u>			
2	REAR NUMBER PLATE (SN)	BENT	50.00	45.00
2	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
2	TAIL LAMP PD (SN)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN)	NOT WORKING	300.00	200.00
			510.00	285.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING.TO CUT/WELD PANELS.REAR PORTION.INCLUSIVE OF THE REPAIR OF BOOTLID HINGE LH/RH,SPARE TYRE PANEL AND EXHAUST MUFFLER.		1,600.00	800.00
	TO PUTTY,RESPRAY PAINTING AND POLISH AFFECTED AREAS.REAR PORTION.		1,800.00	800.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		100.00	30.00
	TO REMOVE AND REFIT REVERSE SENSOR.		150.00	30.00
	TO REMOVE AND REFIT INTERIOR TRIMS,SEATS,CARPET AND UPHOLSTERY TO FACILITATE REPAIR.		200.00	50.00
	TO REMOVE AND TRANSFER BOOTLID COMPONENTS.		150.00	60.00
	TO REMOVE AND REFIT EXHAUST PIPE AND ALIGN.		180.00	60.00
	TO RUST PROOF AFFECTED AREAS.		200.00	60.00
			4,380.00	1,890.00
	GRAND TOTAL		12,305.35	6,081.10

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,850.00
---	--	--	-----------------

Report Ref No. CS/SMO18000260/T1vbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.