



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

**GST Reg No : MR-8500111-X**

Invoice Name & Address		Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd  60 Anson Road #11-01 Mapletree Anson Singapore 079914  Contact No Mobile: 67420984	Cust No/Name	/Lion City Rentals Pte Ltd	
	Reg No/Reg Date	SLF2119E	/ 18/08/201
	Date In/Mileage		/ 0
	Chassis No	MMBSTA13AHH001781	
	Engine No	3A92UDH3880	
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT	
	Colour/Trim	W05 WHITE PEARL / BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	03/01/2018/ 14:40	-	465 / Tay Jian Ye	19230

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E	PNT88000 TO RENEW FRT BUMPER , FRT LH FENDER, REPAIR LH FRT DOOR				2200.00
E	PNT98000 PAINT WORK SPRAY FRT BUMPER , FRT LH FENDER, FRT LH DOOR				1680.00
A	54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				50.00
A	10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M	SUNDRY TO APPLY ANTI COROSSION ON AFFECTED PORTION				80.00
M	SUNDRY SUNDRIES				50.00
M	FACE,FR BUMPER	1.00	696.00	00.00	696.00
M	BRACKET,FR BUMPER,LH	1.00	13.00	00.00	13.00
M	CLIP,FR BUMPER	10.00	3.00	00.00	30.00
M	HEADLAMP ASSY,LH	1.00	654.00	00.00	654.00
M	FENDER,FR LH	1.00	458.00	00.00	458.00
M	SHIELD,FR WHEELHOUSE,LH	1.00	97.00	00.00	97.00
M	CLIP,FR BUMPER	15.00	3.00	00.00	45.00
M	MIRROR ASSY,DOOR,LH	1.00	632.00	00.00	632.00
M	COVER,DOOR MIRROR,OTR LH	1.00	127.00	00.00	127.00

SURVEYOR NAME : \_\_\_\_\_

SURVEYOR SIGNATURE: \_\_\_\_\_

DATE : \_\_\_\_\_

REMARKS: \_\_\_\_\_

Confirm & accepted by

	Nett	7,012.00
7% GST on	7012.00	490.84

Total Payable	7,502.84
---------------	----------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.