

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHA 4204C

MAKE :

MODEL : HYUNDAI i40

DATE 29/12/2017 14:45

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>dented</i>			\$ 603.60
	Rear Bumper Reinforcement <i>X nn</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X nn</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X nn</i>			\$ 49.00
	Rear Bumper Clips <i>nec</i>			\$ 22.00
	Rear Bumper Sponge <i>X nn</i>			\$ 143.40
	Rear Bumper Under Cover <i>nn</i>			\$ 225.00
	<b>SUB TOTAL</b>			<b>\$ 1,907.35</b>
	<b>LESS 20%</b>			<b>\$ 381.47</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,525.88</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ <del>350.00</del>
	Spray Painting Charge			\$ <del>200.00</del> <del>180</del>
	<b>TOTAL LABOUR</b>			<b>\$ 550.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,075.88</b>
<i>Kalvin LKK</i> <i>11/4/18 1110 L</i> <i>2075-</i> <i>P/P</i> <i>Before part photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				