

ASS. REC. BY:

REF CS/CT18000265 / St b

Special Instructions

DATE/TIME

Sebastian

ASSIGNMENT (Office)

MEMO

From (Person):

Jowyn Tay

of

CT1

Date/Time

04.01.2018 2:51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SKN 2300S

Insured:

at Workshop in/s

Trans Eurokars

Tel:

6360 2845

of

12 Sungai Kadut Ave

Policy No.

DMPCSN1618871701

Claim No.

SNM18D00021C01

Sum Insured

Excess:

\$3500.00

Make of Veh:

D.O.A.

29.12.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

08.01.2018 @ 11am

owner waiting

H.O.D. Endorsement

Date/Time

04.01.2018 3:20pm

Person Contacted

Eva

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SKN 2300S
8/1-	Revert via menimen
9/1	authorise repair Alfred
10/1 -	Email eva authorise repair excess \$3500-
27/1/18 @	4.36pm Confirmed with Jessica final fig \$25731.18, 10 days
	Cred \$17131.13, 40%

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	04 Jan 2018		04 Jan 2018 14:51 Assign			
						New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CREDIT LINK PTE LTD, Co. Reg. No.: 199603276W		
Vehicle Reg. No.:	SKN2300S	Date of Loss:	29/12/2017 14:00 - :59
Claim Type:	OD / SNM18D00021C01	Policy/Cover Note No.:	DMPCSN1618871701 (Comprehensive) Coverage: 17/04/2017 - 16/04/2018
		Excess:	\$43,500.00
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/01/2018]		
Driver/Custodian:	NG TING TING (50 / Female), NRIC: S1793268C, Tel: +6596717048		
Adj Asp. Remarks:	PLEASE PROCEED TO SURVEY AND REVERT. EXCESS OF \$3500.00 APPLIES.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18000265/Stb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 04-01-2018		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKN 2300S
Policy No. DMPCSN1618871701		Coverage (\$)		0.00
Claim No. SNM18D00021C01		Excess (\$)		3,500.00
Assign From MERIMEN (JOWYN TAY)		Assign Date		04/01/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 29/12/2017		Inspection Date		
Survey held at TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648				
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 22 March 2018 4:26 PM
To: 'jessicahs@eurokars.com.sg'; Mei Kwan (LKKAuto); Sebastian Yeang (LKK Auto); Denise Tay (LKKAuto)
Cc: CS A Team; Admin A; SUR
Subject: RE: finalization CHINA TP - SKN2300S (OD).xls *** LKK REF: CS/CTI18000265/Stb

Dear Jessica,

Confirm final fig \$25,731.18 before excess \$3,500.00 & GST and 10 repair days.

Please send the relevant documents to China Taiping Insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jessicahs@eurokars.com.sg [mailto:jessicahs@eurokars.com.sg]
Sent: Thursday, 22 March 2018 9:04 AM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: finalization CHINA TP - SKN2300S (OD).xls *** LKK REF: CS/CTI18000265/Stb

Dear Denise, **2nd Reminder**

The below matter refers.

Please let us have closure of this case by this week if we do not hear from you we will deal with insurer directly.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602863

Fax: +65 63602899

From: Jessica Harry Shastri
Sent: Tuesday, March 20, 2018 10:31 AM
To: 'Mei Kwan (LKKAuto)' <Meikwan@lkkauto.com>; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>

View Received Message

This mail is associated with :

***SKN2300S (SNM18D00021C01)**

OD

Dec 29 2017 2:00PM

[CREDIT LINK PTE LTD]

Trans Eurokars Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 09/01/2018 17:23 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$29593.53) - SKN2300S - Claim Handler: Jowyn Tay

Approved:29593.53:Please proceed to authorize repairs at \$29,593.53 BEFORE Excess of \$3,500.00, RE-INSPECTION of vehicle required.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 10 January 2018 9:56 AM
To: 'eva.kok@eurokars.com.sg'
Cc: SUR
Subject: SKN2300S OD CHINATIPING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKN2300S (Excess \$3500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2018 08:50
Date Of Accident	29/12/2017 14:30
Exact Location Of Accident	ALONG ORANGE GROVE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN2300S
Insured/Policyholder	
Name Of Registered Owner	CREDIT LINK PTE LTD
Co Reg No	199603276W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96717048
Alternative Phone No	OFFICE-96717048

Vehicle Particulars

Manufacturer	PORSCHE
Model	PORSCHE CAYENNE DIESEL TIPTRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVITE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1618871701
Cover Note Number	

Driver

Name of Driver	NG TING TING
NRIC No	S1793268C
Date Of Birth	10/03/1967
Occupation	INDOOR
Date Of Driving Pass	29/09/1986
Driving Experience	31 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96717048
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	23 SPRINGLEAF WALK
Postcode	787875
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : TOH CHONG HUI GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT546G
Vehicle Make/Model/Colour	MERC BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/12/17 @ 1200H



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A - SKN 2300 S

B - SKT 546 G



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I was driving along Orange Grove Road on 29/12/17 at around 2:30 pm, all of a sudden, I felt an impact on my left side of my vehicle involving with SKT 546 G. Nobody was hurt in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 30/12/17 @ 1200 H

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		NAME : Ng Ting Ting c/o Credit Link Pte Ltd ADDRESS : 23 Springleaf Walk Singapore 787875	WIP : 30562 DATE: 30/12/2017
ATTN : MOTOR CLAIMS	TEL :		
FAX :			
VEH NO : SKN2300S	DATE IN :	CONTACT PERSON :	RICK /TOMMY 63602443
CHASSIS NO : WP1ZZZ92ZELA40151	MILEAGE :	TYPE OF CLAIM :	OD
MODEL : Cayenne Diesel Tiptronic	DATE REG : 17/4/2014	POLICY NO :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	PRICES
1	P958-503-031-02-GRV/WING LEFT PRIME COAT <i>✓ R</i>	1	P958-503-031-03-GRV	\$ 1,405.90
2	P958-505-411-10-G2X/LINING REAR PRIME CO <i>✓ cut</i>	1	P958-505-411-11-G2X	\$ 940.10
3	GUIDE BUMPER REAR LEFT <i>3 XNN</i>	1	P958-505-393-00-	\$ 66.00
4	BARE DOOR SHELL LEFT FRONT <i>✓ M Fin Door</i>	1	P958-531-011-00-GRV	\$ 2,767.40
5	BLIND RIVET	1	PN -016-185-6 -	\$ 1.10
6	BLIND RIVET NUT <i>✓ NRC</i>	1	PN -910-167-02-	\$ 1.70
7	BLIND RIVET NUT	2	PN -106-185-01-	\$ 5.60
8	EXPANDER NUT	1	PN -106-213-01-	\$ 1.50
9	INSULATION DOOR	2	P955-556-821-01-	\$ 30.80
10	(WH17) ADHESIVE TAPE DOOR IN WHIT <i>X NN</i>	1	P958-537-437-40-	\$ 110.20
11	NUT SPECIAL NUT <i>✓ NRC</i>	3	P955-803-115-00-	\$ 3.60
12	DOOR SEAL OUTER DOOR FRONT <i>✓ NRC</i>	1	P958-537-911-00-	\$ 390.30
13	CAVITY PRESERVATION <i>X NN</i>	1	P000-043-305-51-	\$ 79.60
14	GROMMET <i>✓ NRC</i>	9	P955-559-586-00-	\$ 19.80
15	P958-533-011-00-GRV/BARE DOOR SHELL LEFT <i>✓ DT Rear Door</i>	1	P958-533-011-01-GRV	\$ 2,682.10
16	BLIND RIVET	1	PN -016-185-6 -	\$ 1.10
17	BLIND RIVET NUT	2	PN -106-185-01-	\$ 5.60
18	EXPANDER NUT <i>✓ NRC</i>	1	PN -106-213-01-	\$ 1.50
19	NUT SPECIAL NUT	3	P955-803-115-00-	\$ 3.60
20	INSULATION DOOR	2	P955-556-821-01-	\$ 30.80
21	DOOR SEAL OUTER DOOR REAR	1	P958-539-911-00-	\$ 331.90
22	CAVITY PRESERVATION <i>X NN</i>	1	P000-043-305-51-	\$ 79.60
23	GROMMET <i>✓ NRC</i>	5	P955-559-586-00-	\$ 11.00
24	(WH17) ADHESIVE TAPE DOOR IN WHIT <i>X NN</i>	1	P958-537-437-40-	\$ 110.20
25	DOOR SEAL OUTER REAR LEFT <i>✓ NRC (Ponder rubber)</i>	1	P958-533-761-02-	\$ 249.40
26	DOOR SEAL FRONT LEFT <i>✓ NRC (center rubber)</i>	1	P958-533-717-05-	\$ 83.60
27	COVER SIDE WINDOW FRONT LE <i>✓ NRC 7-clamp</i>	1	P958-559-475-02-7Z7	\$ 243.10
28	COVER SIDE WINDOW REAR LEF <i>✓ NRC 7-mounting</i>	1	P958-559-477-02-7Z7	\$ 243.10
29	SIDE SECTION OUTER LEFT C- <i>R</i>	1	P958-503-985-00-GRV	\$ 4,470.30
30	CAVITY PRESERVATION <i>X NN</i>	1	P000-043-305-51-	\$ 79.60
31	P000-043-204-85-/CAVITY PRESERVATION <i>X NN</i>	3	P000-043-305-51-	\$ 238.80
32	Threaded pin <i>✓ X NN</i>	50	PN -909-876-02-	\$ 60.00
33	Threaded pin	50	PN -906-547-04-	\$ 50.00
34	P958-544-111-03-/SIDE WINDOW REAR LEFT <i>X NN</i>	1	P958-845-297-00-	\$ 1,093.20
35	BLIND RIVET NUT <i>X NN</i>	2	PN -910-167-02-	\$ 3.40
36	WHEEL COVER SIDE SECTION R <i>✓ SCR</i>	1	P958-559-827-20-9B9	\$ 376.20
37	CLIP FOR WHEEL ARCH COVER <i>✓ NRC</i>	2	P000-043-984-00-	\$ 4.20
38	CLIP FOR COVER	10	P000-043-986-00-	\$ 34.00

39	CLAMP FOR WHEEL COVER X NN	2	P958-559-107-00-	\$ 5.00
40	WHEEL COVER BUMPER FRONT L X NN	1	P958-559-727-20-9B9	\$ 376.20
41	STRIP DOOR FRONT LEFT ✓ <i>note SCR</i> } <i>Door</i>	1	P958-559-787-04-G2X	\$ 536.80
42	STRIP DOOR REAR LEFT ✓ <i>PEC SCR</i> } <i>lower</i>	1	P958-559-789-00-G2X	\$ 339.40
43	GROMMET ✓ <i>PEC NEC</i>	18	P955-559-586-00-	\$ 39.60
44	COVER WING LEFT PRIME COAT ✓ <i>SCR</i>	1	P958-559-959-01-G2X	\$ 166.50
	<i>Adhesive Tape for Door Garnish. ✓ NEC</i>			<i>TBA</i>
Total Parts				\$ 17,773.40
LESS 10%				\$ 1,777.34
Nett Total Parts				\$ 15,996.06
Labour Description				
1	TO REMOVE LH DAMAGED & AFFECTED BODY PARTS. <i>1560/day</i>			\$ 12,600.00
	KNOCK, REPAIR, REPLACE REAR BUMPER, LHR FENDER, <i>9360</i>			
	LHR DOOR, LHF DOOR & FENDER. REPLACE AFFECTED BODY			
	PARTS & FITTINGS WHICHEVER NECESSARY INCLUDING			
	ALIGNMENT OF BODY STRUCTURE			
2	TO SPRAY PAINT FRONT BUMPER, FRT LH FENDER, <i>large panel 1300/panel</i>			\$ 6,800.00
	FRT LH DOOR, REAR LH DOOR, REAR LH FENDER <i>Normal panel 1100/panel</i>			<i>5100</i>
	& REAR BUMPER			
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL			\$ 720.00
	AFFECTED AREAS <i>350</i>			
4	TO APPLY THEROSTAT SEALANT TO AFFECTED AREAS <i>X</i>			\$ 500.00
5	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER <i>NETT X</i>			\$ 380.00
	FUNCTION ABILITY INCLUDING PARKING ASSIST			
	SENSORS			
6	TO REMOVE, REPLACE, REFIT REAR LH FENDER <i>NETT X</i>			\$ 480.00
	GLASS TO FACILITATE REPAIRS			
7	REMOVE & REFIT LHR C PILLAR TRIMS, OUTER MOULDING, <i>NETT X</i>			\$ 1,400.00
	ROOF LINING, BOOT INNER COVERS, FLOOR			
	CARPET & REAR SEAT CUSHION.			
	(TO FACILITATE THE REPLACEMENT OF LHR FENDER)			
8	SUPPLY WINDSCREEN SEALANT <i>NETT X</i>			\$ 186.25
9	TO SUPPLY /INSTALL SUN SHIELD TO LHR FENDER GLASS. <i>NETT X</i>			\$ 300.00
10	TO REMOVE /REFIT BOTH LH DOORS INCLUDE TRANSFER <i>NETT</i>			\$ 2,800.00
	WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR <i>1560</i>			
	& CHECK FUNCTION ABILITY			
11	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES <i>NETT</i>			\$ 600.00
	AFTER ACCIDENT REPAIR.			

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
FINALIZATION COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		NAME : Ng Ting Ting c/o Credit Link Pte Ltd ADDRESS : 23 Springleaf Walk Singapore 787875	WIP : 30562 DATE: 30/12/2017
ATTN. :	MOTOR CLAIMS	TEL :	
FAX :			
VEH NO :	SKN2300S	DATE IN :	CONTACT PERSON : RICK /TOMMY 63602445
CHASSIS NO :	WP1ZZZ92ZELA40151	MILEAGE :	TYPE OF CLAIM : OD
MODEL :	Cayenne Diesel Tiptronic	DATE REG : 17/4/2014	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description			(NETT)	
		QTY	PART NO	REVISED	PRICES
1	P958-503-031-02-GRV/WING LEFT PRIME COAT	1	P958-503-031-03-GRV	\$ -	\$ 1,405.90
2	P958-505-411-10-G2X/LINING REAR PRIME CO	1	P958-505-411-11-G2X	\$ 940.10	\$ 940.10
3	GUIDE BUMPER REAR LEFT	1	P958-505-393-00-	\$ -	\$ 66.00
4	BARE DOOR SHELL LEFT FRONT	1	P958-531-011-00-GRV	\$ 2,767.40	\$ 2,767.40
5	BLIND RIVET	1	PN -016-185-6 -	\$ 1.10	\$ 1.10
6	BLIND RIVET NUT	1	PN -910-167-02-	\$ 1.70	\$ 1.70
7	BLIND RIVET NUT	2	PN -106-185-01-	\$ 5.60	\$ 5.60
8	EXPANDER NUT	1	PN -106-213-01-	\$ 1.50	\$ 1.50
9	INSULATION DOOR	2	P955-556-821-01-	\$ 30.80	\$ 30.80
10	(WH17) ADHESIVE TAPE DOOR IN WHIT	1	P958-537-437-40-	\$ -	\$ 110.20
11	NUT SPECIAL NUT	6	P955-803-115-00-	\$ 7.20	\$ 3.60
12	DOOR SEAL OUTER DOOR FRONT	1	P958-537-911-00-	\$ 390.30	\$ 390.30
13	CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 79.60
14	GROMMET	9	P955-559-586-00-	\$ 19.80	\$ 19.80
15	P958-533-011-00-GRV/BARE DOOR SHELL LEFT	1	P958-533-011-01-GRV	\$ 2,682.10	\$ 2,682.10
16	BLIND RIVET	1	PN -016-185-6 -	\$ 1.10	\$ 1.10
17	BLIND RIVET NUT	2	PN -106-185-01-	\$ 5.60	\$ 5.60
18	EXPANDER NUT	1	PN -106-213-01-	\$ 1.50	\$ 1.50
19	NUT SPECIAL NUT	3	P955-803-115-00-	\$ 3.60	\$ 3.60
20	INSULATION DOOR	2	P955-556-821-01-	\$ 30.80	\$ 30.80
21	DOOR SEAL OUTER DOOR REAR	1	P958-539-911-00-	\$ 331.90	\$ 331.90
22	CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 79.60
23	GROMMET	5	P955-559-586-00-	\$ 11.00	\$ 11.00
24	(WH17) ADHESIVE TAPE DOOR IN WHIT	1	P958-537-437-40-	\$ -	\$ 110.20
25	DOOR SEAL OUTER REAR LEFT	1	P958-533-761-02-	\$ 249.40	\$ 249.40
26	DOOR SEAL FRONT LEFT	1	P958-533-717-05-	\$ 83.60	\$ 83.60
27	COVER SIDE WINDOW FRONT LE	1	P958-559-475-02-7Z7	\$ 243.10	\$ 243.10
28	COVER SIDE WINDOW REAR LEF	1	P958-559-477-02-7Z7	\$ 243.10	\$ 243.10
29	SIDE SECTION OUTER LEFT C-	1	P958-503-985-00-GRV	\$ -	\$ 4,470.30
30	CAVITY PRESERVATION	1	P000-043-305-51-	\$ -	\$ 79.60
31	P000-043-204-85-/CAVITY PRESERVATION	3	P000-043-305-51-	\$ -	\$ 238.80
32	Threaded pin	50	PN -909-876-02-	\$ -	\$ 60.00
33	Threaded pin	50	PN -906-547-04-	\$ -	\$ 50.00
34	P958-544-111-03-/SIDE WINDOW REAR LEFT	1	P958-845-297-00-	\$ -	\$ 1,093.20
35	BLIND RIVET NUT	2	PN -910-167-02-	\$ -	\$ 3.40
36	WHEEL COVER SIDE SECTION R	1	P958-559-827-20-9B9	\$ 376.20	\$ 376.20
37	CLIP FOR WHEEL ARCH COVER	2	P000-043-984-00-	\$ 4.20	\$ 4.20
38	CLIP FOR COVER	10	P000-043-986-00-	\$ 34.00	\$ 34.00

39	CLAMP FOR WHEEL COVER	2	P958-559-107-00-	\$ -	\$ 5.00
40	WHEEL COVER BUMPER FRONT L	1	P958-559-727-20-9B9	\$ -	\$ 376.20
41	STRIP DOOR FRONT LEFT	1	P958-559-787-04-G2X	\$ 536.80	\$ 536.80
42	STRIP DOOR REAR LEFT	1	P958-559-789-00-G2X	\$ 339.40	\$ 339.40
43	GROMMET	18	P955-559-586-00-	\$ 39.60	\$ 39.60
44	COVER WING LEFT PRIME COAT	1	P958-559-959-01-G2X	\$ 166.50	\$ 166.50
	supplementary				
1	ADHESIVE TAPE <i>NEE</i>	1	P000-043-985-00	\$ 28.20	
2	MIRROR HOUSING LOW <i>SCR</i>	1	P958-731-527-11-9B	\$ 205.90	
3	PLUG <i>NEE</i>	1	P955-559-108-00	\$ 2.10	
4	CLIP DOOR TRIM <i>NEE</i>	2	P955-243-00	\$ 5.00	
			Total Parts	\$ 9,790.20	\$ 17,773.40
			LESS 10%	\$ 979.02	\$ 1,777.34
			Nett Total Parts	\$ 8,811.18	\$ 15,996.06
	Labour Description				
1	TO REMOVE LH DAMAGED & AFFECTED BODY PARTS, KNOCK, REPAIR, REPLACE REAR BUMPER, LHR FENDER, LHR DOOR, LHF DOOR & FENDER. REPLACE AFFECTED BODY PARTS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.			\$ 9,360.00	\$ 12,600.00
2	TO SPRAY PAINT FRONT BUMPER, FRT LH FENDER, FRT LH DOOR, REAR LH DOOR, REAR LH FENDER & REAR BUMPER.			\$ 5,100.00	\$ 6,800.00
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS.			\$ 250.00	\$ 720.00
4	TO APPLY THEROSTAT SEALANT TO AFFECTED AREAS			\$ -	\$ 500.00
5	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.	NETT		\$ -	\$ 380.00
6	TO REMOVE, REPLACE, REFIT REAR LH FENDER GLASS TO FACILITATE REPAIRS	NETT		\$ -	\$ 480.00
7	REMOVE & REFIT LHR C PILLAR TRIMS, OUTER MOULDING, ROOF LINING, BOOT INNER COVERS, FLOOR CARPET & REAR SEAT CUSHION. (TO FACILITATE THE REPLACEMENT OF LHR FENDER)	NETT		\$ -	\$ 1,400.00
8	SUPPLY WINDSCREEN SEALANT	NETT		\$ -	\$ 186.25
9	TO SUPPLY /INSTALL SUN SHIELD TO LHR FENDER GLASS.	NETT		\$ -	\$ 300.00
10	TO REMOVE /REFIT BOTH LH DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR	NETT		\$ 1,560.00	\$ 2,800.00

	& CHECK FUNCTION ABILITY				
11	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES	NETT	\$ 600.00	\$ 600.00	
	AFTER ACCIDENT REPAIR.				
12	SUNDRIES.		\$ 50.00	\$ 100.00	
			TOTAL LABOUR	\$ 16,920.00	\$ 26,866.25
			TOTAL PARTS NETT	\$ 8,811.18	\$ 15,996.06
			GRAND TOTAL	\$ 25,731.18	\$ 42,862.31
			LESS EXCESS	\$ 3,500.00	
			TOTAL AFTER EXCESS	\$ 22,231.18	
			GST 7 %	\$ 1,556.18	
			TOTAL AFTER GST	\$ 23,787.36	

NUMBER OF DAYS: 10 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN,PH)

Line	T	Product	Description	Quantity	Price	Disc%	Total
1	L	NOTES	OD CLAIM UNDER	0	0	0	0
51	L	EXC	Insurance Excess	-3500	1	0	\$ (3,500.00)
3	P	P958-505-411-11-G	P958-505-411-10-G2X/LINING REAR PRIME CO	1	940.1	20	\$ 940.10
5	P	P958-531-011-00-G	BARE DOOR SHELL LEFT FRONT	1	2767.4	20	\$ 2,767.40
6	P	PN -016-185-6 -	BLIND RIVET	1	1.1	20	\$ 1.10
7	P	PN -910-167-02-	BLIND RIVET NUT	1	1.7	20	\$ 1.70
8	P	PN -106-185-01-	BLIND RIVET NUT	2	2.8	20	\$ 5.60
9	P	PN -106-213-01-	EXPANDER NUT	1	1.5	20	\$ 1.50
10	P	P955-556-821-01-	INSULATION DOOR	2	15.4	20	\$ 30.80
12	P	P955-803-115-00-	NUT SPECIAL NUT	3	1.2	20	\$ 3.60
13	P	P958-537-911-00-	DOOR SEAL OUTER DOOR FRONT	1	390.3	20	\$ 390.30
15	P	P955-559-586-00-	GROMMET	9	2.2	20	\$ 19.80
16	P	P958-533-011-01-G	P958-533-011-00-GRV/BARE DOOR SHELL LEF	1	2682.1	20	\$ 2,682.10
17	P	PN -016-185-6 -	BLIND RIVET	1	1.1	20	\$ 1.10
18	P	PN -106-185-01-	BLIND RIVET NUT	2	2.8	20	\$ 5.60
19	P	PN -106-213-01-	EXPANDER NUT	1	1.5	20	\$ 1.50
20	P	P955-803-115-00-	NUT SPECIAL NUT	3	1.2	20	\$ 3.60
21	P	P955-556-821-01-	INSULATION DOOR	2	15.4	20	\$ 30.80
22	P	P958-539-911-00-	DOOR SEAL OUTER DOOR REAR	1	331.9	20	\$ 331.90
24	P	P955-559-586-00-	GROMMET	5	2.2	20	\$ 11.00
26	P	P958-533-761-02-	DOOR SEAL OUTER REAR LEFT	1	249.4	20	\$ 249.40
27	P	P958-533-717-05-	DOOR SEAL FRONT LEFT	1	83.6	20	\$ 83.60
28	P	P958-559-475-02-72	COVER SIDE WINDOW FRONT LE	1	243.1	20	\$ 243.10
29	P	P958-559-477-02-72	COVER SIDE WINDOW REAR LEF	1	243.1	20	\$ 243.10
37	P	P958-559-827-20-9B	WHEEL COVER SIDE SECTION R	1	376.2	20	\$ 376.20
38	P	P000-043-984-00-	CLIP FOR WHEEL ARCH COVER	2	2.1	20	\$ 4.20
39	P	P000-043-986-00-	CLIP FOR COVER	10	3.4	20	\$ 34.00
42	P	P958-559-787-04-G	STRIP DOOR FRONT LEFT	1	536.8	20	\$ 536.80
43	P	P958-559-789-00-G	STRIP DOOR REAR LEFT	1	339.4	20	\$ 339.40
44	P	P955-559-586-00-	GROMMET	18	2.2	20	\$ 39.60
45	P	P958-559-959-01-G	COVER WING LEFT PRIME COAT	1	166.5	20	\$ 166.50
46	P	P958-731-527-11-9B	P958-731-527-10-9B9/MIRROR HOUSING LOW	1	205.9	20	\$ 205.90
47	P	P000-043-985-00-	ADHESIVE TAPE	1	28.2	20	\$ 28.20
48	P	P955-559-108-00-	PLUG	1	2.1	20	\$ 2.10
49	P	P955-803-115-00-	NUT SPECIAL NUT	3	1.2	20	\$ 3.60
50	P	P955-555-243-00-	CLIP DOOR TRIM	2	2.5	20	\$ 5.00
52	L	EXC	Insurance Excess	3500	1	0	\$ 3,500.00

\$ 9,790.20

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018		04 Jan 2018 14:51 Edit Adj Rpt	S\$25,731.18 Edit Estimates	S\$25,731.18 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CREDIT LINK PTE LTD , Co. Reg. No.: 199603276W								
Vehicle Reg. No.:	SKN2300S	Date of Loss:	29/12/2017 14:00 - :59						
Claim Type:	OD / SNM18D00021C01	Policy/Cover Note No.:	DMPCSN1618871701 (Comprehensive) Coverage: 17/04/2017 - 16/04/2018						
		Excess:	S\$3,500.00						
Repairster:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 15/01/2018]								
Driver/Custodian:	NG TING TING (50 / Female), NRIC: S1793268C, Tel: +6596717048								
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY AND REVERT. EXCESS OF \$3500.00 APPLIES.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (09/01/2018): Alert - Adj Mandate Approved (S\$29593.53) - SKN2300S - Claim Handler: Jowyn Tay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN2300S (SNM18D00021C01)

OD

Dec 29 2017 2:00PM

[CREDIT LINK PTE LTD]

Trans Eurokars Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/18 16:28	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/01/18 08:59	General View	 Load JPG	☒
2	09/01/18 08:59	General View	 Load JPG	☒
3	09/01/18 08:59	General View	 Load JPG	☒
4	09/01/18 08:59	General View	 Load JPG	☒
5	09/01/18 08:59	General View	 Load JPG	☒
6	09/01/18 08:59	General View	 Load JPG	☒
7	09/01/18 08:59	General View	 Load JPG	☒
8	09/01/18 08:59	General View	 Load JPG	☒
9	09/01/18 08:59	General View	 Load JPG	☒
10	09/01/18 08:59	General View	 Load JPG	☒
11	09/01/18 08:59	General View	 Load JPG	☒
12	09/01/18 08:59	General View	 Load JPG	☒
13	09/01/18 08:59	General View	 Load JPG	☒
14	09/01/18 08:59	General View	 Load JPG	☒
15	09/01/18 08:59	General View	 Load JPG	☒
16	09/01/18 08:59	General View	 Load JPG	☒
17	09/01/18 08:59	General View	 Load JPG	☒
18	09/01/18 08:59	General View	 Load JPG	☒
19	09/01/18 08:59	General View	 Load JPG	☒
20	09/01/18 08:59	General View	 Load JPG	☒
21	09/01/18 08:59	General View	 Load JPG	☒
22	09/01/18 08:59	General View	 Load JPG	☒
23	09/01/18 08:59	General View	 Load JPG	☒
24	09/01/18 08:59	General View	 Load JPG	☒
25	09/01/18 08:59	General View	 Load JPG	☒
26	09/01/18 08:59	General View	 Load JPG	☒
27	09/01/18 08:59	General View	 Load JPG	☒
28	09/01/18 08:59	General View	 Load JPG	☒
29	09/01/18 08:59	General View	 Load JPG	☒
30	09/01/18 08:59	General View	 Load JPG	☒
31	09/01/18 08:59	General View	 Load JPG	☒
32	09/01/18 08:59	General View	 Load JPG	☒
33	09/01/18 08:59	General View	 Load JPG	☒

34	09/01/18 08:59	General View	1	Load JPG	☒
35	09/01/18 08:59	General View	1	Load JPG	☒
36	09/01/18 08:59	General View	1	Load JPG	☒
37	09/01/18 08:59	General View	1	Load JPG	☒
38	09/01/18 08:59	General View	1	Load JPG	☒
39	09/01/18 08:59	General View	1	Load JPG	☒
40	09/01/18 08:59	General View	1	Load JPG	☒
41	09/01/18 08:59	General View	1	Load JPG	☒
42	09/01/18 08:59	General View	1	Load JPG	☒
43	09/01/18 08:59	General View	1	Load JPG	☒
44	09/01/18 08:59	General View	1	Load JPG	☒
45	09/01/18 08:59	General View	1	Load JPG	☒
46	09/01/18 08:59	General View	1	Load JPG	☒
47	09/01/18 08:59	General View	1	Load JPG	☒
Documentation			1 per page	☒	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/01/18 14:49	Quotation/Replacement/Repair invoice	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/01/18 16:47	estimate	1	Load PDF	
2	27/03/18 09:49	SUPPLEMENTARY PART	1	Load PDF	

Linked Accident Report Documents

			View	View in Browser	
Assessment Reports			1 per page	☒	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	02/01/18 09:47	Accident Statement	1	Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	02/01/18 09:42	Accident Photo	1	Load JPG	☒
2	02/01/18 09:42	Accident Photo	1	Load JPG	☒
3	02/01/18 09:42	Accident Photo	1	Load JPG	☒
4	02/01/18 09:42	Accident Photo	1	Load JPG	☒
5	02/01/18 09:42	Accident Photo	1	Load JPG	☒
6	02/01/18 09:42	Accident Photo	1	Load JPG	☒
7	02/01/18 09:42	Accident Photo	1	Load JPG	☒
8	02/01/18 09:42	Accident Photo	1	Load JPG	☒
Documentation			1 per page	☒	
No	Finalized On	Trans Eurokars Pte Ltd (Sungei Kadut)		Thumbnail	Print
1	02/01/18 09:05	Sketch Plan	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118000265/STBQ2

Date: 27/03/2018

REFERENCE

Insured/Claimant: CREDIT LINK PTE LTD Policy No: DMPCSN1618871701
Date of Loss: 29/12/2017 Nature of Claim: OD Claim No: SNM18D00021C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN2300S**
Make & Model: PORSCHE CAYENNE DIESEL, 3.0 D V6 (92A) (A) Engine No: 164416
Reg. Date: 17/04/2014 (Man. Year: 2013) Chassis No: WP1ZZZ92ZELA40151
Colour: Grey Odometer: 69986 km
Engine Capacity: 2967 cc
Market Value/New Car Price: S\$250,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/45 R20 Rear Tyre Size: 275/45 R20
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,316.38	8,861.18	7,455.20	45.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	26,766.25	16,870.00	9,896.25	36.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,082.63	25,731.18	17,351.45	40.27
- Excess (S\$)	3,500.00	3,500.00	0.00	0.00
(S\$)	39,582.63	22,231.18	17,351.45	43.84
+ GST 7.00/7.00% (S\$)	2,770.78	1,556.18	1,214.60	43.84
Nett Amount (S\$)	42,353.41	23,787.36	18,566.05	43.84

INSPECTION

Date of Assignment: 04/01/2018

Date Inspected: 08/01/2018 Inspected At:

Trans Eurokars Pte Ltd (Sungei Kadut)
12 Sungei Kadut Ave
Singapore 729648

Estimated Period of Repair: 10.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Mar 2018)

Parts: M1-SUV PORSCHE CAYENNE DIESEL 3.0 D V6 (92A) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKN2300S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRV/WING LEFT PRIME COAT	Repair	1,405.90 FL	*- FL
2	1		*G2X/LINING REAR PRIME CO	Cut	940.10 FL	*940.10 FL
3	1		*GUIDE BUMPER REAR LEFT	Not Necessary	66.00 FL	*- FL
4	1		*BARE DOOR SHELL LEFT FRONT	Dented	2,767.40 FL	*2,767.40 FL
5	1		*BLIND RIVET	Necessary	1.10 FL	*1.10 FL
6	1		*BLIND RIVET NUT	Necessary	1.70 FL	*1.70 FL
7	2		*BLIND RIVET NUT	Necessary	5.60 FL	*5.60 FL
8	1		*EXPANDER NUT	Necessary	1.50 FL	*1.50 FL
9	2		*INSULATION DOOR	Necessary	30.80 FL	*30.80 FL
10	1		*(WH17) ADHESIVE TAPE DOOR IN WHIT	Not Necessary	110.20 FL	*- FL
11	3		*NUT SPECIAL NUT	Necessary	7.20 FL	*7.20 FL
12	1		*DOOR SEAL OUTER DOOR FRONT	Necessary	390.30 FL	*390.30 FL
13	1		*CAVITY PRESERVATION	Not Necessary	79.60 FL	*- FL
14	9		*GROMMET	Necessary	19.80 FL	*19.80 FL
15	1		*GRV/BARE DOOR SHELL LEFT	Dented	2,682.10 FL	*2,682.10 FL
16	1		*BLIND RIVET	Necessary	1.10 FL	*1.10 FL
17	2		*BLIND RIVET NUT	Necessary	5.60 FL	*5.60 FL
18	1		*EXPANDER NUT	Necessary	1.50 FL	*1.50 FL
19	3		*NUT SPECIAL NUT	Necessary	3.60 FL	*3.60 FL
20	2		*INSULATION DOOR	Necessary	30.80 FL	*30.80 FL
21	1		*DOOR SEAL OUTER DOOR REAR	Necessary	331.90 FL	*331.90 FL
22	1		*CAVITY PRESERVATION	Not Necessary	79.60 FL	*- FL
23	5		*GROMMET	Necessary	11.00 FL	*11.00 FL
24	1		*(WH17) ADHESIVE TAPE DOOR IN WHIT	Not Necessary	110.20 FL	*- FL
25	1		*DOOR SEAL OUTER REAR LEFT	Necessary	249.40 FL	*249.40 FL
26	1		*DOOR SEAL FRONT LEFT	Necessary	83.60 FL	*83.60 FL
27	1		*COVER SIDE WINDOW FRONT LE	Necessary	243.10 FL	*243.10 FL
28	1		*COVER SIDE WINDOW REAR LEF	Necessary	243.10 FL	*243.10 FL
29	1		*SIDE SECTION OUTER LEFT C	Repair	4,470.30 FL	*- FL
30	1		*CAVITY PRESERVATION	Not Necessary	79.60 FL	*- FL
31	3		*CAVITY PRESERVATION	Not Necessary	238.80 FL	*- FL
32	1		*THREADED PIN (50 PCS)	Not Necessary	60.00 FL	*- FL
33	1		*THREADED PIN (50 PCS)	Not Necessary	50.00 FL	*- FL
34	1		*SIDE WINDOW REAR LEFT	Not Necessary	1,093.20 FL	*- FL
35	2		*BLIND RIVET NUT	Not Necessary	3.40 FL	*- FL
36	1		*WHEEL COVER SIDE SECTION R	Scratched	376.20 FL	*376.20 FL
37	2		*CLIP FOR WHEEL ARCH COVER	Necessary	4.20 FL	*4.20 FL
38	10		*CLIP FOR COVER	Necessary	34.00 FL	*34.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	2		*CLAMP FOR WHEEL COVER	Not Necessary	5.00 FL	*- FL
40	1		*WHEEL COVER BUMPER FRONT L	Not Necessary	376.20 FL	*- FL
41	1		*STRIP DOOR FRONT LEFT	Scratched	536.80 FL	*536.80 FL
42	1		*STRIP DOOR REAR LEFT	Scratched	339.40 FL	*339.40 FL
43	18		*GROMMET	Necessary	39.60 FL	*39.60 FL
44	1		*COVER WING LEFT PRIME COAT	Scratched	166.50 FL	*166.50 FL
45	1		*ADHESIVE TAPE FOR DOOR GARNISH (NPA)	Necessary	0.00 FL	*- FL
46	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
47	1		*ADHESIVE TAPE	Necessary	28.20 FL	*28.20 FL
48	1		*MIRROR HOUSING LOW	Scratched	205.90 FL	*205.90 FL
49	1		*PLUG	Necessary	2.10 FL	*2.10 FL
50	2		*CLIP DOOR TRIM	Necessary	5.00 FL	*5.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,118.20	9,840.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,801.82	979.02
Total Parts (\$\$)	16,316.38	8,861.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE LH DAMAGED & AFFECTED BODY PARTS,KNOCK ,REPAIR ,REPLACE REAR BUMPER ,LHR FENDER,LHR DOOR ,LHF DOOR & FENDER REPLACE AFFECTED BODY PARTS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	New	12,600.00	9,360.00
2	TO SPRAY PAINT FRONT BUMPER ,FRT LH FENDER,FRT LH DOOR ,REAR LH DOOR ,REAR LH FENDER & REAR BUMPER	New	6,800.00	5,100.00
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS	New	720.00	250.00
4	TO APPLY THEROSTAT SEALANT TO AFFECTED AREAS	New	500.00	0.00
5	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS	New	380.00	0.00
6	TO REMOVE,REPLACE ,REFIT REAR LH FENDER GLASS TO FACILITATE REPAIRS	New	480.00	0.00
7	REMOVE & REFIT LHR C PILLAR TRIMS ,OUTER MOULDING,ROOF LINING ,BOOT INNER COVERS,FLOOR CARPET & REAR SEAT CUSHION.(TO FACILITATE THE REPLACEMENT OF LHR FENDER)	New	1,400.00	0.00
8	SUPPLY WINDNSCREEN SEALANT	New	186.25	0.00
9	TO SUPPLY /INSTALL SUN SHIELD TO LHR FENDER GLASS	New	300.00	0.00
10	TO REMOVE/REFIT BOTH LH DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	New	2,800.00	1,560.00
11	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	New	600.00	600.00
Gross Labour Cost (S\$)			26,766.25	16,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >