

NGS TRADING

Blk 10 Ang Mo Kio Ind. Pk 2a #02-01 AMK AutoPoint Singapore 568047
Tel: 64815727 Fax: 64815772 Email: evelynngstrading@gmail.com
Reg No.: 51106300L

QUOTATION

No. : QT-09290

AXA INS SINGAPORE PTE LTD
MOTOR CLAIMS DEPT
143 CECIL STREET
#01-01 GB BUILDING
SINGAPORE 069542

Your Ref. :
Our Ref : QT-09290/SFP3088
C. C. :
Date : 06-01-2018
Page : 1 of 1

TEL : 6880 4832

FAX : 6880 4838

Description	Qty	U/ Price S\$	Amount S\$
<i>Not Authorised</i> <i>11 Sep @ 2100</i>			
ACCIDENT ON 23/12/17 @14:10 ALONG ORCHARD RD INVOLVING SFP3088Y & SHD9987C CLAIMS AGAINST SHD9987C			
<i>Running After Party</i> <i>4 days</i>			
REPLACEMENT PARTS:-			
FRT FENDER LH <i>715.48</i>	1	882.20 <i>Bu</i>	882.20
FRT BUMPER <i>491.60</i>	1	526.40 <i>Bu</i>	526.40
BUMPER GARNISH LH	1	64.20 <i>bu</i>	64.20
FRT BUMPER RETAINER LH	1	59.57 <i>bu</i>	59.57
HEADLAMP LH <i>917.00</i>	1	989.05 <i>bu</i>	989.05
SubTotal			2,521.42
LESS 25%	1	-630.36	-630.36
TO REMOVE ALL DAMAGED PARTS WITH ALL NECESSARY COMPONENT/ATTACHMENT.	1	550.00	550.00 <i>400</i>
STRAIGHTEN CHASSIS MEMBER, REPAIR/RESHAPE DENTED BODY PANEL. REPLACE DAMAGED PARTS. REFIT INTO POSITION			
SPRAY PAINTING	1	600.00	600.00 <i>480</i>
CHECK WIRING/LIGHT PROPER FUNCTION	1	40.00	40.00 <i>20</i>

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @ HP 96955547 to arrange for survey. Thank you.

Yours faithfully,



Administrator

Total **3,081.06**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: