

S. REC. BY:

REF:

CS/AWA13000267/Tlvb 82

Special Instructions:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Kim Wong

of

AWA

Date/Time:

03/01/2018 536pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDV 188D

Insured:

SIL 2915L

at Workshop m/s

Kah motor

Tel:

9072 1769

of

No. 255 Alexandra Rd

Policy No:

BVPPSB 0511454/1600

Claim No:

NSV1701396 / TKL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20-12-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

05-02-2018

H.O.D. Endorsement:

Date/Time:

04/01/2018 937am

Person Contacted:

Sin Hai

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SDV 188D - X
	SIL 2915L - X
13/2/18	Final fig \$ 4645.94 confirmed by email (Ref 752966, 6270)



## Survey Department Check List (Case Handler)

Reference No.: CS/ AWA/800>67/ Tivb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

### (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

### (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 13/11/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18000267/T1vb

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 04-01-2018



Code : AWA

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 2925L	Veh. Inspected	SDV 188D
Policy No.	BVPPSB0544541600	Coverage (\$)	0.00
Claim No.	NSV1701396/TKL	Excess (\$)	0.00
Assign From	KIN WONG	Assign Date	03/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	20/12/2017	Inspection Date
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**Catherine Chong (LKK Auto)**

---

**From:** Wong, Kin <Kin.Wong@awac.com> on behalf of Motorsurvey  
<Motorsurvey@awac.com>  
**Sent:** Wednesday, 3 January, 2018 5:36 PM  
**To:** LKK (assignments@lkkauto.com)  
**Cc:** SUR (sur@lkkauto.com); shng@kahmotor.onmicrosoft.com  
**Subject:** TP Survey assignment for SJL 2925L DOA: 20.12.2017 Our ref: NSV1701396/TKL

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	SDV 188 D
Insured Vehicle	:	SJL 2925 L
Policy Number	:	BVPPSB0544541600
Name of Workshop	:	Kah Motor Co.Sdn.Bhd
Contact Number	:	6471 5419
Person to Contact	:	9072 1769
Estimated Cost of repairs	:	\$ N.A

Regards,  
Claims Division

Copy to Kah Motor Co.Sdn.Bhd via Email

Note -

- ( x )
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards  
Motor Claims  
Claims Group  
Global Market

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/12/2017 20:12
Date Of Accident	20/12/2017 16:30
Exact Location Of Accident	BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDV188D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE HUI
NRIC No	S7637033H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97395596
Alternative Phone No	OFFICE-97395596
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEE HUI
NRIC No	S7637033H
Date Of Birth	27/10/1976
Occupation	INDOOR
Date Of Driving Pass	08/04/2002
Driving Experience	15 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97395596
Fax Number	
Contact Number	OFFICE-97395596
Email Address	NOEMAIL

Address	198 BOON LAY DRIVE
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL2925L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	SOMPO INSURANCE SINGAPORE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	



# Sketch Plan

Vehicle No \_\_\_\_\_

## SKETCH PLAN

Annex B

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



Please continue in Annex C



Vehicle No \_\_\_\_\_

AR03 E


**Describe Circumstances of the Accident**


I was traveling along Bukit Timah Road going to PIE.  
while driving straight, vehicle B just came out from the lane  
and hit my vehicle A. My vehicle A left portion is  
damaged due to the accident.


You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

**Declaration**

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b> :	ALLIED WORLD ASSURANCE	<b>Document No.</b> :	SQT18000465	<b>Page</b> 1
	60 ANSON ROAD	<b>Date</b> :	30. Jan 2018	
	MAPLETREE ANSON	<b>Customer No.</b> :	WZR002	
	SINGAPORE 079914	<b>Svc Advisor</b> :		
<b>Registration No</b> :	SDV188D	<b>Engine No</b> :	L15B4531415	
<b>Chassis No</b> :	JHMRU1830GX201413	<b>Date   Time</b> :	30. Jan 2018 12:20:10 PM	
<b>Model</b> :	HRV LX-SIN CVT YM 2016	<b>Surveyor Name</b> :		
<b>Owner's Name</b> :	LEE HUI	<b>Survey Date</b> :		
<b>Ins Policy No.</b> :		<b>Authorisation Date</b> :		
<b>Date of Accident</b> :	20/12/2017			

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: )						
	OWNER:LEE HUI						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:20/12/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:ALLIED WORLD ASSURANCE COMPANY LTD						
	TP VEH:SJL2925L						
BO-TOW-SW	TOWING SERVICE (KING DOLLY DUE TO BRAKE JAM)	1	250.00		250.00	17.50	267.50
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	<b>Sum Ext. Service</b>				<b>430.00</b>	<b>30.10</b>	<b>460.10</b>
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	450.00		450.00	31.50	481.50
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)	1	1800.00		1800.00	126.00	1926.00
BKFE11R	REMOVE & RENEW FR L FENDER AND ALL DAMAGED PARTS	1	2500.00		2500.00	175.00	2675.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2500.00		2500.00	175.00	2675.00
BOMISC1	REMOVE AND RENEW LHF RIM/TYRE/WHEEL	1	50.00		50.00	3.50	53.50
	<b>Sum Labor</b>				<b>7580.00</b>	<b>530.60</b>	<b>8,110.60</b>
33150-T7S-E11	HEAD LIGHT ASSY,L.	1	1479.70	35	961.80	67.33	1029.13
33950-SLE-J51	LIGHT ASSYL.FR.FOGLIGHT	1	235.00	35	152.75	10.69	163.44
71152-T7A-000	BEAML.FR.GRILLE SIDE UPPER	1	4.50	35	2.92	0.20	3.12
91505-TM8-003	CLIPBUMPER	12	2.00	35	15.60	1.09	16.69
04711-T7A-N00ZZ	FACEFR.BUMPER	1	466.20	35	303.03	21.21	324.24
71102-T7B-000	FACE FR. BUMPER LOWER	1	344.20	35	223.73	15.66	239.39



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : ALLIED WORLD ASSURANCE  
60 ANSON ROAD  
MAPLETREE ANSON  
SINGAPORE 079914  
Registration No : SDV188D  
Chassis No : JHMRU1830GX201413  
Model : HRV LX-SIN CVT YM 2016  
Owner's Name : LEE HUI  
Ins Policy No :  
Date of Accident : 20/12/2017

Document No. : SQT18000465 Page 2  
Date : 30. Jan 2018  
Customer No. : WZR002  
Svc Advisor :  
Engine No : L15B4531415  
Date | Time : 30. Jan 2018 12:20:10 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
71106-T7A-000	GARNISH LFR.FOG LIGHT	1	21.10 X	35	13.71	0.96	14.67
71116-T7A-000	GUIDEL.FR.BUMPER AIR	1	27.90 X	35	18.13	1.27	19.40
71190-T7A-000	BEAML.FR.BUMPER UPPER	1	23.90 X	35	15.53	1.09	16.62
71198-T7A-000	SPACER LFR.BUMPER SIDE	1	10.40 rel	35	6.76	0.47	7.23
91505-TM8-003	CLIPBUMPER	22	2.00 rel	35	28.60	2.00	30.60
60260-T7A-010ZZ	PANEL COMPL.FR.FENDER	1	387.20 Rel	35	251.68	17.62	269.30
74150-T7A-N00	FENDER ASSYL.FR.INNER	1	88.20 Rel	35	57.33	4.01	61.34
74157-T7B-003	PROTECTOR.LFR.WHEEL ARCH	1	150.60 rel	35	97.89	6.85	104.74
91501-TR0-003	CLIPINNER FENDER	22	2.30 rel	35	32.89	2.30	35.19
42700-T7A-J91	DISKALUMINIUM WHEEL	1	765.80 rel	35	497.77	34.84	532.61
44300-T6A-J51	BEARING ASSYFR.HUB	1	135.50 ?	35	88.07	6.16	94.23
44600-T0B-A00	HUB ASSYFR.	1	183.50 ?	35	119.27	8.35	127.62
67050-T7A-300ZZ	PANEL COMPL.FR.DOOR	1	817.50 ddr	35	531.37	37.20	568.57
67366-T7A-003	TAPEL.FR.DOOR SASH	1	18.50 rel	35	12.02	0.84	12.86
72365-T7A-003	SUB SEALL ROOF	1	71.00 ?	35	46.15	3.23	49.38
72367-T7A-J01	SUB SEALL.FR.DOOR CENTER	1	45.60 ?	35	29.64	2.07	31.71
71850-T7A-J02ZE	GARNISH ASSYL.SIDE SILL	1	377.50 org	35	245.37	17.18	262.55
Sum Item					3752.01	262.62	4,014.63

Survey By

Date & Time

Excess

Status

Signature

Total Amount 11,762.01 823.32 12,585.33

Total (Inclusive of GST) 12,175.60 12,585.33

*Signature* 97495749  
5/2/18 @ 5:15 pm  
WP  
*Signature*  
5 days - 7 days.  
Resurvey before paint  
sur@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 30/1/2018 1:46:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 13 February 2018 5:05 PM  
**To:** Ng Sin Hai (shng@kahmotor.onmicrosoft.com)  
**Cc:** SUR  
**Subject:** RE: Submission Pre-Invoice for vehicle SDV 188D

Dear Sin Hai,

Confirmed Cost of repair : S\$4,645.94 (before GST)

No of working days : 05 days.

**Final invoice and all supporting documents sent to ALLIED WORLD ASSURANCE**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiao Chan (LKKAUTO)  
**Sent:** Monday, 12 February 2018 10:01 AM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** FW: Submission Pre-Invoice for vehicle SLQ9523S

Best Regards,

**Shiao Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Taufikh (LKKAUTO)  
**Sent:** Monday, 12 February 2018 9:37 AM  
**To:** Shiao Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Subject:** FW: Submission Pre-Invoice for vehicle SLQ9523S

---

**From:** Ng Sin Hai [<mailto:shng@kahmotor.onmicrosoft.com>]  
**Sent:** Friday, 9 February 2018 1:10 PM  
**To:** [Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)  
**Subject:** RE: Submission Pre-Invoice for vehicle SLQ9523S

Dear Mr Taufikh,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair : S\$4,645.94 (before GST)

No of working days : 05 days. (LOR)

We will proceed for closing after 1 week of submission to you.  
Kindly contact me if there is any discrepancy

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai

**Kah Motor Co. Sdn. Bhd**

*(A member of Oriental Holdings Berhad)*

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: [shng@honda.com.sg](mailto:shng@honda.com.sg)



BLUE SKIES FOR  
OUR CHILDREN



Visit our  
Facebook page



CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer: WZR002 / ALLIED WORLD  
Chassis No: JHMRU1830GX201413  
License No: SDV188D  
Mileage: 11424  
Engine No: L15B4531415

Document No: SVO18007510  
Printed By: SHNG  
Order Date: 5. February 2018  
Order Time: 5:28:32 PM  
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld Amount	GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: LEE HUI OWNER INSURER: TOKIO MARINE ACC DATE: 20/12/2017 SURVEYED BY: TAUFIKH DATE: 05/02/2018 REF NO: TP INSURER: ALLIED WORLD ASSURANCE COMPANY LTD TP VEH: SJL2925L ADDITIONAL PART						
71198-T7A-000	SPACER L.FR. BUMPER SIDE	1	10.40	35	6.76	0.47	7.23
91505-TM8-003	CLIP BUMPER	22	2.00	35	28.60	2.00	30.60
60260-T7A-010ZZ	PANEL COMPL.FR.FENDER	1	387.20	35	251.68	17.62	269.30
74157-T7B-003	PROTECTOR, L.FR.WHEEL ARCH	1	150.60	35	97.89	6.85	104.74
91501-TR0-003	CLIP INNER FENDER	22	2.30	35	32.89	2.30	35.19
42700-T7A-J91	DISK ALUMINIUM WHEEL	1	765.80	35	497.77	34.84	532.61
67050-T7A-300ZZ	PANEL COMPL.FR.DOOR	1	817.50	35	531.37	37.20	568.57
67366-T7A-003	TAPEL.FR.DOOR SASH	1	18.50	35	12.02	0.84	12.86
71850-T7A-J02ZE	GARNISH ASSYL.SIDE SILL	1	377.50	35	245.37	17.18	262.55
76251-T7A-J01ZD	CAPL.SKULL	1	64.70	35	42.05	2.94	44.99
76258-T7A-J02	MIRROR SET, L.	1	571.60	35	371.54	26.01	397.55
	<b>SUM PARTS:</b>				<b>2,117.94</b>	<b>148.25</b>	<b>2,266.19</b>
BOSUN	0701	1	30.00		30.00	2.10	32.10
BML01I	SUNDRIES	1	120.00	10	108.00	7.56	115.56
	1466 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	450.00	10	405.00	28.35	433.35
BKDR11R	1466 REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST & ALIGN FR L DR.(N)	1	900.00	10	810.00	56.70	866.70
BKFE11R	1466 REMOVE & RENEW FR L FENDER AND ALL DAMAGED PARTS	1	1,050.00	10	945.00	66.15	1,011.15
BP06R	1637 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	50.00		50.00	3.50	53.50
BOMISC1	1466 REMOVE AND RENEW LHF RIM/TYRE/WHEEL						
	<b>SUM LABOUR:</b>				<b>2,348.00</b>	<b>164.36</b>	<b>2,512.36</b>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	<b>SUM EXT SERVICE:</b>				<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
	<b>TOTAL SGD</b>				<b>4,645.94</b>	<b>325.21</b>	<b>4,971.15</b>

**Total Payable (SGD)****4,971.15**

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : ALLIED WORLD ASSURANCE  
60 ANSON ROAD  
MAPLETREE ANSON  
SINGAPORE 079914  
Registration No : SDV188D  
Chassis No : JHMRU1830GX201413  
Model : HRV LX-SIN CVT YM 2016  
Owner's Name : LEE HUI  
Ins Policy No. :  
Date of Accident :

Document No. : SQT18000628  
Date : 9. Feb 2018  
Customer No. : WZR002  
Svc Advisor :  
Engine No : L15B4531415  
Date | Time : 9. Feb 2018 1:05:26 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: )						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
	SUPPLEMENTARY						
76251-T7A-J012D	CAPL.SKULL cut	1	64.70	35	42.05	2.94	44.99
76258-T7A-J02	MIRROR SET,L dist	1	571.60	35	371.54	26.01	397.55
	Sum Item				413.59	28.95	442.54

Survey By \_\_\_\_\_  
Date & Time \_\_\_\_\_  
Excess \_\_\_\_\_  
Status \_\_\_\_\_  
Signature \_\_\_\_\_

Total Amount 413.59 28.95 442.54  
Total (Inclusive of GST) 442.54

Printed on 9/2/2018 1:07:00 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18000267/T1vbs2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 21-02-2018



Code : AWA

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 2925L	Veh. Inspected	SDV 188D
Policy No.	BVPPSB0544541600	Coverage (\$)	0.00
Claim No.	NSV1701396/TKL	Excess (\$)	0.00
Assign From	KIN WONG	Assign Date	03/01/2018

### 2. Vehicle Particulars & Condition

Make & Model	HONDA HRV	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMRU1830GX201413	Colour	RED
Odometer	19135	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	6 mm
L/H Front Tyre	215/60R16	DUNLOP	6 mm
R/H Rear Tyre	215/60R16	DUNLOP	6 mm
L/H Rear Tyre	215/60R16	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	20/12/2017	Inspection Date	05/02/2018
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDV 188D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HEAD LIGHT ASSY,L. (SN)	NOT NECESSARY	961.80	-
1	LIGHT ASSYL.FR.FOGLIGHT (SN)	NOT NECESSARY	152.75	-
1	BEAML.FR.GRILLE SIDE UPPER (SN)	NOT NECESSARY	2.92	-
12	CLIPBUMPER (SN)	NOT NECESSARY	15.60	-
1	FACEFR.BUMPER (SN)	NOT NECESSARY	303.03	-
1	FACE FR. BUMPER LOWER (SN)	NOT NECESSARY	223.73	-
1	GARNISHL.FR.FOG LIGHT (SN)	NOT NECESSARY	13.71	-
1	GUIDE.FR.BUMPER AIR (SN)	NOT NECESSARY	18.13	-
1	BEAML.FR.BUMPER UPPER (SN)	NOT NECESSARY	15.53	-
1	SPACERL.FR.BUMPER SIDE (SN)	NECESSARY	6.76	6.76
22	CLIPBUMPER (SN)	NECESSARY	28.60	28.60
1	PANEL COMPL.FR.FENDER (SN)	BENT	251.68	251.68
1	FENDER ASSYL.FR.INNER (SN)	NOT NECESSARY	57.33	-
1	PROTECTOR,L.FR.WHEEL ARCH (SN)	CUT	97.89	97.89
22	CLIPINNER FENDER (SN)	NECESSARY	32.89	32.89
1	DISKALUMINIUM WHEEL (SN)	CUT	497.77	497.77
1	BEARING ASSYFR.HUB (SN)	NOT NECESSARY	88.07	-
1	HUB ASSYFR. (SN)	NOT NECESSARY	119.27	-
1	PANEL COMPL.FR.DOOR (SN)	DENTED	531.37	531.37
1	TAPEL.FR.DOOR SASH (SN)	NECESSARY	12.02	12.02
1	SUB SEALL.ROOF (SN)	NOT NECESSARY	46.15	-
1	SUB SEALL.FR.DOOR CENTER (SN)	NOT NECESSARY	29.64	-
1	GARNISH ASSYL.SIDE SILL (SN)	CRACKED	245.37	245.37
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	CAPL.SKULL (SN) (ADDITIONAL)	CUT	42.05	42.05
1	MIRROR SET, L. (SN) (ADDITIONAL)	DISTORTED	371.54	371.54
			4,265.60	2,147.94
<b>LABOUR</b>				
	TOWING SERVICE (KING DOLLY DUE TO BRAKE JAM)	NOT NECESSARY	250.00	-
	WHEEL ALIGNMENT X4.		180.00	180.00
	INSPECT FR LIGHTING MECHANISM & FOCUS.		180.00	108.00
	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST.		450.00	405.00
	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.	NOT NECESSARY	1,800.00	-

Report Ref No. CS/AWA18000267/T1vbs2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & RENEW FR L FENDER AND ALL DAMAGED PARTS.		2,500.00	810.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,500.00	945.00
	REMOVE AND RENEW LHF RIM / TYRE / WHEEL.		50.00	50.00
			7,910.00	2,498.00
GRAND TOTAL			12,175.60	4,645.94
RECOMMENDED COST OF REPAIRS				4,645.94

Report Ref No. CS/AWA18000267/T1vbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.