1202200 -		10.3			
ASS_REC.BY:	REF (S/CTII8	)00268 / UN	beld Special in	เรียวสนอก:	
ZMINEARL.	ASSIGNMI				
From (Person): Joll Go			Detek	Time:	04012018 989am
Estimated Cost:		Bill to:			
OD /TP WS / TP RES / OD	RES/EVA/INV/MV/C	:s	<u>",</u>		
To Inspect Vehicle No:	GBA 9708T		Insured:	CCS	7629B
at Workshop m/s	Abwin Sente				
of	8 Kalá Bulát Ave	4 #07-4	<u> </u>		
Policy No: OMPCSN	3071241700	Claim No:	SNM18DOL	0520	(1)
Sum Insured:		Excess:			
Make of Veh: (Client's Record)			D.O.	A3	06-122017
CA / REV / REP. / REV 2	4 HTRS (Mn)		ti d	) Ev Elledon	sement:
Date/Time: OUDI JUIS 10.11	Fam Person Contacted.	Ivan_	Vehici	e.IN LQ	(I)
	ion (V) Estimate	·-···			
68A Trest			<del></del>		
	5 - 003 /AUGUUCOIG	12/Fazin		ĵ	)U1: 150/00(0
		<u></u>	w		
				<del></del>	

į

Reference No.: (S) CTI 18000>68 Uvb

/ سامسالس	): Case handler to make sure all inform		landler by the assi	enment te:	m are A
<u>ldmin</u> (	): Case nandler to make sure all inform Assign Form	Y-Date		Y-Date	N-Date
C	Reference No.				
c	Customer Code	· · ·			_
N	A-rice France				
'`` ·	Ancien Dato	~			
C	Veh No (Inspected)	~			
C	Veh No (Insured)				
	D.O.A	~			
	Policy No				
<u>с</u>	Claim No	~			
	Insurance Authorisation (CA /REV/REP)				
<u> </u>					
<u>C</u>	Report Type		<del>                                     </del>		
C	Weekend Charges		†		
<u> </u>	Survey held at/Repairer	<del> </del>			
С	Excess		<u></u>		
urveyo	or ( ): Case handler to make sure the	ne surveryor c	ompleted a	ill required	intorma
L) Assign	nment Form	<u></u>			
C	Vehicle No	<u> </u>		<u> </u>	
c	Regn Month/Year				
N	Vehicle Type	<u></u>			ļ
N	Make & Model	~			<u> </u>
C	Engine Capacity. (C.C)	~			<u> </u>
N	Colour				<u> </u>
C	Odometer. (Sp.Reading)	~			
C	Chassis No	~			<u> </u>
— <del>.</del> _	General Condition	V			<u> </u>
N	Steering	~			<u></u>
N N	Brake	~			<u> </u>
	Modification (Modi)	~			
N		~			T
C	Tyre Size	~			T
N	Tyre Make	~			
<u>C</u>	Tyre Balance	v	<del>                                     </del>		
<u>C</u>	Date of Inspection	-			
N	Survey held		<u> </u>		
N	Des.of Damages	<del>L</del>		, <u>L</u>	
2) Syste	em - (Views/Merimen)	· · · · · · · · · · · · · · · · · · ·	<u> </u>	1	1
С	Damaged Vehicle Photographs Uploaded			ı L	<u> </u>
(3) Wor	kshop Estimate/Assignment Form		<del></del>	, <del>,</del>	· · · · · ·
N	ALL Parts condition				
C	Market Value for OD cases			]	_
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
<u>č</u>	Days of repair	~		<b>」</b>	
C	Finalised Amount	~		ļ	
- <u>C</u>	Re-inspection Cases to Finalize within 5 Days			]	
	em - (Views/Merimen)			, <del>,</del>	
(-) <u>-) -) -</u> C	Resurvey photo Uploaded			J L	_L

8/1/125 VERON Check By: Date Case Handler



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Residence of States Children Processes	Affiliated to Federation Int	ernationale Des Experts En Automo	bile
CHIN	NA TAIPING INSU	JRANCE (S) PTE LTD	Ref : CS/CTI18000268	J/Uvb
SPR.		RSINGAPORE 079909	Date : 04-01-2018 Code : CTI	
l A in	AND SOMETHING A TA	Policy Partic	ulars :- THIRD PARTY CLAIM	Augustin and the second se
	Insured Veh.	SJD 7629B	Veh. Inspected	GBA 9908T
	Policy No.	DMPCSN3071241700	Coverage (\$)	0.00
	Claim No.	SNM18D00052C02	Excess (\$)	0.00
	Assign From	MERIMEN (JOEL GOH)	Assign Date	04/01/2018
2		Vehicle	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	<del></del>
	Chassis No.		Colour	
	Odometer	<u> </u>	Steering	<u> </u>
	Brakes		Modification	,
	General			
***			onditions of Tyres	
_		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
* * 500	L/H Rear Tyre			mm
: ::::::::::::::::::::::::::::::::::::		V. Desc	ription of Damages	
	Edina Per	Co.	neral information	
	Accident Date	26/12/2017		en e
		ABWIN SERVICE PTE LTD	Inspection Date	
		No. 8 KAKI BUKIT AVENUE #07-48 PREMIER@KAKI B SINGAPORE 415875	E 4	
	Silver of Kreens	The state of the s	Remarks	and the second s
ı. þg				

Merimen e-Claims

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted   Adj A	ssigned A	dj Rpt	Adj Submit	tted	Ins Auth'ed	Status	
Main	03 Jan 2018	. 09	n 2018 9:59 sign					New Assignation Cancel Case	
	Main	Reference	<u> </u>	Clain	n Details		Docume	ents	Show All
CLAIM S Insured:	UBFOLDER DET	AILS					[Created b	y insurer]	
Main Cla		HONG AN ENGINEER	ING PTE LTD.	Co. Rea.	No.: 2004002	88K			
Vehicle F	Reg. No.:	GBA9908T			e of Loss:		26/12/2017	00:00 - :59	
Claim Ty	pe:	TP / SNM18D00052C02		Poli	Policy/Cover Note No.:		DMPCSN3071241700		
Vehicle F (Insured		SJD7629B		Policy No. (Claimant):					
					ess:		5\$0.00		
Repairer	:	Abwin Service Pte Lt Tel: 6713 9400	t <b>d (HQ)</b> No. 8 k	Kaki Bukit A	venue 4, #07·	-48 Premi	ier@Kaki Bukit	Gate 2, 41587	5 Kaki Bukit -
Handling	Insurer:	China Taiping Insura	nce (Singapo	re) Pte. Lt	<b>d. (HQ)</b> - Tel:	6389 61	11 [Handled	by <b>Joel Goh</b> ]	
Adjuster		LKK Auto Consultant					t due 15/01/	2018]	
Adj Asg.	Remarks:	ESTIMATE AMOUNT \$4	976.14, ASSIGI	N MARCUS	CHUA AS SJE.				
ASSOCIA	ATED MAIL REC	EIVED					View A	II Compo:	se Case Mail
There are	no mail for this c	ase.							
	OCIATED TASK	 'S			View All	Search Ta	asks Cre	ate New Task	Complete
⊟ ALL ASS	OCIATED TASK						Completed On		On Done

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

¥ Owner ID:

0288K

Vehicle Details

Vehicle No.:

**GBA9908T** 

Vehicle to be Exported:

Nο

Intended De-registration

17 Jan 2018

Date:

Vehicle Make:

TOYOTA

Vehicle Model:

**DYNA 150 MANUAL** 

Primary Colour:

White

Manufacturing Year:

2008

Engine No.:

1KD1806721

Chassis No.:

JTFAT35Y203001765

Maximum Power Output:

Open Market Value:

\$24,243.00

Original Registration Date:

08 May 2008

First Registration Date:

08 May 2008

Transfer Count:

0

Actual ARF Paid:

\$1,213.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry

Date:

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

07 May 2018

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$15,002.00

COE Rebate Amount:


\$457.00

**Total Rebate Amount:** 

\$457.00

The information contained herein is correct as at 17 Jan 2018

ОК



MABW17169518 / Abwin Service Pte Ltd - HQ ENTRY DATE & TIME: 26/12/2017 17:26 SUBMITTED BY: Ivan Teo

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	26/12/2017 17:26
Date Of Accident	26/12/2017 07:25
Exact Location Of Accident	OUTSIDE ANG MO KIO SECONDARY SCHOOL AMK ST 22
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBA9908T

Insured/Policyholder

Name Of Registered Owner HONG AN ENGINEERING PTE LTD

Co Reg No 200400288K

Email Address DAPHNE@HAENGRG.COM.SG

Mobile Phone No

Alternative Phone No OFFICE-65090990

Vehicle Particulars

Manufacturer TOYOTA
Model DYNA

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5077032757-01

Cover Note Number

Driver

Name of Driver PENTAM SUDHAKAR

Passport No/FIN G7409796R

Date Of Birth 14/08/1980

Occupation OUTDOOR

Date Of Driving Pass 30/03/2005

Driving Experience 12 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96975564

Fax Number

Contact Number

EMail Address NOEMAIL

Address

Postcode 408555

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING STRAIGHT WHEN VEHICLE B SUDDENLY MAKE A RIGHT TURN INTO ANG MO KIO SECONDARY SCHOOL FROM THE OPPOSITE SIDE OF THE ROAD, OUR VEHICLE COLLIDED INTO EACH OTHER.

NO

NO

NO

NO. 1 UBI VIEW #03-21

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJD7629B

Vehicle Make/Model/Colour

Details Of Properties VEH B

Vehicle Category PRIVATE CAR

Name of Driver CHEW TZE MING BENJAMIN

NRIC/Passport Number S9345415D

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### **SKETCH PLAN**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy flability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature


Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

#### Sketch Plan Pg. 2



#### **DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

I WAS TRAVELLING STRAIGHT WHEN VEHICLE B SUDDENLY MAKE A RIGHT TURN INTO ANG MO KIO SECONDARY SCHOOL FROM THE OPPOSITE SIDE OF THE ROAD, OUR VEHICLE COLLIDED INTO EACH OTHER.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

27 DE 101

Name: NRIC/FIN No.:

GIARMC SketchPlanForm\_V3

2

Please arrange to survey vehicle at 8 KAKI BUKIT AVENUE 4 - GATE 2 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875



Accident Date: 26/12/2017

Company Registration No. 201318685G

Acknowledged by Repairer

IVAN TEO

Date : 16/01/2018 ABWIN SERVICE PTE LTD

TP Vehicle No. : SJD-7629-B DID: 67139416

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD Fax: 67139415
Attn : Motor Claim Department HP: 86680608

Owner : HONG AN ENGINEERING PTE LTD

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 5077032757-01

Vehicle No. : GBA-9908-T

Make & Model : TOYOTA DYNA 150 MANUAL

#### **ESTIMATED REPAIR COST DETAILS**

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Iter	<del></del>		
1	FRONT PANEL 3. 6500	\$1,109.30	//
1	EMBLEM DYNA 2a	\$64.40	
1	FRONT GRILLE	\$475.50	
1	FRONT GRILLE LOGO MM	\$75.60	
1	HEADLAMP RH U 1	\$611.30	*_
1	HEADLAMP LH CM	\$611.30	
1	FRONT BUMPER Suf	\$433.40	
	Sub Total	\$3,380.80	-185
	Discount 25% on Parts	(\$845.20)	2769.5
		\$2,535.60	
<u>Special</u>	<u>Nett</u>		
1	FRONT NUMBER PLATE BY	\$35.00	155.W
1	AIRPORT GREEN STICKER 14	\$30.00	155.W
	Sub Total	\$65.00	
<u>Labour</u>	& Misc		
	LABOUR TO FACILIATE REPAIR	\$1,000.00 \$1,000.00	600
	TO SPRAY PAINT ON AFFECTED AREAS	\$1,000.00	600
	TO RUST PROOF AFFECTED AREA	\$80.00	
	TO INSTALL HEADLAMP AND FOCUS LIGHT	\$50.00	20
	Sub Total	\$2,130.00	,
	· c AM. 1		3357.12
	No f Allul Sub Total Mik John GST 7%	\$4,730.60	, ,
	MUK VOL. GST 7%	\$331.14	
	Met Vol. GST 7% Total	\$5,061.74	
	177	LKK.∆uto Consultan	t <u>s</u> hence <b>notify</b>
	4 407	the Repairer of the fe • To resurvey before/afte	ollowing:
	17/1/18 the upon the photo Ather upon	<ul> <li>To display damaged pa</li> </ul>	rt(s) during resurvey
	1/ 2 hoto from	<ul> <li>Parts prices are subject</li> </ul>	t to confirmation a a "Without Prejudice" basis
	The 1.	<ul> <li>No illega! medification(</li> </ul>	s) is allowed Page 1 of 1
	ABWIN SERVICE PTE LTD, 8 KAKI BUKIT AV	ENUE 4 GATE Supplementary item(s)	must be resurveyed and MINOR PISUIS AND 413875

Merimen e-Claims Page 1 of 1

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj R	pt	Adj Subm	iitted I	ns Auth'ed	Stati	ıs	
Main	03 Jan 2018		04 Jan 2018 09:59 Edit Adj Rpt	1 ' '	650.00 it Estimates	\$\$2,650 View Rp	4		Surv	ding for ey Report ncel Case	
	Main	Refere	nce	Cla	im Details		Doc	uments		Show All	
CLAIM SU	JBFOLDER DET	AILS	Y		·		[[	Created by	insurer]		
Insured:	_	-, Co. Reg. N	lo.: -								
Main Claim	nant:	HONG AN EN	GINEERING PTE	LTD,	Co. Reg. No.	: 20040028	38K	,			
Vehicle Re	g. No.:	GBA9908T	GBA9908T			Date of Loss: 26/			26/12/2017 00:00 - :59		
Claim Type	 2:	TP / SNM18	TP / SNM18D00052C02			Policy/Cover Note No.:		DMPCSN3071241700			
Vehicle Re	g. No. (Insured):	SJD7629B	SJD7629B			Policy No. (Claimant):					
			İ	Excess:		S	S\$0.00				
Repairer:		Abwin Service Bukit - Tel: 67	e Pte Ltd (HQ) N 13 9400	No. 8 Kal	ki Bukit Aven	ue 4, #07-	48 Premier	@Kaki Bukit	Gate 2, 41	5875 Kaki	
Handling I	nsurer:	China Taipin	g Insurance (Sin	gapore	) Pte. Ltd. (	HQ) - Tel:	6389 6111	[Handled	by Joel G	oh]	
Adjuster:		due 15/01/2	nsultants Pte Ltd 2018]	- (QH) t	Tel: 6256-3	561 [Ha	ndled by M	ARCUS CHU	JA] [ <b>Fi</b> i	nal Rpt	
Adj Asg. R	emarks:	ESTIMATE AM	OUNT \$4976.14, A	ASSIGN I	MARCUS CHU	JA AS SJE.					
ASSOCIA	TED MAIL REC	EIVED			***************************************			View All	Compo	se Case Mail	
There are	no mail for this ca	ase.			-						
ALL ASS	OCIATED TASK	sE			Vie	ew All   S	earch Task	s Create	New Task	Complete	
					- 10		103K	- 1 -,	,,,,,,,		

No results.

Merimen e-Claims Page 1 of 2

### **Claim Documents**

\*GBA9908T (SNM18D00052C02) [SJD7629B] TP HONG AN ENGINEERING PTE LTD Dec 26 2017 12:00AM [-] Abwin Service Pte Ltd

Pho	tos/Images		3 per page ✓		$\overline{\mathbf{Z}}$
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/01/18 13:31	General View	0	Load JPG	<b>☑</b>
2	17/01/18 13:31	General View	0	Load JPG	<b>7</b>
3	17/01/18 13:31	General View	0	Load JPG	$\overline{\mathbf{v}}$
4	17/01/18 13:31	General View	0	Load JPG	☑
5	17/01/18 13:31	General View	0	Load JPG	☑
6	17/01/18 13:31	General View	0	Load JPG	$\mathbf{Z}$
7	17/01/18 13:31	General View	0	Load JPG	$\overline{\mathbf{Z}}$
8	17/01/18 13:31	General View	0	Load JPG	<b>4</b>
9	17/01/18 13:31	General View	0	Load JPG	<b>☑</b>
10	17/01/18 13:31	General View	0	Load JPG	☑
11	17/01/18 13:31	General View	0	Load JPG	<b>2</b>
12	17/01/18 13:31	General View	0	Load JPG	Ø
13	17/01/18 13:31	General View	0	Load JPG	<b>Z</b>
14	17/01/18 13:31	General View	0	Load JPG	$\mathbf{Z}$
15	17/01/18 13:31	General View	0	Load JPG	<b>☑</b>
16	17/01/18 13:31	General View	0	Load JPG	<b>☑</b>
17	17/01/18 13:31	General View	6	Load JPG	<b>Z</b>
18	17/01/18 13:31	General View	0	Load JPG	<b>☑</b>
19	17/01/18 13:31	General View	0	Load JPG	✓
20	17/01/18 13:31	General View	0	Load JPG	Ø
21	17/01/18 13:31	General View	0	Load JPG	<b>☑</b>
22	17/01/18 13:31	General View	0	Load JPG	☑
23	17/01/18 13:31	General View	0	Load JPG	<b>✓</b>
24	17/01/18 13:31	General View	O	Load JPG	<b>✓</b>
25	17/01/18 13:31	General View	0	Load JPG	<b>√</b>
26	17/01/18 13:31	General View	0	Load JPG	<b>\sqrt</b>
27	17/01/18 13:31	General View	0	Load JPG	<b>\S</b>
28	17/01/18 13:31	General View	0	Load JPG	<b>\S</b>
29	17/01/18 13:31	General View	6	Load JPG	<b>\S</b>
30	17/01/18 13:31	General View	0	Load JPG	<b>\( \)</b>
31	17/01/18 13:31	General View	0	Load JPG	<b>\S</b>
32	17/01/18 13:31	General View	0	Load JPG	5
33	17/01/18 13:31	Chassis Number	0	Load JPG	<b>\( \)</b>
34	17/01/18 13:31	Odometer Reading	0	Load JPG	3
35	17/01/18 13:31	General View	0	Load JPG	<b>₹</b>

Merimen e-Claims Page 2 of 2

36	17/01/18 13:31	General View	0	Load JPG	$\square$
37	17/01/18 13:31	General View	0	Load JPG	<b>3</b>
38	17/01/18 13:31	General View	0	Load JPG	☑
39	17/01/18 13:31	General View	0	Load JPG	V
40	22/01/18 08:08	Reinspection Photo	0	Load JPG	<b>4</b>
41	22/01/18 08:08	Reinspection Photo	0	Load JPG	<b>☑</b>
42	22/01/18 08:08	Reinspection Photo	0	Load JPG	<b>Z</b>
43	22/01/18 08:08	Reinspection Photo	0	Load JPG	<b>2</b>
Doc	umentation		1 pe	r page 🔍	$\mathbf{Z}$
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/01/18 09:57	REPAIR ESTIMATE	•	Load PDF	
2	04/01/18 09:57	TP GIA REPORT	0	Load PDF	
3	04/01/18 09:57	ACCIDENT PHOTO	0	Load JPG	<b>Z</b>

## **Documents Checklist**

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.	***************************************			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
	^			
	<b>~</b>			
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.				

#### LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18000268/UVBE2

Date:

26/01/2018

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN3071241700

Claimant Vehicle

**GBA9908T** No:

**Insured Vehicle** No:

SJD7629B

Nο

Date of Loss:

26/12/2017

Nature of Claim: TP

Claim No:

SNM18D00052C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

**GBA9908T** 

Make & Model:

TOYOTA DYNA 1.5T, 3.0 (M)

Engine No:

Odometer:

1KD1806721

Reg. Date: Colour:

08/05/2008 (Man. Year: 2008) White

Chassis No: JTFAT35Y203001765 381080 km

**Engine Capacity:** 

2982 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size:

195 R15

Rear Tyre Size:

155 R12 (D)

Front Left Side: Front Right Side: Yokohama 6 mm Yokohama 6 mm

Rear Left Side: Rear Right Side: Yokohama 6/6 mm Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,600.60	2,107.12	493.48	18.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,250.00	880.00	41.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,730.60	3,357.12	1,373.48	29.03
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	4,730.60	2,650.00	2,080.60	43.98
+ GST 7.00/7.00% (S\$)	331.14	185.50	145.64	43.98
Nett Amount (S\$)	5,061.74	2,835.50	2,226.24	43.98

INSPECTION

Date of Assignment:

04/01/2018

Date Inspected:

17/01/2018 Inspected At:

Abwin Service Pte Ltd (HQ) No. 8 Kaki Bukit Avenue 4, #07-48

Premier@Kaki Bukit Gate 2

Singapore 415875

Estimated Period of Repair:

4.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

### Reference

Part Source:

(Last Synchronised: 26 Jan 2018)

Parts:

N/A

TOYOTA DYNA 1.5T 3.0 (M) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBA9908T)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT PANEL	Badly Dented	1,109.30 FL	*1,109.30 FL
1		*EMBLEM DYNA	Necessary	64.40 FL	*64.40 FL
1		*FRONT GRILLE	Cracked	475.50 FL	*475.50 FL
1		*FRONT GRILLE LOGO	Necessary	75.60 FL	*75.60 FL
1		*HEADLAMP RH	Not Necessary	611.30 FL	*-FL
1		*HEADLAMP LH	Cracked	611.30 FL	*611.30 FL
1		*FRONT BUMPER	Bent	433.40 FL	*433.40 FL
1		*FRONT NUMBER PLATE	Bent	35.00 FS	*15.00 FS
1		*AIRPORT GREEN STICKER	Necessary	30.00 FS	*15.00 FS
nchise	part. S=SpcNe	tt. L=ListItemDisc.	· –		
			Sub Total (S\$)	3,445.80	2,799.50
		- List Item Discount on L Items 25.00/25.00% (S\$)			692.38
			Total Parts (S\$)_	2,600.60	2,107.12
	1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1	1 *FRONT PANEL 1 *EMBLEM DYNA 1 *FRONT GRILLE 1 *FRONT GRILLE LOGO 1 *HEADLAMP RH 1 *HEADLAMP LH 1 *FRONT BUMPER 1 *FRONT NUMBER PLATE 1 *AIRPORT GREEN STICKER Inchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT PANEL Badly Dented 1 *EMBLEM DYNA Necessary 1 *FRONT GRILLE Cracked 1 *FRONT GRILLE LOGO Necessary 1 *HEADLAMP RH Not Necessary 1 *HEADLAMP LH Cracked 1 *FRONT BUMPER Bent 1 *FRONT NUMBER PLATE Bent 1 *AIRPORT GREEN STICKER Necessary Inchise part. S=SpcNett. L=ListItemDisc.  Sub Total (\$\$) - List Item Discount on L Items 25.00/25.00% (\$\$)	1       *FRONT PANEL       Badly Dented       1,109.30 FL         1       *EMBLEM DYNA       Necessary       64.40 FL         1       *FRONT GRILLE       Cracked       475.50 FL         1       *FRONT GRILLE LOGO       Necessary       75.60 FL         1       *HEADLAMP RH       Not Necessary       611.30 FL         1       *HEADLAMP LH       Cracked       611.30 FL         1       *FRONT BUMPER       Bent       433.40 FL         1       *FRONT NUMBER PLATE       Bent       35.00 FS         1       *AIRPORT GREEN STICKER       Necessary       30.00 FS         Inchise part. S=SpcNett. L=ListItemDisc.       Sub Total (S\$)       3,445.80         - List Item Discount on L Items 25.00/25.00% (S\$)       845.20

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			,
1	LABOUR TO FACILITATE REPAIR	New	1,000.00	600.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	600.00
3	TO RUST PROOF ON AFFECTED AREA	New	80.00	30.00
4	TO INSTALL HEADLAMP AND FOCUS LIGHT	New	50.00	20.00
		Gross Labour Cost (S\$)	2,130.00	1,250.00
	Report was uns	submitted during this print-out.		

< END OF ESTIMATES >