

ASS. REC. BY:

REF:

CS/MSG18000273/Avb⁰²

Special Instruction:

Surveyor

ASSIGNMENT (Office)

merimen

From (Person):

Jasmine Luk

of

MSLH

Date/Time: 04/01/2018 10:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 9319G

Insured:

GFA 524B

at Workshop m/s

Premium

Tel:

6768 9828

of

55 Ubi Road 1

Policy No:

D27814617TMV

Claim No:

543828

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01-01-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI

11-01-2018 @ 2:30pm

H.O.D. Endorsement:

Date/Time:

04/01/2018 11:12am

Person Contacted:

Tony

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 9319G - X

GFA 524B - X

12/1/18

Send preli revised by merimen

14/2/18

final fig \$15,950.60 (Red 11,856.50, 437) confirmed by email

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 1/2 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIN 93196 Yr Regn: 2017 June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1395

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 10354 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222 F40HA1.62287

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60 R16

R: 205 / 60 R16

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.I. <u>11/01/18</u>	

Survey held at: Premium

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>7P MS16.</u>

RECEIVED 28 FEB 2018

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

2) 14/2 - typist

Report Format : merimen

Lump Sum / I.B.I. (\$) 15,950.60

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Weekend (\$)

Survey Fee: 300

Transportation: 10

S + P + SI

Photos

Others

TOTAL

310

Survey Department Check List (Case Handler)

Reference No. : CS / MSG 18000 273 / Avb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURA

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: 9/erun 14 / 2 / 18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18000273/Avb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 04-01-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 524B	Veh. Inspected	SLN 9319G	
Policy No.	D27814617TMV	Coverage (\$)	0.00	
Claim No.	543828	Excess (\$)	0.00	
Assign From	MERIMEN (JASMINE LOK)	Assign Date	04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/01/2018	Inspection Date		
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jan 2018		04 Jan 2018 10:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	POH LEONG TRACTORS PTE LTD, Co. Reg. No.: 197901638N		
Main Claimant:	TAN WEE KIAT, ID: S7040717E		
Vehicle Reg. No.:	SLN9319G	Date of Loss:	01/01/2018 15:00 - :59
Claim Type:	TP / 543828	Policy/Cover Note No.:	D27814617TMV (Third Party Only) Coverage: 22/01/2017 - 21/01/2018
Vehicle Reg. No. (Insured):	GBA524B	Policy No. (Claimant):	
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/01/2018]		
Driver/Custodian (Insured):	TAN CHUR TENG (), NRIC: S1359632H, Tel: +6590222965		
Adj Asg. Remarks:	ON WP		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jasmine Lok Kheng Kwei	Date: 12 Jan 2018

Preliminary Advice

Insured Vehicle No	: GBA524B	Accident Date	: 01/01/2018
TP Vehicle No	: SLN9319G	Assignment Date	: 04/01/2018
Make	: AUDI A4	Est. Duration of Repair	: 5.00
Date of Inspection	: 11/01/2018		
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,785.00
Revised Amount	:S\$	16,032.00
Check Items (Estimated)	:S\$	2,823.00
Total	:S\$	18,855.00
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 14 February 2018 5:17 PM
To: (boojohnny@gmail.com)
Cc: Admin A; SUR; Carrine Leong; Nora Khai
Subject: RE: FINAL REVISION - SLM9319G - TP MSIG - SURVEYED 11 JAN 18

Dear Johnny,

Confirm repair cost of \$15,950.60 before GST @ 5 days of repairs.

Final invoice and all supporting documents sent to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 6 February 2018 7:23 PM
To: assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FW: FINAL REVISION - SLM9319G - TP MSIG - SURVEYED 11 JAN 18

Hi Cath,

Please check.

No ref in our system.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [<mailto:boojohnny@gmail.com>]
Sent: Tuesday, 6 February, 2018 4:48 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION - SLM9319G - TP MSIG - SURVEYED 11 JAN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$15,950.60 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN WEE KIAT
Period of Insurance : 13 Jun 2017 To 12 Jun 2018
Engine No. : CVN038664
Chassis No. : WAUZZZF40HA162287

Vehicle No. : SLN9319G
Policy No. : 1700016362
Endorsement No. : 000000000120470
Issued Date : 29 Jun 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (15 days)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN WEE KIAT - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

59CKSA

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7040717E**

Name
TAN WEE KIAT

Birth Date: **05 Nov 1970**
Issue Date: **08 Jan 2004**

 001080879G

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7040717E**



Name
TAN WEE KIAT

陈伟杰
Race
CHINESE

Date of Birth: **05-11-1970** Sex: **M**

Country of Birth
SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 **Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms**

PASS DATE
08 Nov 1990

 Licence No: S7040717E

NP 428A

 DB47459

NPIC No: **S7040717E**



Blood Group: **O+** Date of issue: **23-03-1993**

Address
**APT BLK 503C CANBERRA LINK #09-37
SINGAPORE 753503**

NPIC No: **S7040717E** Date: **21-11-2001** No: **4087688**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0004/2017/GW
Date : 2-Jan-18

Vehicle not IN workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way

#23-01 SGX Centre 2

Singapore 068896

Attn: Motor Claims Dept

Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Mr. Tan Wee Kiat
Address : Blk 503C Canberra Link
#09-37
Singapore 753503
Telephone : HP 94885530
Type of Claim : Third party Claims
Policy No. : 1700016362
Vehicle No : **SLM 9319 G**
Model Code : Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year : Jun-17
Engine No : CVN 038664
Chassis No : WAUZZZF40HA162287
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Jan-18
Place of Accident : CARPARK AT JUNCT BETWEEN LOR 4 & LOR 5 TOA PAYOH

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 9319 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ ✓
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,100.00	X .
3	To dismantle front bumper, lhs front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise front cash management components. Reinstall all parts removed.	\$ 3,900.00	1500. ✓
4	To respray front bumper, lhs front fender and bonnet.	\$ 2,300.00	1300 ✓
5	To carry out diagnostic check.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 7,852.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9319 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,703.00	✓ 1703
2	FRONT BUMPER SECURING STRIP <i>new</i>	\$ 57.00	+
3	FRONT BUMPER CENTRE GRILLE <i>new</i>	\$ 163.00	+
4	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 171.00	+
5	FRONT BUMPER AIR GUIDE - LH <i>new</i>	\$ 67.00	+
6	RADIATOR GRILLE <i>Cancelled</i>	\$ 941.00	✓ 940.50
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$ 112.00	+
8	FRONT BUMPER FOAM FILLER PIECE <i>Not New</i>	\$ 101.00	? X
9	FRONT BUMPER CARRIER <i>Not New</i>	\$ 674.00	? X
10	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$ 29.00	+
11	FRONT BUMPER TOP COVER <i>new</i>	\$ 104.00	+
12	HOOD RELEASE LEVER <i>new</i>	\$ 12.00	+
13	BOWDEN CABLE <i>new</i>	\$ 49.00	+
14	FRONT BUMPER SUPPORT - LH/RH <i>Not New</i>	2 \$ 46.00	? X
15	FRONT BUMPER LOCK CARRIER BRACKET <i>Not New</i>	\$ 112.00	? X
16	CAUTION SIGN <i>new</i>	\$ 12.00	+
17	A/C STICKER <i>new</i>	\$ 6.00	+
18	FRONT FENDER - LH <i>Not New</i>	\$ 643.00	+
19	FRONT FENDER CLOSING ELEMENT - LH <i>new</i>	\$ 42.00	+
20	FRONT FENDER BRACKET - LH <i>new</i>	\$ 29.00	+
SUB - TOTAL SPARE PARTS		\$ 5,073.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9319 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER INNER BRACKET - LH	\$	42.00 +
22	FRONT FENDER BRACE - LH	\$	100.00 +
23	FRONT FENDER TOP COVER - LH	\$	19.00 +
24	FRONT FENDER LEDGE COVER - LH	\$	24.00 +
25	FRONT WHEEL HOUSING LINER - LH	\$	208.00 +
26	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	76.00 +
27	FRONT WHEEL SPOILER - LH <i>3 new</i>	\$	61.00 +
28	FRONT SONE CHIP GUARD - LH	\$	43.00 +
29	LED HEADLIGHT - LH <i>cut</i>	\$	7,861.00 ✓ 7861
30	LED HEADLIGHT CYLINDER - LH <i>Not new</i>	\$	180.00 ? X
31	LED HEADLIGHT CYLINDER BRACKET - LH <i>Not new</i>	TBC	? X
32	BONNET <i>Dented</i>	\$	2,001.00 ✓ 2001
33	BONNET ATTACHMENT PARTS <i>Not new</i>	\$	103.00 ✓ X
34	BONNET IMPACT PROTECTION <i>new</i>	3 \$	46.00 ✓ 6810
35	BONNET STRIKER - LH/ RH <i>new</i>	\$	86.00 +
36	BONNET LID LOCK <i>new</i>	2 \$	360.00 +
37	LOCK CARRIER <i>Not new</i>	\$	878.00 ? X
38	A/C CONDENSER <i>2 new</i>	\$	525.00 +
39	PRESSURE SENDER <i>1 new</i>	\$	159.00 +
40	HIGH PRESSURE SWITCH	\$	45.00 +
SUB - TOTAL SPARE PARTS		\$	12,817.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9319 G

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
41	RADIATOR { new	\$ 572.00	+
42	RUBBER BUSH	4 \$ 38.00	+
43	ADDITIONAL RADIATOR { new	\$ 444.00	✓
44	COOLANT CONCENTRATE	\$ 132.00	+
45	RADIATOR AIR GUIDE -LH Not New	2 \$ 32.00	? X
46	FRONT NO. PLATE Not Best	S/N \$ 25.00	→ 5
47	SUNDRIES Not Nec	\$ 800.00	? X
TOTAL SPARE PARTS		:	\$ 19,933.00
TOTAL LABOUR CHARGES		:	\$ 7,852.00
GRAND TOTAL		:	\$ 27,785.00

27,807.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adnan

Surveyed Date

: 11/01/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorized 05 Rps

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0004/2017/GW
Date : 2-Jan-18

Vehicle not IN workshop. Kindly arrange for survey.

MSIG Insurance (Singapore) Pte Ltd

No 4 Shenton Way
#23-01 SGX Centre 2
Singapore 068896

Hi Adrian

5 days - ok - jb - 6 Feb 18

Attn: Motor Claims Dept
Tel: 6827 2762 - Fax: 6225 7402

Owner's Name : Mr. Tan Wee Kiat
Address : Blk 503C Canberra Link
#09-37
Singapore 753503
Telephone : HP 94885530
Type of Claim : Third party Claims
Policy No. : 1700016362
Vehicle No : **SLM 9319 G**
Model Code : Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year : Jun-17
Engine No : CVN 038664
Chassis No : WAUZZZF40HA162287
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Jan-18
Place of Accident : CARPARK AT JUNCT BETWEEN LOR 4 & LOR 5 TOA PAYOH

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 9319 G

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,100.00	
3	To dismantle front bumper, lhs front fender and bonnet. Renew front lock carrier and align to position. Renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise front cash management components. Reinstall all parts removed.	\$ 3,900.00	\$ 1,500.00
4	To respray front bumper, lhs front fender and bonnet.	\$ 2,300.00	\$ 1,300.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 7,852.00	\$ 3,352.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9319 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,703.00	\$ 1,703.00
2	FRONT BUMPER SECURING STRIP	\$ 57.00	
3	FRONT BUMPER CENTRE GRILLE	\$ 163.00	
4	FRONT BUMPER CLOSING ELEMENT	\$ 171.00	
5	FRONT BUMPER AIR GUIDE - LH	\$ 67.00	
6	RADIATOR GRILLE	\$ 941.00	\$ 940.50
7	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 112.00	
8	FRONT BUMPER FOAM FILLER PIECE	\$ 101.00	
9	FRONT BUMPER CARRIER	\$ 674.00	
10	FRONT BUMPER GUIDE SECTION - LH	\$ 29.00	
11	FRONT BUMPER TOP COVER	\$ 104.00	
12	HOOD RELEASE LEVER	\$ 12.00	
13	BOWDEN CABLE	\$ 49.00	
14	FRONT BUMPER SUPPORT - LH/RH	2 \$ 46.00	
15	FRONT BUMPER LOCK CARRIER BRACKET	\$ 112.00	
16	CAUTION SIGN	\$ 12.00	
17	A/C STICKER	\$ 6.00	
18	FRONT FENDER - LH	\$ 643.00	
19	FRONT FENDER CLOSING ELEMENT - LH	\$ 42.00	
20	FRONT FENDER BRACKET - LH	\$ 29.00	
SUB - TOTAL SPARE PARTS		\$ 5,073.00	\$ 2,643.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9319 G

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	2,643.50
21	FRONT FENDER INNER BRACKET -LH		\$ 42.00	
22	FRONT FENDER BRACE -LH		\$ 100.00	
23	FRONT FENDER TOP COVER- LH		\$ 19.00	
24	FRONT FENDER LEDGE COVER - LH		\$ 24.00	
25	FRONT WHEEL HOUSING LINER - LH		\$ 208.00	
26	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 76.00	
27	FRONT WHEEL SPOILER- LH		\$ 61.00	
28	FRONT SONE CHIP GUARD - LH		\$ 43.00	
29	LED HEADLIGHT - LH		\$ 7,861.00	\$ 7,861.00
30	LED HEADLIGHT CYLINDER - LH		\$ 180.00	
31	LED HEADLIGHT CYLINDER BRACKET- LH		TBC	
32	BONNET		\$ 2,001.00	\$ 2,001.00
33	BONNET ATTACHMENT PARTS		\$ 103.00	
34	BONNET IMPACT PROTECTION	3	\$ 46.00	\$ 68.10
35	BONNET STRIKER - LH/ RH	2	\$ 86.00	
36	BONNET LID LOCK		\$ 180.00	
37	LOCK CARRIER		\$ 878.00	
38	A/C CONDENSER		\$ 525.00	
39	PRESSURE SENDER		\$ 159.00	
40	HIGH PRESSURE SWITCH		\$ 45.00	
SUB - TOTAL SPARE PARTS			\$ 12,637.00	\$ 12,573.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 9319 G

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f		\$ 12,573.60
41	RADIATOR		\$ 572.00	
42	RUBBER BUSH	4	\$ 38.00	
43	ADDITIONAL RADIATOR		\$ 444.00	
44	COOLANT CONCENTRATE		\$ 132.00	
45	RADIATOR AIR GUIDE -LH	2	\$ 32.00	
46	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
47	SUNDRIES		\$ 800.00	
	TOTAL SPARE PARTS	:	\$ 19,753.00	\$ 12,598.60
	TOTAL LABOUR CHARGES	:	\$ 7,852.00	\$ 3,352.00
	GRAND TOTAL	:	\$ 27,605.00	\$ 15,950.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG1800273/AVBN2

Date: 21/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D27814617TMV
Claimant Vehicle No :	SLN9319G	Insured Vehicle No :	GBA524B
Date of Loss:	01/01/2018	Nature of Claim:	TP
		Claim No:	543828

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN9319G	Engine No:	CVN038664
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF40HA162287
Reg. Date:	13/06/2017 (Man. Year: 2017)	Odometer:	10354 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,955.10	12,598.60	7,356.50	36.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,852.00	3,352.00	4,500.00	57.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	27,807.10	15,950.60	11,856.50	42.64
+ GST 7.00/7.00% (\$\$)	1,946.50	1,116.54	829.96	42.64
Nett Amount (\$\$)	29,753.60	17,067.14	12,686.46	42.64

INSPECTION

Date of Assignment:	04/01/2018	
Date Inspected:	11/01/2018	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2018)
Parts:	143	AUDI A4 1.4 TFSI S TRONIC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN9319G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,703.00 FS	*1,703.00 FS
2	1		*FRONT BUMPER SECURING STRIP	Not Necessary	57.00 FS	*- FS
3	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	163.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	171.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	67.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cracked	941.00 FS	*940.50 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	112.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	101.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	674.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	29.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Not Necessary	104.00 FS	*- FS
12	1		*HOOD RELEASE LEVER	Not Necessary	12.00 FS	*- FS
13	1		*BOWDEN CABLE	Not Necessary	49.00 FS	*- FS
14	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	46.00 FS	*- FS
15	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	112.00 FS	*- FS
16	1		*CAUTION SIGN	Not Necessary	12.00 FS	*- FS
17	1		*A/C STICKER	Not Necessary	6.00 FS	*- FS
18	1		*FRONT FENDER-LH	Not Necessary	643.00 FS	*- FS
19	1		*FRONT FENDER CLOSING ELEMENT-LH	Not Necessary	42.00 FS	*- FS
20	1		*FRONT FENDER BRACKET-LH	Not Necessary	29.00 FS	*- FS
21	1		*FRONT FENDER INNER BRACKET-LH	Not Necessary	42.00 FS	*- FS
22	1		*FRONT FENDER BRACE-LH	Not Necessary	100.00 FS	*- FS
23	1		*FRONT FENDER TOP COVER-LH	Not Necessary	19.00 FS	*- FS
24	1		*FRONT FENDER LEDGE COVER-LH	Not Necessary	24.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	208.00 FS	*- FS
26	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	76.00 FS	*- FS
27	1		*FRONT WHEEL SPOILER-LH	Not Necessary	61.00 FS	*- FS
28	1		*FRONT SONE CHIP GUARD-LH	Not Necessary	43.00 FS	*- FS
29	1		*LED HEADLIGHT-LH	Cut	7,861.00 FS	*7,861.00 FS
30	1		*LED HEADLIGHT CYLINDER-LH	Not Necessary	180.00 FS	*- FS
31	1		*LED HEADLIGHT CYLINDER BRACKET-LH (NPA)	Not Necessary	0.00 FS	*- FS
32	1		*BONNET	Dented	2,001.00 FS	*2,001.00 FS
33	1		*BONNET ATTACHMENT PARTS	Not Necessary	103.00 FS	*- FS
34	3		*BONNET IMPACT PROTECTION	Necessary	68.10 FS	*68.10 FS
35	2		*BONNET STRIKER-LH/RH	Not Necessary	86.00 FS	*- FS
36	2		*BONNET LID LOCK	Not Necessary	360.00 FS	*- FS
37	1		*LOCK CARRIER	Not Necessary	878.00 FS	*- FS
38	1		*A/C CONDENSER	Not Necessary	525.00 FS	*- FS
39	1		*PRESSURE SENDER	Not Necessary	159.00 FS	*- FS
40	1		*HIGH PRESSURE SWITCH	Not Necessary	45.00 FS	*- FS
41	1		*RADIATOR	Not Necessary	572.00 FS	*- FS
42	4		*RUBBER BUSH	Not Necessary	38.00 FS	*- FS
43	1		*ADDITIONAL RADIATOR	Not Necessary	444.00 FS	*- FS
44	1		*COOLANT CONCENTRATE	Not Necessary	132.00 FS	*- FS
45	2		*RADIATOR AIR GUIDE-LH	Not Necessary	32.00 FS	*- FS
46	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
47	1		*SUNDRIES	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,955.10 12,598.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER,RADIATOR,ADDITIONAL RADIATOR,ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,100.00	-
3	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER AND BONNET.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,900.00	1,500.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND BONNET	New	2,300.00	1,300.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,852.00	3,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >