ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	1050HRS	BUS REGISTRATION
ACCIDENT DATE	30-Dec-17	BUS TYPE (SD/DD)
BUS CAPTAIN NAME	ONG TENG PHENG @ ONG PETER	BUS ROUTE NUME
EMPLOYEE NUMBER		BUS ADVERTS (Y/I

BUS REGISTRATION NUMBER	SBS6376C	
BUS TYPE (SD/DD)	SD	
BUS ROUTE NUMBER		
BUS ADVERTS (Y/N)	N	

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

Part No.	Part or Item Description	Quantity	Total Cost
77014042	Mirror - Heated/Electronically Adjustable	1	CRI \$986.36
77014042			
		7% GST	\$69.04
		FINAL TOTAL COST	\$1,055.4

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTA	L COST
TO REPLACE/REPAIR THE DAMAGED PARTS		200	\$300.00
	7% GST		\$21.00
	FINAL TOTAL COST		\$321.00

PAGE 1

ESTIMATED ACCIDENT REPAIR COST



SECTION 5	REPAIRS TO BUS	ADVERTISMENT	VINYLS/PANELS	(ADVERTISEMENT	COST)	
SECTION 5.	KELMING IO DOS	UD A PILLIPITATION				

TOTAL ADVERTISEMENT REPAIR COST

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	5/1/2017
		Date Out From Repairs	6/1/2017
BUS TYPE (SD / DD)	SD	Number of Days Under Repair	1
	LOSS OF USE COST		\$300.00

SUMMARY		
SECTION NO.	COST	
1	\$1,055.40	
2	\$321.00	
3	-	
4	-	
5	\$300.00	
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$1,676.40	

Rosene
H 90010068
Idays
05/01/18@1600
Roy after year

PAGE 2

986.36 200.00 (186.36