

INS. CASE OWNER:

CC4/AXA1800

LKK:  
IDAC:

## ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

5-1-18 @ 9:45 AM, CALLED OI, NO ANSWER.

5-1-18 @ 9:25 AM, OI CALLED BACK, ASK US TO CALL HIS OFFICE (2964289) LOOK FOR DON. (9837 8823). SPOKE W/DON, CONFIRMED ACC DETAILS AWARE INSURANCE WILL SETTLE, AWARE NCD ISSUE.

FOR MANDATE

RECEIVED 16 OCT 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

4,280

Loss of Rental (LOR):

S\$

900

(9

days)

x

100

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

5,187.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

5,187.45

Name 1:

CT AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 16/10/18

REF: AXA

Smart claim

## ASSIGNMENT

From: Date: 05012018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GX 4825B

at Workshop m/s CT Auto

of SM ming

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 813K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 3/18 Vehicle: IN / OUT

Person Contacted:

Veh No: GX 4825B Yr Regn: 06 04

Types: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Liteace cc 2184

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 403782 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: CP42 5009485

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 165R13 X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Delium

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 2/1/18

Survey held at

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 5/1/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/11 File pass to Corbin

L/S \$ 4,000 + GST = \$ 4,280.xx

R(\$ 9,118.45/.697.)

Date/Time: File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee

Date/Time: File Return to?

Transportation

2)

Add Fee:

☐

Site Insp (\$)

) \$ - PS \$

☐

Interview (\$)

) Photos

☐

Tech. Insp (\$)

) Others

☐

Weaving (\$)

Total

Report Format:

Lump Sum / I.B.I: \$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                       |                 |                           |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|-----------------|---------------------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                  |                                                                                       |                 | Ref : CC4/ASM18000277/jb3 |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811                                                                                      |                                                                                       |                 | Date : 04-01-2018         |  |
|                                                                                                                                        |                                                                                       |                 | Code : ASM                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                       |                 |                           |                                                                                     |
| Insured Veh.                                                                                                                           | GBB 8632P                                                                             | Veh. Inspected  | GX 4825B                  |                                                                                     |
| Policy No.                                                                                                                             |                                                                                       | Coverage (\$)   | 0.00                      |                                                                                     |
| Claim No.                                                                                                                              |                                                                                       | Excess (\$)     | 0.00                      |                                                                                     |
| Assign From                                                                                                                            |                                                                                       | Assign Date     | 04/01/2018                |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                       |                 |                           |                                                                                     |
| Make & Model                                                                                                                           |                                                                                       | c.c             | 0                         |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                | Year of Reg.    |                           |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                       | Colour          |                           |                                                                                     |
| Odometer                                                                                                                               | -                                                                                     | Steering        |                           |                                                                                     |
| Brakes                                                                                                                                 |                                                                                       | Modification    |                           |                                                                                     |
| General                                                                                                                                |                                                                                       |                 |                           |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                       |                 |                           |                                                                                     |
|                                                                                                                                        | Size                                                                                  | Make            | Balance                   |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                                       |                 | mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                                       |                 | mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                                       |                 | mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                                       |                 | mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                       |                 |                           |                                                                                     |
|                                                                                                                                        |                                                                                       |                 |                           |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                       |                 |                           |                                                                                     |
| Accident Date                                                                                                                          | 02/01/2018                                                                            | Inspection Date |                           |                                                                                     |
| Survey held at                                                                                                                         | CT AUTO PTE LTD<br>160 SIN MING DRIVE<br>#02-14 SIN MING AUTOCITY<br>SINGAPORE 575722 |                 |                           |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                       |                 |                           |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                       |                 |                           |                                                                                     |

# CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722

Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

## ESTIMATE

Date: 3/1/2018

DOA: 2/1/2018

Vehicle No: GX4825B

Make & Model: Toyota Liteace

| S/N      | Qty | Item Description                       | Parts Price  | Surveyor |
|----------|-----|----------------------------------------|--------------|----------|
| 1        | 1   | Rear Tail Gate                         | \$ 1,197.00  | ✓        |
| 2        | 1   | Rear Tail Gate Outer Moulding          | \$ 118.10    | ✓        |
| 3        | 1   | Rear Tail Gate Outer Opening Mechanism | \$ 118.00    | X        |
| 4        | 2   | Rear Tail Gate Carplate Lamp           | \$ 119.90    | X        |
| 5        | 1   | Rear Tail Gate Lock Mechanism          | \$ 384.40    | ✓        |
| 6        | 1   | Rear Tail Gate Key Lock Mechanism      | \$ 135.30    | ✓        |
| 7        | 1   | Rear Tail Gate Weatherstrip            | \$ 320.70    | 50ln     |
| 8        | 1   | Rear Tail Gate Windscreen Moulding     | \$ 147.30    | ✓        |
| 9        | 1   | Rear Tail Gate Inner Board             | \$ 167.20    | ✓        |
| 10       | 2   | Rear Tail Gate Hydraulic Damper        | \$ 491.00    | X        |
| 11       | 2   | Rear Tail Gate Hinges                  | \$ 145.80    | X        |
| 12       | 1   | Rear End Lower Panel (Inner)           | \$ 581.10    | ✓        |
| 13       | 1   | Rear End Lower Panel (Outer)           | \$ 465.70    | ✓        |
| 14       | 1   | Rear End Lower Panel Top Garnish       | \$ 105.10    | ✓        |
| 15       | 1   | Rear Floor Panel                       | \$ 1,249.70  | X        |
| 16       | 1   | Rear Floor Panel Top Carpet            | \$ 697.10    | X        |
| 17       | 2   | Rear Fender Inner Cover                | \$ 194.80    | X        |
| 18       | 2   | Rear Fender Inner Trim Board           | \$ 334.20    | X        |
| 19       | 2   | Rear Fender Mudflap                    | \$ 236.00    | X        |
| 20       | 2   | Rear Fender Mud Shield                 | \$ 274.20    | X        |
| 21       | 2   | Rear Tail Lamp                         | \$ 854.10    | X        |
| 22       | 2   | Rear Tail Lamp Base Panel              | \$ 594.80    | X        |
| 23       | 1   | Rear Bumper                            | \$ 624.50    | ✓        |
| 24       | 2   | Rear Bumper Retainer                   | \$ 89.90     | ✓        |
| 25       | 2   | Rear Bumper Bracket                    | \$ 92.70     | X        |
| 26       | 2   | Rear Bumper Reflector                  | \$ 145.80    | X        |
| 27       | 1   | Rear Exhaust Assy                      | \$ 684.70    | X        |
| 28       | 2   | Rear Exhaust Mounting                  | \$ 96.80     | X        |
| 29       | 1   | Rear Spare Tyre Bracket                | \$ 238.70    | ✓        |
| Less 25% |     |                                        | \$ 10,904.60 |          |
|          |     |                                        | \$ 2,726.15  |          |
|          |     |                                        | \$ 8,178.45  |          |

### Special Nett Items

|    |       |                                                 |           |      |
|----|-------|-------------------------------------------------|-----------|------|
| 1  |       | Sundries                                        | \$ 50.00  | X    |
| 2  | 1 set | Rear Tail Gate Outer Moulding Clips             | \$ 80.00  | X    |
| 3  | 1 set | Rear Tail Gate Inner Board Clips                | \$ 50.00  | ✓    |
| 4  | 1     | Rear Tail Gate Sticker "70 km/h"                | \$ 80.00  | 15ln |
| 5  | 1     | Rear Tail Gate Windscreen Moulding Sealant      | \$ 120.00 | 40ln |
| 6  | 1     | Rear Tail Gate Windscreen Moulding Damping Seal | \$ 120.00 | 30ln |
| 7  | 1     | Rear End Lower Panel (Inner) Sealant            | \$ 120.00 | 50ln |
| 8  | 1     | Rear End Lower Panel (Outer) Sealant            | \$ 120.00 |      |
| 9  | 1 set | Rear End Lower Panel Top Garnish Clips          | \$ 50.00  | ✓    |
| 10 | 1     | Rear Floor Panel Sealant                        | \$ 120.00 | X    |
| 11 | 1 set | Rear Floor Panel Top Carpet Clips               | \$ 50.00  | X    |
| 12 | 2 set | Rear Fender Inner Trim Board Clips              | \$ 80.00  | X    |
| 13 | 2 set | Rear Fender Mudflap Clips                       | \$ 50.00  | X    |
| 14 | 2 set | Rear Fender Mud Shield Clips                    | \$ 50.00  | X    |



- 15 2 set Rear Tail Lamp Clips  
16 2 Rear Tail Lamp Base Panel Sealant  
17 1 set Rear Bumper Clips  
18 1 Rear No Plate

|             |    |             |   |
|-------------|----|-------------|---|
| 15          | \$ | 50.00       | X |
| 16          | \$ | 80.00       | X |
| 17          | \$ | 50.00       | ✓ |
| 18          | \$ | 80.00       | X |
|             |    | \$ 1,400.00 |   |
| Total parts |    | \$ 9,578.45 |   |

S/N Labour Description

|                                                                                                                                | Amount      | Amount |
|--------------------------------------------------------------------------------------------------------------------------------|-------------|--------|
| 1 Labour for panel beating, cut, weld, straighten and replace rear damaged parts.                                              |             |        |
| 2 To putty and spray painting rear portion.                                                                                    | \$ 1,200.00 | 700    |
| 3 To check rear lighting and wiring.                                                                                           | \$ 1,000.00 | 600    |
| 4 To remove and install rear tail gate lock mechanism.                                                                         | \$ 80.00    | 200    |
| 5 To remove and install inner garnish and trim to facilitate the repair.                                                       | \$ 120.00   | 60     |
| 6 To apply anti rust proofing to rear affected area.                                                                           | \$ 350.00   | 500    |
| 7 To remove and install rear reverse sensor.                                                                                   | \$ 250.00   | 600    |
| 8 To remove and install rear windscreen.                                                                                       | \$ 120.00   | X      |
| 9 To remove and install exhaust muffler and rear exhaust centre pipe                                                           | \$ 120.00   | ✓      |
| 10 To remove & refit tail gate component to replace tail gate, check & re-adjust the close gap and alignment and water seepage | \$ 180.00   | X      |
| Total labour :                                                                                                                 | \$ 120.00   | X      |
|                                                                                                                                | \$ 3,540.00 |        |

Total parts :

Total labour :

Total repair cost : (Before GST)

\$ 9,578.45

\$ 3,540.00

\$ 13,118.45

LKR Auto Consultants hereby notify the Receiver of the following:

- To receive compensation for spray painting
- To replace damaged parts (during recovery)
- Repair prices are subject to consultation
- Third party survey is on a "Without Prejudice" basis
- No time limit for claims is allowed
- Supplementary costs of repair to the damaged part is subject to final approval from insurance Company.

Authorised by Receiver

Signature:

Date:

# CT AUTO PTE LTD

160 Sin Ming Drive, #02-14, Sin Ming AutoCity, Singapore 575722

Tel: 62666727 Fax: 62666358 Email: admin@ctauto.com.sg

Business Registration No. 201420132H

GST Registration No. 201420132H

*Not Authorized  
L1 Reg & ?  
Recovery After Paint  
6 days*

## ESTIMATE

Date: 3/1/2018

DOA: 2/1/2018

Vehicle No: GX4825B

Make & Model: Toyota Liteace

| S/N      | Qty | Item Description                       | Parts Price         | Surveyor |
|----------|-----|----------------------------------------|---------------------|----------|
| 1        | 1   | Rear Tail Gate                         | \$ 1,197.00         | ✓        |
| 2        | 1   | Rear Tail Gate Outer Moulding          | \$ 118.10           | ✓        |
| 3        | 1   | Rear Tail Gate Outer Opening Mechanism | \$ 118.00           | X        |
| 4        | 2   | Rear Tail Gate Carplate Lamp           | \$ 119.90           | X        |
| 5        | 1   | Rear Tail Gate Lock Mechanism          | \$ 384.40           | ✓        |
| 6        | 1   | Rear Tail Gate Key Lock Mechanism      | \$ 135.30           | X        |
| 7        | 1   | Rear Tail Gate Weatherstrip            | \$ 320.70           | ?        |
| 8        | 1   | Rear Tail Gate Windscreen Moulding     | \$ 147.30           | ✓        |
| 9        | 1   | Rear Tail Gate Inner Board             | \$ 167.20           | ?        |
| 10       | 2   | Rear Tail Gate Hydraulic Damper        | \$ 491.00           | X        |
| 11       | 2   | Rear Tail Gate Hinges                  | \$ 145.80           | X        |
| 12       | 1   | Rear End Lower Panel (Inner)           | \$ 581.10           | ✓        |
| 13       | 1   | Rear End Lower Panel (Outer)           | \$ 465.70           | ✓        |
| 14       | 1   | Rear End Lower Panel Top Garnish       | \$ 105.10           | ✓        |
| 15       | 1   | Rear Floor Panel                       | \$ 1,249.70         | X        |
| 16       | 1   | Rear Floor Panel Top Carpet            | \$ 697.10           | ?        |
| 17       | 2   | Rear Fender Inner Cover                | \$ 194.80           | X        |
| 18       | 2   | Rear Fender Inner Trim Board           | \$ 334.20           | X        |
| 19       | 2   | Rear Fender Mudflap                    | \$ 236.00           | X        |
| 20       | 2   | Rear Fender Mud Shield                 | \$ 274.20           | X        |
| 21       | 2   | Rear Tail Lamp                         | \$ 854.10           | X        |
| 22       | 2   | Rear Tail Lamp Base Panel              | \$ 594.80           | X        |
| 23       | 1   | Rear Bumper                            | \$ 624.50           | ✓        |
| 24       | 2   | Rear Bumper Retainer                   | \$ 89.90            | ✓        |
| 25       | 2   | Rear Bumper Bracket                    | \$ 92.70            | ?        |
| 26       | 2   | Rear Bumper Reflector                  | \$ 145.80           | X        |
| 27       | 1   | Rear Exhaust Assy                      | \$ 684.70           | X        |
| 28       | 2   | Rear Exhaust Mounting                  | \$ 96.80            | X        |
| 29       | 1   | Rear Spare Tyre Bracket                | \$ 238.70           | ✓        |
|          |     |                                        | <b>\$ 10,904.60</b> |          |
| Less 25% |     |                                        | <b>\$ 2,726.15</b>  |          |
|          |     |                                        | <b>\$ 8,178.45</b>  |          |

### Special Nett Items

|    |       |                                                 |           |         |
|----|-------|-------------------------------------------------|-----------|---------|
| 1  |       | Sundries                                        | \$ 50.00  | ?       |
| 2  | 1 set | Rear Tail Gate Outer Moulding Clips             | \$ 80.00  | X       |
| 3  | 1 set | Rear Tail Gate Inner Board Clips                | \$ 50.00  | ✓       |
| 4  | 1     | Rear Tail Gate Sticker "70 km/h"                | \$ 80.00  | 15.50   |
| 5  | 1     | Rear Tail Gate Windscreen Moulding Sealant      | \$ 120.00 | 40.50   |
| 6  | 1     | Rear Tail Gate Windscreen Moulding Damping Seal | \$ 120.00 | 30.50   |
| 7  | 1     | Rear End Lower Panel (Inner) Sealant            | \$ 120.00 | } 50.50 |
| 8  | 1     | Rear End Lower Panel (Outer) Sealant            | \$ 120.00 |         |
| 9  | 1 set | Rear End Lower Panel Top Garnish Clips          | \$ 50.00  | ✓       |
| 10 | 1     | Rear Floor Panel Sealant                        | \$ 120.00 | X       |
| 11 | 1 set | Rear Floor Panel Top Carpet Clips               | \$ 50.00  | X       |
| 12 | 2 set | Rear Fender Inner Trim Board Clips              | \$ 80.00  | X       |
| 13 | 2 set | Rear Fender Mudflap Clips                       | \$ 50.00  | X       |
| 14 | 2 set | Rear Fender Mud Shield Clips                    | \$ 50.00  | X       |

|    |       |                                   |    |    |                 |   |
|----|-------|-----------------------------------|----|----|-----------------|---|
| 15 | 2 set | Rear Tail Lamp Clips              | nn | \$ | 50.00           | X |
| 16 | 2     | Rear Tail Lamp Base Panel Sealant | nn | \$ | 80.00           | X |
| 17 | 1 set | Rear Bumper Clips                 | nn | \$ | 50.00           | ✓ |
| 18 | 1     | Rear No Plate                     | nn | \$ | 80.00           | X |
|    |       |                                   |    | \$ | <b>1,400.00</b> |   |

**Total parts \$ 9,578.45**

| S/N | Labour Description                                               | Amount              | Amount |
|-----|------------------------------------------------------------------|---------------------|--------|
|     | Labour for panel beating, cut, weld, straighten and replace rear |                     |        |
| 1   | damaged parts.                                                   | \$ 1,200.00         | 700    |
| 2   | To putty and spray painting rear portion.                        | \$ 1,000.00         | 600    |
| 3   | To check rear lighting and wiring.                               | \$ 80.00            | 200    |
| 4   | To remove and install rear tail gate lock mechanism.             | \$ 120.00           | 600    |
| 5   | To remove and install inner garnish and trim to facilitate the   |                     |        |
| 6   | repair.                                                          | \$ 350.00           | 500    |
| 7   | To apply anti rust proofing to rear affected area.               | \$ 250.00           | 600    |
| 8   | To remove and install rear reverse sensor.                       | nn \$ 120.00        | X      |
| 9   | To remove and install rear windscreen.                           | \$ 120.00           | ✓      |
|     | To remove and install exhaust muffler and rear exhaust centre    |                     |        |
| 10  | pipe                                                             | nn \$ 180.00        | X      |
|     | To remove & refit tail gate componenet to replace tail gate,     |                     |        |
|     | check & re-adjust the close gap and alignment and water          |                     |        |
|     | seepage                                                          | \$ 120.00           | X      |
|     | <b>Total labour :</b>                                            | <b>\$ 3,540.00</b>  |        |
|     | <b>Total parts :</b>                                             | <b>\$ 9,578.45</b>  |        |
|     | <b>Total labour :</b>                                            | <b>\$ 3,540.00</b>  |        |
|     | <b>Total repair cost : (Before GST)</b>                          | <b>\$ 13,118.45</b> |        |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                      |        |              |
|-------------------|----------------------|--------|--------------|
| Vehicle No:       | GBB 8632P (Insd veh) | Model: | TOYOTA       |
|                   | GX 4825B (TP veh)    |        | LITEACE 2.2M |
| Date of Accident: | 02/01/2018           |        |              |

|                       |   |                              |                                        |
|-----------------------|---|------------------------------|----------------------------------------|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate       | : | \$                           | 14,036.74                              |
| Final Repair Cost     | : | \$                           | 4,280.00                               |
| Loss of Use           | : | \$                           | days at \$0.00 per day                 |
| Rental (if any)       | : | \$                           | 900.00 9 days                          |
| LTA / GIA Search Fee  | : | \$                           | 7.45                                   |

|         |   |    |  |
|---------|---|----|--|
| Others: | : | \$ |  |
|---------|---|----|--|

|                      |   |    |          |
|----------------------|---|----|----------|
|                      | : | \$ |          |
| Final Settlement Sum | : | \$ | 5,187.45 |

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                 |   |             |
|----------------------------------------|-----------------|---|-------------|
| 1)                                     | CT AUTO PTE LTD | : | \$ 5,187.45 |

NUR SHAQILAH BTE ABDOL  
WAHAB

22/10/2018  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



## Service Request Details

|                                                                       |                   |          |           |               |
|-----------------------------------------------------------------------|-------------------|----------|-----------|---------------|
| Claim                                                                 | S8M0081Q          |          |           |               |
| Reference                                                             |                   |          |           |               |
| CC4/ASM18000277Kp3s2                                                  | Loss Date         |          |           |               |
| January 2, 2018                                                       | Request Date      |          |           |               |
| January 23, 2018                                                      | Due Date          |          |           |               |
| January 4, 2019                                                       | Vendor Name       |          |           |               |
| LKK AUTO CONSULTANTS PTE LTD (TP)                                     | Type of Loss      |          |           |               |
| Third Party Vehicle Damage                                            | Services          |          |           |               |
| Direct settlement                                                     |                   |          |           |               |
| Actions                                                               |                   |          |           |               |
| Next Step                                                             | Finish the work   |          |           |               |
| Complete Work                                                         | More              |          |           |               |
| Document Type                                                         | Document SubType  |          |           |               |
| Upload Documents                                                      |                   |          |           |               |
| Vehicle Information                                                   |                   |          |           |               |
| Incident Vehicle Registration #                                       | GX4825B           |          |           |               |
| Make                                                                  | Service Address   |          |           |               |
| TPVD                                                                  | Model             |          |           |               |
|                                                                       | 119               |          |           |               |
|                                                                       | GENTING LANE, ... |          |           |               |
|                                                                       | 349570            |          |           |               |
| Primary Contact/Insured                                               |                   |          |           |               |
| HOBEE PRINT PTE LTD                                                   |                   |          |           |               |
| 119 GENTING LANE, 349570, Singapore                                   |                   |          |           |               |
| 67456219                                                              |                   |          |           |               |
| accounts@hobee-media.com                                              |                   |          |           |               |
| Claim Handler                                                         |                   |          |           |               |
| LOH Cynthia                                                           |                   |          |           |               |
| 6568804843                                                            |                   |          |           |               |
| cynthia.loh@axa.com.sg                                                |                   |          |           |               |
| Additional Instructions                                               |                   |          |           |               |
| (1) TP-CT Auto; Non-ARC (2) H2R (3) Please check validity of ID's D/L |                   |          |           |               |
| NAME                                                                  | TYPE              | SUB-TYPE | AUTHOR    | DATE UPLOADED |
| Messages                                                              | Invoices          | History  | Documents |               |
| Assessment                                                            | Metrics           | Notes    |           |               |

SERVICE REQUESTS   MESSAGES   CLAIMS

<< Service Request Details

|                                                                       |                                   |                  |                 |                   |
|-----------------------------------------------------------------------|-----------------------------------|------------------|-----------------|-------------------|
| Claim                                                                 | S8M006IQ                          | Actions          |                 | Add               |
| Reference                                                             | CC4/ASM18000277/Kb3s2             | Next Step        | Finish the work | Complete Work     |
| Loss Date                                                             | January 2, 2018                   | More             |                 |                   |
| Request Date                                                          | January 23, 2018                  |                  |                 |                   |
| Due Date                                                              | January 4, 2019                   |                  |                 |                   |
| Vendor Name                                                           | LKK AUTO CONSULTANTS PTE LTD (TP) |                  |                 |                   |
| Type of Loss                                                          | Third Party Vehicle Damage        |                  |                 |                   |
| Services                                                              | Direct settlement                 |                  |                 |                   |
| Vehicle Information                                                   |                                   |                  |                 |                   |
| Incident Vehicle Registration #                                       | GX4825B                           | Make             | Service Address |                   |
| TPVD                                                                  |                                   | Model            |                 |                   |
|                                                                       |                                   |                  |                 | 119               |
|                                                                       |                                   |                  |                 | GENTING LANE, . . |
|                                                                       |                                   |                  |                 | 349570            |
| Primary Contact/Insured                                               |                                   |                  |                 |                   |
| HOBEE PRINT PTE LTD                                                   |                                   |                  |                 |                   |
| 119 GENTING LANE, 349570, Singapore                                   |                                   |                  |                 |                   |
| 67456219                                                              |                                   |                  |                 |                   |
| accounts@hobeemedia.com                                               |                                   |                  |                 |                   |
| Claim Handler                                                         |                                   |                  |                 |                   |
| LOH Cynthia                                                           |                                   |                  |                 |                   |
| 6568804843                                                            |                                   |                  |                 |                   |
| cynthia.loh@axa.com.sg                                                |                                   |                  |                 |                   |
| Additional Instructions                                               |                                   |                  |                 |                   |
| (1) TP-CT Auto: Non-ARC (2) H2R (3) Please check validity of ID's D/L |                                   |                  |                 |                   |
| CREATED USER                                                          | VERSION DATE                      | ESTIMATED AMOUNT | APPROVED AMOUNT | STATUS            |
|                                                                       |                                   |                  |                 | SHARE             |
|                                                                       |                                   |                  |                 | CLONE             |
| Messages                                                              | Invoices                          | History          | Documents       |                   |
| Assessment                                                            | Metrics                           | Notes            |                 |                   |



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary

### Vehicle & Driver Details

|                       |                                           |                         |                                         |
|-----------------------|-------------------------------------------|-------------------------|-----------------------------------------|
| Vehicle Registration# | GX4825B                                   | Purchase Date           | <input type="text" value="mm/dd/yyyy"/> |
| Registration State    | <input type="text" value="SINGAPORE"/>    | Registration Date *     | <input type="text" value="06/03/2004"/> |
| Mileage               | <input type="text" value="423782"/>       | Age of Vehicle          | 13                                      |
| Driver Details        |                                           |                         |                                         |
| CATEGORY              | POLICY INFORMATION                        | FNOL INFORMATION        | POST SURVEY INFORMATION                 |
| Manufacturing Year    | <input type="text" value="2004"/>         | Driver Name             | <input type="text" value="TBC"/>        |
| Make                  | TPVD                                      | Date of Birth           | <input type="text" value="mm/dd/yyyy"/> |
| Model                 | <input type="text" value="LITEACE 2.2M"/> | Age                     | 0                                       |
| Type                  | <input type="text" value=""/>             | Occupation              | <input type="text" value="Unknown"/>    |
| Type of Paint         | <input type="text" value=""/>             | Education Qualification | <input type="text" value="Other"/>      |
| Chassis No            | <input type="text" value="CR425009485"/>  | Driving Experience      | 0                                       |
| Engine No             | <input type="text" value="3C3995658"/>    | Driver License #        | <input type="text" value=""/>           |
| Engine Capacity       | <input type="text" value="2184 cc"/>      | License Type            | <input type="text" value=""/>           |

Assessment Details

|                                           |                          |                   |                                        |                |               |         |
|-------------------------------------------|--------------------------|-------------------|----------------------------------------|----------------|---------------|---------|
| General & Workshop Details                | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio                          | Parts & Labour | Miscellaneous | Summary |
| Detailed Assessment                       |                          |                   |                                        |                |               |         |
| Inspection Date *                         | 01/05/2018               |                   | Condition of Vehicle at time of survey |                |               |         |
| Total Loss                                | Yes                      | No                | General condition                      | Good           |               |         |
| Towing Charges                            | 0                        |                   | Steering (Serviceable)                 | Yes            | No            |         |
| Voluntary Excess                          | 0                        |                   | Footbrake (Serviceable)                | Yes            | No            |         |
| Compulsory Excess                         | 0                        |                   | Handbrake (Serviceable)                | Yes            | No            |         |
| Young/Inexperienced/Unarmed Driver Excess | 0                        |                   | Engine Modification                    | Yes            | No            |         |
| Other Excess                              |                          |                   | Pre-accident condition                 | Good           |               |         |
| Tyre Condition                            |                          |                   |                                        |                |               |         |
| Age of Tyres                              |                          |                   | Spare wheel                            |                |               |         |
| Front Tyre Size                           | 165 R13X8                |                   | Rear Tyre Size                         | 165 R13X8      |               |         |
| Front left side                           | DELUM 8mm                |                   | Rear left side                         | DELUM 3mm      |               |         |
| Front right side                          | DELUM 8mm                |                   | Rear right side                        | DELUM 3mm      |               |         |

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

| General & Workshop Details |       |           | Vehicle & Driver Details |      | Vehicle Condition                             |             | Taxes & Ratio          |             | Parts & Labour |              | Miscellaneous |           | Summary         |                | Parts  |  |
|----------------------------|-------|-----------|--------------------------|------|-----------------------------------------------|-------------|------------------------|-------------|----------------|--------------|---------------|-----------|-----------------|----------------|--------|--|
| EDIT                       | SR NO | QUAN TITY | MATERIAL                 | SIDE | PART NAME                                     | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE     | DEPR./ BTRR% | DISC OUNT%    | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE |  |
|                            |       | 1         |                          |      | REAR TAIL GATE (DISC 25%)                     |             |                        | Bent        | 897.75         |              | 0             |           | 897.75          | Reviewing      |        |  |
|                            |       | 2         |                          |      | REAR TAIL GATE OUTER MOULDING (DISC 25%)      |             |                        | Damaged     | 88.58          |              | 0             |           | 88.58           | Reviewing      |        |  |
|                            |       | 3         |                          |      | REAR TAIL GATE OUTER OPENING MECHANISM        |             |                        | Serviceable | 0              |              | 0             |           | 0               | Reviewing      |        |  |
|                            |       | 4         |                          |      | REAR TAIL GATE CARPLATE LAMP                  |             |                        | Serviceable | 0              |              | 0             |           | 0               | Reviewing      |        |  |
|                            |       | 5         |                          |      | REAR TAIL GATE LOCK MECHANISM (DISC 25%)      |             |                        | Damaged     | 288.3          |              | 0             |           | 288.3           | Reviewing      |        |  |
|                            |       | 6         |                          |      | REAR TAIL GATE KEY LOCK MECHANISM             |             |                        | Serviceable | 0              |              | 0             |           | 0               | Reviewing      |        |  |
|                            |       | 7         |                          |      | REAR TAIL GATE WINDSCREEN MOULDING (DISC 25%) |             |                        | Necessary   | 110.48         |              | 0             |           | 110.48          | Reviewing      |        |  |
|                            |       | 8         |                          |      | REAR TAIL GATE INNER BOARD (DISC 25%)         |             |                        | Cracked     | 125.4          |              | 0             |           | 125.4           | Reviewing      |        |  |
|                            |       | 9         |                          |      | REAR TAIL GATE HYDRAULIC DAMPER               |             |                        | Serviceable | 0              |              | 0             |           | 0               | Reviewing      |        |  |



| EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                          | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPL/ BTR% | DISC COUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE |
|------|-------|-----------|----------|------|------------------------------------|-------------|------------------------|-------------|------------|------------|-------------|-----------|-----------------|----------------|--------|
|      | 23    | 1         |          |      | REAR BUMPER RETAINER (DISC 25%)    |             |                        | Damaged     | 33.71      |            | 0           |           | 33.71           | Reviewing      |        |
|      | 24    | 2         |          |      | REAR BUMPER BRACKET                |             |                        | Repair      | 0          |            | 0           |           | 0               | Reviewing      |        |
|      | 25    | 2         |          |      | REAR BUMPER REFLECTOR              |             |                        | Serviceable | 0          |            | 0           |           | 0               | Reviewing      |        |
|      | 26    | 1         |          |      | REAR EXHAUST ASSY                  |             |                        | Repair      | 0          |            | 0           |           | 0               | Reviewing      |        |
|      | 27    | 2         |          |      | REAR EXHAUST MOUNTING              |             |                        | Serviceable | 0          |            | 0           |           | 0               | Reviewing      |        |
|      | 28    | 1         |          |      | REAR SPARE TYRE BRACKET (DISC 25%) |             |                        | Damaged     | 179.02     |            | 0           |           | 179.02          | Reviewing      |        |

Labour

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                                                                                                     | LABOUR R & R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE |
|------|-------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------|--------------|---------------|-------|-----------------|---------|--------|
|      | 1     |                         | LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AND REPLACE REAR DAMAGED PARTS,                                               | 700          | 0             | 0     | Reviewing       |         |        |
|      | 2     |                         | TO PUTTY AND SPRAY PAINTING REAR PORTION,                                                                                     | 600          | 0             | 0     | Reviewing       |         |        |
|      | 3     |                         | TO CHECK REAR LIGHTING AND WIRING,                                                                                            | 20           | 0             | 0     | Reviewing       |         |        |
|      | 4     |                         | TO REMOVE AND INSTALL REAR TAIL GATE LOCK MECHANISM. )                                                                        | 60           | 0             | 0     | Reviewing       |         |        |
|      | 5     |                         | TO REMOVE & REFIT TAIL GATE COMPONENT TO REPLACE TAIL GATE, CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE ) | 0            | 0             | 0     | Reviewing       |         |        |
|      | 6     |                         | TO REMOVE AND INSTALL INNER GARNISH AND TRIM TO FACILITATE THE REPAIR,                                                        | 50           | 0             | 0     | Reviewing       |         |        |

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

| EDIT | SR NO | NAME                                            | ACTION    | AMOUNT | COMMENT       | REMOVE |
|------|-------|-------------------------------------------------|-----------|--------|---------------|--------|
|      | 1     | DAYS OF REPAIR                                  | Reviewing |        | 4             |        |
|      | 2     | REAR TAIL GATE WEATHERSTRIP (50%)               | Reviewing | 160.35 | CUT           |        |
|      | 3     | SUNDRIES                                        | Reviewing | 0      | NOT NECESSARY |        |
|      | 4     | SET REAR TAIL GATE OUTER MOULDING CLIPS         | Reviewing | 0      | NOT NECESSARY |        |
|      | 5     | SET REAR TAIL GATE INNER BOARD CLIPS            | Reviewing | 50     | NECESSARY     |        |
|      | 6     | REAR TAIL GATE STICKER "70KM/H"                 | Reviewing | 15     | NECESSARY     |        |
|      | 7     | REAR TAIL GATE WINDSCREEN MOULDING SEALANT      | Reviewing | 40     | NECESSARY     |        |
|      | 8     | REAR TAIL GATE WINDSCREEN MOULDING DAMPING SEAL | Reviewing | 30     | NECESSARY     |        |



SERVICE REQUESTSMESSAGESCLAIMS

<< Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Claim Amount\$5,110.88

Claim Amount\$5,110.88

| CATEGORY      | ESTIMATE   | REVISED AMOUNT |
|---------------|------------|----------------|
| Spare Parts   | \$3,055.53 | \$3,055.53     |
| Labour        | \$1,610.00 | \$1,610.00     |
| Miscellaneous | \$445.35   | \$445.35       |

Submit for Review

SERVICE REQUESTSMESSAGESCLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Scan All

| EDIT                              | SR NO | NAME           | ACTION    | AMOUNT | COMMENT | REMOVE                            |
|-----------------------------------|-------|----------------|-----------|--------|---------|-----------------------------------|
| <div><div></div><div></div></div> | 1     | FINAL LUMP SUM | Reviewing | 4000   |         | <div><div></div><div></div></div> |