

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 24/01/2018
TP Vehicle No. : SKZ-4703-L
To : **AIG ASIA PACIFIC INSURANCE PTE LTD**
Attn : **Motor Claim Department**

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : WELLBUILT PTE LTD
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5078661476-01
Vehicle No. : GBE-8270-J
Make & Model : NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Accident Date: 01/01/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE RH	117 \$1,053.70	
1	RH TAILLAMP 257.60	110 \$356.60	very
1	RH REAR FENDER	1505.80/dec \$1,650.80	
1	RH REAR FENDER ARCH GARNISH	117 \$456.90	X 1155.56
	Sub Total	\$3,518.00	
	Discount 30% on Parts	(\$1,055.40)	
		\$2,462.60	

Nett Item

1	REAR BUMPER 683.20	21 \$740.00	
1	REAR BUMPER RETAINER RH	21 \$35.20	
1	REAR BUMPER RETAINER LH	117 \$35.20	X
	Sub Total	\$810.40	974
	Discount 10% on Parts	(\$81.04)	876.60
		\$729.36	

Special Nett

1	REAR BUMPER REVERSE SENSOR	117 \$360.00	X
	Sub Total	\$360.00	

Labour & Misc

TO PANEL BEAT , REAR FENDER RH, RH TAILGATE	\$1,200.00	800
TO SPRAY PAINT ON AFFECTED AREAS	\$1,100.00	500
Sub Total	\$2,300.00	3332.16
		2668
Sub Total	\$5,851.96	
GST 7%	\$409.64	
Total	\$6,261.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ABWIN SERVICE PTE LTD, 8 KAKI BUKIT AVENUE 4 - GATE 2, #07-48 PREMIER @ KAKI BUKIT, SINGAPORE 415875