

REF:

NG/INC18000282/Svber

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

G8A 1177

Policy No.

5084148064 - 01 20072017

Claims No.

MT/0976168-002

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHB 1235C

Yr Regn:

28/11/2017.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4.

C.C. 1798

Colour

Maroon.

A/C: Insured / Std / NI / NA

Sp. Reading

15702

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4803573855

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

31/12/2017.

D.O.I.

31/1/18

Survey held at

SMRT.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHB 1235C - N/A / INC1507055 / F3

Date: 27/01/18

TAX/12/12/2159

G8A 1177 - X

LKK.

NMC.

&gt;&gt;1/18 Sebastian confirmed \$ 6997.74 (Red 9245.56, 5670)

RECEIVED 3 JAN 2018

Date/Time, File Pass to?



Preli. Report



Final Report

1)

Date/Time, File Return to?

2) 23/1 - typist

Report Format:

Lump Sum / I.B.I. (\$) 6997.74

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

160
39
199

## Survey Department Check List (Case Handler)

Reference No. : **NS/INC/8000282/SVB**  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor** ( ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Vejon 22/11/18  
 Case Handler Date

\*C: Critical \*N: Non-Critical




# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18000282/Svb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 04-01-2018	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBA 117T	Veh. Inspected	SHB 1235C	
Policy No.	5084148064-01	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	31/12/2017	Inspection Date	03/01/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

## Veron Chen (LKKAUTO)

**From:** mtreg <mtreg@income.com.sg>  
**Sent:** Tuesday, 23 January 2018 11:27 AM  
**To:** Veron Chen (LKKAUTO)  
**Subject:** FW: REQUEST FOR CLAIM NUMBER

Hi

All claim created.

With Regards

**Azlin Rani**  
Senior Administrator, Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Tuesday, 23 January, 2018 8:52 AM  
**To:** mtreg  
**Subject:** REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us the claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/0976517-002	SMRT TAXIS PTE LTD	SHC 4628C	YM 8585I
2	MT/0976168-002	SMRT TAXIS PTE LTD	SHB 1235C	GBA 1177

D.O.A	Time of Accident	Estimate	Tentative repair cost
4/1/2018	21:00	\$9,483.30	\$3,550.00
31/12/2017	22:30	\$16,243.30	\$6,997.74

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

eBaoTech

GeneralClaim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5084148064-01	AEROHUB LOGISTICS PTE. LTD.	200410773N	GFT	Third Party, Fire & Theft	GBA117T	GBA117T	20/07/2017	

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	5369K

### Vehicle Details

Vehicle No.:	SHB1235C
Vehicle to be Exported:	No
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS102857
Chassis No.:	JTDKB3FU803573855
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	28 Nov 2017
First Registration Date:	28 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2025

PARF Rebate Amount: \$3,750.00

#### Intended COE Rebate Details

COE Expiry Date: 27 Nov 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$33,596.00

COE Rebate Amount: \$33,164.00

**Total Rebate Amount: \$36,914.00**

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jan 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/01/2018 16:09
Date Of Accident	31/12/2017 22:30
Exact Location Of Accident	SLIP ROAD FROM JURONG TOWNHALL RD TOWARDS AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1235C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	LIM KUI KEE
NRIC No	S0984291H
Date Of Birth	10/08/1944
Occupation	OUTDOOR
Date Of Driving Pass	23/08/1980
Driving Experience	37 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	336 TAH CHING ROAD 02-185
Postcode	610336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS STATIONARY ALONG THE SLIP ROAD FROM JURONG TOWNHALL RD TOWARDS AYE AS I WAS LOOKING OUT FOR THE OMCOMING TRAFFIC. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE GBA117T HAD COLLIDED ONTO THE REAR OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA1117T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ISMAL BIN IDRIS

NRIC/Passport Number	S6924335E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

### SKETCH PLAN

AGE



A- SHB1235C  
B- GBA117T

Jurong Town Hall Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

**Date & Time:**

Reporting Centre Personnel's Signature

**Name:**

NRIC/FIN No.:


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


# SMRT Accident Vehicle Repair Estimates

NTUC

6117

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1235C  
Ref. No : TAX/12/17/2159  
Reg. Date : 28/11/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : LIM KUI KEE  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 31/12/2017 10:30:00 PM  
Accident Reported Date / Time : 02/01/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024093875  
Special Instruction to ARC, if any :  
DROVE IN / GBA1117T  
Prepared Date : 02/01/2018 11:06:13 AM



Sebastian  
31/1/18.

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

  
8/1/18

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKB3FU803573855

Mileage : 0

Work Shop :

Repair Completed Date / Time :

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 2,034.00	0.00
Total Material Charges	: 9,083.28	9,083.28
Other Charges	: 1,300.00	0.00
<b>TOTAL</b>	<b>: 13,600.28</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 7.00	0.00
Prepared / Adjusted By	:	5 days
Arc / Surveyor Sign Off Date	: 02/01/2018 06:11:07 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/01/2018 06:09:43 PM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 1/2/2018 6:11:28 PM

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	<del>0.00</del> 600
<b>Total Labour</b>	<b>1,183.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	<del>0.00</del> 200
TO RESPRAY TAIL GATE	378.00	<del>0.00</del> 200
TO RESPRAY REAR SPOILER	180.00	<del>0.00</del> 100
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	<del>0.00</del> 100
TO RESPRAY FLOOR CORNER PANEL LH	180.00	0.00 ?
TO RESPRAY REAR PANEL	180.00	<del>0.00</del> 100
TO RESPRAY REAR FENDER LH	378.00	0.00 X
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 ?
<b>Total Spray Painting &amp; Panel Beating</b>	<b>2,034.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	<del>0.00</del> 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	<del>0.00</del> 30
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X
TO REMOVE AND REFIT WIRE HARDESS	120.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	<del>0.00</del> 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	<del>0.00</del> 6
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	<del>0.00</del> 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>1,300.00</b>	<b>0.00</b>

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
21594793			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓ CRK	No
24534700			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓ Deform	No
25664790			FILLER, RR BUMPER, LH	1	119.90	25.00	89.92	Replace	Replace R	No
21611600			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓ NEC	No
25764700			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace ✓ NEC	No
25924700			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Replace ?	No
24624700			PAD, RR BUMPER, RH & LH, 1	1	3.80	25.00	2.85	Replace	Replace ?	No
24624700			PAD, RR BUMPER, RH & LH, 2	1	3.80	25.00	2.85	Replace	Replace ?	No
24624700			PAD, RR BUMPER, RH & LH, 3	1	3.80	25.00	2.85	Replace	Replace ?	No
21914700			SEAL, RR BUMPER ARM, RH & LH	1	11.00	25.00	8.25	Replace	Replace ?	No
20234700			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ✓ Bt	No
15914700			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace ✓ Cmt	No
15614711			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace ✓ CRK	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✗	No ?
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ NEC	No
21834700			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Replace ?	No
99973010			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace ?	No
70054740			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace R	No
68014710A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace R	No
54034800			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace ✓ NSC	No
55714700			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace ✗	No
61175010			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace ✗	No
55754701			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.77	Replace	Replace ✗	No
55744700			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	25.00	22.42	Replace	Replace ✗	No
55734710			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	25.00	22.42	Replace	Replace ✗	No



Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace X	No
935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace ✓ JM	No
775047030C0			TAILGATE BOARD ASSY	1	251.50	25.00	188.62	Replace	Replace X	No
7544147030			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	25.00	270.52	Replace	Replace X Reuse	No
943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace ?	No
93214700			TAIL GATE LOCK COVER , BACK DOOR	1	25.30	25.00	18.97	Replace	Replace ?	No
60854796			SPOILER SUB-ASSY, REAR	1	1,322.10	25.00	991.57	Replace	Replace R	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
830747050			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace ✓ DT	No
83114710			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Replace ?	No
83164700			EXTENSION, REAR FLOOR SIDE PANEL , LH	1	76.20	25.00	57.15	Replace	Replace ?	No
83994700			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.72	Replace	Replace ?	No
47184700C0			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Replace ?	No
47164710C0			END PANEL , COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Replace ?	No
84154710C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Replace ?	No
49974700			BOX, DECK FLOOR, LH	1	303.40	25.00	227.55	Replace	Replace ?	No
47404710C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.52	Replace	Replace ?	No
16024710			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	25.00	618.60	Replace	Replace X	No
56384700			LINER, REAR FENDER , LH	1	135.80	25.00	101.85	Replace	Replace X	No
29404700			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	25.00	48.75	Replace	Replace X	No
TOTAL MATERIALS								9,083.37	9,083.28	
TOTAL MATERIALS(Discounted)							9,083.28	9,083.28		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------



# SMRT Accident Vehicle Repair Estimates

3-1-18/14:56

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SHB1235C  
Ref. No : TAX/12/17/2159  
Reg. Date : 28/11/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : LIM KUI KEE  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 31/12/2017 10:30:00 PM  
Accident Reported Date / Time : 02/01/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Sebastian  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024093875

Special Instruction to ARC, if any :

DROVE IN / GBA1117T NTUC P/P

BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)  
& Email : sebastianyeang @lkkauto.com HP:90036121

Prepared Date : 02/01/2018 11:06:13 AM



Recording Camera

Radio Antenna

1st witness

2nd witness

Date

Date

15699  
1 1/4 1/2 3/4

15761KM  
1 1/4 1/2 3/4

Supplementary

to Refer to the Supplementary part 11/1

QC 11/01/18 2.00 p.m.s

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

10/01/2018

Vehicle Return Time:

16:40

SMRT staff sign:

**Section.B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU803573855

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	700.00
Total Spray Painting Charges	: 2,214.00	800.00
Total Material Charges	: 6,747.56	5,057.77
Other Charges	: 1,300.00	440.00
<b>TOTAL</b>	<b>: 11,444.56</b> 16,243.30	<b>6,997.77</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	7.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 02/01/2018 06:11:07 PM	03/01/2018 02:56:37 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/01/2018 06:09:43 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No	: QN-1807-0402	Invoice No	:
Quotation Date	: 1/1	Invoice Date	:
Invoice Amount	: 0.00	Prepared Date	: 1/2/2018 6:11:28 PM

5057.74 /  
700 /  
+ 1240 /  
-----  
6997.74 /

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	700.00 /
<b>Total Labour</b>	<b>1,183.00</b>	<b>700.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY REAR SPOILER	180.00	100.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY FLOOR CORNER PANEL LH	180.00	0.00
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR FENDER LH	378.00	0.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY PANEL SIDE ROOF LH	180.00	100.00 S /
<b>Total Spray Painting &amp; Panel Beating</b>	<b>2,214.00</b>	<b>800.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO REMOVE / REFIT SEAT	120.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	80.00 S /
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	180.00 S /
TO REMOVE AND REFIT WIRE HARDESS	120.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>1,300.00</b>	<b>440.00</b>

16 213.30

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No ✓	OK
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No ✓	Defon
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.93 89.92	Replace	Replace S	No ✓	Defon
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50 15	25.00	11.25	Replace	Replace	No ✓	
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No ✓	NEC
5259247040			SEAL, RR BUMPER, LH	1	85.20	25.00	63.90	Replace	Check	No x	
5246247030			PAD, RR BUMPER, RH & LH, 1	1	3.80	25.00	2.85	Replace	Check	No x	
5246247020			PAD, RR BUMPER, RH & LH, 2	1	3.80	25.00	2.85	Replace	Check	No x	
5246247010			PAD, RR BUMPER, RH & LH, 3	1	3.80	25.00	2.85	Replace	Check	No x	
5219147030			SEAL, RR BUMPER ARM, RH & LH	1	11.00	25.00	8.25	Replace	Check	No x	
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No ✓	BT
8159147010			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	10.00	438.12	Replace	Replace	No ✓	Cut
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Replace	No ✓	OK
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace S	No ✓	DMG
			PIXEL STICKER	2	60.00 120	0.00	120.00	Replace	Replace	No ✓	NIC
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Check	No x	
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Check	No x	NA
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace S	No ✓	BT
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace S	No ✓	Defon
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No ✓	NEC
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.28 22.27	Replace	Replace S	No ✓	NEC
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	0	27.90	25.00	0.00	Replace	Not given	No x	NA
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	25.00	14.78 14.77	Replace	Replace S	No ✓	
7557447040			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	25.00	22.43 22.42	Replace	Replace S	No ✓	
7557347110			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	25.00	22.43 22.42	Replace	Replace S	No ✓	NEC

5087.90

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No	MEC
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace	No	JM
6775047080C0			TAILGATE BOARD ASSY	0	251.50	25.00	0.00	Replace	Not given	No	MM
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No	
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No	NEC
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	0	360.70	25.00	0.00	Replace	Not given	No	
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.68	Replace	Check	No	MM
6932147010			TAIL GATE LOCK COVER , BACK DOOR	1	25.30	25.00	18.98	Replace	Check	No	
7608547916			SPOILER SUB-ASSY, REAR	1	1,322.10	100.00	0.00	Replace	Repair	No	
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	NEC
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No	DT
5831147130			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	25.00	423.60	Replace	Check	No	
5831647010			EXTENSION, REAR FLOOR SIDE PANEL , LH	1	76.20	25.00	57.15	Replace	Check	No	
5839947030			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.73	Replace	Check	No	
6471847080C0			END PANEL , COVER, DECK TRIM SERVICE HOLE	1	47.00	25.00	35.25	Replace	Check	No	
6471647130C0			END PANEL , COVER, DECK TRIM, REAR	1	122.80	25.00	92.10	Replace	Check	No	
5841547110C2			BOARD, REAR FLOOR, NO.1	1	502.20	25.00	376.65	Replace	Check	No	
6499747060			BOX, DECK FLOOR, LH	1	303.40	25.00	227.55	Replace	Check	No	
6474047190C2			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	25.00	258.53	Replace	Replace	No	Def
6160247160			PANEL SUB-ASSY, FENDER REAR LH	0	824.80	25.00	0.00	Replace	Not given	No	
6563847060			LINER, REAR FENDER , LH	0	135.80	25.00	0.00	Replace	Not given	No	
6294047010			DUCT ASSY, QUARTER VENT , RH & LH	0	65.00	25.00	0.00	Replace	Not given	No	MM
TOTAL MATERIALS							6,747.60	5,057.77			
TOTAL MATERIALS(Discounted)							6,747.56	5,057.77			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
-------------	---------	-----------	-----	-----------------	--------------	------------------	-----------	----------------	----------


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

Thatcham *escribe*

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18000282/Svbe2			
73 BRAS BASAH ROAD		Date: 25-01-2018	
#05-01 NTUC TRADE UNION HOUSESINGAPORE		Code: INC4	
189556			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBA 117T	Veh. Inspected	SHB 1235C
Policy No.	5084148064-01	Coverage (\$)	0.00
Claim No.	MT/0976168-002	Excess (\$)	0.00
Assign From		Assign Date	03/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803573855	Colour	MAROON
Odometer	15702	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	31/12/2017	Inspection Date	03/01/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1235C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	COVER,RR BUMPER ASSY (DISC 25%)	CRACKED	423.90	317.92
1	GUARD, RR BUMPER LOWER (DISC 25%)	DEFORMED	558.30	418.72
1	FILLER, RR BUMPER, LH (DISC 25%)	DEFORMED	119.90	89.92
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	RETAINER, RR BUMPER, LH (DISC 25%)	NECESSARY	111.50	83.62
1	REAR BUMPER REINFORCEMENT (DISC 25%)	BENT	318.80	239.10
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR (DISC 25%)	BENT	929.60	697.20
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (DISC 25%)	DEFORMED	891.20	668.40
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.72
1	TAIL GATE MOULDING GLASS, BACK DOOR (DISC 25%)	NECESSARY	29.70	22.27
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR (DISC 25%)	NECESSARY	19.70	14.77
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH (DISC 25%)	NECESSARY	29.90	22.42
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR (DISC 25%)	NECESSARY	29.90	22.42
1	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	NECESSARY	52.30	39.22
1	END PANEL SUB-ASSY, BODY LOWER BACK (DISC 25%)	DENTED	629.80	472.35
1	PANEL ASSY, DECK TRIM SIDE, LH (DISC 25%)	DEFORMED	344.70	258.52
1	LENS & BODY ASSY, RR BUMPER, LH (DISC 10%)	CUT	486.80	438.12
1	LENS & BODY, REAR COMBINATION LAMP , LH (DISC 10%)	CRACKED	438.10	394.29
1	TAIL GATE LOCK ASSY, BACK DOOR (DISC 10%)	JAMMED	452.10	406.89
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEAL, RR BUMPER, LH	NOT NECESSARY	85.20	-

Report Ref No. NS/INC18000282/Svbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PAD, RR BUMPER RH & LH, 1	NOT NECESSARY	3.80	-
1	PAD, RR BUMPER, RH & LH, 2	NOT NECESSARY	3.80	-
1	PAD, RR BUMPER, RH & LH, 3	NOT NECESSARY	3.80	-
1	SEAL, RR BUMPER ARM, RH & LH	NOT NECESSARY	11.00	-
1	WIRE, LUGGAGE ROOM	NOT NECESSARY	143.50	-
1	ANTENNA, ELECTRICAL KEY	NOT NECESSARY	60.30	-
1	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	NOT NECESSARY	27.90	-
1	TAILGATE BOARD ASSY	NOT NECESSARY	251.50	-
1	TAIL GATE WEATHERSTRIP, BACK DOOR	NOT NECESSARY	360.70	-
1	TAIL GATE STRIKER ASSY, BACK DOOR	NOT NECESSARY	24.90	-
1	TAIL GATE LOCK COVER, BACK DOOR	NOT NECESSARY	25.30	-
1	SPARE TYRE PANEL, PAD, REAR FLOOR	NOT NECESSARY	564.80	-
1	EXTENSION, REAR FLOOR SIDE PANEL, LH	NOT NECESSARY	76.20	-
1	COVER, REAR FLOOR UNDER, LH	NOT NECESSARY	234.30	-
1	END PANEL, COVER, DECK TRIM SERVICE HOLE	NOT NECESSARY	47.00	-
1	END PANEL, COVER, DECK TRIM, REAR	NOT NECESSARY	122.80	-
1	BOARD, REAR FLOOR, NO.1	NOT NECESSARY	502.20	-
1	BOX, DECK FLOOR, LH	NOT NECESSARY	303.40	-
1	PANEL SUB-ASSY, FENDER REAR LH	NOT NECESSARY	824.80	-
1	LINER, REAR FENDER, LH	NOT NECESSARY	135.80	-
1	DUCT ASSY, QUARTER VENT, RH & LH	NOT NECESSARY	65.00	-
1	SPOILER SUB-ASSY, REAR	TO REPAIR	1,322.10	-
			11,546.30	5,057.74
	<b>LABOUR</b>			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		2,223.00	1,110.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		2,314.00	830.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			4,697.00	1,940.00
	<b>GRAND TOTAL</b>		<b>16,243.30</b>	<b>6,997.74</b>

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>6,997.74</b>
--	--	--	-----------------

Report Ref No. NS/INC18000282/Svbe2

Report Ref No. NS/INC18000282/Svbe2

**YEANG WAI KEEN**

**Automotive Assessor**

A handwritten signature in black ink, appearing to be "K.K. LAU", written in a cursive, stylized script.

**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**