

Culina

CC 4 / AIG1

800 0287, K uasg

LAA:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

5-1-18

Date / Time:

4-1-18

Registered in NCTA as:

4-1-18

Pre-assign / CCU / FTE

STY 3407



Insured Vehicle No.:

Claim No.:

851379651956

Name of Insured:

Lim Tze Jit

Policy No.:

20046381X

Insured Tel No.:

HP:

97895037

Make / Model:

WVVO XC90

Excess Sec II :S\$

D.O.A.:

2-1-18

Place of Accident:

Upper Serangoon Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

6869725



INSRS:

WSP:

Tel:

Liability:

RMKS:

Gump motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:


LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

6869725-X: STY 3407-X



Based on accident scene photos, OI was within his own lane and TP encroached into OI lane.

RECEIVED 07 MAR 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

9320

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 2/3/18

Sachin

REF: Alb

ASSIGNMENT

From: _____ Date: 05/01/2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 9172S
at Workshop no: Guan motor

of _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.13.1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBC 9172S Yr Regn: 11 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy 1154 C.C. 2882

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 2182 T/Ratio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFH702 P9002 3342

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 195R, 15x8

R: _____

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 2/1/18 D.O.I. 5/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S in

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

8/1 File pass to Corina, EM not ready

\$ 2131.40 (Red: \$ 2824.75 / 57%)

\$ 96.00 check item

Date/Time File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transporter

____ \$ - \$ ____

Phone

Caret

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Insp: \$

☐

Weekend: \$

Report Format: _____

Lump Sum / L.B. / \$

TOTAL




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18000287/Kua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-01-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJY 340T	Veh. Inspected	GBG 9172S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/01/2018	Inspection Date	05/01/2018
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6803

Not Author
1-B-1
Resurvey B4 painting

REPAIR ESTIMATE FOR GBG91725

No.	Qty	List Items	
1	1	Front bumper	\$ B1 489.10 ✓
2	1	Front bumper grille	\$ 128.00 ?
3	1	Front bumper RH cover	\$ 30.00 ✓
4	1	Front bumper RH side retainer	\$ CM 175.00 ✓
5	1	Front bumper inner reinforcement	\$ R 427.00 X
6	1 set	Front bumper clips	\$ R 30.00 ✓
7	1	RH headlamp	\$ 635.10 ✓
8		Air cleaner box	\$ 537.00 X
9	1	Front RH door	\$ R 1,681.00 X
10	1	Front RH step panel top garnish	\$ 156.00 ✓
			\$ 4,288.20
		Less 25%	\$ 1,072.05
		Total :	\$ 3,216.15
<u>Special Nett Items</u>			
11	1	Front RH door company black sticker	\$ 40.00 25% ✓
		Total :	\$ 40.00
<u>Labour</u>			
1		Labour Charges for remove/refit and replace damage part:	\$ 700.00 400 ✓
2		To putty and spray Spray Paintings charges.	\$ 800.00 550 ✓
3		To check wirings and lightings.	\$ 40.00 20 ✓
4		To remove, refit door fittings.	\$ 80.00 X
5		To supply and apply anti rust treatment	\$ 80.00 X
		Total :	\$ 1,700.00
Total Parts and Labour :			\$ 4,956.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

- Pre repair inspection request - GBG9172SVS SJY340T (OI) DOA: 02/01/2018

From: Chan, Yoke Shi
To: Admin A, ASSIGNMENTS@LKKAUTO.COM
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baijit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang
Sent: Thursday, 4 January, 2018 4:43:19 PM
Attachments:  Fax3C28.tif

Hi,

Please refer to the enclosed request from **CK TEO & CO.**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign KENNETH KONG as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

04/01/18 @ 5:46pm
Ah Heng veh in
not

From: Willow Tuang [mailto:wtuang@gmail.com]

Sent: Thursday, January 04, 2018 4:40 PM

To: Chan, Yoke Shi

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJY340T AND GBG9172S ON 02/01/2018

Dear Ms Chan,

Dear Sir,

We refer to your email of even date.

We are agreeable of appointing KENNETH KONG (LKK AUTO) as a Single Joint Expert.

Our client's vehicle is available for pre-repair survey at:

Venue : Guan Motor Works
176 Sin Ming Drive #02-03
Sin Ming AutoCare
Singapore 575721
Tel: 6453 6111 (AH HENG)

Regards

Tuang Willow

CK TEO & CO

Tel: 65354788

On Thu, Jan 4, 2018 at 4:19 PM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:
Without Prejudice

Your Reference : GBG9172S

Our Reference : SJY340T

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd

Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Wednesday, 7 March 2018 11:59 AM
To: 'guanmotorworks@gmail.com'
Subject: ACCIDENT ON 02/01/2018 INVOLVING VEHICLES SJY 340T AND GBG 9172S
Attachments: Accident Photo 3.jpg; Accident Photo 1.jpg; Accident Photo 2.jpg; OI Sketch Plan.pdf

Your Ref: GBG 9172S
Our Ref: CC4/AIG18000287/Kua3

Dear Sir,

ACCIDENT ON 02/01/2018 INVOLVING VEHICLES SJY 340T AND GBG 9172S

We refer to the below matter.

Our insured has reiterated that the accident was caused due to the negligence of your client.

Our insured vehicle was travelling within in his own lane and your client vehicle encroached into our insured lane and collided with our insured vehicle.

Attached herewith our insured's sketch plan for your perusal.

Under such a circumstances, we are denying liability and unable to look into your client's claim, unless you have concrete evidence to prove otherwise.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Thin Thin (LKKAUTO)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Tuesday, 13 February 2018 10:24 AM
To: Thin Thin (LKKAUTO)
Subject: RE: ACCIDENT ON 02/01/2018 INVOLVING VEHICLES SJY 340T AND GBG 9172S

Hi Thin Thin,

please proceed with rejection.

Saliha Syed Yusoff
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1917 | Fax +(65) 68357416

saliha.syed-yusoff@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Thin Thin (LKKAUTO) [mailto:thinthin@lkkauto.com]
Sent: Thursday, February 01, 2018 12:13 PM
To: Syed-Yusoff, Saliha
Subject: ACCIDENT ON 02/01/2018 INVOLVING VEHICLES SJY 340T AND GBG 9172S
Importance: High

Your Ref: 8513796519SG
Our Ref: CC4/AIG18000287/Kua3

Dear Saliha,

ACCIDENT ON 02/01/2018 INVOLVING VEHICLES SJY 340T AND GBG 9172S

We refer to the above matter.

TP reported that he was driving along Jalan Toa Payoh towards Upper Serangoon road. He slow down at the junction of the traffic light, OI suddenly cut into his lane. Please see attached TP's statement.

OI reported that he was filtering left after exiting PIE to get into Upper Serangoon Road. As he was driving in his own lane, TP cut into his lane from left lane and collided onto his vehicle. Please see attached OI's statement

We did call OI to verify the nature of accident. OI disputed on the liability and he mentioned that TP cut into his lane from left and collided onto his vehicle. Base on scene photo provided by OI, our insured vehicle is within the lane and TP vehicle is in between two lane. Based on the circumstances of accident, scenario from both parties, we are of opinion that our insured version is more credible and accurate.

As such, we intend to reject the claim and kindly let us have your instruction / approval please.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jan 2018 Edit Reg		04 Jan 2018 00:00 Edit Adj Rpt	S\$2,131.40 Edit Estimates	S\$2,131.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIM TZE JIAT (LIN ZIJIE) , ID: S80122341								
Main Claimant:	SURE COOL AIRCONDITIONING & ENGINEERING PTE. LTD. , Co. Reg. No.: 201003071M								
Vehicle Reg. No.:	GBG9172S	Date of Loss:	02/01/2018 19:00 - :59						
Claim Type:	TP / 8513796519SG	Policy/Cover Note No.:	2100463817						
Vehicle Reg. No. (Insured):	SJY340T	Policy No. (Claimant):	5096597835						
	Excess:								
Repairer:	Guan Motor Works (HQ) 176 Sin Ming Drive #02-03 Sin Ming Autocare, 575721 Sin Ming - Tel: 64536111								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG91725 (8513796519SG)

[SJY340T]

TP

SURE COOL AIRCONDITIONING & ENGINEERING PTE. LTD.

Jan 2 2018 7:00PM

[LIM TZE JIAT (LIN ZIJIE)]

Guan Motor Works

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser ▼
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	---------------------------------------------------------------------------

Assessment Reports					1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	05/01/18 09:12	Accident Statement <small>From: SC - Reg. No: SJY340T, Claimant: LIM TZE JIAT</small>		Load HTM		

Photos/Images					3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
2	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
3	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
4	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
5	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
6	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
7	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
8	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
9	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
10	01/02/18 12:11	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>	
11	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
12	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
13	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
14	01/02/18 12:11	General View		Load JPG	<input checked="" type="checkbox"/>	
15	01/02/18 12:12	Chassis Number		Load JPG	<input checked="" type="checkbox"/>	

Documentation					1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	04/01/18 19:09	ACKNOWLEDGEMENT EMAIL TO AIG DD 04.01.2018		Load PDF		
2	04/01/18 19:09	EMAIL FROM AIG DD 04.01.2018		Load PDF		
3	04/01/18 19:09	NOTIFICATION FROM WORKSHOP + TP GIA REPORT		Load TIF		
4	09/01/18 10:49	TP ESTIMATE - MARKED		Load PDF		
5	07/03/18 17:33	Instruction from AIG		Load PDF		
6	07/03/18 17:33	Email to TP		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000287/KUA3Q2

Date: 08/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100463817
 Claimant Vehicle No: GBG9172S Insured Vehicle No: SJY340T
 Date of Loss: 02/01/2018 Nature of Claim: TP Claim No: 8513796519SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG9172S
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2750798
 Reg. Date: 30/11/2017 (Man. Year: 2017) Chassis No: JTFHT02P900233421
 Colour: Silver Odometer: 2182 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8
 Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
 Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,256.15	1,161.40	2,094.75	64.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	970.00	730.00	42.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,956.15	2,131.40	2,824.75	56.99
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 04/01/2018
 Date Inspected: 05/01/2018 Inspected At: Guan Motor Works (HQ)
 176 Sin Ming Drive #02-03 Sin Ming
 Autocare
 Singapore 575721
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	489.10 FL	*489.10 FL
2	1		*FRONT BUMPER GRILLE	*Check	128.00 FL	*- FL
3	1		*FRONT BUMPER RH COVER	Distorted	30.00 FL	*30.00 FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Cracked	175.00 FL	*175.00 FL
5	1		*FRONT BUMPER INNER REINFORCEMENT	Repair	427.00 FL	*- FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*RH HEADLAMP	Cut	635.10 FL	*635.10 FL
8	1		*AIR CLEANER BOX	Serviceable	537.00 FL	*- FL
9	1		*FRONT RH DOOR	Repair	1,681.00 FL	*- FL
10	1		*FRONT RH STEP PANEL TOP GARNISH	Mtg Cracked	156.00 FL	*156.00 FL
11	1		*FRONT RH DOOR COMPANY BLACK STICKER	Necessary	40.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,328.20	1,540.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,072.05	378.80
Total Parts (\$\$)	3,256.15	1,161.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES FOR REMOVE/REFIT AND REPLACE DAMAGE PARTS	New	700.00	400.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	800.00	550.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE,REFIT DOOR FITTINGS	New	80.00	0.00
5	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			1,700.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >