

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not in thank
1-B.1
Re Body B4 painting

REPAIR ESTIMATE FOR GBG9172S

No.	Qty	List Items	
1	1	Front bumper	\$ <i>B1</i> 489.10 ✓
2	1	Front bumper grille	\$ 128.00 ?
3	1	Front bumper RH cover	\$ <i>DI</i> 30.00 ✓
4	1	Front bumper RH side retainer	\$ <i>CM</i> 175.00 ✓
5	1	Front bumper inner reinforcement	\$ <i>R</i> 427.00 X
6	1 set	Front bumper clips	\$ <i>RM</i> 30.00 ✓
7	1	RH headlamp	\$ <i>CR</i> 635.10 ✓
8		Air cleaner box	\$ <i>SR</i> 537.00 X
9	1	Front RH door	\$ <i>R</i> 1,681.00 X
10	1	Front RH step panel top garnish	<i>mg</i> \$ <i>CM</i> 156.00 ✓
			\$ 4,288.20
			Less 25% \$ 1,072.05
			Total : \$ 3,216.15
			<u>Special Nett Items</u>
11	1	Front RH door company black sticker	\$ <i>NCC</i> 40.00 <i>255m</i>
			Total : \$ 40.00
			<u>Labour</u>
1		Labour Charges for remove/refit and replace damage part:	\$ 700.00 <i>4001</i>
2		To putty and spray Spray Paintings charges.	\$ 800.00 <i>5501</i>
3		To check wirings and lightings.	\$ 40.00 <i>201</i>
4		To remove, refit door fittings.	\$ <i>NN</i> 80.00 X
5		To supply and apply anti rust treatment	\$ <i>NN</i> 80.00 X
			Total : \$ 1,700.00
			Total Parts and Labour : \$ 4,956.15

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____