

HUI WANG ENTERPRISE PTE LTD

Blk 5 Defu Lane 10 #01-576 Singapore 539186
Telephone: 62864541 Fax: 62810647

Estimate

Name: _____
Address: _____
Policy No: _____

Date: 03/01/2018
Vehicle No: SLJ9481R
Type/Model: HONDA SHUTTLE
Acc.Date: 28/12/2017

QTY	DESCRIPTION	PRICE
	REAR TAILGATE <i>Bedson 1458.20</i>	1,754.80
	REAR LEFT BOOTLID TAIL LAMP <i>11</i>	856.36
	REAR RIGHT BOOTLID TAIL LAMP <i>11</i>	856.36
	REAR TAILGATE CHROME GARNISH	356.44
	REAR TAILGATE 'H' EMBLEM <i>1pc 38</i>	80.00
	REAR TAILGATE 'SHUTTLE' EMBLEM <i>1pc</i>	80.00
	REAR TAILGATE INNER COVER	76.55
	REAR BOOTLID WEATHER STRIP <i>1pc 285.20</i>	354.78
	REAR BOOTLID LOCK SET <i>1pc/5000</i>	344.20
	REAR END PANEL <i>15.1500 600.10</i>	856.80
	REAR END PANEL TOP GARNISH <i>1pc</i>	257.12
	REAR BUMPER <i>DIS</i>	1,027.20
	REAR RIGHT FOGLAMP REFLECTOR <i>11</i>	128.40
	REAR LEFT FOGLAMP COVER <i>11</i>	128.40
	REAR TOW HOOK COVER <i>11</i>	65.80
	REAR SPARE TYRE PANEL <i>11</i>	865.00
		8,088.21
	LESS 20%	6,470.57
	SPECIAL NETT	
	REVERSE CAMERA <i>11</i>	350.00
<i>164</i>	REVERSE SENSOR <i>SHUT</i>	200.00
	LICENCE PLATE AND FRAME <i>Bed</i>	50.00
		600.00
	LABOUR FOR TRANSFERING REAR WINDSCREEN AND SEALANT	150.00
	LABOUR FOR TRANSFERING REAR BOOTLID LOCK MECHANISM	80.00
	LABOUR TO REPLACE / WELD/ REPAIR AFFECTED PANELS	1,200.00
	RUST PROOF	100.00
	SPRAY PAINTING	1,200.00
	WIRING OF LIGHTS, REVERSE CAMERA, REVERSE SENSOR	80.00
		2,810.00
	Total	9,880.57
	Gst 7%	691.64
	Grand Total	10,572.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Ardent
11/11/18
Take up Mr. Bapua part...
5/11/18

120
60
800
60
1100
50