

201/5/043 - (6)

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way # 07- 16
Singapore 079120

Date : 02.01.2018

Motor Claim Dept

Vehicle number : **GBF 3203 G**
Make/Model : **NISSAN NV200**
Date of accident : **27.12.2017**
Claim Type : **TP Claim**

Accident involving GBF 3203 G & GBE 6328 R along PIE to ECP on 27.12.2017.

Re : Supplementary Estimate

1.	1 pc	Rear wiper motor	✓ DMG		\$	555.60
2.	1 pc	Rear door rubber LH	✓	NEC	\$	153.40
3.	1 pc	Rear door rubber RH	✓	NEC.	\$	95.80
4.	1 pc	Rear step garish	✓ CRK.	} Nett	\$	75.00
5.	6 pcs	Rear step clip	✓ NEC		\$	18.00
6.	1 set	Rear reverse sensor	✓	DMG.	\$	280.00 200
7.	1 pc	Rear bumper foam	✓ CRK.		\$	460.80
8.	1 pc	Rear end panel (big)	✓	PT	\$	1,018.30
9.	1 pc	Rear tyre panel	R		\$	1,568.40
Total					\$	4,225.30

Yours Faithfully,

李光華 摩哆燒焊
LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648119
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way # 07- 16
Singapore 079120

KL Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: 02.01.2018

Sebastian 3/1/2018

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.

90036121

sebastianyeang@lktawto.com

Motor Claim Dept

Vehicle number : **GBF 3203 G**
Make/Model : **NISSAN NV200**
Date of accident : **27.12.2017**
Claim Type : **TP Claim**

Accident involving GBF 3203 G & GBE 6328 R along PIE to ECP on 27.12.2017.

Re : Estimate

1.	1 pc	Rear door LH	✓ DT		\$	1,281.10	✓
2.	1 pc	Rear door RH	✓ DT		\$	960.90	✓
3.	1 pc	Rear door glass LH	✓ CRK		\$	920.70	✓
4.	1 pc	Rear door logo	✓ NEC		\$	64.60	✓
5.	1 pc	Rear door lock LH	✓ JM		\$	323.10	✓
6.	1 pc	Rear bumper	✓ DT		\$	650.40	✓
7.	1 pc	Rear bumper reflexor	?	x	\$	57.10	?
8.	2 pcs	Rear door hinge LH	?	x	\$	270.20	?
9.	2 pcs	Rear door hinge RH	?	x	\$	270.20	?
10.	1 pc	Rear door wiper handle	✓ MS		\$	351.50	✓
11.	2 pcs	Rear lamp LH,RH	✗	PK ✓ CRK	\$	514.60	✓
12.	2 pcs	Rear end panel	✓ DT		\$	373.60	✓

					\$	6,038.00	

To Towing Service	\$	120.00	✓	
To Wiring Service	\$	150.00	30	✓
To Sealant & Inner Sponge Tape	\$	50.00	40	✓
To Replace Door Glass Labour Charge	\$	100.00	90	✓
To Replace & Repair Labour Charge	\$	1,400.00	1000	✓ 1200
To Putty & Spray Painting	\$	1,000.00	700	✓

Yours Faithfully, 李光華 廖 哆 燒 焊

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648119
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712