

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way # 07- 16
Singapore 079120

Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 02.01.2018

Motor Claim Dept

Vehicle number : **GBF 3203 G**
Make/Model : **NISSAN NV200**
Date of accident : **27.12.2017**
Claim Type : **TP Claim**

Sebastian 3/1/2018.
- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint.
90036121
sebastianyeang@lktauto-can.

Accident involving GBF 3203 G & GBE 6328 R along PIE to ECP on 27.12.2017.

Re : Estimate

1.	1 pc	Rear door LH	✓DT	} m.	\$	1,281.10
2.	1 pc	Rear door RH	✓DT		\$	960.90
3.	1 pc	Rear door glass LH	✓CRK		\$	920.70
4.	1 pc	Rear door logo	✓NEC		\$	64.60
5.	1 pc	Rear door lock LH	✓J		\$	323.10
6.	1 pc	Rear bumper	✓DT		} Nett	\$
7.	1 pc	Rear bumper reflexor	?	\$		57.10
8.	2 pcs	Rear door hinge LH	?	} m s	\$	270.20
9.	2 pcs	Rear door hinge RH	?		\$	270.20
10.	1 pc	Rear door wiper handle			\$	351.50
11.	2 pcs	Rear lamp LH,RH	×		\$	514.60
12.	2 pcs	Rear end panel	✓DT		\$	373.60

					\$	6,038.00

To Towing Service	\$	120.00	✓
To Wiring Service	\$	150.00	30
To Sealant & Inner Sponge Tape	\$	50.00	40
To Replace Door Glass Labour Charge	\$	100.00	90
To Replace & Repair Labour Charge	\$	1,400.00	1000
To Putty & Spray Painting	\$	1,000.00	700

Total

\$ 8,858.00

Yours Faithfully,

李光華 廖 哆 燒 焊

LEE KUAN HWA MOTOR SERVICE

39, Westwood Avenue, Singapore 648719

TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712