

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Lew Jenny of 401 Date/Time: 4/01/18 @ 4:54pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLA 8361 H Insured: SKM 8697Mat Workshop m/s: 1<sup>st</sup> Autoworks Tel: 829 88933of 23 Kaki Bkt Ave 4 #04-01Policy No: \_\_\_\_\_ Claim No: M11D02781801

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 28/12/2017  
(Client's Record)CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: \_\_\_\_\_Date/Time: 902am @ 5/1/18 Person Contacted: Suhaimi Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 8361 H - X
	SKM 8697 M - cc3 / AIG / 14014670 / Amy3q2 D.O.A: 31/03/2014
	lump sum \$12450 (Red: 15420.58 : 55%)

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLA8361H Yr Regn: 2016 March.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1598Colour: sil/ues A/C: Insured / Std / NI / NASp. Reading: 143192 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MROS3REH104542095Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 08/01/18Survey held at 1st AutoworkDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 401

RECEIVED 19 JAN 2018

Date/Time, File Pass to?

1) 19/1 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$

☐: Prel. Report☒: Final ReportDays Of Repair: 12Resurvey No. of Trip: 1Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech. Insp (\$☐: Weekend (\$

Survey Fee:

Transportation

☐ S - RS - SIPhoto 580Others OSP23/1/18

17x15-255

170+255

50

50

125

650

**Nivitha (LKK Auto)**

---

**From:** LEW JENNY <jennylew@uoi.com.sg>  
**Sent:** Thursday, 4 January, 2018 4:54 PM  
**To:** suhaimi@firstautoworks.com.sg; 'SUR'; 'assignments'  
**Cc:** LEE KATIE  
**Subject:** RE: Accident vehicle between our insured SLA8361H and your insured SKM8697M on 28/12/2017  
**Attachments:** SAS2333445.zip

WITHOUT PREJUDICE

Dear Shiau Chan,

Please arrange to conduct the survey at 1st Autoworks Pte Ltd.

Password for attachment: uoi123

Thank You.

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

**UOB EMAIL DISCLAIMER**

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

**From:** Suhaimi [mailto:[suhaimi@firstautoworks.com.sg](mailto:suhaimi@firstautoworks.com.sg)]  
**Sent:** Thursday, 4 January, 2018 4:53 PM  
**To:** LEW JENNY <jennylew@uoi.com.sg>  
**Cc:** LEE KATIE <katielee@uoi.com.sg>  
**Subject:** RE: Accident vehicle between our insured SLA8361H and your insured SKM8697M on 28/12/2017

Hi Jenny,

We are agreeable to your proposal of appointing LKK auto Consultants as the single joint expert for this accident case.

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

Fax : 6844 5185

---

**From:** "LEW JENNY" <jennylew@uoi.com.sg>

**Sent:** Thursday, 4 January, 2018 4:50 PM

**To:** "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>

**Cc:** "LEE KATIE" <katielee@uoi.com.sg>

**Subject:** RE: Accident vehicle between our insured SLA8361H and your insured SKM8697M on 28/12/2017

WITHOUT PREJUDICE

Dear Ong,

We refer to your email dated 4.1.2018.

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case, we propose to appoint M/s LKK Auto Consultants Pte Ltd.

Please revert to the undersigned within **two (2) working days** whether you have any objections to the appointment of any of our Surveyors, failing which we shall proceed to carry out the survey of your client's vehicle by our appointed Surveyors.

Please forward us a copy of the estimated cost of repair.

We reserve all our rights in this matter.

Warmest Regards

Jenny Lew

Claims Department

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • [jennylew@uoi.com.sg](mailto:jennylew@uoi.com.sg)

**UOB EMAIL DISCLAIMER**

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

**From:** Suhaimi [<mailto:suhaimi@firstautoworks.com.sg>]

**Sent:** Thursday, 4 January, 2018 2:18 PM

**To:** LEE KATIE <katielee@uoi.com.sg>

**Subject:** Accident vehicle between our insured SLA8361H and your insured SKM8697M on 28/12/2017

Dear Sirs,

Re : Surveyors

We are instructed by our client(s) to put you on notice of the accident in which our clients' vehicle was involved in.

We are giving you 2 days notice that our clients' vehicle is in our workshop at this time and would require your appointed surveyor to attend at our workshop to conduct a survey prior to our commencement of repairs of our client(s) vehicle.

We look forward in having a direct settlement and request that the following named surveyor will not be attending to this survey due to finalization/processing of the claims after finalization not done promptly on the above said vehicle.

- 1)
- 2)
- 3)

**Take Notice** : This notification is not an affirmation of your appointed surveyor's report neither does it imply that our client(s) are agreeable to your surveyor's assessment of the quantum for the repairs. For the avoidance of all doubt, we have been instructed by our client(s) that an independent surveyor shall be appointed for the survey of the repairs required to our client(s) vehicle.

Please note that this notification does not in any way prejudice our client(s) rights nor shall it be deemed as a waiver of any of their rights, as such our client(s) rights are expressly reserved.

Thanks & Regards

Suhaimi Ong

Service Executive

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4,

#04-01 (South Wing)

S'pore 415933

Tel : 6844 1985

Fax : 6844 5185



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI18000307/Atd3

3 ANSON ROAD #28-01  
SPRINGLEAF TOWER SINGAPORE 079909

Date : 05-01-2018



Code : UOI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 8697M	Veh. Inspected	SLA 8361H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JENNY (UOI)	Assign Date	05/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	28/12/2017	Inspection Date	05/01/2018
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/01/2018 11:28
Date Of Accident	28/12/2017 18:30
Exact Location Of Accident	NEWTON FLYOVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA8361H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ALPINE CAR RENTAL PTE LTD
Co Reg No	199003483E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65113043
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5093613878
Cover Note Number	

### Driver

Name of Driver	YUEN KOK CHEE THOMAS
NRIC No	S1157344D
Date Of Birth	06/08/1956
Occupation	OUTDOOR
Date Of Driving Pass	29/08/1979
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84811048
Fax Number	
Contact Number	
EMail Address	THOMASANUGUSTUSWILLY@GMAIL.COM

Address 554 BEDOK NORTH ST 3  
 Postcode 460554  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 5  
 Passenger 1  
 NAME: : JAMALUDIN  
 GENDER: : MALE  
 Passenger 2  
 NAME: : JUNAIDAH  
 GENDER: : FEMALE  
 Passenger 3  
 NAME: : TODDLE  
 GENDER: : MALE  
 Passenger 4  
 NAME: : TODDLE 2  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name GEYLANG SERAI NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 111 ALJUNIED CRESCENT #01-102 , POSTCODE: 380111 ,  
 COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-7459999 - FAX NO: 67455673  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

SEE POLICE REPORT ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV478X



Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver CHUA MUI HIA

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKM8697M

Vehicle Make/Model/Colour CHAN KONG FAI

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLF8801D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver SERENE CHAN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name YUEN KOK CHEE THOMAS

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

#### DETAILS OF INJURED PERSON 2

Name JAMALUDIN BIN KASMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

## SKETCH PLAN

### IMPORTANT NOTICE

- 1 - Please report correctly the details of the accident to speed up the claims process.
- 2 - This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 - Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 - The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 - Any false reporting may be referred to the Police for investigation.
- 6 - The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 - By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 - **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:





*K. L. Yuen*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# S KITCH PLAN

Balmoral Rd	Bukit Timah Rd	Charney Lane
1 - 		SLF 8801 D
2 - 		SJV 478 X
3 - 		Myself
4 - 		SKM 8697 M

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The first 3 cars were in stationary position.

Please refer to police report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20171230/2102

Police Station Of Origin:  
Geylang Serai NPP  
111 Aljunied Crescent #01-102 SINGAPORE  
380111  
Tel No: 1800-7459999

2 of 5

Report No. T/20171230/2102

**CONTINUATION OF REPORT**

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	CHAN KONG FAI		ID No.	S7607632D
Related Vehicle	SJV478X (Car)		Contact No.	96715620
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	SERENE CHAN LOO YONG		ID No.	S7202798A
Related Vehicle	SKM8697M (Car)		Contact No.	96811016
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Passenger				
Name	JAMALUDIN BIN KASMAN		ID No.	S0157418C
Related Vehicle	SLA8361H (Car)		Contact No.	93844366
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight



# SINGAPORE POLICE FORCE



T/20171230/2102

3 of 5

Police Station Of Origin:  
Geylang Serai NPP  
111 Aljunied Crescent #01-102 SINGAPORE  
380111  
Tel No: 1800-7459999

Report No. T/20171230/2102

**CONTINUATION OF REPORT**

<b>Passenger</b>			
Name	JUNAIDAH BINTE TARJO	ID No.	S1274884A
Related Vehicle	SLA8361H (Car)	Contact No.	91822627
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	YUEN KOK CHEE THOMAS	ID No.	S1157344D
Related Vehicle	SLA8361H (Car)	Contact No.	84811048
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/12/2017	Date Discharge	28/12/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight
<b>Driver</b>			
Name	CHUA MUI HIA	ID No.	S8716856E
Related Vehicle	SLF8801D (Car)	Contact No.	97733525
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 28 December 2017 at about 6.12pm, I picked up my passengers from ICA Building. I had a total of 4 passengers, two of them are toddlers. I then drove them to their requested destination to Block 489D Choa Chu Kang Ave 5. I then drove along Bukit Timah Road. As I was driving along Bukit Timah Road there was a traffic Jam at Newton Flyover. I then stop my vehicle as traffic had stop. As my vehicle was stationary, on the descending part of Newton flyover, I saw through my rear view mirror that there was a black vehicle coming from the rear of my vehicle. I saw that the said vehicle was not slowing down. The black vehicle then hit onto the rear of my vehicle, causing my vehicle to shift forward and hit onto the vehicle in front of me.

I then checked with my passengers if there were ok. My male passenger suffered a cut on his right eye. I then went out of my vehicle to exchange particulars with the other drivers. There was a total of 4 vehicles



**SINGAPORE  
POLICE FORCE**



T/20171230/2102

4 of 5

Police Station Of Origin:

Geylang Serai NPP

111 Aljunied Crescent #01-102 SINGAPORE

380111

Tel No: 1800-7459999

Report No. T/20171230/2102

**CONTINUATION OF REPORT**

involved in the accident. My vehicle rear bumper and boot were dented badly. The front bumper and bonnet were also dented badly. Only the Honda, which is the first vehicle has a in-car camera.





# SINGAPORE POLICE FORCE



T/20171230/2102

5 of 5

Report No. T/20171230/2102

Police Station Of Origin:

Geylang Serai NPP

111 Aljunied Crescent #01-102 SINGAPORE

380111

Tel No: 1800-7459999

## CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

*US*

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: *US*  
G /  
Sgt 2 MUHAMMAD HIDAYAT BIN ABD WAHAB

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
SI ANG YI TING, STEPHANIE  
Contact No.: 65476414

Authentication Stamp  
NP165 SINGAPORE  
POLICE FORCE

*US*

Signature Of Informant:

*Adi Vun*

Date/Time:  
30/12/2017 17:15

Classification Of Case:



# REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1157344D

Name

YUEN KOK CHEE THOMAS

袁國志

Race

CHINESE

Date of Birth


06-08-1956

Sex

M

Country of Birth

SINGAPORE



NRIC No. S1157344D



Blood Group

A

Date of issue

20-04-1993

APT BLK 554 BEDOK NORTH STREET 3 #06-233

SINGAPORE 460554

NRIC No: S1157344D

Date: 28/01/2013

No: 6959807

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

29 Aug 1979

Class 3

Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg.

Licence No. S1157344D




NP 428A

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S1157344D

Signature

YUEN KOK CHEE THOMAS



Birth Date: 06 Aug 1956

Issue Date: 04 Aug 2004

001269207F



1st Autoworks Pte Ltd  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 8/1/2018

Reference: SLA8361H  
TOYOTA  
COROLLA  
Make: ALTIS

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLA8361H  
CHASSIS NO.: MR053REH104542095  
ENGINE NO.: 1ZR539268

Name of insured : Alpine Car Rental Pte Ltd  
Date of accident.: 28/12/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Bonnet <i>Dented</i>	\$ 1,050.00
2	1	LH Bonnet Hinge <i>3M</i>	\$ 75.00
3	1	RH Bonnet Hinge	\$ 75.00
4	1	Bonnet Lock Mechanism <i>2</i>	\$ 145.00
5	1	RHF Fender <i>Repair</i>	\$ 795.00
6	1	RHF Fender Liner <i>new</i>	\$ 220.00
7	1	LHF Fender <i>Repair</i>	\$ 795.00
8	1	LHF Fender Liner <i>new</i>	\$ 220.00
9	1	Front Bumper <i>Dented</i>	\$ 485.00
10	1	Front Bumper Radiator Grille with Chrome <i>at</i>	\$ 620.00
11	1	Front Bumper Lower Grille <i>reformed</i>	\$ 155.00
12	1	RHF Bumper Bracket <i>new</i>	\$ 75.00
13	1	RHF Bumper Retainer <i>new</i>	\$ 110.00
14	1	LHF Bumper Bracket <i>new</i>	\$ 75.00
15	1	LHF Bumper Retainer <i>new</i>	\$ 110.00
16	1	RHF Headlamp <i>2 changed</i>	\$ 850.00
17	1	LHF Headlamp	\$ 850.00
18	1	RHF Foglamp Cover <i>2</i>	\$ 70.00
19	1	RHF Foglamp <i>1</i>	\$ 355.00
20	1	LHF Foglamp Cover <i>1</i>	\$ 70.00
21	1	LHF Foglamp	\$ 355.00
22	1	Front Bumper Absorber <i>Replaced</i>	\$ 110.00
23	1	Front Bumper Reinforcement Bar <i>Replaced</i>	\$ 395.00
24	1	Front Support Panel Assy <i>Replaced</i>	\$ 985.00

25	1	Condensor <i>guts</i>		\$ 1,475.00	✓
26	1	Radiator <i>Best</i>		\$ 1,790.00	✓
27	1	Radiator Fan Cowling <i>2</i>		\$ 255.00	+
28	1	Radiator Fan Motor <i>1st</i>		\$ 485.00	+
29	1	Radiator Fan Blade <i>1st</i>		\$ 165.00	+
30	1	Bootlid <i>Dented</i>		\$ 755.00	—
31	1	Toyota Emblem <i>2</i>		\$ 60.00	✓
32	1	Lettering Corolla <i>1st</i>		\$ 40.00	—
33	1	Lettering Altis		\$ 40.00	—
34	1	Rear Bootlid Chrome <i>new</i>		\$ 230.70	+
35	1	Number Plate Lamp <i>new</i>		\$ 128.20	+
36	1	LHR Bootlid Lamp <i>1st</i>		\$ 395.00	+
37	1	RHR Bootlid Lamp <i>1st</i>		\$ 395.00	+
38	1	LHR Bootlid Hinge <i>2 Best</i>		\$ 68.00	✓
39	1	RHR Bootlid Hinge <i>1st</i>		\$ 68.00	✓
40	1	Bootlid Inner Trim <i>new</i>		\$ 320.00	+
41	1	Bootlid Latch <i>Dented</i>		\$ 382.50	—
42	1	Bootlid Striker <i>new</i>		\$ 55.00	+
43	1	LHR Fender <i>2 Repair</i>		\$ 1,095.00	+
44	1	RHR Fender <i>1st</i>		\$ 1,095.00	+
45	1	LHR Fender Liner <i>new</i>		\$ 54.00	+
46	1	RHR Fender Liner <i>new</i>		\$ 54.00	+
47	1	LHR Taillamp <i>cracked</i>		\$ 385.00	✓
48	1	RHR Taillamp <i>1st</i>		\$ 385.00	—
49	1	Rear Windscreen <i>new</i>		\$ 611.70	+
50	1	Rear Bumper <i>Dented</i>		\$ 495.00	—
51	1	LHR Bumper Reflector <i>2nd</i>		\$ 58.00	+
52	1	RHR Bumper Reflector <i>1st</i>		\$ 58.00	+
53	1	LHR Bumper Centre Bracket <i>new</i>		\$ 68.00	+
54	1	RHR Bumper Centre Bracket <i>new</i>		\$ 68.00	+
55	1	LHR Bumper Retainer <i>2nd</i>		\$ 120.00	✓
56	1	RHR Bumper Retainer <i>1st</i>		\$ 120.00	✓
57	1	Rear Bumper Reinforcement Bar <i>Best</i>		\$ 395.00	✓
58	1	Rear End Panel <i>Dented</i>		\$ 590.00	✓
59	1	Rear End Panel Trim <i>cracked</i>		\$ 240.00	✓
60	1	LHR Fender Inner Trim <i>2nd</i>		\$ 320.00	✓
61	1	RHR Fender Inner Trim <i>2nd</i>		\$ 320.00	✓
62	1	Rear Spare Tyre Panel Board <i>Dented</i>		\$ 254.00	—
63	1	Rear Spare Tyre Panel <i>Repair</i>		\$ 797.00	+
64	1	Rear Exhaust Pipe <i>Best</i>		\$ 929.00	✓

149515

112362

Parts Total: \$ 24,664.10

Less 25%: \$ 6,166.03

Total : \$ 18,498.08

#### Labour

#### Labour Description

No.

Price (SGD)

### Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 1,400.00	800
2	Carry out spray painting on accident affected area (\$200 per panel)	\$ 1,400.00	600
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 180.00	80
5	To remove and refix radiator and conduct pressure test	\$ 50.00	✓
6	To refocus headlamp	\$ 80.00	+

### Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,000.00	1000
2	Carry out spray painting on accident affected area	\$ 1,600.00	800
3	To conduct anti rust of under carriage tuff coat	\$ 120.00	60
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
5	To remove and refix reverse sensor and conduct test	\$ 80.00	50
6	Conduct chasis alignment of vehicle	\$ 250.00	+
7	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	60
8	To conduct water leakage test after repairs of vehicle	\$ 80.00	+
9	To remove and replace exhaust pipe	\$ 80.00	2
10	To remove and refit rear windscreen due to replacement of rear fender	\$ 150.00	+

3640

Labour Total : \$ 7,610.00

### Others

### Other Description

No.	Qty		Price (SGD)	
<u>Front portion</u>				
1	1	Number plate with casement Bent	\$ 45.00	✓
2	10	Front bumper clip new	\$ 65.00	30
3	10	Bonnet insulator clip new	\$ 65.00	+
4	1	Coolant new	\$ 120.00	50
5	5	Front support panel top garnish clip new	\$ 32.50	+
6	6	Front fender liner clip new	\$ 39.00	+
<u>Rear portion</u>				
1	1	Rear number plate new	\$ 45.00	+
2	10	Bootlid Inner Trim Clips new	\$ 65.00	2
3	10	Rear bumper clip new	\$ 65.00	30
4	6	Rear fender liner clips new	\$ 39.00	+



5	6	Rear end panel trim clip <i>New</i>	\$ 39.00	18
6	1	Rear end panel insulation seal <i>New</i>	\$ 80.00	60
7	1	Rear floor panel insulation seal <i>New</i>	\$ 150.00	+
8	12	Rear fender inner trim clip <i>New</i>	\$ 78.00	4
9	1	Reverse sensor (2pcs) <i>2pcs</i>	\$ 280.00	2w
10	2	Rear exhaust mounting <i>New</i>	\$ 180.00	+
11	1	Rear windscreen sealant <i>New</i>	\$ 120.00	+

A30

Other Total: \$ 1,507.50

GRAND TOTAL: \$ 27,615.58

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

27950.58

Yours faithfully

Suhaimi Ong

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax:6844 5185

Adrian G  
08/01/18

4/s 12 days

Supplementary: 315

total: 15676.62

2/s: 12450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO: SLA 8361H

VEHICLE NO: SLA 8361H

[illegible]

Adrian: Finalisation

**1st Autoworks Pte Ltd**  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**TAX INVOICE**

UNITED OVERSEAS INSURANCE LIMITED  
3 ANSON ROAD, #28-01  
SPRINGLEAF TOWER  
SINGAPORE 079909

GST Ref. No: 20-0000274-Z

Vehicle No: SLA8361H  
Chasis No: MR053REH104542095  
Engine No: 1ZR539268

Invoice No:

Invoice Date:

DESCRIPTION				AMOUNT	SGD
<b>Parts</b>					
No.	Qty.	Description		Price (SGD)	
1	1	Bonnet		\$ 1,050.00	
2	1	Front Bumper		\$ 485.00	
3	1	Front Bumper Radiator		\$ 620.00	
4	1	Front Bumper Lower Grille		\$ 155.00	
5	1	RHF Bumper Retainer		\$ 110.00	
6	1	LHF Bumper Retainer		\$ 110.00	
7	1	RHF Headlamp		\$ 850.00	
8	1	LHF Headlamp		\$ 850.00	
9	1	Front Bumper Absorber		\$ 110.00	
10	1	Front Bumper		\$ 395.00	
11	1	Front Support Panel Assy		\$ 985.00	
12	1	Condensor		\$ 1,475.00	
13	1	Radiator		\$ 1,790.00	
14	1	Bootlid		\$ 755.00	
15	1	Toyota Emblem		\$ 60.00	
16	1	Lettering Corolla		\$ 40.00	
17	1	Lettering Altis		\$ 40.00	
18	1	LHR Bootlid Hinge		\$ 68.00	
19	1	RHR Bootlid Hinge		\$ 68.00	
20	1	Bootlid Latch		\$ 382.50	
21	1	LHR Taillamp		\$ 385.00	
22	1	RHR Taillamp		\$ 385.00	
23	1	Rear Bumper		\$ 495.00	
24	1	LHR Bumper Retainer		\$ 120.00	
25	1	RHR Bumper Retainer		\$ 120.00	
26	1	Rear Bumper		\$ 395.00	

27	1	Rear End Panel		\$	590.00
28	1	Rear End Panel Trim		\$	240.00
29	1	LHR Fender Inner Trim		\$	320.00
30	1	RHR Fender Inner Trim		\$	320.00
31	1	Rear Spare Tyre Panel		\$	254.00
32	1	Rear Exhaust Pipe		\$	929.00

#### **Supplementary Parts**

33	1	Front Brace Panel		\$	130.00
34	1	Frt Radiator Top Support		\$	78.00
35	1	Frt Bumper Under Dust		\$	212.00

Total: \$ 15,371.50  
Less 25%: \$ 3,842.88  
Parts Total : \$ 11,528.63

#### **Labour**

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
<b><u>Front portion</u></b>		
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 800.00
<u>2</u>	Carry out spray painting on accident affected area (\$200 per panel)	\$ 600.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 80.00
<u>5</u>	To remove and refix radiator and conduct pressure test	\$ 50.00
<b><u>Rear portion</u></b>		
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,000.00
<u>2</u>	Carry out spray painting on accident affected area	\$ 800.00
<u>3</u>	To conduct anti rust of under carriage tuff coat	\$ 60.00
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 50.00
<u>6</u>	To conduct transfer of parts from old bootlid to new bootlid	\$ 60.00
<u>7</u>	To remove and replace exhaust pipe	\$ 80.00

Labour Total : \$ 3,640.00

#### **Other**

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
<b><u>Front portion</u></b>		



1	1	Number plate with casement	\$	45.00
2	10	Front bumper clip	\$	30.00
3	1	Coolant	\$	50.00

**Rear portion**

1	10	Rear bumper clip	\$	30.00
2	6	Rear end panel trim clip	\$	15.00
3	1	Rear end panel insulation seal	\$	60.00
4	1	Reverse sensor (2pcs)	\$	200.00

Other Total : \$ 430.00

Total : \$ 15,598.63


Less Lump Sum 20% : \$ 3,119.73

After Lump Sum 20% : \$ 12,450.00

GST (7%) \$ 871.50

**Grand Total: \$ 13,321.50**

Yours Faithfully,

  
Sohaimi Ong

Service Advisor

Tel: 68441985 Fax:68445185

**E & O E**

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

**Please check and finalize with me this invoice**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI18000307/Atd3n2

3 ANSON ROAD #28-01  
SPRINGLEAF TOWER SINGAPORE 079909

Date : 24-01-2018



Code : UOI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 8697M	Veh. Inspected	SLA 8361H
Policy No.		Coverage (\$)	0.00
Claim No.	M11D02781801	Excess (\$)	0.00
Assign From	JENNY	Assign Date	04/01/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104542095	Colour	SILVER
Odometer	143192	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	28/12/2017	Inspection Date	08/01/2018
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 8361H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	DENTED	1,050.00	1,050.00
1	LH BONNET HINGE	NOT NECESSARY	75.00	-
1	RH BONNET HINGE	NOT NECESSARY	75.00	-
1	BONNET LOCK MECHANISM	NOT NECESSARY	145.00	-
1	RHF FENDER	TO REPAIR SEE LABOUR	795.00	-
1	RHF FENDER LINER	NOT NECESSARY	220.00	-
1	LHF FENDER	TO REPAIR SEE LABOUR	795.00	-
1	LHF FENDER LINER	NOT NECESSARY	220.00	-
1	FRONT BUMPER	DEFORMED	485.00	485.00
1	FRONT BUMPER RADIATOR GRILLE WITH CHROME	CUT	620.00	620.00
1	FRONT BUMPER LOWER GRILLE	DEFORMED	155.00	155.00
1	RHF BUMPER BRACKET	NOT NECESSARY	75.00	-
1	RHF BUMPER RETAINER	NECESSARY	110.00	110.00
1	LHF BUMPER BRACKET	NOT NECESSARY	75.00	-
1	LHF BUMPER RETAINER	NECESSARY	110.00	110.00
1	RHF HEADLAMP	CRACKED	850.00	850.00
1	LHF HEADLAMP	CRACKED	850.00	850.00
1	RHF FOGLAMP COVER	NOT NECESSARY	70.00	-
1	RHF FOGLAMP	NOT NECESSARY	355.00	-
1	LHF FOGLAMP COVER	NOT NECESSARY	70.00	-
1	LHF FOGLAMP	NOT NECESSARY	355.00	-
1	FRONT BUMPER ABSORBER	DEFORMED	110.00	110.00
1	FRONT BUMPER REINFORCEMENT BAR	BENT	395.00	395.00
1	FRONT SUPPORT PANEL ASSY	BUCKLED	985.00	985.00
1	CONDENSOR	BENT	1,475.00	1,475.00
1	RADIATOR	BENT	1,790.00	1,790.00
1	RADIATOR FAN COWLING	NOT NECESSARY	255.00	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	485.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	165.00	-
1	BOOTLID	DENTED	755.00	755.00
1	TOYOTA EMBLEM	NECESSARY	60.00	60.00
1	LETTERING COROLLA	NECESSARY	40.00	40.00

Report Ref No. CS/UOI18000307/Atd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LETTERING ALTIS	NECESSARY	40.00	40.00
1	REAR BOOTLID CHROME	NOT NECESSARY	230.70	-
1	NUMBER PLATE LAMP	NOT NECESSARY	128.20	-
1	LHR BOOTLID LAMP	NOT NECESSARY	395.00	-
1	RHR BOOTLID LAMP	NOT NECESSARY	395.00	-
1	LHR BOOTLID HINGE	BENT	68.00	68.00
1	RHR BOOTLID HINGE	BENT	68.00	68.00
1	BOOTLID INNER TRIM	NOT NECESSARY	320.00	-
1	BOOTLID LATCH	DAMAGED	382.50	382.50
1	BOOTLID STRIKER	NOT NECESSARY	55.00	-
1	LHR FENDER	TO REPAIR SEE LABOUR	1,095.00	-
1	RHR FENDER	TO REPAIR SEE LABOUR	1,095.00	-
1	LHR FENDER LINER	NOT NECESSARY	54.00	-
1	RHR FENDER LINER	NOT NECESSARY	54.00	-
1	LHR TAILLAMP	CRACKED	385.00	385.00
1	RHR TAILLAMP	CRACKED	385.00	385.00
1	REAR WINDSCREEN	NOT NECESSARY	611.70	-
1	REAR BUMPER	DISTORTED	495.00	495.00
1	LHR BUMPER REFLECTOR	NOT NECESSARY	58.00	-
1	RHR BUMPER REFLECTOR	NOT NECESSARY	58.00	-
1	LHR BUMPER CENTRE BRACKET	NOT NECESSARY	68.00	-
1	RHR BUMPER CENTRE BRACKET	NOT NECESSARY	68.00	-
1	LHR BUMPER RETAINER	NECESSARY	120.00	120.00
1	RHR BUMPER RETAINER	NECESSARY	120.00	120.00
1	REAR BUMPER REINFORCEMENT BAR	BENT	395.00	395.00
1	REAR END PANEL	DENTED	590.00	590.00
1	REAR END PANEL TRIM	CRACKED	240.00	240.00
1	LHR FENDER INNER TRIM	DEFORMED	320.00	320.00
1	RHR FENDER INNER TRIM	DEFORMED	320.00	320.00
1	REAR SPARE TYRE PANEL BOARD	DEFORMED	254.00	254.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	797.00	-
1	REAR EXHAUST PIPE	BENT	929.00	929.00
1	FRT BRACE PANEL (ADDITIONAL)	BENT	130.00	130.00
1	FRT RADIATOR TOP SUPPORT (ADDITIONAL)	CRACKED	78.00	78.00

Report Ref No. CS/UOI18000307/Atd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRT BUMPER UNDER DUST COVER (ADDITIONAL)	CRACKED	212.00	212.00
	LESS 25% DISCOUNT		-6,271.02	-3,842.88
			18,813.08	11,528.62
	<b><u>SPECIAL NETT ITEMS</u></b>			
6	REAR END PANEL TRIM CLIP (SN)	NECESSARY	39.00	15.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	80.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
12	REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	78.00	-
1	REVERSE SENSOR (2 PCS)(SN)	DAMAGED	280.00	200.00
2	REAR EXHAUST MOUNTING (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
1	NUMBER PLATE WITH CASEMENT (SN)	BENT	45.00	45.00
10	FRONT BUMPER CLIP (SN)	NECESSARY	65.00	30.00
10	BONNET INSULATOR CLIP (SN)	NOT NECESSARY	65.00	-
1	COOLANT (SN)	NECESSARY	120.00	50.00
5	FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	32.50	-
6	FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	39.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
10	BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	65.00	-
10	REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
6	FRONT FENDER LINER CLIPS (SN)	NOT NECESSARY	39.00	-
			1,507.50	430.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF RHF FENDER AND LHF FENDER.		1,400.00	800.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,400.00	600.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REMOVE AND REFIT AIRCON CONDENSOR,VACUUM,REFILL AND CHECK AIR CON GAS SYSTEM.		180.00	80.00
	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		50.00	50.00
	TO REFOCUS HEADLAMP.	NOT NECESSARY	80.00	-

Report Ref No. CS/UOI18000307/Atd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF LHR FENDER,RHR FENDER AND REAR SPARE TYRE PANEL.		2,000.00	1,000.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,600.00	800.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		120.00	60.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	50.00
	CONDUCT CHASSIS ALIGNMENT OF VEHICLE.	NOT NECESSARY	250.00	-
	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID.		80.00	60.00
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REPLACE EXHAUST PIPE.		80.00	80.00
	TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER.	NOT NECESSARY	150.00	-
			7,610.00	3,640.00
GRAND TOTAL			27,930.58	15,598.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,450.00

Report Ref No. CS/UOI18000307/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.