

Surveyor

ASSIGNMENT (Office)

From (Person): Yee Pei Li of EGI Date/Time: 3:20pm @ 4/1/2018

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKZ 878S Insured: SJN 2546 Lat Workshop m/s Autolution Industrial Tel: 98450079of 19 ubi Road 4Policy No: _____ Claim No: DSMPCR1703/00/SE/p/

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/12/2017
(Client's Record) 08/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement: _____

Date/Time: 9:07am @ 5/1/18 Person Contacted: Hamzah Vehicle-IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 878S - x
	SJN 2546 L - cc4/AXA/2017471/GvJc3 D.O.A: 11/07/2012
16/1/18	Email preli revised to ERGO
7/3/18	Final fig \$1457.84 confirmed by email (Real 1751.52, 549)

REF: EGI

ASSIGNMENT

From: Date: 15/01/2018

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SK2 8785

at Workshop m/s: Autolution

of 19 ubi Road 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

12.30pm @ owner waiting

Make of Veh:

Hamzah

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SK2878S- Yr Regn: 2015 Dec.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Qashqai cc: 1197

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 40710 T/Radio Insured / Std / NI / NA

Eng/No:

C/No: SINPEASJ111540672

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: 215/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 15/01/18

Survey held at: Tan Chong Cubi

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 MAR 2018

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation:

S + P + B:

Photo:

Other:

Date/Time: File Return to?

1/ 7/3 - typist

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: \$ 1457.84

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18000311/Avd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 05-01-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 2546L	Veh. Inspected	SKZ 878S
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPVCV1703100/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	05/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/12/2017	Inspection Date
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: DSMPCV1703100/SE/pl
Our ref: CS/EGII8000311/Avd3

Date : 16/1/2018

The Motor Claims Department
M/s: ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKZ 878S


We thank you for your instruction on 4/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/1/2018 at the premises of M/s AUTOLUTION IND PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,209.36
Revised Estimate Amount	: S\$1,457.84
"Check" Items Amount	: S\$1,048.08
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B,Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No.: CS EGI 1800 311 Avc3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 7/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 16 January 2018 9:54 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SJN2546L / TP : SKZ878S/LKK / DOA : 26/12/2017 (DSMPCV1703100)
Attachments: SKZ 878S PRELI REVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKZ 878S
Date of survey: 15/1/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 5 January 2018 9:14 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJN2546L / TP : SKZ878S/LKK / DOA : 26/12/2017 (DSMPCV1703100)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 08/01/2017.

"Wishes you a Happy New Year 2018"

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 4 January, 2018 3:20 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SJN2546L / TP : SKZ878S/LKK / DOA : 26/12/2017 (DSMPCV1703100)

Dear Ashley,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **AUTOLUTION INDUSTRIAL PTE LTD**.

ADDRESS : 19 UBI ROAD 4
SINGAPORE 408623

PERSON TO CONTACT : HAMZAH SA'AD @ 6703 8690 / 9645 0079

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 4 January, 2018 3:20 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SJN2546L / TP : SKZ878S/LKK / DOA : 26/12/2017 (DSMPCV1703100)
Attachments: SJN2546L- SAS.pdf; SKZ878S - SAS.pdf; SKZ878S - PRS FORM.pdf

Dear Ashley,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **AUTOLUTION INDUSTRIAL PTE LTD**,

ADDRESS : 19 UBI ROAD 4
SINGAPORE 408623

PERSON TO CONTACT : HAMZAH SA'AD @ 6703 8690 / 9645 0079

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 04.01.2018
Our Reference: DSMPC1703100/SE/pl
Your Reference: SKZ 8785

Sent via Fax

or

Email

hamzah_saad@tanchong.com

To: AUTOLUTION INDUSTRIAL PTE. LTD.

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKZ 8785
Insured's Vehicle: SJN 2546L
Date Of Accident: 26.12.2017


We acknowledge receipt of your request for PRS on: 03.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto Consultants Pte. Ltd.

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd ✓
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☒	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0758/17
DATE : 28-DEC-2017

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : GOH CHEE YEW
ADDRESS : BLK 259C PUNGGOL FIELD
#14-51
S(823259)
TELEPHONE NO : 90046176

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SKZ878S
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2213062A
CHASSIS NO : SJNFEAJ11U1540672
MILEAGE : 39433 KM
DATE IN : 28/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH
ACCIDENT DATE : 26/12/2017

- 96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKZB7B5

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR REAR PANEL AND RENEW REAR BUMPER.	650.00 390	✓
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00 250	✓
3	ZZ/003	REMOVE AND INSTALL REVERSE SENSOR.	110.00	✓ ✓
TOTAL LABOUR CHARGES			1360.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SK28785

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	S/NETT REMARKS
1	SUNDRIES <i>Not New</i>	NPN		100.00 + 20 ✓
2	SENSOR-REVERSE <i>Not New</i>	SENSOR		250.00 ? X
3	REAR BUMPER STAY LH <i>Not New</i>	H5211-4EAMA	126.00	? X
4	REAR BUMPER STAY RH <i>Not New</i>	H5210-4EAMA	126.00	? X
5	REAR BUMPER REINFORCEMENT <i>Not New</i>	H5030-4EAMA	619.20	? X
6	ENERGY ABSORBER REAR BUMPER <i>Not New</i>	B5090-4EA08	126.40	? X
7	REAR BUMPER CLIP @ \$23.00 EACH <i>Not New</i>	791B4-4EADA	142.80	✓ ✓
8	REAR BUMPER TOW HOOK COVER <i>Not New</i>	B5071-4EADA	16.80	X
9	REAR BUMPER FASCIA <i>Deformed</i>	B5022-4EA0H	717.00	✓ ✓
SUB TOTAL			1874.20	0.00 350.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			374.84	0.00 0.00
GRAND TOTAL			1499.36	0.00 350.00
OVERALL TOTAL			1849.36	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SK28785

TOTAL LABOUR CHARGES	1360.00
TOTAL SPARE PARTS CHARGES	1849.36
GRAND TOTAL	3209.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Adrian Wang T/P
15/01/18
030hrs.

96893735.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 March 2018 8:06 AM
To: 'Hamzah Saad / TCMS'; Adrian Ling (LKKAUTO)
Cc: Admin A; Admin-D (LKKAUTO)
Subject: RE: SKZ878S - for survey

Dear Hamzah,

Confirmed final amount \$1457.84 before GST

No of days: 3 days

Final invoice and all supporting documents sent to ERGO

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hamzah Saad / TCMS [mailto:hamzah_saad@tanchong.com]
Sent: Tuesday, 6 March 2018 11:44 AM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: Fwd: SKZ878S - for survey

Dear Adrian,

Attachment final repair copy.

Kindly revert for invoicing.

Regards

----- Forwarded message -----

From: Hamzah Saad / TCMS <hamzah_saad@tanchong.com>
Date: Thu, Jan 4, 2018 at 1:09 PM
Subject: SKZ878S - for survey
To: "ERGO Insurance Pte. Ltd. (Claims Department)" <claims@ergo.com.sg>

Hi,

Pls refer to the attachment and arrange LKK to survey.

Regards

--
Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S(408623)
Tel: +65 6490 9666 DID: +65 6703 8690 Fax: +65 6846 7483
H/P: +65 9645 0079
Email: hamzah_saad@tanchong.com
Website: www.tanchong.com www.nissan.com.sg

--
Hamzah Sa'ad
Service Supervisor
Autolution Industrial Pte Ltd
19 Ubi Road 4
S(408623)
Tel: +65 6490 9666 DID: +65 6703 8690 Fax: +65 6846 7483
H/P: +65 9645 0079
Email: hamzah_saad@tanchong.com
Website: www.tanchong.com www.nissan.com.sg

Adrian LKK

AUTOLUTION INDUSTRIAL PTE. LTD.

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0756/17
DATE : 28-DEC-2017

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

3 days.

OWNER'S NAME : GOH CHEE YEW
ADDRESS : BLK 259C PUNGGOL FIELD
#14-51
S(823259)
TELEPHONE NO : 90046176

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SKZ8785
MODEL CODE : FRLAR8ZJ11UEA--A--
MODEL/YEAR : NISSAN DASHDAI 1.2
ENGINE NO : HRA2213062A
CHASSIS NO : SJNFEAJ11U1540672
MILEAGE : 39433 KM
DATE IN : 28/12/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HANIZAH
ACCIDENT DATE : 26/12/2017

- 96450079

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SK2876S

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR REAR PANEL AND RENEW REAR BUMPER.	650.00	390.00
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	250.00
3 ZZ/003	REMOVE AND INSTALL REVERSE SENSOR.	110.00	110.00
	TOTAL LABOUR CHARGES	1360.00	750.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SK28785

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			20.00 OK
2	SENSOR-REVERSE	SENSOR			250.00 X
3	REAR BUMPER STAY LH	H5211-4EAMA	126.00		X
4	REAR BUMPER STAY RH	H5210-4EAMA	126.00		X
5	REAR BUMPER REINFORCEMENT	H5030-4EAMA	619.20		X
6	ENERGY ABSORBER REAR BUMPER	B5090-4EAOB	126.40		X
7	REAR BUMPER CLIP @ \$23.80 EACH	75164-4EADA	142.80		OK
8	REAR BUMPER TOW HOOK COVER	B5071-4EADA	16.80		X
9	REAR BUMPER FASCIA	B5022-4EAOH	717.00		OK
SUB TOTAL			859.80	0.00	20.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			171.96	0.00	0.00
GRAND TOTAL			687.84	0.00	20.00
OVERALL TOTAL			707.84		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SK28785

NETT ITEM	859.80
LESS 20.00%	-171.96
NETT AMOUNT	687.84
LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	20.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	20.00
TOTAL LABOUR CHARGES	750.00
TOTAL SPARE PARTS CHARGES	707.84
TOTAL CHARGES	1457.84
ADD 7 % GST	102.06
GRAND TOTAL	1559.89



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18000311/Avd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 09-03-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 2546L	Veh. Inspected	SKZ 878S	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1703100/SE/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN QASHQAI	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	SJNFEAJ11U1540672	Colour	GREY	
Odometer	40710	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/12/2017	Inspection Date	15/01/2018	
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 878S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER STAY LH (N)	NOT NECESSARY	126.00	-
1	REAR BUMPER STAY RH (N)	NOT NECESSARY	126.00	-
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	619.20	-
1	ENERGY ABSORBER REAR BUMPER (N)	NOT NECESSARY	126.40	-
1	REAR BUMPER RETAINER (N)	NECESSARY	142.80	142.80
1	REAR BUMPER TOW HOOK COVER (N)	NOT NECESSARY	16.80	-
1	REAR BUMPER FASCIA (N)	DEFORMED	717.00	717.00
	LESS 20% DISCOUNT		-374.84	-171.96
			1,499.36	687.84
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	SENSOR-REVERSE (SN)	NOT NECESSARY	250.00	-
			350.00	20.00
LABOUR				
	LABOUR CHARGES TO REPAIR REAR PANEL AND RENEW REAR BUMPER.		650.00	390.00
	CHARGES TO SPRAY PAINTING SAME.		600.00	250.00
	REMOVE AND INSTALL REVERSE SENSOR.		110.00	110.00
			1,360.00	750.00
GRAND TOTAL			3,209.36	1,457.84
RECOMMENDED COST OF REPAIRS				1,457.84

Report Ref No. CS/EGI18000311/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.