

22/09/2007

ASS. REC. BY:

REF:

033 / AXA 17004190 / R165-1

Special Instruction:

SURVIVOR

Mufiman

## ASSIGNMENT (Office)

From (Person):

Ernest Tay

of

AXA

Date/Time:

05.01.2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 992M

Insured:

SEV 180B

at Workshop m/s

Twincar Automotive

Tel:

6842 0051

of

Blk 2 Kaki Bukit Ave 2 #01-17

Policy No:

GA 101933

Claim No:

00422871

Sum Insured:

Excess:

Make of Veh:

D.O.A

24/02/07

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

07.03.2017 @ morning

H.O.D. Endorsement:

Date/Time: 01/03/2017 11:58am

Person Contacted:

Hui Xin

Vehicle IN/OUT

Date/Time

Action/Instruction ( X ) Estimate

SKE 992M: INV / AXA 17004190 / F3

AXA 24/02/07

SEV 180B - X

Dismantle Part: 03.03.2017

After repair: 07/03/2017


150317 236pm

Email to Ernest Tay

Submit

Lump Sum \$5,500/- (Red: 13,300,707.)

6 days.



21/2/2018

RECEIVED 21 FEB 2018

08/11/17

Surveyor

Muzman

REF: AXA

## ASSIGNMENT

From: Date 02/03/2017

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE 9192M

at Workshop m/s

of 2 Kaki Bukit Ave 2 #01-17

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: SKE 9192M Yr Regn: 2012, P68

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA OPTIMA 2.0A c.c. 1998

Colour: White A/C: Insured / Std / NI / NA

Sp Reading: 128653 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KWAGN411MC5214778

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/402R18

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

WSS/LEAG

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 24/02/17

D.O.I. 02/03/17 @ 232pm

Survey held at Tmcar

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1) 15.03.2017

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) \$ + RS \$

) Photos

) Others

Report Format: PRS

Lump Sum / I.B.I: (\$)

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS3/AXA17004190/R1qb-1

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 05-01-2018



Code : AXA2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFV 180B	Veh. Inspected	SKE 9192M
Policy No.	GA101933	Coverage (\$)	0.00
Claim No.	C0422877	Excess (\$)	0.00
Assign From	MERIMEN (ERNEST TAY)	Assign Date	05/01/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	24/02/2017	Inspection Date	05/01/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## ...CLAIM SUBFOLDER...(Pending for Payment)

Reinspection: PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2017		01 Mar 2017 11:44		17 Apr 2017 10:01 <b>S\$0.00</b> (S\$107.00)		<b>Pending for Payment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
<b>Insured:</b> SUE KRISTAL SUMATHI SUPPIAH, ID: S7123762A, Tel: +6598386410, Email: SUEKRISTAL@YAHOO.COM.SG									
<b>Main Claimant:</b> CHNG SOK HUNAY, Co. Reg. No.: -									
<b>Vehicle Reg. No.:</b> SKE9192M		<b>Date of Loss:</b> 24/02/2017 19:00 - :59							
<b>Claim Type:</b> TP / C0422877		<b>Policy/Cover Note No.:</b> GA101933 (Comprehensive)							
<b>Vehicle Reg. No. (Insured):</b> SFV180B		<b>Policy No. (Claimant):</b>							
		<b>Excess:</b> S\$0.00							
<b>Repairer:</b> Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:									
<b>Handling Insurer:</b> AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chen Xinyou - 6880 4269]									
<b>Adjuster:</b> LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... <b>[Final Rpt due 10/03/2017]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AXA_SG (05/01/2018): Re: WP/ PRI Assignment - C0422877/GA101933</li> <li>AXA_SG (05/01/2018): Reinspection - C0422877/GA101933</li> <li>AXA_SG (01/03/2017): WP/ PRI Assignment - C0422877/GA101933</li> <li>AXA_SG (01/03/2017): WP / New TP Assignment - C0422877/GA101933</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Catherine Chong (LKK Auto)**

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Friday, 5 January, 2018 11:40 AM  
**To:** sur@lkkauto.com; assignments@lkkauto.com  
**Subject:** Re: WP/ PRI Assignment - C0422877/GA101933

This mail is associated with :  
\*SKE9192M (C0422877)  
[SFV180B]  
TP  
CHNG SOK HUNAY  
Feb 24 2017 7:00PM  
[SUE KRISTAL SUMATHI SUPPIAH]  
Twincar Automotive Pte Ltd

Dear LKK

Pls assist with paper re-inspection of the 3rd party vehicle.

Thank you.

Best Regards  
Xinyou

<-- Original Message -->

From: AXA\_SG  
To: LKK\_HQ;sur@lkkauto.com;assignments@lkkauto.com  
CC: AXA\_SG  
Sent On: 01/03/2017 11:44 AM  
Subject: WP/ PRI Assignment - C0422877/GA101933

Dear LKK Auto Consultants Pte Ltd,

Please conduct pre-repair inspection.

Workshop Name: Twincar Automotive Pte Ltd  
Policy Number: GA101933  
Vehicle Number: SKE9192M  
Date of Accident:24/02/2017  
Estimated Claim Amount:  
Excess: 0.00  
Claim Handler Name: Ernest Tay

[ This mail is sent from a mailer account - do not reply to this email address ]

Sent by : Chen Xinyou (AXA Insurance Pte Ltd)

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks  
(Incorporated with limited liability)

Unique Entity Number: 200721148H

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI DAO MUNIANDY  
SEGA PARAM  
TITWARY ANURADHA  
ONG BOCK KEE  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
TAN YINGXIAN SEL WYN

✓ Head Office:  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch:  
490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

Branch:  
133 New Bridge Road  
#10-03 Chinatown Point  
Singapore 059413

HEAD OFFICE:  
TEL : (65) 65342811 (Hunting)  
FAX : (65) 65330868 (General)  
E-MAIL: annatan@visionlawllc.com

TEL : (65) 63580703  
TEL : (65) 65330868

BRANCH

3019245247 - - -  
TEL : (65) 65342811 (Hunting)  
TEL : (65) 65330868

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this

Our Ref : AKN-atv-Ins-T140-104715-17  
Your Ref : SFV 180 B

URGENT

61125122

Date: 22 November 2017

AXA INSURANCE SINGAPORE PTE LTD  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811  
Attn: Motor Claims Department

WITHOUT PREJUDICE  
BY HAND



SUE KRISTAL SUMATHI SUPPIAH  
Apt Blk 333 Kang Ching Road  
#10-266  
Singapore 610333

CERTIFICATE OF POSTAGE  
[For your information only]

Dear Sir,

CLAIMANT : CHONG SOK HUAY  
ACCIDENT INVOLVING SKE 9192 M & SFV 180 B ON 24-FEB-2017 ALONG PIE TOWARDS  
CHANGI AFTER ADAM FLYOVER AT ABOUT 1950HOURS

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **24-FEB-2017 ALONG PIE TOWARDS CHANGI AFTER ADAM FLYOVER AT ABOUT 1950HOURS** involving our client's vehicle registration number **SKE 9192 M** and vehicle registration number **SFV 180 B** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

01.	Cost of Repair	\$20,116.00
02.	Rental fees	\$ 2,400.00
03.	Survey report fees	\$ 1,181.00
04.	Towing fees	\$ 100.00
05.	Ceramic coating	\$ 600.00
06.	GIA & LTA search / report fees	\$ 42.35
07.	Cost Contribution (at this stage)	\$ 2,675.00
08.	Disbursements (at this stage)	\$ 50.00

**TOTAL \$27,164.35**

.../2 to be continued next page

#### CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

# VISION LAW LLC

Advocates & Solicitors

Page 2

Our Ref : AKN-atv-Ins-T140-104715-17  
Your Ref : SFV 180 B

Date: 22 November 2017

**AXA INSURANCE SINGAPORE PTE LTD**  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811  
**Attn: Motor Claims Department**

**SUE KRISTAL SUMATHI SUPPIAH**  
Apt Blk 333 Kang Ching Road  
#10-266  
Singapore 610333

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of SKE 9192 M;
  - (b) LTANet Search;
  - (c) Certificate of Insurance;
  - (d) Registration Card;
  - (e) Towing receipt;
  - (f) Ceramic coating invoice;
  - (g) Rental agreement, rental invoice & rental receipt;
  - (h) Final Repair Bill;
  - (i) Surveyor's report & invoice; and
  - (j) 162 coloured photographs depicting the damages to motor vehicle SKE 9192 M.
- (P.S:- Original photographs will be sent to insurance co. only)


The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

  
(HEAD OFFICE)  
Enc. (By PDX Only)

**CONFIDENTIALITY**

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Print Date/Time : 25 Feb 2017 / 11:09:24

Receipt Date/Time : 25 Feb 2017 / 11:09:24

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-170225-000382

Previous Receipt No. :

**S/N Item Description/  
Business Transaction  
Reference No.**

Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
--------------------------------	-------------------------	-------------------------------

Result of Insurance Enquiry - SFV180B

As at 24 Feb 2017/19:47:00

Insurance Co: AXA INSURANCE SINGAPORE PTE LTD

1 Insurance Enquiry - SFV180B  
Enquiry Fee  
20170225110831526452

	5.00	0.35	5.35
<b>Sub-Total</b>	5.00	0.35	5.35
<b>Total Before Rounding</b>	5.00	0.35	5.35
<b>Rounding Difference</b>			0.00
<b>Total Amount Payable</b>			5.35
<b>Paid By</b>			
xxxxxxxxxxxx2392	Credit Card: Visa/MasterCard		5.35
<b>Total</b>			5.35
<b>Cash Change</b>			0.00
<b>Tendered Amount</b>			5.35
<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/02/2017 16:22
Date Of Accident	24/02/2017 19:50
Exact Location Of Accident	PIE TWDS CHANGI AFT ADAM FLYOVER
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE9192M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHNG SOK HLAY
NRIC No	S7004459E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98008472
Alternative Phone No	Others-98008472
<b>Vehicle Particulars</b>	
Manufacturer	KIA
Model	K5 FORTIE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
<b>Insurance Company</b>	
Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2100291605-04300
Cover Note Number	
<b>Driver</b>	
Name of Driver	KOH SWEE BENG
NRIC No	S1701917A
Date Of Birth	23/08/1965
Occupation	Indoor
Date Of Driving Pass	05/02/2008
Driving Experience	9 Years And 0 Months
Gender	Male
Mobile Number	(Local) +65-94682326
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 418 WOODLANDS ST 41 #05-115
Postcode	730418
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Spouse
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	Collision- Head to Side
Weather Conditions	DRIZZLING
Road Surface	Wet

#### Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Remarks/ Reasons:	WITH THE WORKSHOP
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFV180B
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	CHRISTOPHER JOSHUA RATNAM
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

#### DETAILS OF INJURED PERSON 1

Name	KOH SWEE BENG
------	---------------

Approximate Age

Injuries Sustain

SLIGHT

Injured person in which vehicle?

SKE9192M

Were seat belts worn?

Yes

Was injured conveyed to hospital by ambulance?

No

Address

Postcode

### SKETCH PLAN

\* Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability

Providing false information to an insurance company is not an admission of policy liability on the part of the insurance company.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5 Any false reporting may be referred to the Police for investigation

5. Any false reporting may be referred to the Police for investigation

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.

5 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(f) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(a) investigating the accident and/or my claims

(e) carrying out and/or dealing with my instructions or responding to any enquiries by me

(k) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or QIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

### Sketch Plan

Free download of *Psychology* (2016) PDF eBook (PDFDrive)

Witnessed by Reporting Centre  
Personnel

Vehicle A - Skidmark

VEHICLE B - SFVIRUS

Handwritten: 11/10/11

## Describe Circumstances of the Accident

I WAS TRAVELLING ON THE EXTREME RIGHT LANE OF A 4 LANE  
1 WAY EXPRESS WAY. I WAS TOWARDS CHANGLI AIRPORT DIRECTION.  
AS THE VEHICLE AHEAD BRAKE TO STOP DUE TO THE HEAVY  
TRAFFIC. AND AS I WAS ABOUT TO FULLY STOP  
A FEW SECONDS I FELT A CRASH IMPACT FROM THE BACK  
OF MY VEHICLE. I REMEMBERED THAT AS I WAS STOPPED  
A VEHICLE BEHIND (SEV 803) HAD COLLIDED IN  
THE REAR OF MY VEHICLE.

THE VEHICLE BEHIND WAS A WHITE HATCHBACK. I  
DID NOT SEE THE DRIVER.

THE VEHICLE BEHIND WAS A WHITE HATCHBACK. I  
DID NOT SEE THE DRIVER.

VEHICLE A - SEV 7192 M  
VEHICLE B - SEV 803 B

## Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &  
Time

Driver's Signature (if driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

4/2/2017.

I Christopher Joshua Adams (attorney), driving services driving  
 back to along the PCEE towards Cherry Hill vehicle the 2014  
 as it private settle on claim through my insurance I will inform  
 my firm on 21 Feb my decision on how to proceed

Christopher Joshua Adams  
 attorney  
 CJA

# TWINCAR RENTAL

Business Registration Number : 53092815M

Blk 2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 68420051 Fax : 67410510 email: sales@n51.com.sg

Invoice To :

CHNG SOK HUAY  
Blk 418 Woodlands Street 41  
#05-115  
Singapore 730418

## INVOICE

Invoice No. 13-1619

Date 8/3/2017

Hirer's Car No.	VHA No.	Terms
SKE9192M	71229	CASH

No. of Day	Description	Per Day	Amount (S\$)
12	Car Rental from the period of 24/02/2017 to 08/03/2017. Vehicle no. SJV6301H  Singapore Dollars Two Thousand and Four Hundred Only	200.00	2,400.00
Total			\$2,400.00

TWINCAR RENTAL



Authorised Signature



# TWINCAR RENTAL

Kaki Bukit Autohub @ 2 Kaki Bukit Ave. 2 #01-18  
Singapore 417921 Tel: 6744 0510 / 6842 0051

VHA No: 71229  
SKE 9192M (TC)

ROC NO. 53092815M

## VEHICLE RENTAL AGREEMENT

### HIRER'S PARTICULAR


Name: (as in I/C) CNG SOK HUAY  
NRIC/PASSPORT No: S 7004451 E  
Address (Res): BLK 418 WOODLANDS ST41  
#05-115 S(730418)  
Name & Address of Employer: \_\_\_\_\_

Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_  
Driving Licence No: \_\_\_\_\_ D/L Type: Local / International  
Issue Date: \_\_\_\_\_ Date of Birth: 01/02/1970  
Tel: (O) \_\_\_\_\_ (R) \_\_\_\_\_ HP/PG: 9468 7326

### ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) KOH SUEE BLNG  
NRIC/PASSPORT No: S 12019AA  
Address (Res): BLK 418 WOODLANDS ST41  
#05-115 S(730418)  
Driving Licence No: S1209AA D/L Type: Local / International  
Issue Date: 03/09/2015 Date of Birth: 23/08/1985  
Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_

### VEHICLE CHECKLIST



### ACCESSORIES CHECK

☐ Ashtray ☐ Cig Lighter ☐ S/Tyre  
☐ STD Tools ☐ Jack ☐ Hub Caps  
☐ Radio / Cass ☐ CD ☐ Cartridges

Vehicle No: SJV 6301 H Replace Veh No: \_\_\_\_\_  
Mileage Out: \_\_\_\_\_ Mileage Out: \_\_\_\_\_  
Make & Model: TOYOTA Auto / Manual  
WISH Group: \_\_\_\_\_  
OUT: Date 24/02/17 Time: 2200HRS  
HIRE/PERIOD EXPIRY \_\_\_\_\_  
NON-WAIVER EXCESS : \$ \_\_\_\_\_

CHARGES			
Daily @ \$	200	per day	12
Weekly @ \$		per week	
Monthly @ \$		per month	
Hours @ \$		per hour	
Others @ \$			
CDW @ \$		per day/month	
PAI @ \$		per day/month	
Delivery Service			
SUB-TOTAL \$			

PETROL LEVEL						
Out	E	1/4	1/2	3/4	F	
In	E	1/4	1/2	3/4	F	
EXTENSION						
Collection Service						
Misc.						
TOTAL CHARGE \$						2400.00

Rented out by: \_\_\_\_\_

Hirer's Signature 


Addition Driver's Signature 

I have read and agree to the terms & condition on both sides of this agreement. If I have presented a change/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given TWINCARD RENTAL in connection with this Agreement is true.

### \* IMPORTANT

- ONLY PERSONS ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY TWINCAR RENTAL.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO TWINCAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS
08/03/2017	19:30HRS			
				 SIGNATURE OF HIRER/DRIVER

**AIG**TOLLFREE TEL: (65) 6419-3000  
FAX: (65) 6411-3723**CERTIFICATE OF INSURANCE**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 169)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1967  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

U X 1

KIA AUTO PROTECTOR

CERTIFICATE NO. 2100291605-04000

OWN DAMAGE EXCESS S\$600.00 (1)  
WINDSCREEN EXCESS S\$100.00  
(The above excess is subject to 100%)  
(The above excess will effect from 1st November 2007)SUM INSURED Market Value  
INSURING WITH COE/PARF Yes  
SKE9192M

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

Chng Sok Huay

3) EFFECTIVE DATE OF THE COMMENCEMENT  
OF INSURANCE FOR THE PURPOSES OF THE ACT

1 Mar 2016

4) DATE OF EXPIRY OF INSURANCE

28 Feb 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE\*

SUBJECT TO AGE CONDITION: All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 22 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE\*

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES (RAC) / AUTHORIZED REPAIRERS

1. Cycle &amp; Carriage Pandan Gardens Service Centre - 209 Pandan Gardens (Tel: 6568 4567)

APPROVED REPORTING CENTRES (RAC) / AUTHORIZED REPAIRERS (FOR CLAIMS-RELATED ROP/RAH)

2. ComfortDrive Engg - 205 Braddell Rd (Tel: 63037118) 3. Ethos - 30 Bukit Batok Cres (Tel: 66547777)

4. Glass-Plus - 52 Ubi Ave 3 (Tel: 62780667) - For windscreen only 5. Kan Fook Sing Motor - 61 Delfi Lane 12 (Tel: 67479500)

6. Lai Hui (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64536110) 7. Nova Automotive - 100d Bukit Merah Lane 3 (Tel: 62723502)

8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 9. SME Motor - 1 Kaki Bukit Ave 5 Bld D (Tel: 67476106)

LOSS OF USE \*15 Days Replacement Car only for repairs at C&amp;C - Refer to policy wordings for details

\* NAMED DRIVER NA

HIRE PURCHASE COMPANY MayBank

EMPLOYER'S LOAN

\*Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 169) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 19 Jan 2016

AIG Asia Pacific Insurance Pte. Ltd.

500709-050

CYCLE & CARRIAGE - CORPORATE  
239 ALEXANDRA ROADSINGAPORE 159336  
AGENT/ACTOR

AUTHORIZED REPRESENTATIVE

ORIGINAL

CYC08

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 4459E

### Vehicle Details

Vehicle No.: SKE9192M  
Vehicle to be Exported: No  
Intended De-registration Date: 25 Feb 2017  
Vehicle Make: KIA  
Vehicle Model: CPTIMA 2.0 A/T ABS D/AB 2WD 4DR HID SR  
Primary Colour: White  
Manufacturing Year: 2011  
Engine No.: G4KDBS191742  
Chassis No.: KNAGN411MC5214778  
Maximum Power Output: 121.0 kW (162 bhp)  
Open Market Value: \$20,666.00  
Original Registration Date: 29 Feb 2012  
First Registration Date: 29 Feb 2012  
Transfer Count: 0  
Actual ARF Paid: \$20,666.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 28 Feb 2022  
PARF Rebate Amount: \$15,499.00

### Intended COE Rebate Details

COE Expiry Date: 28 Feb 2022  
COE Category: E - Open Category  
E Period(Years): 10  
QP Paid: \$67,101.00  
COE Rebate Amount: \$33,610.00  
**Total Rebate Amount: \$49,109.00**

The information contained herein is correct as at 25 Feb 2017

OK

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.  
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.  
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution  
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

**CASH SALE**

(TWINING?)

No \_\_\_\_\_

Sold to: \_\_\_\_\_

SKE 9192 M-

Date: 25/2/17

Item	Quantity	Description	Unit Price	Amount
		Auto Hub to U6: WAK		\$ 100
		Reporting Two Trips		
E. & O. E			Sub Total :	
			GST Tax :	
			Total :	\$ 100

Issued by: \_\_\_\_\_

CROWN

Submit claim

## J2 Professional Carcare Pte Ltd

10 Ang Mo Kio Industrial Park 2A #03-01  
Singapore 568047  
Mobile: 9889 1100 (Derek)  
Telephone: 6753 9906

Invoice Number:

Customer Number: NSI


Date: 8/3/17

Time:

Customer Vehicle Number: SKF 9192M

Payment Mode: Cash/ Nets/ Credit Card

S/No.	Item Description	Unit Price	Quantity	Total Price
1	CERAMIC COATING	-	-	\$600=-
Amount Payable				\$600=-

  
J2 Authorised Signature

Thank you for choosing J2 as your car protection choice!  
Have a nice day ☺

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6342 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714615M  
GST Registration No. : 200714616M

CHNG SOK HUAY  
BLK 418 WOODLANDS ST 41 #05-115  
SINGAPORE 730418

Contact : 98008472, 94682326

## TAX INVOICE

Date : 13/10/2017  
Date in : 24/02/2017  
Vehicle Num. : SKE9192M  
Make/Model : KIA OPTIMA 2.0 A/T ABS D/AB 2WD 4DR HID SR-2011  
Chassis/Eng# : KNAGN411MC5214778/G4KDBS191742  
Accident Date : 24/02/2017  
Claim No : CLM13617  
Reference : FEB-34/2017  
Policy No. : 2100291605-04000 (28/02/2017)

Amount S\$  
18,800.00

LUMPSUM REPAIR BILL  
AS PER SURVEYOR REPORT  
REF : CAS/17-10/022 DATED 02/03/2017  
BY CONSTANT APPRAISER SERVICES

E. & O.E.	Sub SS :	18,800.00
	Add GST ( 7 % ) SS :	1,316.00
	Total Amount SS :	20,116.00



for TWINCAR AUTOMOTIVE PTE LTD

**Enquire Vehicle & Owner Information ( Vehicle No. SFV180B As At 24 Feb 2017 / 19:50:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: T140-104715-17

**Current Owner Details**

Owner ID Type: Singapore NRIC  
Owner ID: S7123762A  
Owner Name: SUE KRISTAL SUMATHI SUPPIAH  
Registered Address Type: HDB / HUDC  
Registered Block/House No.: 333  
Registered Street Name: KANG CHING ROAD  
Registered Unit No.: # 10 - 266  
Registered Building Name: -  
Registered Postal Code: 610333

**Current Vehicle Details**

Vehicle No.: SFV180B  
Make Description/Model: NISSAN / SUNNY 1.6EXA  
Insurance Company Name: AXA INSURANCE PTE LTD

Thank you



Ng Ching Boon Eric has successfully logged out.

Your last login date and time was 21 Nov 2017, 19:19:48.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

<u>S/No</u>	<u>Asset</u> <u>Type</u>	<u>Asset ID</u>	<u>Asset</u> <u>Owner ID</u>	<u>Transaction Type</u>	<u>Transaction</u> <u>Amount(S\$)</u>	<u>Log</u> <u>Date/Time</u>
1	Vehicle	SFV180B	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	5.35	21 Nov 2017 / 19:20:12

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## INVOICE


To: Chng Sok Huay  
Blk 418 Woodlands St 41  
#05-115  
Singapore 730418

Date : 09/10/2017  
Invoice No : IV17-10022/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of:  Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle SKE 9192M (Inclusive Of Photographs And Transport Charges)  Our reference : CAS/17-10/022	\$1,181.00
Total	\$1,181.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
Blk 2 Rivervale Link, #09-02 Singapore 545040  
Tel/Fax: 6886 1106 Mobile: 9007 5234  
Email: constant\_as@yahoo.com.sg  
RCB No. 53138015K

## Automobile Inspection Report

To: Chng Sok Huay  
Blk 418 Woodlands St 41 #05-115  
Singapore 730418

Date : 09/10/2017

Reference No : CAS/17-10/C22

### General Information

Registration No. : SKE 9192M  
Accident Date : 24/02/2017

### Particulars of Damaged Vehicle

Colour	: Pearl White	Make & Model	: Kia Optima 2.0
Engine Capacity	: 1998 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 128653	Engine No.	: G4KDBS191742
Chassis No.	: KNAGN411MC5214778	Steering	: In Order
Registration Date	: 29/02/2012	Brake	: In Order

### Tyre Condition

	Size	Make	Balance
R/H Front Tyre	245/40R18	WESTLAKE	90%
L/H Front Tyre	245/40R18	WESTLAKE	90%
R/H Rear Tyre	245/40R18	WESTLAKE	90%
L/H Rear Tyre	245/40R18	WESTLAKE	90%

### Inspection

Repairer : Twincar Automotive Pte Ltd  
2 Kaki Bukit Ave 2, #01-17 Kaki Bukit Autohub, Singapore 417921

### Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$26,350.75  
Revised Amount : \$18,800.00  
Less Excess : -  
Nett Total : \$18,800.00

### Remarks

- (A) Survey was done on 02/03/2017
- (B) Re-survey was done on 03/03/2017
- (C) Re-survey after repair was done on 07/03/2017
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

**Constant Appraiser Services**

Vehicle No : SKE 9192M

Our ref : CAS/17-10/022

**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<b><u>PARTS REPLACEMENT – LIST ITEMS</u></b>					
1	1pc	Rear bootlid	Dented/Buckled	828.00	828.00 R
2	2pcs	Rear bootlid hinges L/R @ \$60.00	Repair	120.00	-
3	1pc	Rear bootlid inner handle	Serviceable	73.00	-
4	1pc	Rear bootlid inner upholstery trim	Deformed	148.00	148.00 X SVC
5	1pc	Rear bootlid mechanism lock	Bent/Jammed	89.00	89.00
6	2pcs	Rear bootlid number plate lamp L/R @ \$29.00	Cracked	58.00	58.00 X SVC
7	1pc	Rear bootlid outer garnish	Broken	252.00	252.00 X SVC
8	1pc	Rear bootlid outer lock handle switch	Damaged	73.00	73.00 X SVC
9	4pcs	Rear bootlid reflector lamp clips L/R @ \$6.50	Necessary	26.00	26.00 X NN
10	2pcs	Rear bootlid reflector lamp L/R @ \$643.00	Cracked/Broken	1,286.00	1,286.00 X SVC
11	4pcs	Rear bootlid rubber guide stopper L/R @ \$9.00	Necessary	36.00	36.00 X SVC
12	1pc	Rear bootlid weather strip	Distorted	86.00	86.00 X SVC
13	1pc	Rear bumper	Dented/Broken	686.00	686.00
14	1pc	Rear bumper inner bootlid antenna sensor	Damaged	78.00	78.00 X NN
15	1pc	Rear bumper inner sponge	Broken	102.00	102.00
16	1pc	Rear bumper lower diffuser	Broken	88.00	88.00
17	1pc	Rear bumper reinforcement	Broken	541.00	541.00
18	2pcs	Rear bumper reinforcement bracket L/R @ \$49.00	Bent	98.00	98.00
19	2pcs	Rear bumper reinforcement lower bracket L/R @ \$22.00	Broken	44.00	44.00
20	2pcs	Rear bumper reinforcement top bracket L/R @ \$22.00	Bent	44.00	44.00
21	4pcs	Rear bumper reverse sensor 'original' @ \$184.00	Damaged	736.00	* 736.00
22	4pcs	Rear bumper reverse sensor holder @ \$18.50	Necessary	74.00	74.00
23	4pcs	Rear bumper reverse sensor rubber seal @ \$8.50	Necessary	34.00	34.00
24	1set	Rear bumper reverse sensor wire harness - set	Serviceable	290.00	-
25	2pcs	Rear bumper side retainer L/R @ \$297.00	Necessary	594.00	594.00
26	1pc	Rear end panel	Dented	233.00	233.00
27	1pc	Rear end panel inner bootlid antenna sensor	Damaged	89.00	89.00
28	1pc	Rear end panel inner top garnish	Deformed/Broken	86.00	86.00
29	1pc	Rear end panel inner top garnish clips	Necessary	6.50	6.50
30	1pc	Rear end panel lock striker	Bent	18.00	18.00
31	1pc	Rear end panel lock striker cover	Serviceable	15.00	-

Constant Appraiser Services

Vehicle No : SKE 9192M

Our ref : CAS/17-10/022

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS (CONT'D)</u>					
32	1pc	Rear exhaust aluminium heat shield	Repair	141.00	-
33	1pc	Rear exhaust gasket	Necessary	25.00	NN 25.00 X
34	2pcs	Rear exhaust rubber mounting @ \$28.00	Distorted	56.00	SVC 56.00 X
35	1pc	Rear exhaust silencer box	Bent	994.00	994.00 R
36	2pcs	Rear fender inner air vent L/R @ \$39.00	Serviceable	78.00	-
37	2pcs	Rear fender inner shield L/R @ \$189.00	Serviceable	378.00	-
38	2pcs	Rear fender inner upholstery trim L/R @ \$398.00	Deformed	796.00	SVC 796.00 X
39	2pcs	Rear sub chassis frame L/R @ \$630.00	Repair	1,260.00	-
40	2pcs	Rear taillamp clips L/R @ \$6.50	Necessary	13.00	13.00
41	2pcs	Rear taillamp inner panel L/R @ \$124.00	Dented	248.00	248.00 R
42	2pcs	Rear taillamp L/R @ \$813.00	Cracked/Broken	1,626.00	SVC 1,626.00 X
43	1pc	Spare tyre panel	Repair	607.00	-
44	1pc	Spare tyre panel inner top upholstery board	Dented/Deformed	290.00	SVC 290.00 X
45	1pc	Spare tyre retainer lock	Serviceable	18.00	-
46	2pcs	Spare tyre side panel L/R @ \$78.00	Repair	156.00	-
				13,617.50	10,481.50
Less 10%				(1,361.75)	(1,048.15)
Sub total				12,255.75	9,433.35
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	1pc	Rear bootlid 'GT logo' emblem with L.E.D lamp	Damaged	350.00	350.00 50
2	1set	Rear bootlid inner upholstery trim clips - set	Necessary	30.00	30.00
3	1pc	Rear bootlid number plate	Serviceable	25.00	-
4	1pc	Rear bootlid number plate holder	Serviceable	50.00	-
5	1set	Rear bootlid outer garnish clips - set	Necessary	30.00	30.00
6	1set	Rear bootlid reverse sensor	Damaged	800.00	800.00 X SVC
7	1pc	Rear bootlid spoiler 'fluxion & bliss'	Broken	800.00	800.00 X NN
8	1set	Rear bumper clips - set	Necessary	30.00	30.00
9	1pc	Rear bumper lower lip 'carbon' sticker	Necessary	500.00	500.00 200
10	1pc	Rear bumper lower lip 'fluxion & bliss'	Broken	2,800.00	* 2,800.00 1000
11	1pc	Rear bumper lower lip L.E.D lamp	Damaged	190.00	190.00 X SVC
12	2pcs	Rear bumper reflector L.E.D lamp L/R - set @ \$580.00	Cracked/Broken	1,160.00	1,160.00 X SVC

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS (CONT'D)</u>					
13	2pcs	Rear bumper side black frame sticker L/R @ \$50.00	Necessary	100.00	100.00
14	1pc	Rear bumper top black frame sticker	Necessary	300.00	300.00 100
15	1pc	Rear bumper top reflective red line sticker	Necessary	200.00	200.00 50
16	1pc	Rear exhaust end chrome pipe	Dented	580.00	580.00 R
17	2pcs	Rear fender black frame sticker L/R @ \$300.00	Necessary	600.00	600.00 X NN
18	2sets	Rear fender inner shield clips L/R – set @ \$30.00	Necessary	60.00	60.00
19	2pcs	Rear fender inner upholstery trim clips L/R – set @ \$30.00	Necessary	60.00	60.00
20	1pc	Rear LH exhaust dummy pipe	Dented/Bent	580.00	580.00 R
21	1pc	Spare tyre	Serviceable	280.00	-
22	1pc	Spare tyre panel insulator mat	Not Necessary	350.00	-
Sub total				22,130.75	18,603.35
<u>LABOUR &amp; MISC. CHARGES</u>					
1		To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor		150.00	80.00 40
2		To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)		140.00	100.00 60
3		To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper		1,750.00	1,500.00 1000
4		To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident		160.00	120.00 60
5		To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident		1,500.00	1,300.00 800
6		To mount vehicle on to Car 'O' Liner		400.00	300.00 X
7		To apply anti-rust chemical on repaired and replaced panel		120.00	120.00 60
Grand total				26,350.75	22,123.35
Recommended cost of lump sum repair (To its pre-accident condition)					18,800.00

**Constant Appraiser Services**

Vehicle No : SKE 9192M

Our ref : CAS/17-10/022

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$18,800.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,

**Constant Appraiser Services**



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA

3217.95  
1710.00 ✓  
2020.00 ✓  
6947.95  
20%  
5558.36  
435,550  
6 days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 9192M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	828.00	-
2	REAR BOOTLID HINGES L/R @ \$60.00	TO REPAIR SEE LABOUR	120.00	-
1	REAR BOOTLID INNER HANDLE	SERVICEABLE	73.00	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM	SERVICEABLE	148.00	-
1	REAR BOOTLID MECHANISM LOCK	BENT / JAMMED	89.00	89.00
2	REAR BOOTLID NUMBER PLATE LAMP L/R @ \$29.00	SERVICEABLE	58.00	-
1	REAR BOOTLID OUTER GARNISH	SERVICEABLE	252.00	-
1	REAR BOOTLID OUTER LOCK HANDLE SWITCH	SERVICEABLE	73.00	-
4	REAR BOOTLID REFLECTOR LAMP CLIPS L/R @ \$6.50	NOT NECESSARY	26.00	-
2	REAR BOOTLID REFLECTOR LAMP L/R @ \$643.00	SERVICEABLE	1,286.00	-
4	REAR BOOTLID RUBBER GUIDE STOPPER L/R @ \$9.00	SERVICEABLE	36.00	-
1	REAR BOOTLID WEATHER STRIP	SERVICEABLE	86.00	-
1	REAR BUMPER	DENTED / BROKEN	686.00	686.00
1	REAR BUMPER INNER BOOTLID ANTENNA SENSOR	NOT NECESSARY	78.00	-
1	REAR BUMPER INNER SPONGE	BROKEN	102.00	102.00
1	REAR BUMPER LOWER DIFFUSER	BROKEN	88.00	88.00
1	REAR BUMPER REINFORCEMENT	BROKEN	541.00	541.00
2	REAR BUMPER REINFORCEMENT BRACKET L/R @ \$49.00	BENT	98.00	98.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET L/R @ \$22.00	BROKEN	44.00	44.00
2	REAR BUMPER REINFORCEMENT TOP BRACKET L/R @ \$22.00	BENT	44.00	44.00
4	REAR BUMPER REVERSE SENSOR 'ORIGINAL' @ \$184.00	DAMAGED	736.00	736.00
4	REAR BUMPER REVERSE SENSOR HOLDER @ \$18.50	NECESSARY	74.00	74.00
4	REAR BUMPER REVERSE SENSOR RUBBER SEAL @ \$8.50	NECESSARY	34.00	34.00
1	SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	SERVICEABLE	290.00	-
2	REAR BUMPER SIDE RETAINER L/R @ \$297.00	NECESSARY	594.00	594.00
1	REAR END PANEL	DENTED	233.00	233.00
1	REAR END PANEL INNER BOOTLID ANTENNA SENSOR	DAMAGED	89.00	89.00

Report Ref No. CS3/AXA17004190/R1qbs2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL INNER TOP GARNISH	DEFORMED / BROKEN	86.00	86.00
1	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	6.50	6.50
1	REAR END PANEL LOCK STRIKER	BENT	18.00	18.00
1	REAR END PANEL LOCK STRIKER COVER	SERVICEABLE	15.00	-
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	TO REPAIR SEE LABOUR	141.00	-
1	REAR EXHAUST GASKET	NOT NECESSARY	25.00	-
2	REAR EXHAUST RUBBER MOUNTING @ \$28.00	SERVICEABLE	56.00	-
1	REAR EXHAUST SILENCER BOX	TO REPAIR SEE LABOUR	994.00	-
2	REAR FENDER INNER AIR VENT L/R @ \$39.00	SERVICEABLE	78.00	-
2	REAR FENDER INNER SHIELD L/R @ \$189.00	SERVICEABLE	378.00	-
2	REAR FENDER INNER UPHOLSTERY TRIM L/R @ \$398.00	SERVICEABLE	796.00	-
2	REAR SUB CHASSIS FRAME L/R @ \$630.00	TO REPAIR SEE LABOUR	1,260.00	-
2	REAR TAILLAMP CLIPS L/R @ \$6.50	NECESSARY	13.00	13.00
2	REAR TAILLAMP INNER PANEL L/R @ \$124.00	TO REPAIR SEE LABOUR	248.00	-
2	REAR TAILLAMP L/R @ \$813.00	SERVICEABLE	1,626.00	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	607.00	-
1	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	SERVICEABLE	290.00	-
1	SPARE TYRE RETAINER LOCK	SERVICEABLE	18.00	-
2	SPARE TYRE SIDE PANEL L/R @ \$78.00	TO REPAIR SEE LABOUR	156.00	-
	LESS 10% DISCOUNT		-1,361.75	-357.55
			12,255.75	3,217.95
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BOOTLID 'GT LOGO' EMBLEM WITH L.E.D LAMP (SN)	DAMAGED	350.00	50.00
1	SET REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	REAR BOOTLID NUMBER PLATE HOLDER (SN)	SERVICEABLE	50.00	-
1	SET REAR BOOTLID OUTER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00

Report Ref No. CS3/AXA17004190/R1qbs2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BOOTLID REVERSE SENSOR (SN)	SERVICEABLE	800.00	-
1	REAR BOOTLID SPOILER 'FLUXION & BLISS' (SN)	NOT NECESSARY	800.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER LOWER LIP 'CARBON' STICKER (SN)	NECESSARY	500.00	200.00
1	REAR BUMPER LOWER LIP 'FLUXION & BLISS' (SN)	BROKEN	2,800.00	1,000.00
1	REAR BUMPER LOWER LIP L.E.D LAMP (SN)	SERVICEABLE	190.00	-
2	REAR BUMPER REFLECTOR L.E.D LAMP L/R - SET @ \$580.00 (SN)	SERVICEABLE	1,160.00	-
2	REAR BUMPER SIDE BLACK FRAME STICKER L/R @ \$50.00 (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER TOP BLACK FRAME STICKER (SN)	NECESSARY	300.00	100.00
1	REAR BUMPER TOP REFLECTIVE RED LINE STICKER (SN)	NECESSARY	200.00	50.00
1	REAR EXHAUST END CHROME PIPE (SN)	TO REPAIR SEE LABOUR	580.00	-
2	REAR FENDER BLACK FRAME STICKER L/R @ \$300.00 (SN)	NOT NECESSARY	600.00	-
2	SETS REAR FENDER INNER SHIELD CLIPS L/R @ \$30.00 (SN)	NECESSARY	60.00	60.00
2	REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R - SET @ \$30.00 (SN)	NECESSARY	60.00	60.00
1	REAR LH EXHAUST DUMMY PIPE (SN)	TO REPAIR SEE LABOUR	580.00	-
1	SPARE TYRE (SN)	SERVICEABLE	280.00	-
1	SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	350.00	-
			9,875.00	1,710.00
	<b>LABOUR</b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		150.00	40.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		1,750.00	1,000.00

Report Ref No. CS3/AXA17004190/R1qbs2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		160.00	60.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BOOTLID, REAR BOOTLID HINGES L/R, REAR EXHAUST ALUMINIUM HEAT SHIELD, REAR EXHAUST SILENCER BOX, REAR SUB CHASSIS FRAME L/R, REAR TAILLAMP INNER PANEL L/R, SPARE TYRE PANEL, SPARE TYRE SIDE PANEL L/R, REAR EXHAUST END CHROME PIPE AND REAR LH EXHAUST DUMMY PIPE.		1,500.00	800.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			4,220.00	2,020.00
	<b>GRAND TOTAL</b>		<b>26,350.75</b>	<b>6,947.95</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,500.00</b>

Report Ref No. CS3/AXA17004190/R1qbs2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.