

INS. CASE OWNER:

CC

H1800

LKK:

IDAC:

Surveyor:

Flaneth

DOI:

4/1/18

Date / Time :

4/1/18

Registered in Merimen:

5/1/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SH 6600L

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : S\$ _____ D.O.A : 31/12/17

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHD 5489u

INSRS:
WSP:
Tel :
Liability :
RMKS:trans
CMBINSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

8/1/18

SHD 5489u - X

SH 6600L - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(S

x

days)

Loss of Income (LOI):

S\$

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
21/1/18

ASS. REC. BY:

REF: 10/1Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 1/2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S1AD 5589U Yr Regn: 01, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Perant Latitude c.c. 1995Colour: M. White / R A/C: Insured / Std / NI / NASp. Reading: 663285 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFIABL15AUC 276797Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: Prime Well 215/60R16Ling R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 31/12/17

Survey held at

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 4/1/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/1 File 199174 Certificate16/1/18 Confirm US \$ 6800.00 with 2.5 working days

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

(RD-A 65)49.77
91%)

Claim Audit

AUDIT TRAIL				By
No.	On	Audit	Remarks	
1	05 Jan 2018 12:46	Cim Veh Model Changed	(205460) RENAULT LATITUDE 2.0 L DCI (A).	[A] Lau Shu Pei
2	05 Jan 2018 12:46	Cim Created	Reg No: SHD5589U. Acct Date: 2017/12/31. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)	[A] Lau Shu Pei
3	05 Jan 2018 12:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	05 Jan 2018 12:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/16	[A] Lau Shu Pei
5	05 Jan 2018 12:46	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	05 Jan 2018 12:46	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	05 Jan 2018 12:46	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	08 Jan 2018 09:00	Cim Cancelled	Cancelled:SH6600L is not insured under us.	[I] Gabriel Wee

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	05 Jan 2018 12:46	Clim Veh Model Changed	(205460) RENAULT LATITUDE 2.0 L DCI (A).		[A] Lau Shu Pei
2	05 Jan 2018 12:46	Clim Created	Reg No: SHD5589U. Acct Date: 2017/12/31. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)		[A] Lau Shu Pei
3	05 Jan 2018 12:46	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] Lau Shu Pei
4	05 Jan 2018 12:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/01/16		[A] Lau Shu Pei
5	05 Jan 2018 12:46	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] Lau Shu Pei
6	05 Jan 2018 12:46	Label Added	(30653):Direct Settlement.		[A] Lau Shu Pei
7	05 Jan 2018 12:46	Adj Adjuster Assigned	[None] -> KENNETH KONG		[A] Lau Shu Pei
8	08 Jan 2018 09:00	Clim Cancelled	Cancelled:SH6600L is not insured under us.		[I] Gabriel Wee

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
No billing items							

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD5589U
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000966
Chassis No.:	VF1ABL15AUC276797
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	14 Jan 2014
First Registration Date:	14 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	13 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,888.00
COE Rebate Amount:	\$30,628.00
Total Rebate Amount:	\$40,001.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Jan 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/01/2018 17:27
Date Of Accident	31/12/2017 01:15
Exact Location Of Accident	HAVELOCK ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD5589U
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	CHEONG MENG ENG
NRIC No	S1642535D
Date Of Birth	10/07/1964
Occupation	OUTDOOR
Date Of Driving Pass	25/11/1986
Driving Experience	31 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-85230918
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 986C BUANGKOK CRESCENT #02-70
Postcode	533986
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 31 Dec 2017 @ 0115hrs, I was travelling along Havelock Road at Lane 4. Suddenly a comfort taxi, SH 6600L just cut into my lane and hit onto the front right portion of my taxi.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH6600L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: - 2 JAN 2018

Reporting Centre Personnel's Signature
Name: JASMINE TAN SIEW KHA
NRIC/FIN No.: S74056361

SKETCH PLAN

SPC

A	B			
↑	↑	↑	↑	
5	4	3	2	1

A : 010 0001 0
B : 011 0001 0

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or printed text on the page.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: - 2 JAN 2018

Reporting Centre Personnel's Signature _____

Name: S7405636I

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: - 2 JAN 2018

Reporting Centre Personnel's Signature
Name: JASMINE TAN SIEW KIM
NRIC/FIN No.: S74056361

Sketch Plan #2 Pg. 1

SKETCH PLAN

A hand-drawn diagram on graph paper showing a 4x4 grid. The grid is labeled 'SPC' on the left. A path is marked with arrows starting from a point labeled 'A' at the top-left and ending at a point labeled 'B' at the bottom-right. The path consists of four steps: right, down, right, and down. The grid is divided into four quadrants by a vertical line between columns 2 and 3, and a horizontal line between rows 2 and 3. The path starts at the top-left corner of the top-left quadrant, moves right to the top-right corner, then down to the bottom-right corner, then right to the bottom-left corner, and finally down to the bottom-right corner of the bottom-right quadrant.

A : SHI GSHU
B : SHI GSHU

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: - 2 JAN 2018

Reporting Centre Personnel's Signature

Name:

S7405636I

NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5589U**AAD1801-013***Not Authored
1/1/8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 5589U

VF1ABL15AUC276797

RENAULT

LATITUDE

31.12.2017

III**PART****LIST**

1	1 BUMPER COVER FRT	\$	<i>CMA</i> 1,259.42 ✓
2	1 BUMPER SPOILER FRT	\$	<i>M1</i> 181.75 ✓
3	1 BUMPER ABSORBER FRT	\$	<i>M1</i> 394.68 ✓
4	1 BUMPER RETAINER FRT LH	\$	<i>D1</i> 151.41 ✓
5	1 BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
6	1 BUMPER RETAINER FRT RH	\$	<i>CMA</i> 150.77 ✓
7	1 BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88 X
8	1 BUMPER UNDERTRAY FRT	\$	<i>D1</i> 472.83 ✓
9	1 BUMPER GRILLE LOWER FRT	\$	<i>Rd</i> 266.80 ✓
10	1 BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 207.21 X
11	1 BUMPER FOG LAMP GRILLE RH	\$	<i>M1</i> 207.21 ✓
12	1 BUMPER BEAM FRT	\$	<i>R</i> 914.08
13	1 TOW COVER FRT	\$	<i>Sm</i> 28.61
14	1 RADIATOR GRILLE	\$	<i>Sm</i> 1,707.78
15	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 225.36
16	1 RADIATOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75
17	1 FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 615.90
18	1 FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
19	1 FRONT BRACE PANEL	\$	<i>R</i> 177.22
20	1 HORN	\$	<i>Sm</i> 314.17
21	1 HORN BRACKET	\$	<i>R</i> 40.45
22	1 HEADLAMP LH	\$	<i>Sm</i> 1,184.43
23	1 HEADLAMP RH	\$	<i>M3CM</i> 1,184.43 ✓
24	1 HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
25	1 HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
26	1 BONNET	\$	<i>R</i> 1,941.63 X
27	1 BONNET INSULATOR	\$	<i>Sm</i> 405.73 X
28	1 BONNET STRUT LH	\$	<i>Sm</i> 88.61 X
29	1 BONNET STRUT RH	\$	<i>Sm</i> 88.61 X
30	1 BONNET HINGE LH	\$	<i>R</i> 348.31 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5589U**AAD1801-013**

31	1 BONNET HINGE RH	\$	K	348.31	X
32	1 BONNET LOCK	\$	K	305.48	X
33	1 BONNET CABLE	\$	Sm	119.19	X
34	1 BONNET CABLE COVER	\$	Sm	161.03	X
35	1 BONNET SEAL OUTER	\$	Sm	92.36	X
36	1 BONNET SEAL INNER	\$	Sm	157.28	X
37	1 FENDER PANEL FRT LH	\$	K	783.83	X
38	1 FENDER PANEL FRT RH	\$	Bz	783.83	✓
39	1 WHEELARCH FRT LH	\$	Sm	278.84	X
40	1 WHEELARCH FRT RH	\$	CM	278.84	✓
41	1 FENDER BRACKET LOWER LH	\$	Sm	15.79	X
42	1 FENDER BRACKET LOWER RH	\$	Sm	15.79	X
43	1 FENDER INSULATOR LH	\$	Sm	130.84	X
44	1 FENDER INSULATOR RH	\$	Sm	130.84	X
45	1 WIPER RESERVOIR	\$	De	348.25	✓
46	1 WIPER RESERVOIR NECK	\$	Sm	136.11	} X
47	1 WIPER RESERVOIR MOTOR	\$	Sm	270.06	
48	1 AIR CLEANER LOWER	\$	Sm	271.26	
49	1 AIR CLEANER HOSE	\$	Sm	76.14	
50	1 AUTO COMPUTER	\$	Sm	5,032.17	
51	1 STEERING PUMP ELECTRIC	\$	Sm	2,306.90	
52	1 STEERING PINION RACK	\$	Sm	4,413.11	
53	1 ENGINE HARNESS	\$	Sm	4,084.54	
54	1 SUBFRAME OUTER FRT	\$	Sm	2,652.45	
55	1 SUBFRAME BRACKET OUTER LH	\$	K	92.36	
56	1 SUBFRAME BRACKET OUTER RH	\$	K	92.36	
57	1 ENGINE UNDERTRAY	\$	Sm	564.98	
58	1 A/C CONDENSER	\$	Sm	2,020.37	
59	1 A/C CONDENSER GARNISH LH UPPER	\$	Sm	39.67	
60	1 A/C CONDENSER GARNISH RH UPPER	\$	Sm	39.67	
61	1 A/C CONDENSER GARNISH LH	\$	Sm	58.81	
62	1 A/C CONDENSER GARNISH RH	\$	Sm	59.60	
63	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	Sm	208.39	
64	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sm	658.72	
65	1 A/C PIPE COMPRESSOR	\$	Sm	334.29	
66	1 A/C PIPE	\$	Sm	658.72	
67	1 A/C COMRPESSOR	\$	Sm	2,684.61	
68	1 AIR COOLER	\$	Sm	792.60	
69	1 AIR INTERCOOLER HOSE (LONG)	\$	Sm	1,014.13	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5589U

AAD1801-013

70	1 AIR INTERCOOLER HOSE (Short)	\$	S _h	375.14	}
71	1 TRANSMISSION COOLER	\$	S _h	1,219.30	
72	1 TRANSMISSION COOLER PAD	\$	S _h	17.96	
73	1 RADIATOR	\$	S _h	1,202.20	
74	2 RADIATOR STUD UPPER	\$	S _h	14.41	
75	2 RADIATOR BUSH UPPER	\$	S _h	50.12	
76	2 RADIATOR MTG LOWER	\$	S _h	55.85	
77	1 RADIATOR FAN COWLING	\$	S _h	820.54	
78	1 RADIATOR FAN MOTOR LH	\$	S _h	967.36	
79	1 RADIATOR FAN MOTOR RH	\$	S _h	1,479.46	
80	1 RADIATOR TANK	\$	S _h	324.62	
81	1 RADIATOR HOSE UPPER	\$	S _h	240.56	
82	1 RADIATOR HOSE LOWER	\$	S _h	491.18	
83	1 RADIATOR TANK HOSE	\$	S _h	61.18	
84	1 WINDSCREEN FRT	\$	S _h	1,364.06	
85	1 INJECTION COMPUTER	\$	S _h	4,706.30	

TOTAL	\$	60,455.76
10%	\$	5,700.26
	\$	51,302.31

54410.18

Special Nett

1	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
2	1SET BUMPER CLIP FRT	\$	na	66.00	✓
3	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	}
4	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
5	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1 TOW COVER FRT	\$	S _h	14.50	
8	1SET RADIATOR GRILLE SCREW	\$	na	16.00	
9	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
10	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2 FRAME FULL SUPPORT PANEL STUD	\$	S _h	30.00	}
13	1SET WHEELARCH CLIP FRT LH	\$	na	30.50	
14	1SET WHEELARCH CLIP FRT RH	\$	na	29.40	
15	1 CAP HUB LH FRT	\$	S _h na	35.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5589U**AAD1801-013**

16	1 TYRE LH FRT	\$	<i>Sm</i>	<i>Pu</i>	330.00	<i>808sm</i>	X
17	1 CAP HUB RH FRT	\$		<i>Nu</i>	35.00		
18	1 RIM RH FRT	\$		<i>Nu</i>	385.00		
19	1 TYRE RH FRT	\$		<i>Pu</i>	330.00	<i>808sm</i>	
20	1SET Front licence plate with holder	\$		<i>Sm</i>	80.00		X
21	1 RIM LH FRT	\$		<i>Sm</i>	385.00		X
22	1SET NUMBER PLATE	\$		<i>Sm</i>	120.00		X
TOTAL		\$			2,142.40		
TOTAL PARTS		\$			53,444.71		

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 5,600.00 *400*

Towing Fees.

\$ 120.00 *50*

To apply paint protection system (PPS) maintain and enhancement

\$ *Nu* 380.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 *400 660*

To rust-proofing of the affected areas.

\$ 170.00 *30*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *Nu* 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 *60*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *20*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *Nu* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *Nu* 380.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5589U**AAD1801-013**

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To lift-up engine with gear box and refit.	\$	440.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

TOTAL \$ 16,940.00**Over All Total \$ 70,384.71**

< parts by parts > Repair Days

20 DAYS

2 1/2 days

75157.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD5589U - JASMINE
VF1ABL15AUC276797
RENAULT
LATITUDE
31.12.2017
III

SUPPLEMENTARY PART

LIST

30 1 DOOR MIRROR RH
31 1 DOOR MIRROR GLASS RH
32 1 DOOR MIRROR BACK COVER RH

\$ CM 1,483.40 ✓
\$ na 148.20 ✓
\$ na 218.46 ✓

TOTAL	\$	1,850.06
10%	\$	185.01
	\$	1,665.06

Specical Nett

TOTAL	\$	-
TOTAL PARTS	\$	1,665.06
TOTAL	\$	-
Over All Total	\$	1,665.06

Repair Days

0 Days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CC3/TP18000314/Kwb3n2		
NO.2 ANG MO KIO STREET 63 SINGAPORE 569111		Date : 26-02-2018		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SHD 5589U	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		04/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC276797	Colour	METALLIC WHITE / RED	
Odometer	663285	Steering	JAMMED	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	PRIMEWELL	9 mm	
L/H Front Tyre	215/60 R16	PRIMEWELL	9 mm	
R/H Rear Tyre	215/60 R16	LING LONG	6 mm	
L/H Rear Tyre	215/60 R16	LING LONG	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2017	Inspection Date	04/01/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5589U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	MISSING	181.75	181.75
1	BUMPER ABSORBER FRT	MISSING	394.68	394.68
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	CRACKED	150.77	150.77
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	DISTORTED	472.83	472.83
1	BUMPER GRILLE LOWER FRT	DENTED	266.80	266.80
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	MISSING	207.21	207.21
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-

Report Ref No. CC3/TP18000314/Kwb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	WHEELARCH FRT RH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	WIPER RESERVOIR	DENTED	348.25	348.25
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	STEERING PUMP ELECTRIC	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK	SERVICEABLE	4,413.11	-
1	ENGINE HARNESS	SERVICEABLE	4,084.54	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH	TO REPAIR SEE LABOUR	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-

Report Ref No. CC3/TP18000314/Kwb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	WINDSCREEN FRT	SERVICEABLE	1,364.06	-
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	DOOR MIRROR RH	CRACKED	1,483.40	1,483.40
1	DOOR MIRROR GLASS RH	NOT NECESSARY	148.20	-
1	DOOR MIRROR BACK COVER RH	NOT NECESSARY	218.46	-
	LESS 10% DISCOUNT		-6,230.58	-716.36
			56,075.24	6,447.26
	<u>SPECIAL NETT ITEMS</u>			
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-

Report Ref No. CC3/TP18000314/Kwb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	SERVICEABLE	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	SET WHEELARCH CLIP FRT RH (SN)	NECESSARY	29.40	29.40
1	CAP HUB LH FRT (SN)	SERVICEABLE	35.00	-
1	TYRE LH FRT (SN)	SERVICEABLE	330.00	-
1	CAP HUB RH FRT (SN)	DENTED	35.00	35.00
1	RIM RH FRT (SN)	DENTED	385.00	385.00
1	TYRE RH FRT (80%)(SN)	PUNCTURE	330.00	264.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	RIM LH FRT (SN)	SERVICEABLE	385.00	-
1	SET NUMBER PLATE (SN)	SERVICEABLE	120.00	-
			2,142.40	779.40
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL,HORN BRACKET,HEADLAMP PANEL FRT LH,HEADLAMP PANEL FRT RH,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,FENDER PANEL FRT LH,SUBFRAME BRACKET OUTER LH AND SUBFRAME BRACKET OUTER RH.		5,600.00	400.00
	TOWING FEES.		120.00	50.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.		170.00	20.00

Report Ref No. CC3/TP18000314/Kwb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			16,940.00	1,240.00
	GRAND TOTAL		75,157.64	8,466.66
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CC3/TP18000314/Kwb3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.