

Shenini

CC 3/1111800

0216, Fwbbg

Surveyor:

Fennetu

DOI:

4/1/18

Date / Time:

4/1/18

Registered in Merimen:

5/1/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 1652B

Name of Insured : LTEL

Insured Tel No. : HP:

Excess Sec II :SS D.O.A : 21/1/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO. Driver Name / Age : RBO TRUB B MUSTAPA

Driver Tel No. : (V/L: YES / NO)

Claim No. : MCT1311067

Policy No. : MCOM0016

Make / Model : TOYOTA

Place of Accident : WURUH ST CROSS WURUH

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability : % Final ? Yes / No

SHD 1187



INSRS:

WSP:

Tel :

Liability :

RMKS:

Trans Cab



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date / Time

8/1/18

union

11/1/18

11/1/18

11/1/18

SHD 1187 - 4/1/18 11/1/18 11/1/18

SHC 1652B - X

Seek liability under not merimen

Receive video from TP, reject TP claim

Email to workshop reject claim. TP cut into O.D's lane

RECEIVED 15 JAN 2018

V. V. 11-01-18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

reject 10/1

\$450.00

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF: 711 /


ASSIGNMENT

Heinrich

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MY
 To Inspect Vehicle No: _____
 at Workshop m/s: Trans Cob
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 121 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
5/11	Mk pass to Corrine
	82810:62 with 2 working days

Veh No: S110 218E Yr Regn: 10, 15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perout Latitude cc 1995
 Colour: M. White / Red A/C: Insured / Std / NI / NA
 Sp. Reading: 372104 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VEIABL15AUC 281615

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: Prime Well 215/60R16
 R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

R/Bal: 9 mmL/Bal: 9 mmD.O.A. 31/12/17

Rear

R/Bal: 9 mmL/Bal: 9 mmD.O.I. 4/1/18

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1)

Data/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Phone

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

(Ref: # 21551-11)
 8871)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC3/III18000316/Kwb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 05-01-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1652B		Veh. Inspected	SHD 218Z
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	05/01/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	31/12/2017		Inspection Date
				04/01/2018
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 218Z**AAD1801-047**

Not Authored
1.B1
Resony B4 paint 8 29/10/02

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 218Z

VF1ABL15AUC281615

RENAULT

LATITUDE

31.12.2017

III**PART****LIST**

1 FENDER PANEL FRT RH	\$	<i>Bz</i> 783.83	✓
2 FENDER BRACKET LOWER RH	\$	<i>Sm</i> 15.79	}
3 FENDER BRACKET FRT RH	\$	<i>Sm</i> 13.02	
4 WHEELARCH FRT RH	\$	<i>Sm</i> 278.84	
5 FENDER INSULATOR RH	\$	<i>Sm</i> 130.84	
6 DOOR PANEL FRT RH	\$	<i>Mc</i> 2,844.66	
7 DOOR HINGE UPPER RH	\$	<i>Mc</i> 261.28	
8 DOOR HINGE LOWER RH	\$	<i>Mc</i> 300.55	
9 DOOR CHECK FRT RH	\$	<i>Sm</i> 194.77	
10 DOOR CHECK BOLT	\$	<i>Sm</i> 22.69	
11 DOOR LOCK FRT RH	\$	<i>Mc</i> 908.75	
12 DOOR CATCH FRT RH	\$	<i>Sm</i> 131.23	} X
13 DOOR HANDLE OUTER FRT RH	\$	<i>Sm</i> 477.76	
14 DOOR HANDLE COVER FRT RH	\$	<i>Sm</i> 13.22	
15 DOOR HANDLE MODULE FRT RH	\$	<i>Sm</i> 133.60	
16 DOOR REGULATOR FRT RH	\$	<i>Sm</i> 505.19	
17 DOOR REGULATOR MOTOR FRT RH	\$	<i>Sm</i> 796.46	
18 DOOR REGULATOR GUIDE FRT RH	\$	<i>Sm</i> 120.97	
19 DOOR GLASS FRT RH	\$	<i>Sm</i> 625.96	
20 DOOR FINISHER FRT RH	\$	<i>Sm</i> 515.06	
21 DOOR MOULDING FRT RH	\$	<i>Sm</i> 176.82	
22 DOOR FINISHER CLIP KIT FRT RH	\$	<i>Sm</i> 90.97	
23 DOOR CASING FRT RH	\$	<i>Sm</i> 1,509.06	
24 DOOR CASING LIGHT	\$	<i>Sm</i> 82.49	
25 DOOR GRAB HANDLE FRT RH	\$	<i>Sm</i> 210.96	
26 DOOR MIRROR RH	\$	<i>Sm</i> 1,725.73	
27 DOOR WEATHERSTRIP FRT RH	\$	<i>Sm</i> 410.27	
28 DOOR SEAL LOWER FRT RH	\$	<i>Sm</i> 91.17	
29 DOOR GLASS RUNNER SEAL FRT RH	\$	<i>Sm</i> 626.36	
30 DOOR WAIST SEAL OUTER FRT RH	\$	<i>Sm</i> 291.27	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 218Z

31 DOOR WAIST SEAL INNER FRT RH	\$	122.15 X
32 BUMPER COVER FRT	\$	1,259.42 ✓
33 BUMPER SPOILER FRT	\$	181.75 X
34 BUMPER ABSORBER FRT	\$	394.68 X
35 BUMPER SUPPORT FRT	\$	123.88 X
36 BUMPER RETAINER FRT RH	\$	150.77 ✓
37 BUMPER SUPPORT FRT	\$	123.88 X
38 BUMPER UNDERTRAY FRT	\$	472.83 X
39 BUMPER GRILLE LOWER FRT	\$	266.80 X
40 BUMPER FOG LAMP GRILLE RH	\$	207.21 X
41 BUMPER BEAM FRT	\$	914.08 X

TOTAL	\$	18,507.04
10%	\$	1,850.70
	\$	16,656.34

Special Nett

1SET	DOOR CASING CLIP	\$	12.63 X
1SET	DOOR HINGE BOLT	\$	10.85 X
1SET	DOOR HINGE NUT RH	\$	14.60 X
1SET	DOOR HANDLE CAP FRT RH	\$	35.52 X
1SET	DOOR HANDLE SEAL FRT RH	\$	7.89 X
1SET	DOOR HANDLE SEAL REAR RH	\$	7.89 X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00 X
1	Front Door sticker 'Trans-cab'	\$	80.00 X
1	Front Door sticker 'Chassis'	\$	30.00 X
1SET	BUMPER CLIP FRT	\$	66.00 ✓
1	BUMPER BRACKET CLIP FRT LH	\$	12.00 X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50 X
1	BUMPER BRACKET CLIP FRT RH	\$	12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50 X

TOTAL \$ 345.40**GRAND TOTAL \$ 17,001.73**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 218Z

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	400
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	400
To Rust-Proofing Of The Affected Areas.	\$	170.00	30
To transfer of door fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
TOTAL	\$	7,460.00	
Over All Total	\$	24,461.73	

LKK Auto Consultants hence notify
(PARTS BY PARTS)
Repair Days

- To resurvey vehicle after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10-Days

2 days

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD218Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	03 Jan 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002760
Chassis No.:	VF1ABL15AUC281615
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	02 Oct 2015
First Registration Date:	02 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Oct 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	

COE Expiry Date:	01 Oct 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,439.00
COE Rebate Amount:	\$32,627.00
Total Rebate Amount:	\$47,625.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jan 2018

OK

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Thursday, 11 January, 2018 3:12 PM
To: 'Jasmine Tan'; 'Zhe Wei'; 'Ng Wai Yin'; 'claims@transcab.com.sg'
Cc: Zayyer (LKKAUTO)
Subject: Your Ref: SHD 218Z, Our Ref: CC3/III18000316/Kwb3, Accident on 31/12/2017 involving SHD 218Z & SHC 1652B
Attachments: SHC 1652B.MP4; Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: SHD 218Z
Our Ref: CC3/III18000316/Kwb3

Dear Sir/Madam,

Accident on 31/12/2017 involving SHD 218Z & SHC 1652B

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client encroach into OID's lane

We attached herewith our insured's accident report and your client's accident video for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

As such, we will close the matter at our end.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SHD218Z (MCT17121067)
[SHC16528]**

TP

TRANS-CAB SERVICES PTE LTD
Dec 31 2017 10:00AM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/01/2018 14:36 PM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SHD218Z - Claim Handler: Sherini Pillai

Maintained: Video shows TP encroaching into OI's lane. To reject claim.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Jan 2018 Edit Reg		04 Jan 2018 00:00 Edit Adj Rpt	S\$2,910.62 Edit Estimates	S\$2,910.62 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD218Z	Date of Loss:	31/12/2017 10:00 - :59
Claim Type:	TP / MCT17121067	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHC1652B	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/01/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (11/01/2018): Alert - Adj Mandate Maintained - SHD218Z - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD218Z (MCT17121067)
[SHC1652B]
TP
TRANS-CAB SERVICES PTE LTD
Dec 31 2017 10:00AM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

ViewView in Browser

Video

1 per page

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/01/18 14:36	Video - IV	Load MP4	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/01/18 14:59	TP ESTIMATE- MARKED	Load PDF	
2	05/01/18 14:59	TP GIA REPORT	Load PDF	
3	11/01/18 15:12	Email to wkshop reject claim	Load PDF	
4	15/01/18 11:37	LKK INSPECTION PHOTOS	Load PDF	

No

Finalized On

India International Insurance Pte Ltd (HQ)

Thumbnail

Print

1	08/01/18 08:58	Singapore Accident Statement	Load PDF	
---	----------------	------------------------------	----------	--

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18000316/KWB3Q2

Date: 19/01/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No: SHD218Z

Insured Vehicle No: SHC1652B

Date of Loss: 31/12/2017

Nature of Claim: TP

Claim No: MCT17121067

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD218Z

Make & Model: RENAULT LATITUDE, 2.0 L (A)

Engine No: M9R8839C002760

Reg. Date: 02/10/2015 (Man. Year: 2015)

Chassis No: VF1ABL15AUC281615

Colour: Metallic White/Red

Odometer: 372104 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Primewell 9 mm

Rear Left Side: Linglong 9 mm

Front Right Side: Primewell 9 mm

Rear Right Side: Linglong 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,001.70	2,040.62	14,961.08	88.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,460.00	870.00	6,590.00	88.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,461.70	2,910.62	21,551.08	88.10
+ GST 7.00/7.00% (S\$)	1,712.32	203.74	1,508.58	88.10
Nett Amount (S\$)	26,174.02	3,114.36	23,059.66	88.10

INSPECTION

Date of Assignment: 04/01/2018

Date Inspected: 04/01/2018 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2018)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD218Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
2	1		*FENDER BRACKET LOWER RH	Serviceable	15.79 FL	*- FL
3	1		*FENDER BRACKET FRT RH	Serviceable	13.02 FL	*- FL
4	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
5	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
6	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
7	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*- FL
8	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
9	1		*DOR CHECK FRT RH	Serviceable	194.77 FL	*- FL
10	1		*DOOR CHECK BOLT	Serviceable	22.69 FL	*- FL
11	1		*DOOR LOCK FRT RH	Repair	908.75 FL	*- FL
12	1		*DOOR CATCH FRT RH	Serviceable	131.23 FL	*- FL
13	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*- FL
14	1		*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	*- FL
15	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
16	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	*- FL
17	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*- FL
18	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*- FL
19	1		*DOOR GLASS FRT RH	Serviceable	625.96 FL	*- FL
20	1		*DOOR FINISHER FRT RH	Serviceable	515.06 FL	*- FL
21	1		*DOOR MOULDING FRT RH	Serviceable	176.82 FL	*- FL
22	1		*DOOR FINISHER CLIP KIT FRT RH	Not Necessary	90.97 FL	*- FL
23	1		*DOOR CASING FRT RH	Serviceable	1,509.06 FL	*- FL
24	1		*DOOR CASING LIGHT	Serviceable	82.49 FL	*- FL
25	1		*DOOR GRAB HANDLE FRT RH	Serviceable	210.96 FL	*- FL
26	1		*DOOR MIRROR RH	Serviceable	1,725.73 FL	*- FL
27	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	410.27 FL	*- FL
28	1		*DOOR SEAL LOWER FRT RH	Serviceable	91.17 FL	*- FL
29	1		*DOOR GLASS RUNNER SEAL FRT RH	Serviceable	626.36 FL	*- FL
30	1		*DOOR WAIST SEAL OUTER FRT RH	Serviceable	291.27 FL	*- FL
31	1		*DOOR WAIST SEAL INNER FRT RH	Serviceable	122.15 FL	*- FL
32	1		*BUMPER COVER FRT	Buckled	1,259.42 FL	*1,259.42 FL
33	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	*- FL
34	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
35	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
36	1		*BUMPER RETAINER FRT RH	Distorted	150.77 FL	*150.77 FL
37	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
38	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
39	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
41	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
42	1		*SET DOOR CASING CLIP	Not Necessary	12.63 FS	*- FS
43	1		*SET DOOR HINGE BOLT	Serviceable	10.85 FS	*- FS
44	1		*SET DOOR HINGE NUT RH	Serviceable	14.60 FS	*- FS
45	1		*SET DOOR HANDLE CAP FRT RH	Serviceable	35.52 FS	*- FS
46	1		*SET DOOR HANDLE SEAL FRT RH	Not Necessary	7.89 FS	*- FS
47	1		*SET DOOR HANDLE SEAL REAR RH	Not Necessary	7.89 FS	*- FS
48	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
49	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
50	1		*FRONT DOOR STICKER CHASSIS	Not Necessary	30.00 FS	*- FS
51	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
52	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
53	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
54	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
55	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,852.40	2,260.02
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,850.70	219.40
Total Parts (\$\$)	17,001.70	2,040.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
6	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
8	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			7,460.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >