

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 218Z****AAD1801-047**

*Not Authored*  
*1.B1 8 1862.78*  
*Resony B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 218Z**

VF1ABL15AUC281615

RENAULT

LATITUDE

31.12.2017

**III****PART****LIST**

|                                  |    |                         |     |
|----------------------------------|----|-------------------------|-----|
| 1 FENDER PANEL FRT RH            | \$ | B <sub>1</sub> 783.83   | ✓   |
| 2 FENDER BRACKET LOWER RH        | \$ | S <sub>2</sub> 15.79    | } X |
| 3 FENDER BRACKET FRT RH          | \$ | S <sub>2</sub> 13.02    |     |
| 4 WHEELARCH FRT RH               | \$ | S <sub>2</sub> 278.84   |     |
| 5 FENDER INSULATOR RH            | \$ | S <sub>2</sub> 130.84   |     |
| 6 DOOR PANEL FRT RH              | \$ | K 2,844.66              |     |
| 7 DOOR HINGE UPPER RH            | \$ | K 261.28                |     |
| 8 DOOR HINGE LOWER RH            | \$ | K 300.55                |     |
| 9 DOOR CHECK FRT RH              | \$ | S <sub>2</sub> 194.77   |     |
| 10 DOOR CHECK BOLT               | \$ | S <sub>2</sub> 22.69    |     |
| 11 DOOR LOCK FRT RH              | \$ | K 908.75                |     |
| 12 DOOR CATCH FRT RH             | \$ | S <sub>2</sub> 131.23   |     |
| 13 DOOR HANDLE OUTER FRT RH      | \$ | S <sub>2</sub> 477.76   |     |
| 14 DOOR HANDLE COVER FRT RH      | \$ | S <sub>2</sub> 13.22    |     |
| 15 DOOR HANDLE MODULE FRT RH     | \$ | S <sub>2</sub> 133.60   |     |
| 16 DOOR REGULATOR FRT RH         | \$ | S <sub>2</sub> 505.19   |     |
| 17 DOOR REGULATOR MOTOR FRT RH   | \$ | S <sub>2</sub> 796.46   |     |
| 18 DOOR REGULATOR GUIDE FRT RH   | \$ | S <sub>2</sub> 120.97   |     |
| 19 DOOR GLASS FRT RH             | \$ | S <sub>2</sub> 625.96   |     |
| 20 DOOR FINISHER FRT RH          | \$ | S <sub>2</sub> 515.06   |     |
| 21 DOOR MOULDING FRT RH          | \$ | S <sub>2</sub> 176.82   |     |
| 22 DOOR FINISHER CLIP KIT FRT RH | \$ | K 90.97                 |     |
| 23 DOOR CASING FRT RH            | \$ | S <sub>2</sub> 1,509.06 |     |
| 24 DOOR CASING LIGHT             | \$ | S <sub>2</sub> 82.49    |     |
| 25 DOOR GRAB HANDLE FRT RH       | \$ | S <sub>2</sub> 210.96   |     |
| 26 DOOR MIRROR RH                | \$ | S <sub>2</sub> 1,725.73 |     |
| 27 DOOR WEATHERSTRIP FRT RH      | \$ | S <sub>2</sub> 410.27   |     |
| 28 DOOR SEAL LOWER FRT RH        | \$ | S <sub>2</sub> 91.17    |     |
| 29 DOOR GLASS RUNNER SEAL FRT RH | \$ | S <sub>2</sub> 626.36   |     |
| 30 DOOR WAIST SEAL OUTER FRT RH  | \$ | S <sub>2</sub> 291.27   |     |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 218Z**

|                                 |    |                      |
|---------------------------------|----|----------------------|
| 31 DOOR WAIST SEAL INNER FRT RH | \$ | <i>Pr</i> 122.15 X   |
| 32 BUMPER COVER FRT             | \$ | <i>Bu</i> 1,259.42 ✓ |
| 33 BUMPER SPOILER FRT           | \$ | <i>Pr</i> 181.75 X   |
| 34 BUMPER ABSORBER FRT          | \$ | <i>Pr</i> 394.68 X   |
| 35 BUMPER SUPPORT FRT           | \$ | <i>Pr</i> 123.88 X   |
| 36 BUMPER RETAINER FRT RH       | \$ | <i>Pr</i> 150.77 ✓   |
| 37 BUMPER SUPPORT FRT           | \$ | <i>Pr</i> 123.88 X   |
| 38 BUMPER UNDERTRAY FRT         | \$ | <i>Pr</i> 472.83 X   |
| 39 BUMPER GRILLE LOWER FRT      | \$ | <i>Pr</i> 266.80 X   |
| 40 BUMPER FOG LAMP GRILLE RH    | \$ | <i>Pr</i> 207.21 X   |
| 41 BUMPER BEAM FRT              | \$ | <i>Pr</i> 914.08 X   |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>18,507.04</b> |
| <b>10%</b>   | <b>\$</b> | <b>1,850.70</b>  |
|              | <b>\$</b> | <b>16,656.34</b> |

**Special Nett**

|      |                                |    |                   |
|------|--------------------------------|----|-------------------|
| 1SET | DOOR CASING CLIP               | \$ | <i>Pr</i> 12.63 X |
| 1SET | DOOR HINGE BOLT                | \$ | <i>Pr</i> 10.85 X |
| 1SET | DOOR HINGE NUT RH              | \$ | <i>Pr</i> 14.60 X |
| 1SET | DOOR HANDLE CAP FRT RH         | \$ | <i>Pr</i> 35.52 X |
| 1SET | DOOR HANDLE SEAL FRT RH        | \$ | <i>Pr</i> 7.89 X  |
| 1SET | DOOR HANDLE SEAL REAR RH       | \$ | <i>Pr</i> 7.89 X  |
| 1SET | FENDER WHEELARCH REAR RH CLIP  | \$ | <i>Pr</i> 35.00 X |
| 1    | Front Door sticker 'Trans-cab' | \$ | <i>Pr</i> 80.00 X |
| 1    | Front Door sticker 'Chassis'   | \$ | <i>Pr</i> 30.00 X |
| 1SET | BUMPER CLIP FRT                | \$ | <i>Pr</i> 66.00 ✓ |
| 1    | BUMPER BRACKET CLIP FRT LH     | \$ | <i>Pr</i> 12.00 X |
| 1    | BUMPER SUPPORT CLIP FRT LH     | \$ | <i>Pr</i> 10.50 X |
| 1    | BUMPER BRACKET CLIP FRT RH     | \$ | <i>Pr</i> 12.00 X |
| 1    | BUMPER SUPPORT CLIP FRT RH     | \$ | <i>Pr</i> 10.50 X |

|              |           |               |
|--------------|-----------|---------------|
| <b>TOTAL</b> | <b>\$</b> | <b>345.40</b> |
|--------------|-----------|---------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>GRAND TOTAL</b> | <b>\$</b> | <b>17,001.73</b> |
|--------------------|-----------|------------------|

## Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 218Z**

|                                                                                                                           |    |          |     |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|-----|
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 3,000.00 | 400 |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 2,800.00 | 400 |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | 170.00   | 300 |
| To transfer of door fittings, attachments and perform water seepage test.                                                 | \$ | 170.00   | X   |
| To repair and realign rear exhaust pipe.                                                                                  | \$ | 170.00   | X   |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | 380.00   | X   |
| To transfer of rear fender fittings, attachment and perform water seepage test.                                           | \$ | 380.00   | X   |
| To transfer of rear windscreen fittings and conduct water seepage test.                                                   | \$ | 170.00   | X   |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00   | X   |

**TOTAL \$ 7,460.00**

**Over All Total \$ 24,461.73**

LKK Auto Consultants hence notify  
(PARTS BY PARTS)  
Repair Days

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

10-Days  
2 days