



SLC2397J

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : ECICS
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 3/1/2018

Vehicle Reg. No. : SLC2397J
Vehicle Reg. Date: 5-May-2016
Make / Model : VEZEL 1.5X CVT ABS D/AII
Engine No. : L15B4034719
Chassis No. : RU11114710

COST OF CLAIMS

Parts Cost / List Items : \$ 18,059.70
Plus/Less 20% \$ 3,611.94
Total Cost / List : \$ 14,447.76
Special Nett Items : \$ 1,080.00
Total Parts Amount : \$ 15,527.76
Total Labour Amount : \$ 5,220.00
Gross Total : \$ 20,747.76
GST % : 7% \$ 1,452.34
Nett Amount : \$ 22,200.10

Surveyor Name and Company :

Rasul CLKK

Date of survey : 05/01/18 @ 1740

Part by Part / Lump Sum : 5 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : rasul@lkkauto.com

Fax No : _____

HP No : 90010068

This claim is handled by : Edmond

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC2397J**
 Vehicle Reg. Date: **5/5/2016**
 Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **L15B4034719**
 Chassis No. : **RU11114710**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	OK /	\$ 1,860.00		
2	1	Tailgate outer garnish	X	\$ 285.00		
3	1 set	Tailgate outer garnish clips	X	\$ 40.00		
4	1	Tailgate logo	na /	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	na /	\$ 56.20		
6	2	Tailgate lamp LH/RH	X	\$ 980.00		
7	2set	Tailgate lamp clips	X	\$ 50.00		
8	1	Tailgate outer handle switch	X	\$ 180.00		
9	2	Tailgate damper LH/RH	X	\$ 424.00		
10	1	Tailgate wiper motor	X	\$ 250.00		
11	1	Tailgate wiper blade	X	\$ 75.00		
12	1	Tailgate buzzer	X	\$ 150.00		
13	1	Tailgate inner handle	X	\$ 74.00		
14	1	Tailgate inner lock	OK /	\$ 245.00		
15	1	Tailgate lock sensor	X	\$ 220.00		
16	1	Tailgate striker	X	\$ 32.00		
17	1	Tailgate trimboard	X	\$ 295.00		
18	1 set	Tailgate trimboard clips	X	\$ 45.00		
19	1	Tailgate weatherstrip	OK /	\$ 145.00		
20	1 set	Tailgate windscreen moulding	na /	\$ 164.00		
21	2	Tail lamp LH/RH	X	\$ 978.00		
22	1set	Tail lamp clips	X	\$ 36.00		
23	1	Rear bumper	OK /	\$ 950.00		
24	1set	Rear bumper clips	na /	\$ 50.00		
25	2	Rear bumper retainer LH/RH	OK /	\$ 144.00		
26	2	Rear bumper bracket LH/RH	OK /	\$ 232.00		
27	2	Rear bumper reflector LH/RH	X	\$ 334.00		
28	2	Rear bumper cover LH/RH	LH-X / RH-?	\$ 420.00	A70	
29	1set	Rear bumper cover clips	X	\$ 50.00		
30	2	Rear bumper cover retainer LH/RH	X	\$ 84.00		
31	1	Rear end panel outer	X	\$ 585.00		
32	1	Rear end panel inner	X	\$ 396.00		
33	1	Rear end panel top garnish	?	\$ 184.00		
34	1set	Rear end panel top garnish clips	OK /	\$ 25.00		
35	1	Spare tyre panel	X	\$ 1,230.00		
36	1	Spare tyre panel insulator	X	\$ 240.00		
37	1	Spare tyre panel top board	X	\$ 420.00		
38	1	Spare tyre tool tray	X	\$ 430.00		
39	1	EDLC module	X	\$ 1,750.00		
40	2	Rear fender panel LH/RH	X	\$ 1,900.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC2397J**

Vehicle Reg. Date: **5/5/2016**

Make / Model : **VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR**

Engine No. : **L15B4034719**

Chassis No. : **RU11114710**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	2	Rear fender arch garnish LH/RH	X	\$ 330.00		
42	1set	Rear fender arch garnish clips	X	\$ 50.00		
43	2	Rear fender inner water shield LH/RH	X	\$ 320.00		
44	1set	Rear fender inner water shield clips	X	\$ 50.00		
45	2	Rear fender Air duct LH/RH	X	\$ 150.00		
46	1	Exhaust muffler	X	\$ 855.00		
47	1	Exhaust muffler mounting	X	\$ 79.50		
48	1	Exhaust muffler heat shield	X	\$ 165.00		
49	1	Rear number plate with frame	X		\$ 50.00	
50	1	Tailgate windscreen sealant	new?		\$ 80.00	100
51	1	Tailgate windscreen inner seal	new?		\$ 80.00	
52	1	Rear end panel sealant	X		\$ 80.00	
53	1	Reverse sensor	X		\$ 300.00	220
54	1	Spare tyre panel sealant	X		\$ 80.00	
55	1	Spare tyre panel padding	X		\$ 350.00	
56	1	Sundries			\$ 60.00	20
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]