

LOH HENG

Automotive Repair Services
Accident Insurance Claims

05 Jan 2018

India International Insurance Pte Ltd

64 Cecil st. #04/#05

IOB Building Singapore 901438

Attn. : Motor Claim Department

Re : 1 Quotation

Vehicle No. : SGS459C (Nissan Latio)

S/N	Description	Amount (S\$)
	Parts Replacement	
	Rear bumper Bu	\$ 683.20
	Rear tail lamp CM	\$ 376.10
	Rear bumper retainer Dis	\$ 28.60
		\$ 1,087.90
	less 25% 30%	\$ 815.90
	Labour Charges	
	To remove and replace new parts	\$ 680.00
	To putty and spray paint on rear affected damaged are and the affected area.	\$ 650.00
	Total:	\$ 2,145.90

Not Authorized
Lily 81200
Resony After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare

Sin Ming Drive

Singapore 575721

Tel : 64532237 / 64530797

Fax : 64556384