

INS. CASE OWNER:

Yusoff

CC 4/AIG18000334

1 SKS3 9

LKK:

IDAC

Surveyor:

Sebastian

DOI:

ASSIGNMENT

09.01.2018

Date / Time:

05/01/18

Registered in Merimen:

05/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKF 85042

Claim No.:

0130941974 SG

Name of Insured:

CHINA SOUTHERN AIRLINES COMPANY

Policy No.:

2100207049

Insured Tel No.:

HP: 9338 2139

Make / Model:

HYUNDAI ELANTRA - 1.6 (A7)

Excess Sec II : \$5

D.O.A: 30/12/17

Place of Accident:

GATEWAY LINC

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: ZHANG QIU JING

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: 9338 2139

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

91CB 9824R



INSRS:

WSP: Long sheng motor

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
02/01/18 (Zam)	Non-Reporting 1st:	
08.01.2018 @ 1.42pm	Non-Reporting 1st (2nd):	
	Non-Reporting 1st (Final):	
	Notification 1st (if non-pickup):	
	Call OI:	2. 05/01/2018
	After call 1st to OI:	
	Documentation Check List:	Handler Typist
	Notification 1st (if non-pickup):	
	After call 1st to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

ELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$5	( days) Reduction: %
FINAL SETTLEMENT	Date/Time: 29.01.2018	Confirm with: APPLIC
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.: NIL
Repair Cost:	\$5 6,250.00	
Loss of Rental (LOR):	\$5 720.00	( 6 days) x 120.00
Loss of Use (LOU):	\$5 --	( 5 x days)
Loss of Income (LOI):	\$5 --	( 5 x days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		[Tick only one]
GIA/LTA Search	\$5 2.00	
Medical:	\$5 --	
Reimbursement: (w/lost)	\$5 85.60	(e.g./Tow/Independent)
Total Cost:	\$5 --	
Total:	\$5 7,057.60	Global Sum \$5: 7,050.00
FINAL PAYMENT	Date/Time: 29.01.2018	Confirm with: APPLIC
Payee 1:	\$5 7,050.00	Name 1: Long Sheng Motor Service
Payee 2: (Strike if N.A.)	\$5 --	Name 2:
Payee 3: (Strike if N.A.)	\$5 --	Name 3:

COPY SENT  
06/02/18

REF:

Atg

18000714 / Sk53

## ASSIGNMENT

From:

Date:

09.01.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKB 9884K

at Workshop no:

Long Sheng

of

Blk 6 No. 399A New Teo Ind Est

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Morning

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKB 9884K

Yr Regn:

14/7/11

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Camry

CC

2362

Colour:

Black

A/C

Insured / Std / NI / NA

Sp Reading

160321

T Radio:

Insured / Std / NI / NA

Eng No:

C No:

MK053 BK 4207046399

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A / Rim or

Tyre Size:

F: 215/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MTC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

9/1/18

Survey held at

Long Sheng

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

(Lum: \$6,250.00 / Red: \$3,695.27 / 37%)

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp

\$

☐

Interview

\$

☐

Tech Insp

\$

☐

Witness

\$

Report Format:

Lump Sum / I.B.I. / S

Photos

Notes

TOTAL

Engine Capacity / Power Rating :	2362 cc / -
Maximum Power Output :	123.0 kW ( 164 bhp )
Propellant :	Petrol
Max Unladen Weight :	1540 kg
Maximum Laden Weight :	1970 kg
Open Market Value :	\$24,917.00
PARF Eligibility :	Yes
PARF Eligibility Expiry Date :	13 Jul 2021
Minimum PARF Benefit :	\$12,458.00
No. of Transfers :	0
IU Label No. :	1124261883
COE No. :	2011060103000362M
COE Expiry Date :	13 Jul 2021
COE Category :	B - Car (1601cc & above)
COE Registration Category :	B - Car (1601cc & above)
Quota Premium (QP) / Prevailing Quota Premium :	\$56,011.00 / -
Actual QP Paid :	\$56,011.00
QP (Regn Cat) :	\$56,011.00
OPC Cash Rebate Eligibility :	No
QP during COE Bidding Exercise :	\$56,011.00
Additional Registration Fee Rate :	100.00 %
Actual ARF Paid :	\$24,917.00
Vehicle Lifespan Expiry Date :	No Lifespan
CO2 Emission:	-
CO Emission:	-
HC Emission:	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18000334/Sks3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 05-01-2018		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKF 8504Z	Veh. Inspected	SKB 9884R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	30/12/2017	Inspection Date	09/01/2018	
Survey held at	LONG SHENG MOTOR SERVICE BLK 6, NO. 399-G, WOODLANDS RD YEW TEE IND. ESTATE SINGAPORE 678007.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# 龙胜汽车服务

## LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Date: 05.01.2018

Page 1/2

Owner: Teo Kang Hee

Attention: AIG Asia Pacific Insurance Pte.Ltd.

**RE: Accident to vehicle SKB9884R - Toyota Camry 2.4 Auto (2011) on 30.12.2017**

Estimated cost of repair of the above mentioned vehicle.

### Replacement Parts:-

1pcs	Rear Bumper R	\$	550.30
10pcs	Rear Bumper Clip @ 3.50 ✓ NCC	\$	35.00
1pcs	Rear Bumper Side Retainer ?	\$	55.30
1pcs	Rear Bumper Side Holder ?	\$	48.10
1pcs	Rear Fender RH ✓ DT	\$	920.10
1pcs	Rear Fender Inner Trim RH ?	\$	480.00
10pcs	Rear Fender Inner Trim Clip @ 5.10 ?	\$	51.00
1pcs	Rear Fender Dust Cover ?	\$	97.20
10pcs	Rear Fender Dust Cover Clip @ 3.50 ?	\$	28.00
1pcs	Rear Door RH ✓ DT	\$	1,055.10
1pcs	Rear Door Weatherstrip RH X	\$	189.10
1pcs	Rear Door Protector RH X	\$	115.30
1pcs	Rear Door Protector Moulding RH ✓ NCC	\$	51.60
1pcs	Rear Door Inner Trim Board RH X	\$	750.10
10pcs	Rear Door Inner Trim Board Clip @ X	\$	48.00
1pcs	Rocker Panel Garnish RH ✓ Deform	\$	390.10
1pcs	Rear Shock Absorber ✓ BT	\$	390.60
2pcs	Rear Lower Arm @ 271.60 ✓ BT	\$	543.20
1pcs	Rear Wheel Hub ✓ BMG	\$	790.10
1pcs	Rear Knuckle Arm ✓ BT	\$	491.60
1pcs	Rear Coil Spring ?	\$	390.80
1pcs	Rear Shock Absorber Mounting ?	\$	198.10
1pcs	Rear Axle ?	\$	1,323.10
1pcs	Alloy Rim ✓ cut	\$	481.90
		\$	9,473.70
	Less 25%	\$	(2,368.43)
		\$	7,105.27

### To Repair:

Rocker Panel

# 龙胜汽车服务 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Page 2/2

## SKB 9884R

B/Balance: \$ 7,105.27

## Special Nett:

1pcs	Rear Windscreen Sealant	✓ NEC	\$ 60.00	40
1set	Rear Tyre RH	✓ Bulge	\$ 220.00	200
			<u>\$ 280.00</u>	

## Add:

Spray Painting	\$ 850.00	750
Labour Charges	\$ 950.00	800
To Remove & Refit Boot Compartment Fitting	\$ 180.00	50
To Remove & Install Rear Windscreen	\$ 130.00	120
To Remove & Replace Rear Suspension Carry Out W/Alignment	\$ 450.00	300
	<u>\$ 2,560.00</u>	

Total Amount : \$ 9,945.27

Sebastian.  
9/1/18.  
- Lump Sum Repair.  
- Question mark Iron Photo  
- Photo After Paint  
90036121  
sebastian.gang@lkkauto.com

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# 龙胜汽车服务

## LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Date: 05.01.2018

Page 1/2

Owner: Teo Kang Hee

Attention: AIG Asia Pacific Insurance Pte.Ltd.

RE: Accident to vehicle SKB9884R - Toyota Camry 2.4 Auto (2011) on 30.12.2017

Estimated cost of repair of the above mentioned vehicle.

*24.1.18*

Replacement Parts:-

1pcs	Rear Bumper	R		\$	550.30	
10pcs	Rear Bumper Clip @ 3.50	✓ Nec.		\$	35.00	
1pcs	Rear Bumper Side Retainer	?	) NN	\$	55.30	
1pcs	Rear Bumper Side Holder	?		\$	48.10	
1pcs	Rear Fender RH	✓ BT		\$	920.10	
1pcs	Rear Fender Inner Trim RH	?	NN	\$	480.00	
10pcs	Rear Fender Inner Trim Clip @ 5.10	✓ Nec.		\$	51.00	
1pcs	Rear Fender Dust Cover	?	NN	\$	97.20	
10pcs	Rear Fender Dust Cover Clip @ 3.50	?	NN	\$	28.00	
1pcs	Rear Door RH	✓ BT		\$	1,055.10	
1pcs	Rear Door Weatherstrip RH	X	NN	\$	189.10	
1pcs	Rear Door Protector RH	X	NN	\$	115.30	
1pcs	Rear Door Protector Moulding RH	✓ Nec.		\$	51.60	
1pcs	Rear Door Inner Trim Board RH	X	) NN	\$	750.10	
10pcs	Rear Door Inner Trim Board Clip @	X		\$	48.00	
1pcs	Rocker Panel Garnish RH	✓ Deform		\$	390.10	
1pcs	Rear Shock Absorber	✓ BT		\$	390.60	
2pcs	Rear Lower Arm @ 271.60	✓ BT		\$	543.20	
1pcs	Rear Wheel Hub	✓ DMG		\$	790.10	
1pcs	Rear Knuckle Arm	✓ BT		\$	491.60	
1pcs	Rear Coil Spring	?	DMG	\$	390.80	
1pcs	Rear Shock Absorber Mounting	?	BT	\$	198.10	
1pcs	Rear Axle	?	REAR CROSS MEMBER BT	\$	1,329.10	
1pcs	Alloy Rim	✓ C2		\$	481.90	
1pcs	Idler arm		296.10	\$	9,473.70	
1pcs	Anti low Bar		391.60	\$	(2,368.43)	
			Less 25%	\$	7,105.27	

*1091.10*  
*350*  
*7,436.50*  
*- 25%*

To Repair:

Rocker Panel

*5572.57*

# 龙胜汽车服务 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate  
Singapore 678007

Tel: 67639733 Fax: 67639866  
Email: lsmstyc@singnet.com.sg

Page 2/2

SKB 9884R

B/Balance:

\$ 7,105.27

Special Nett:

1pcs Rear Windscreen Sealant ✓ NEC  
1set Rear Tyre RH ✓ ~~bulge~~ & h.c.

\$ 60.00 40  
\$ 228.00 200.  
\$ 280.00

Add:

Spray Painting  
Labour Charges  
To Remove & Refit Boot Compartment Fitting  
To Remove & Install Rear Windscreen  
To Remove & Replace Rear Suspension Carry Out W/Alignment

\$ 850.00 750  
\$ 950.00 800.  
\$ 180.00 40  
\$ 130.00 120  
\$ 450.00 200.  
\$ 2,560.00

1) Parts \$ 5577.37  
2) 3/Nett \$ 240.00  
3) Labour \$ 2020.00

7837.37  
Lump Sum - 207.  
6269.37

Total Amount : \$ 9,945.27

L/S: \$ 6250 @ 6 days

Sebastian.  
9/1/18.

- Lump Sum Repair.  
- Question mark Even Photo  
- Photo After Paint  
90036121

sebastian.gang@lksauto.com

6 days

LKX Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# 龙胜汽车服务 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate  
Singapore 678007 (Reg.No: 52840117C)  
Tel: 67639733 Fax: 67639866  
Email: lsmstyc@singnet.com.sg

Our Ref : SKB 9884R Date : 23.01.2018  
Your Ref: CC4/AIG18000334/ks3  
To : AIG Asia Pacific Insurance Pte.Ltd.  
AIG Building, 78 Shenton Way,  
Unit 09-16, Singapore 079120  
Attn : Zaini Kusaini (LKK Auto Case Handle)  
Remark : **Third Party Claim (TPPD)**

Dear Sirs,

Accident Involving Vehicle No: SKB 9884R & SKF 8504Z  
Along Junction Of Jurong Town Hall Road & Gateway Link  
On 30.12.2017 At 4:00:00 PM Hours  
We act for Teo Kang Hee, the owner of vehicle No. SKB 9884R was  
involved in the above accident on 30.12.2017 where your insured's vehicle No.  
SKF 8504Z is the sole cause of the accident.

I/We hereby claim for loss damages and expenses suffered.  
I/We append below our claim as follows;

Cost Of Repair * As Per Surveyor's Recommendation *	S \$ <u>6,250.00</u>
Loss Of Use	S <u>-</u>
Car Rental Fees ( 6 Days x S\$ 120.00 Per Days)	S \$ <u>720.00</u>
Survey Report Fees	S <u>-</u>
Towing Fees With GST 7%	S \$ <u>85.60</u>
L.T.A Search / Police Report Fees / GIA Search	S \$ <u>2.00</u>
Document Disbursements / Liability Contribution	S <u>-</u>
<b>Total</b>	<b>S \$ <u>7,057.60</u></b>

**SGD** **Seven Thousand And Fifty Seven Dollars Sixty Cents Only**

Enclosed please find copies of **Authorisation Letter / Long Sheng Invoice / Towing Receipt / Rental Agreement / Rental Invoice / Rental Receipt / GIA Search**.

Kindly let us hear from you within fourteen (14) days from the date hereof, or alternatively, let us have your full and final settlement of SGD \$ 7,057.60 of our claim, failing which our shall have to resort to legal actions to recover losses without further references to you.  
In that event, we shall also be claiming for legal costs and interests due to us.

Your Faithfully



Name Apple Sim  
Address Blk 6, No.399-G, Woodlands Road,  
Yew Tee Industrial Estate,  
Singapore 678007.

## Zaini (LKK Auto)

---

**From:** Zaini (LKK Auto)  
**Sent:** Monday, 29 January 2018 2:49 PM  
**To:** 'LSMTYC'  
**Cc:** Hsiao Tong (LKKAuto)  
**Subject:** RE: Accident Involving Vehicle No. SKB 9884R & SKF8504Z On 30.12.2017 \*LKK REF: CC4/AIG18000334/ks3  
**Attachments:** RV AIG SKB9884R 30122017.pdf

WITHOUT PREJUDICE

Dear Apple,

We refer to our previous tele-conversation.

We confirmed on the global sum settlement of **\$7,050.00 (all in).**

Attach DV for your necessary actions.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com) | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** LSMTYC [mailto:[lsmstyc@singnet.com.sg](mailto:lsmstyc@singnet.com.sg)]  
**Sent:** Tuesday, 23 January 2018 11:59 AM  
**To:** Zaini (LKK Auto) <[Zaini@lkkauto.com](mailto:Zaini@lkkauto.com)>  
**Subject:** RE: Accident Involving Vehicle No. SKB 9884R & SKF8504Z On 30.12.2017 \*LKK REF: CC4/AIG18000334/ks3

Dear Zaini ,

Our Ref: SKB 9884R

"WITHOUT PREJUDICE"

Your Ref: CC4/AIG18000334/ks3

Enclose herewith attached for your perusal.

Please let us have your DV & payment as soon as possible.

TQ

***Wishing you a happy Chinese new year  
Gong Xi Fa Cai***



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref:** CC4/AIG18000334/Sks3

15 JANUARY 2018

**CHINA SOUTHERN AIRLINES COMPANY**  
133 CECIL STREET  
#01-02 KECK SENG TOWER  
SINGAPORE 069535  
ATTN: HR / MANAGEMENT

Dear Sir/Madam,

**ACCIDENT INVOLVING SKF 8504Z AND SKB 9884R ON 30.12.2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

  
Zaini  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [Zaini@lkkauto.com](mailto:Zaini@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

To: Long Sheng Motor Service  
Singapore

RE: ACCIDENT INVOLVING VEHICLE NOS. SKB9884R + SKF8504Z  
ALONG/AT JUNCTION OF JURONG TOWN HALL ROAD + GATEWAY LINK  
ON 30.12.2017 @ 16:00 hrs


I/We TED KANG HEE (NRIC No. S6973511G)  
of 10 TAO CHING ROAD #02-23 SINGAPORE 618725  
the owner of vehicle No. SKB9884R hereby authorise you to commence repair of the  
said vehicle forthwith. In consideration of you repairing my/our vehicle at my/our request, I/We hereby  
authorise you to demand claim settle receive whatever amount settled/payable by the insurance company  
and/or third party or to commence legal proceedings, if necessary, in my name, for the cost of repairs and  
loss of use, etc and to you appointing any Solicitor to act for me in respect of the said accident/claim and all  
and any amount claimed, received and/or settled shall belong absolutely to you. I/We agree to assign the  
whole proceeds of my/our third party claim to you and my/our Solicitors (to be appointed by you on  
my/our behalf) shall accept this as my/our irrevocable authorization to pay the amount compensated direct  
to you after deduction of their costs on Solicitor & Client basis. I/We undertake to co-operate fully with  
you and my/our Solicitor appointed as my/our behalf without claiming my/our expenses or time losses or  
incidental charges etc to see the claim to a successful conclusion. In the event the payment of the settlement  
sum is made in my favour, I shall attend your workshop and give you a replacement cheque or cash (less  
off the deposit, if any), within 14 days of being notified by you. If I/We fail to do the above, I shall be  
liable to you for the sum of repair, legal costs and other costs/expenses incurred by you. I/We undertake to  
ensure that my/our cheque shall be honoured upon presentation by you. In the event that my/our cheque is  
dishonoured, for whatever reason, you may proceed to lodge a police complaint against me for this criminal  
act and may proceed to sue me/us for this breach.


I/we undertake to inform you and/or the Solicitors appointed by you on my behalf in the event the 3<sup>rd</sup>  
party's insurance company communicate with me/us directly orally or in writing and I/we further undertake  
not to accept any monies or offer settlement from the 3<sup>rd</sup> party's insurance without first communicating  
with you and obtaining your consent.

In the event of any of the aforesaid breach, I/We shall have totally no defence to your action/claim against  
me/us and I/We will have to bear your legal costs incurred on an indemnity basis for any legal action may  
arise against me/us including your damages, expenses and other incidental charges.

My/Our Insurers is/are MSIG Insurance (Singapore) Pte. Ltd.  
Policy No. B28981249 QMY Excess \$1000.00 Expiry date 13.07.2018

Dated this 08 day of 01 2018

  
Owner's Signature  
Company stamp

  
Witness's signature  
Name:

Interpreter's signature

Interpreted in English/Chinese/Malay

Name:

PAYMENT AUTHORISATION LETTER

Your ref:

Date: 08-01-2018

To,

*AIG Asia Pacific Insurance Pte. Ltd.*

.....  
.....  
.....

Dear Sir/Madam,

RE: ACCIDENT ON *30.12.2017* BETWEEN VEHICLE NO *SKB 9884R*  
AND YOUR INSURED VEHICLE NO *SKF 8104Z*.....

---

I refer to the above matter, and wish to notify your good selves that I have taken possession of the said vehicle, and I am completely satisfied with the repairs undertaken by **LONG SHENG MOTOR SERVICE**. (Repairer)

Please kindly release payments due to directly to M/s **LONGSHENG MOTOR SERVICE**, Blk. 6, No.399-G, Woodlands Road, Yew Tee Industrial Estate, Singapore 678007.

Your cooperation on the above matter is much appreciated.

Thank You.

Yours faithfully,



.....  
Name: *TED KANG HEE*  
I/C No. *S69735119*  
.....

c.c M/s Long Sheng Motor Service

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, LONG SHENG MOTOR SERVICE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$7,050.00 (Global Sum) for vehicle no. SKB 9884R that was damaged pursuant to the accident which occurred on 30/12/2017 (date) along GATEWAY LINK involving vehicle no/s SKF 8504Z.

This is pursuant to the inspection conducted on 09/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TEO KANG HEE ("the third party claimant") of vehicle no. SKB 9884R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKB 9884R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29 (day) of JAN (month) 2018 (year)



Signed by appointed surveyor

Long Sheng Motor Service  
Blk 6, No. 399-G, Woodlands Road  
Yew Tee Industrial Estate  
Singapore 676007  
Tel: 6763 9733 Fax: 6763 9886

Signed by "the workshop" (with chop)

# 龍勝汽車服務 LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate,  
Singapore 678007

Tel: 6763 9733 Fax: 6763 9866

(Reg. No: 52840117C)

No. 4107

M/s. AIG Asia Pacific Insurance Pte.Ltd

Date: 23.01.2018

## SKB 9884R - Toyota Camry 2.4 Auto (2011)

Cost of Repair (Lump Sum)

\$ 6,250.00


\$ 6,250.00

SGD: Six Thousand And Two Hundred Fifty Dollars Only

\* as per surveyor's recommendation \*

TP Claim Against - SKF 8504Z  
D.O.A : 30.12.2017

LONG SHENG MOTOR SERVICE



# RUYI RENTAL SERVICES

Blk 7, No. 397 B, Woodlands Road, Yew Tee Industrial Estate

Singapore 678032

Tel : 67632149

( Reg. No : 53073068E )

No. 31023

## OFFICIAL RECEIPT

Date: 09.01.2018

Received with thanks from Teo Kang Hee 569735516

the sum of Dollars Seven Hundred Twenty Only.

being payment of Car Rental From 03.01.2018 To 09.01.2018

Vehicle No. SGB 3725D

\$ 720.00

Cheque / Cash

Issued by

# RUYI RENTAL SERVICES

Blk 7 , No. 397 B , Woodlands Road , Yew Tee Industrial Estate

Singapore 678032

Tel : 67632149

( Reg . No : 53073068E )

*Invoice No.:* 31095

M/s: Teo Kang Hee

Date: 09.01.2018

## PARTICULARS

To Supply One Unit Toyota Corolla Altis 1.6

SGB 3725D Drive By Teo Kang Hee

From : 03.01.2018 to 09.01.2018

6 Days X \$120 per day

Total Amount:

\$ 720.00

SGD: Seven Hundred And Twenty Dollars Only.

RUYI RENTAL SERVICES



.....

# RUYI RENTAL SERVICES /nv: 31095

397B Woodlands Road, Yew Tee Est  
Singapore 678032  
Tel: 6763 2149

## VEHICLE RENTAL AGREEMENT

NO: 31195

單號  
VRA NO: \_\_\_\_\_

日期  
DATE: 03.01.2018

### SCHEDULE

#### HIRER

姓名  
Name Teo Kang Hee  
登記號碼  
NRIC/Passport No. S69735176  
地址  
Address 10 Teo Ching Road 402-23  
Singapore 618735  
辦事處電話  
Office Tel. 93855959 住宅  
Home Tel. \_\_\_\_\_  
傳真  
Fax \_\_\_\_\_

#### AUTHORISED DRIVER

姓名  
Name AS About  
登記號碼  
NRIC/Passport No. \_\_\_\_\_  
地址  
Address \_\_\_\_\_  
駕車執照號碼  
Driving Licence No. \_\_\_\_\_  
執照到期  
Date of Expiry \_\_\_\_\_  
辦事處電話  
Office Tel. \_\_\_\_\_ 住宅  
Home Tel. \_\_\_\_\_

The Owner shall not be responsible for any liability demands, claims, injuries or otherwise for any accident, death or other losses arising from the use of the vehicle when the rental period is overdue. Once the rental period is overdue, the rental agreement will not be valid

#### DECLARATION

I/We, the abovementioned Hirer hereby agree with RUYI RENTAL SERVICES that I/We have read and agreed to be bound by the Terms and Conditions of this Rental Agreement and I/We further agree that the schedule above and the general terms and conditions which appear on the back page shall form part and parcel of the Rental Agreement and shall be binding to the Hirer.

Signature of the Hirer /Authorised  
signatory of the Hirer with Co. Stamp

#### VEHICLE

車號  
Vehicle No. S68 3725D  
車型  
Model TOYOTA ALTIS 1.6 AUTO  
租期  
Rental Period 6 days  
出車日期  
Date of taking Delivery 03.01.2018  
出車時間  
Time of taking Delivery 12PM

#### RATE

月  
Month @\$ \_\_\_\_\_  
星期  
Week @\$ \_\_\_\_\_  
日  
Day @\$ \$120.00  
安穩金  
Security Deposit : \$ \_\_\_\_\_  
保險  
Insurance : \$ \_\_\_\_\_  
總數  
Total : \$ \$720.00  
收據  
Receipt No. \_\_\_\_\_

交車日期  
Date of Return 09.01.2018  
交車時間  
Time of Return 2.34 PM  
過期交車  
Late Return : \*Yes (No)  
過期交車費  
Late Return rental Fees : \$ \_\_\_\_\_  
合約總數  
VRA Total Amount : \$ \_\_\_\_\_  
安穩金還  
Deposit Return

I, \_\_\_\_\_ the Hirer/the Hirer's representative/  
the Authorised Driver declare that the contents given  
above are correct.

Third Party Insurance Excess : \$2000/\$3500  
Own Damage Insurance Excess : \$1500/\$2000

Name: Teo Kang Hee  
NRIC No: S69735176





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-000230

Date of Request: 02/01/2018

Your Ref No:

Online Purchase

Long Sheng Motor Service  
399G, 6 Woodlands Road,  
Yew Tee Industrial  
Singapore 678007

Dear Sir/Madam,

Enquiry Date 02/01/2018  
Enquiry By CELEST LING  
TP Vehicle No. SKF8504Z  
Accident Date 30/12/2017

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKF8504Z	AIG Asia Pacific Insurance Pte. Ltd.	11/07/2017-10/07/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jan 2018 <a href="#">Edit Reg</a>		05 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$6,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	CHINA SOUTHERN AIRLINES COMPANY, Co. Reg. No.: S94FC4771H								
Main Claimant:	TEO KANG HEE, ID: S6973551G								
Vehicle Reg. No.:	SKB9884R	Date of Loss:	30/12/2017 16:00 - :59						
Claim Type:	TP / 0130941974SG	Policy/Cover Note No.:	2100307049 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKF8504Z	Policy No. (Claimant):	B28985249QMY						
	Excess:								
Repairer:	Long Sheng Motor Service (HQ) 399G, 6 Woodlands Road,, Yew Tee Industrial, 678007 Woodlands - Tel: 6763 9733								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 16/01/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SKB9884R (0130941974SG)**  
**[SKF8504Z]**  
**TP**  
**TEO KANG HEE**  
**Dec 30 2017 4:00PM**  
**[CHINA SOUTHERN AIRLINES COMPANY]**  
**Long Sheng Motor Service**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <a href="#">View in Browser</a>	
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	---	--

<b>Video</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	08/01/18 16:19	Video - Accident from TP	1	Load AVI	

<b>Letters/Correspondences</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	

<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	08/01/18 09:18	<b>Accident Statement</b> <small>From: DD - Reg. No: SKF8504Z, Claimant: CHINA SOUTHERN AIRLINES COMPANY</small>	1	Load HTM	

<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	22/01/18 15:45	General View	1	Load JPG	

					<input checked="" type="checkbox"/>
26	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	22/01/18 15:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	22/01/18 15:45	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
40	22/01/18 15:45	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
41	22/01/18 15:45	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
42	22/01/18 15:45	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
43	22/01/18 15:45	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
44	22/01/18 15:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	22/01/18 15:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	22/01/18 15:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	22/01/18 15:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	22/01/18 15:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	22/01/18 15:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					1 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/01/18 15:30	EMAIL FROM AIG DD 04.01.2018	1	Load PDF	
2	05/01/18 15:30	ACKNOWLEDGEMENT EMAIL TO AIG DD 04.01.2018	1	Load PDF	
3	05/01/18 15:30	TP GIA REPORT	1	Load PDF	
4	11/01/18 11:39	TP ESTIMATE- MARKED	1	Load PDF	
5	12/02/18 13:17	WORKSHOP INVOICE	1	Load PDF	
6	12/02/18 13:17	AUTHORISATION TO ACT FORM	1	Load PDF	
7	12/02/18 13:17	Release Voucher	1	Load PDF	
8	12/02/18 13:17	RENTAL RECEIPT	1	Load PDF	
9	12/02/18 13:17	GIA SEARCH	1	Load PDF	
10	12/02/18 13:17	TOWING FEE	1	Load PDF	
11	12/02/18 13:17	LETTER TO OI	1	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKF8504Z (Insd veh)	Model:	TOYOTA CAMRY 2.4 ABS
	SKB9884R (TP veh)		AIRBAG (A)
Date of Accident:	30/12/2017		

Global Sum Settlement	: [ X ] Yes [ ] No
Repair Estimate	: \$ 10,455.05
Final Repair Cost	: \$ 7,050.00
Loss of Use	: \$ _____ days at \$0.00 per day
Rental (if any)	: \$ 6 days
LTA / GIA Search Fee	: \$ _____
Others: Towing Fee	: \$ _____
	: \$ _____
Final Settlement Sum (Global Sum)	: \$ 7,050.00
Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)	
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown			
1)	Long Sheng Motor Service	: \$	7,050.00
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

12 Feb  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18000334/SKS3Q2

Date: 12/02/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100307049
Claimant Vehicle No :	SKB9884R	Insured Vehicle No :	SKF8504Z
Date of Loss:	30/12/2017	Nature of Claim:	TP
		Claim No:	0130941974SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB9884R	Engine No:	2AZE222594
Make & Model:	TOYOTA CAMRY, 2.4 ABS AIRBAG (A)	Chassis No:	MR053BK4007046399
Reg. Date:	14/07/2011 (Man. Year: 2011)	Odometer:	160321 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,895.05	5,817.37	2,077.88	26.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	2,020.00	540.00	21.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,455.05</b>	<b>7,837.37</b>	<b>2,617.68</b>	<b>25.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,455.05</b>	<b>6,250.00</b>	<b>4,205.05</b>	<b>40.22</b>
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		85.60		
<b>Nett Liability (S\$)</b>		<b>7,057.60</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,050.00</b>		

INSPECTION

Date of Assignment:	05/01/2018	
Date Inspected:	09/01/2018 Inspected At:	Long Sheng Motor Service (HQ) 399G, 6 Woodlands Road., Yew Tee

Industrial  
Singapore 678007

Estimated Period of Repair: 6.0 days

---

**Adjuster:** Sebastian Yeang Wai Keen

**Manager:** Zaini Bin Kusaini

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	550.30 FL	*- FL
2	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
3	1		*REAR BUMPER SIDE RETAINER	Not Necessary	55.30 FL	*- FL
4	1		*REAR BUMPER SIDE HOLDER	Not Necessary	48.10 FL	*- FL
5	1		*REAR FENDER RH	Dented	920.10 FL	*920.10 FL
6	1		*REAR FENDER INNER TRIM RH	Not Necessary	480.00 FL	*- FL
7	10		*REAR FENDER INNER TRIM CLIP	Necessary	51.00 FL	*51.00 FL
8	1		*REAR FENDER DUST COVER	Not Necessary	97.20 FL	*- FL
9	10		*REAR FENDER DUST COVER CLIP	Not Necessary	20.00 FL	*- FL
10	1		*REAR DOOR RH	Dented	1,055.10 FL	*1,055.10 FL
11	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	189.10 FL	*- FL
12	1		*REAR DOOR PROTECTOR RH	Not Necessary	115.30 FL	*- FL
13	1		*REAR DOOR PROTECTOR MOULDING RH	Necessary	51.60 FL	*51.60 FL
14	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	750.10 FL	*- FL
15	10		*REAR DOOR INNER TRIM BOARD CLIP	Not Necessary	48.00 FL	*- FL
16	1		*ROCKER PANEL GARNISH RH	Deformed	390.10 FL	*390.10 FL
17	1		*REAR SHOCK ABSORBER	Bent	390.60 FL	*390.60 FL
18	2		*REAR LOWER ARM	Bent	543.20 FL	*543.20 FL
19	1		*REAR WHEEL HUB	Damaged	790.10 FL	*790.10 FL
20	1		*REAR KNUCKLE ARM	Bent	491.60 FL	*491.60 FL
21	1		*REAR COIL SPRING	Damaged	390.80 FL	*390.80 FL
22	1		*REAR SHOCK ABSORBER MONTING	Bent	198.10 FL	*198.10 FL
23	1		*REAR AXLE (REAR CROSS MEMBER)	Bent	1,323.10 FL	*1,091.50 FL
24	1		*ALLOY RIM	Cut	481.90 FL	*350.00 FL
25	1		*IDLER ARM	Bent	296.10 FL	*296.10 FL
26	1		*ANTI LOW BAR	Bent	391.60 FL	*391.60 FL
27	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
28	1		*SET REAR TYRE RH	Buckled	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,433.40</b>	<b>7,676.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>2,538.35</b>	<b>1,859.13</b>
<b>Total Parts (S\$)</b>	<b>7,895.05</b>	<b>5,817.37</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	850.00	750.00
2	LABOUR CHARGES	New	950.00	800.00
3	TO REMOVE & REFIT BOOT COMPARTMENT FITING	New	180.00	50.00
4	TO REMOVE & INSTALL REAR WINDSCREEN	New	130.00	120.00
5	TO REMOVE & REPLACE REAR SUSPENSION CARRY OUT W/ALIGNMENT	New	450.00	300.00
Gross Labour Cost (S\$)			2,560.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >