

龙胜汽车服务

LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Date: 05.01.2018

Page 1/2

Owner: Teo Kang Hee

Attention: AIG Asia Pacific Insurance Pte.Ltd.

RE: Accident to vehicle SKB9884R - Toyota Camry 2.4 Auto (2011) on 30.12.2017

Estimated cost of repair of the above mentioned vehicle.

2a.iii

Replacement Parts:-

1pcs	Rear Bumper R	\$	550.30
10pcs	Rear Bumper Clip @ 3.50 ✓ NEC.	\$	35.00
1pcs	Rear Bumper Side Retainer ?	\$	55.30
1pcs	Rear Bumper Side Holder ?	\$	48.10
1pcs	Rear Fender RH ✓ DT.	\$	920.10
1pcs	Rear Fender Inner Trim RH ?	\$	480.00
10pcs	Rear Fender Inner Trim Clip @ 5.10 ?	\$	51.00
1pcs	Rear Fender Dust Cover ?	\$	97.20
10pcs	Rear Fender Dust Cover Clip @ 3.50 ?	\$	28.00
1pcs	Rear Door RH ✓ DT	\$	1,055.10
1pcs	Rear Door Weatherstrip RH X	\$	189.10
1pcs	Rear Door Protector RH X	\$	115.30
1pcs	Rear Door Protector Moulding RH ✓ NEC	\$	51.60
1pcs	Rear Door Inner Trim Board RH X	\$	750.10
10pcs	Rear Door Inner Trim Board Clip @ X	\$	48.00
1pcs	Rocker Panel Garnish RH ✓ Deform	\$	390.10
1pcs	Rear Shock Absorber ✓ BT	\$	390.60
2pcs	Rear Lower Arm @ 271.60 ✓ BT	\$	543.20
1pcs	Rear Wheel Hub ✓ DMG	\$	790.10
1pcs	Rear Knuckle Arm ✓ BT	\$	491.60
1pcs	Rear Coil Spring ?	\$	390.80
1pcs	Rear Shock Absorber Mounting ?	\$	198.10
1pcs	Rear Axle ?	\$	1,323.10
1pcs	Alloy Rim ✓ cut	\$	481.90
		\$	9,473.70
	Less 25%	\$	(2,368.43)
		\$	7,105.27

To Repair:

Rocker Panel

龙胜汽车服务

LONG SHENG MOTOR SERVICE

Blk 6, No. 399-G, Woodlands Road, Yew Tee Industrial Estate

Singapore 678007

Tel: 67639733 Fax: 67639866

Email: lsmstyc@singnet.com.sg

Page 2/2

SKB 9884R

B/Balance:

\$ 7,105.27

Special Nett:

1pcs Rear Windscreen Sealant ✓ NEC .
1set Rear Tyre RH ✓ Bulge -

\$	60.00	40
\$	220.00	200 .
\$	<u>280.00</u>	

Add:

Spray Painting
Labour Charges
To Remove & Refit Boot Compartment Fitting
To Remove & Install Rear Windscreen
To Remove & Replace Rear Suspension Carry Out W/Alignment

\$	850.00	750
\$	950.00	800 .
\$	180.00	50
\$	130.00	120
\$	450.00	300 .
\$	<u>2,560.00</u>	

Total Amount : \$ 9,945.27

6 days

Sebastian.

9/1/18 .

- Lump Sum Repair.
- Question mark Item Photo
- Photo After Paint

90036121

sebastianyang@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: