

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

Insured veh.	SKX1784H	Excess.	NIL
Policy No.	GA288572	Coverage.	Comprehensive
Claiming Against.	GBD1728H	AXA	
Insured Under.	AXA		

Vehicle Particulars & Condition

Make & Model	Nissan Sylphy
Engine No.	
Chassis No.	MNTBBAB17
Odometer	
Engine CC.	1598
Year Of Reg.	2015
Colour.	BLUE
Parf/COE Rebate.	

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Rear portion, L/H side, R/H side, front portion damaged.

General Information

Accident Date. 2/1/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd
SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

Remarks

A) THE SURVEY WAS CONDUCTED ON A "LUMP SUM" BASIS
KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Not Biller
Alan
d/sa
5th
Whopie After
repar
1/1/18

Qty.	Description Of Parts	Pricing
1	Rear taillamp panel RH <i>~</i>	\$ 168.50 <i>X</i>
1	Rear end panel inner garnish	\$ 204.10 <i>?</i>
1	Rear end panel keyless sensor	\$ 69.90 <i>?</i>
1	Rear spare tyre board <i>11</i>	\$ 356.60 <i>X</i>
1	Rear spare tyre bolt <i>11</i>	\$ 38.50 <i>X</i>

Nett \$ 5,027.60
Less 10% \$ 502.76
Total \$ 4,524.84

1	Rear bumper clips (1 set) <i>re</i>	\$ 45.00 <i>30</i>
1	Rear bumper reverse sensor (1 set) <i>sheld</i>	\$ 280.00 <i>200</i>
1	Boot lid inner trim board clips (1 set) <i>re</i>	\$ 35.00 <i>1</i>
1	Rear number plate <i>3rd</i>	\$ 45.00 <i>40</i>
1	Rear reverse camera	\$ 480.00 <i>?</i>
4	Rear taillamp clips <i>11</i>	\$ 32.00 <i>X</i>
1	Rear end panel inner garnish clips (1 set) <i>11</i>	\$ 35.00 <i>X</i>
2	Rear fender quarter glass sealant <i>11</i>	\$ 70.00 <i>X</i>
1	Rear windscreen sealant <i>11</i>	\$ 60.00 <i>a</i>
1	Rear door black tape LH <i>11</i>	\$ 80.00 <i>X</i>
1	Rear door black tape RH <i>11</i>	\$ 80.00 <i>X</i>
1	Front number plate <i>11</i>	\$ 45.00 <i>X</i>
1	Front bumper clips (1 set) <i>11</i>	\$ 45.00 <i>q</i>
2	Front fender inner shield clips (1 set) <i>11</i>	\$ 70.00 <i>q</i>
1	Bonnet insulator clips (1 set) <i>11</i>	\$ 35.00 <i>X</i>
1	Front support panel top garnish clips (1 set) <i>11</i>	\$ 30.00 <i>X</i>
S/N		\$ 1,467.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Rear bumper <i>DO/DC</i>	\$ 637.60 ✓
1	Rear bumper reinforcement	\$ 781.00 ?
1	Boot lid <i>DO/DC</i>	\$ 650.50 ✓
1	Rear end panel <i>3.6 DO</i>	\$ 561.60 ✓
1	Rear spare tyre panel <i>R</i>	\$ 998.10 x
1	Rear fender LH <i>R</i>	\$ 703.40 x
1	Rear fender RH <i>R</i>	\$ 703.40 x
		List \$ 5,035.60
		Less 30% \$ 1,510.68
		Total \$ 3,524.92
1	Rear bumper side retainer LH <i>nu</i>	\$ 91.70 ✓
1	Rear bumper side retainer RH <i>nu</i>	\$ 91.70 ✓
1	Rear bumper bracket LH	\$ 119.20 ?
1	Rear bumper bracket RH	\$ 119.20 ?
1	Rear bumper stay LH	\$ 81.20 ?
1	Rear bumper stay RH	\$ 81.20 ?
1	Rear bumper lower lip <i>NF</i>	\$ 655.10 x
1	Rear bumper reflector LH <i>11</i>	\$ 66.60 x
1	Rear bumper reflector RH <i>11</i>	\$ 66.60 x
1	Rear bumper inner sponge LH	\$ 87.90 ?
1	Rear bumper inner sponge RH	\$ 87.90 ?
1	Rear bumper inner sponge centre	\$ 69.50 ?
1	Boot lid hinges LH <i>1</i>	\$ 85.00 x
1	Boot lid hinges RH <i>1</i>	\$ 85.00 x
1	Boot lid rubber <i>twi</i>	\$ 105.40 ✓
1	Boot lid lock <i>twi</i>	\$ 112.50 ✓
1	Boot lid lock catch <i>11</i>	\$ 57.10 x
1	Boot lid logo <i>nu</i>	\$ 64.60 ✓
1	Boot lid "SYLPHY" emblem <i>nu</i>	\$ 88.10 ✓
1	Boot lid "SIGNATURE" emblem <i>NF</i>	\$ 98.50 x
1	Boot lid "XTRONIC CVT" emblem <i>nu</i>	\$ 64.60 ✓
1	Boot lid lower chrome moulding <i>scr</i>	\$ 129.20 ✓
1	Boot lid outer handle chrome <i>scr</i>	\$ 609.30 ✓
1	Boot lid inner trim board <i>11</i>	\$ 179.00 x
1	Boot lid reflector LH	\$ 120.90 ?
1	Boot lid reflector RH	\$ 120.90 ?
1	Rear taillamp LH	\$ 241.80 ?
1	Rear taillamp RH	\$ 241.80 ?
1	Rear taillamp panel LH <i>n</i>	\$ 168.50 x

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
<u>LABOUR</u>		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 200.00 60
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 100.00 30
	To remove and refit carpet and trims on the rear section to give way to the repair on the rear section.	\$ 120.00 80
	To remove and refit rear bumper sensors.	\$ 80.00 50
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 1,000.00 750
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 1,000.00 900
	LABOUR	\$ 2,500.00
	Sub Total.	\$ 12,016.76
	7% GST	\$ 841.17
	Grand Total	<u>\$ 12,857.93</u>

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.