

PDI TUAS

PDI TUAS

TAN GEK LAN ROSIE
530 EAST COAST ROAD
#02-02
Singapore, 458970
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV026626
Quote No. SER/QUO/1800022
QuoteDate 04/01/18
Salesperson Anthony Yong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 TSI (DSG)RECAT	45,606	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SDX810E	WVWZZZAUZEW415373	28/08/14	Anthony Yong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CXS 205987	5G13GZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				6,080.00
P 5G0807305B	BUMPER REINFORCEMENT	1	Pieces		? 606.53
	Successor 5G0807305D				
P 5G0945096M	TAILLIGHT OUTER	1	Pieces		? 352.22
	Use Predecessor 5G0945096F				
P 5G6807393	BUMPER BRACKET LH	1	Pieces		? 36.45
P 5G6807393A	BUMPER GUIDE LH	1	Pieces		? 36.45
P 5G6807394	BUMPER BRACKET RH	1	Pieces		neu / 36.45
P 5G6807394A	BUMPER GUIDE RH	1	Pieces		? 36.45
P 5G6807417APGRU	REAR BUMPER COVER	1	Pieces		DE / 1,149.75
	Predecessor 5G6807417ARGRU				
P 5G6807568D 9B9	REAR DIFFUSER	1	Pieces		? 322.86
	Use Predecessor 5G6807568D				
P 5G6807863A	STRIP	1	Pieces		? 67.07
	Use Predecessor 5G6807863				
Sum carried forward					8,724.23

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

TAN GEK LAN ROSIE
530 EAST COAST ROAD
#02-02
Singapore, 458970
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV026626
Quote No. SER/QUO/1800022
QuoteDate 04/01/18
Salesperson Anthony Yong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 TSI (DSG)RECAT	45,606	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SDX810E	WVWZZZAUZEW415373	28/08/14	Anthony Yong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CXS 205987	5G13GZ
Continued			8,724.23
Sum Item			2,644.23
Sum Labor			6,080.00
Sum Item			2,644.23
Total SGD			8,724.23
7% GST			8,724.23 610.70
Total SGD Incl. GST			9,334.93

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - ACC: - NO...

Paul
4p 90010068
3 days
09/01/18 @ 0900
Resurvey before paint