Vescesa ASS. REC. BY:	REF CS (	CII 180003501 Ago	3 n2 Special Lastrect	ion:
Arimun From (Person): Estimated Cost	Sharon Han of	SIGNMENT (Office)  CTL  Bill to:	Dete/Tim	05/01/2018 @ 4.01pm
DD T WS Fo Inspect Veh at Workshop m	TP RES / OD RES / EVA / IN	V/MV/CS 2T	_ Insured: _SJA Tel:6	14256K 16 <b>8</b> 9828
	MPCSN 3004 39170	Claim No:	SNM18 DOC	0044002
Sum Insured:_ Make of Veh:		Excess:	DOA	31/12/2017
(Client's Record		Contacted: Tony		Endorsement:
Date/Time	Action/Instruction ( )	Estimate		
213180	SDP 722T-X SIN 4256K-X Stop confirmed with	ne Boo frage +	fig \$ 2836-50,	Z days.
-	Ched 6 3596.50, 3			- U

2015 oct. SDP 722T. 29/1/18 Audi A4 1788 -SOP 722T Brown. 55 ubi Road 1 73903. WA42228K3FA154421 Steering of Organization Leaves Survival to am owner waiting 245/40818 BS DUN ERNOVA BY FS LIZHTYTO DHTSU 🤣 SUV Pamary The Van Had commenced its receivenths time of Inspection TOYS YORG : Ballon Namer Laue 06 Consistent? Yes or No. 010 400 de 11 Pourt 06 3.1 sa 598. Consistent! Yes on No. Est Pacari 03 & 5 cars Pes res in No E. \* + \* \* 1 E Promium. Eliza Yes of No Ter of Director (P) 5. 25. 25. 21-25 Wp erice (N/OUT The U.S. Chasasaffama Body Structura affected signification as TP 1st Cap. China

RECEIVED 2 2 MAR 2018

Definition Person	Days Of Receiver 3	
m/3 mount ========	Resurvey No. of Tell	
	Add Feet 2 to 10	
2836.50		
		220



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	T CARITAL INCLU	The same of the sa	Ref: CS/FCI1800038		
FIRS	ST CAPITAL INSUI	RANCELID	Ref : C5/FC[180003	burAqas	
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date : 05-01-2018		
		Ballan Badlania	Code: FCI2		
1.	h	SJN 4256K	s :- THIRD PARTY CLAI	SDP 722T	
	Insured Veh.	ACTION AND COLOR	Veh. Inspected	0.00	
	Policy No.	DMPCSN3004391701	Coverage (\$)	207,20003	
	Claim No.	SNM18D00044C02	Excess (\$)	0.00	
	Assign From	MERIMEN (SHARON HAN)	Assign Date	05/01/2018	
2.		Vehicle Par	ticulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
Chassis No.			Colour Steering		
Odometer -					
	Brakes		Modification		
	General				
3.		Cond	itions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Descrip	tion of Damages		
5.	Taxonina Mo	Gene	ral Information		
	Accident Date	31/12/2018	Inspection Date		
S	Survey held at	PREMIUM AUTOMOBILES P			
		55 UBI ROAD 1 . SINGAPORE 408699			
5a.	Second Second		Remarks		

# ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authred	Status
Main	04 Jan 2018		05 Jan 2018 16:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETA	ILS	the experience of the control of the	[Created by in	surer]
Insured:	OLI MOHAMED BIN MEIDEEN,	ID: S1767740C	- A Succession and a su	ASSESSED TO THE REAL PROPERTY OF THE PERTY O
Main Claimant:	CHIEW CHIANG SENG, ID: S	6815078G		
Vehicle Reg. No.:	SDP722T	Date of Loss:	31/12/2017 01:0	00 - :59
Claim Type:	<b>TP</b> / SNM18D00044C02	Policy/Cover Note No.:	DMPCSN300439 (Comprehensive	T 1 (T-T)
Vehicle Reg. No. (Insured):	SJN4256K	Policy No. (Claimant):	5075166527-02	
		Excess:	5\$0.00	
Repairer:	Premium Automobiles Pte Ltd	(UBI) 55 Ubi Road 1, 408699	Ubi - Tel: 67689828/98	27/9911
	China Taiping Insurance (Sing	anora) Pta Itd (HO) - Tal:	6389 6111 [Handled	hu Charan Han
Handling Insurer:	63896]	Japore / Fre. Eta. (HQ) - Tel.	osos offf [riandied	by Sharon Han -
Handling Insurer: Claimant's Insurer:			osos offi (riancieu	by Sharon Han -
A STANCE OF THE	63896]	perative Ltd (HQ) - Tel:		N
Claimant's Insurer:	63896] NTUC Income Insurance Co-o	perative Ltd (HQ) - Tel: (HQ) - Tel: 6256-3561 [Fi	nal Rpt due 16/01/2	2018]
Claimant's Insurer: Adjuster:	63896] NTUC Income Insurance Co-o LKK Auto Consultants Pte Ltd	perative Ltd (HQ) - Tel: (HQ) - Tel: 6256-3561 [Fi DLI MOHAMED (27 / Male), N	nal Rpt due 16/01/2	2018]
Claimant's Insurer: Adjuster: Driver/Custodian (Insured):	MTUC Income Insurance Co-op LKK Auto Consultants Pte Ltd MOHAMED KASYFUL KABIR BIN O NO ESTIMATE, ASSIGN XING GU	perative Ltd (HQ) - Tel: (HQ) - Tel: 6256-3561 [Fi DLI MOHAMED (27 / Male), N	nal Rpt due 16/01/2	2018] +6591816330
Claimant's Insurer: Adjuster: Driver/Custodian (Insured): Adj Asg. Remarks:	63896]  NTUC Income Insurance Co-o  LKK Auto Consultants Pte Ltd  MOHAMED KASYFUL KABIR BIN C  NO ESTIMATE, ASSIGN XING GUE  VED	perative Ltd (HQ) - Tel: (HQ) - Tel: 6256-3561 [Fi DLI MOHAMED (27 / Male), N	nal Rpt due 16/01/2 RIC: S9048389G, Tel:	2018] +6591816330
Claimant's Insurer: Adjuster: Driver/Custodian (Insured): Adj Asg. Remarks: ASSOCIATED MAIL RECEI	63896]  NTUC Income Insurance Co-op  LKK Auto Consultants Pte Ltd  MOHAMED KASYFUL KABIR BIN CO  NO ESTIMATE, ASSIGN XING GUE  VED  e.	perative Ltd (HQ) - Tel: (HQ) - Tel: 6256-3561 [Fi DLI MOHAMED (27 / Male), N	nal Rpt due 16/01/2 RIC: S9048389G, Tel:	2018] +6591816330 Compose Case Mail

# Shiau Chan (LKKAuto)

From:

Sent:	Wednesday, 21 March 2018 5:43 PM
Го:	'Boo seng yak'; Carrine Leong; Nora Khai
Cc:	SUR
Subject:	RE: FINAL REVISION SDP722T - TP CHINA - SURVEYED 29 JAN 18
Dear Mr Boo,	
Confirm final fig \$2,83	6.50 before GST and 3 repair days.
Best Regards,	
Shiau Chan (Ms)   Cas	e Handler
LKK Auto Consultant	s Pte Ltd
Phone: 6256-3561   emai	ll: siewsc@lkkauto.com   fax: 6256-4315
Blk 51, Paya Ubi Industri	al Park, Ubi Avenue 1, #02-25   S(408933)
From: Boo seng yak [n	nailto:boojohnny@gmail.com]
Sent: Monday, 19 Mai	rch 2018 4:50 PM
	uto) <siewsc@lkkauto.com></siewsc@lkkauto.com>
Subject: Re: FINAL RE\	VISION SDP722T - TP CHINA - SURVEYED 29 JAN 18
Hi Shiau Chan	
Please take note that	there was a typo error on the estimate by our CA.
have checked the par	rt no and it is the radiator grille closing element that was used.
Please refer to the sec	ond and third photographs for the cracked closure plate.
Thank you !	
Best regards - jb	
On Mon, Mar 19, 2018	B at 4:33 PM, Shiau Chan (LKKAuto) < siewsc@lkkauto.com > wrote:
Dear Mr Boo,	
Kindly provide us the	damage photo of "FRONT BUMPER CLOSING ELEMENT".
Killary provide as the	damage photo of Thorr bown the coosing technicist.
Best Regards,	
Shiau Chan (Ms)   Ca	ase Handler
LKK Auto Consultan	its Pte Ltd

Shiau Chan (LKKAuto)

## Shiau Chan (LKKAuto)

From:

Boo seng yak <boojohnny@gmail.com>

Sent:

Monday, 19 March 2018 4:50 PM

To:

Shiau Chan (LKKAuto)

Subject:

Re: FINAL REVISION SDP722T - TP CHINA - SURVEYED 29 JAN 18

Hi Shiau Chan

Please take note that there was a typo error on the estimate by our CA.

I have checked the part no and it is the radiator grille closing element that was used.

Please refer to the second and third photographs for the cracked closure plate.

Thank you!

Best regards - jb

On Mon, Mar 19, 2018 at 4:33 PM, Shiau Chan (LKKAuto) < siewsc@lkkauto.com > wrote:

Dear Mr Boo,

Kindly provide us the damage photo of "FRONT BUMPER CLOSING ELEMENT".

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, <u>Ubi Avenue 1, #02-25</u> | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Thursday, 15 March 2018 6:03 PM

To: Adrian Ling (LKKAuto) <a href="mailto:adrianling@lkkauto.com">
| SUR < sur@lkkauto.com</a>; Carrine Leong

<carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>

Subject: FINAL REVISION SDP722T - TP CHINA - SURVEYED 29 JAN 18

Hi Adrian and all,

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

	ACCIDENT STATEMENT	
Date Of Report	31/12/2017 18:12	
Date Of Accident	31/12/2017 01:00	
Exact Location Of Accident	159W JALAN LOYANG BESAR	
Country/State of Loss	SINGAPORE	
The state of the s	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDP722T	
Insured/Policyholder		
Name Of Registered Owner	CHIEW CHIANG SENG	
NRIC No	S6815078G	
Email Address	CLUAN@SINGNET.COM.SG	
Mobile Phone No	(LOCAL) +65-98239687	

OFFICE-NOPHONE

### Alternative Phone No Vehicle Particulars

Manufacturer	AUDI
Model	A4-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you	claiming	under	your	own	insurance	policy	

Are you claiming	under	your	own	insurance	policy
for repair to your	vehicle	9?			

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### **Insurance Company**

Marile of modification of Electrical	Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LT
--------------------------------------	---------------------------	---------------------------------------

NO

Type Of Coverage	COMPREHENSIVE
Type of ouverage	OOM INCHESTOR

Fleet Policy NO

5075166527-02 Policy Number

Cover Note Number

#### Driver

Name of Driver	CHIEW CHIANG SENG

NRIC No S6815078G 01/04/1968 Date Of Birth Occupation INDOOR 02/08/1989 Date Of Driving Pass

28 YEARS AND 4 MONTHS Driving Experience

MALE Gender

Mobile Number (LOCAL) +65-98239687

Fax Number

Contact Number OFFICE-NOPHONE

EMail Address CLUAN@SINGNET.COM.SG Address

12 TAMPINES STREET 73

#12-01 PINEVALE

Postcode

528828

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

OI EMAIL TO MOTORVIDEO@INCOME.COM.SG

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number Vehicle Make/Model/Colour SJN4256K

Details Of Properties

Details Of Propertie

PRIVATE CAR

Vehicle Category Name of Driver

KASYFUL

NRIC/Passport Number

S9048389G

Contact Number

91816330

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- This form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding nf insaterial. facts may allow insurance companies to repudiate policy liability.
- the issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- By the lodgment of this report to the insurers, you bereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8 Consent under the Personal Data Protection Act (PDPA)

l understand, ecknowledge, agree and consent that

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) ol
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
  - (ii) investigating the accident and/or my claims,
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders

Policyholder's Signature Date & Time 31/3/1017

Driver's Signature (If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name: HRZell NRIC/FIN NO SEGUISSISS

#### Sketch Plan #2

SKETCH PLAN

169 W JAININ LOVANG PRIME



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31/12/2017 at around orowin my while was parted
at Aloha Layong At Oroomer I found a note on my
we discourse informing the to next the minutes on it Botoso I control
the number, I charted my vehicle and my common and it
showed that another vehicle SJN 43565 had moved into my
parted whicle I called the number and the othe party
continued that he had collided into my partid which als
egines are sustained in the accordant


DECLARATION

I/We declare the horegoing particulars are true in every respect.

Policyholder's Signature
Date & Fime: \$7/13/15-1

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name : HPT+1 a NRIC/FIN No - C 7 2 2 5 7 3 \*P





IDENTITY CARD NO. \$6815078G





CHIEW CHIANG SENG

周长盛 CHINESE

01-04-1968 SINGAPORE



0593553

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive 02 Aug 1989 of the driver; and other motor vehicles =< 2500kg

NP 428A





NEC No. S6815078G

Blood Group Date of issue

0+

01-11-1992

BLK 12 TAMPINES STREET 73 #12-01 SINGAPORE 528828

NRIC No: \$68150786

Dete: 16-04-2007 (R) No: 5742493



#### THE SCHEDULE

#### Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

- 1. any Endorsement specified as operative in the Schedule
- 2. the Conditions and General Exclusions of this Policy, and
- the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document. GST Reg No. M4-0003030-8

Policy Number

: 5075166527-02

The Policyholder

: CHIEW CHIANG SENG

12 TAMPINES STREET 73 #12-01 PINEVALE

SINGAPORE 528828

Period of Insurance

: 27 Oct 2017 To 26 Oct 2018

Sum Insured

: Market Value of Insured Vehicle at Time of Loss

Premium (inclusive GST)

: S\$1,182.06

Interest Insured

Cover Type : drivo PREMIUM Primary Driver : CHIEW CHIANG SENG Named Driver (1)

Named Driver (2) Make/Model Registration Number : CHIA CHER LUAN : N/A : AUDI/A4

: WAUZZZ8K3FA154421

Capacity Registration Year : 2015 Off-peak Car

: 1800cc : No

Chassis Number Repair at Owner's Preferred Workshop: Yes Excess (Section 1)

: \$\$600 : N/A : \$\$100

: SDP722T

Insure with COE : Yes NCD Entitlement : 50% NCD Protection : Yes(Free) Loyalty Discount : 5%

Windscreen Excess Additional Excess Unnamed Driver Excess

Excess (Section 2)

: N/A : Please refer to Terms and Conditions : UNITED OVERSEAS BANK LIMITED

Hire Purchase Company Optional Cover

Transport Allowance Excess Waiver : No

Memo A: N/A

Endorsement Operative: M4, M7

: GRINWEIV PTE. LTD. (00000573511)

Date of Issue

: 07 Oct 2017 09:52 hrs

#### DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors

Chief Executive

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

Estimate Accident Repairs Workshop Ubi Road 1 Contact No 6366 2323

Fax No : 6841 1183 Reference PA/TP/0010/2018/JT

Date 3-lan-18

Vehicle not workshop. Kindly arrange for survey.

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street #19-00 The Octagon Singapore 069534

**Motor Claims Dept** 

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name Mr. Chiew Chiang Seng Address

Blk 12 Tampines St 73

#12-01

Singapore 528828 Telephone HP +65 9823 9687 Type of Claim Third Party Claims Policy No. 5075166527-02

**SDP 722 T** Vehicle No Model Code Audi A4 1.8 TFSI Mu

Model / Year Oct-15 CJE 106665 Engine No

Chassis No WAUZZZ8K3FA154421

Mileage

Date In Liability **Excess Cost** 

Estimated By Johnny Boo / Allan Wu

**Accident Date** 31-Dec-17

Place of Accident Junction of Bishan St 22 & Marymount Road

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

## Estimated Labour Charges for Accident Vehicle SDP 722 T.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	/
2	To dismantle and renew front bumper assy. Re- organize front crash management components. Reinstall all parts removed.		\$ 900:00	600
3	To respray front bumper.		\$ 800.00	600%
4	To carry out diagnostic checks.	S/N	\$ 192.00	/
	TOTAL LABOUR CHARGES	:	\$ 2,252.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Material List for Accident Vehicle Regn No. SDP 722 T.

S/N	Parts Description		Damage Parts & Pric S/NETT REMARKS	es
1	FRONT BUMPER REPLS	\$	1,954.00 *	
2	RADIATOR GRILLE Crucked	\$	899.00 - 898	.50
3	FRONT BUMPER CLOSING ELEMENT HE ME Cracles	\$	161.00 + 161	-
4	FRONT REINFORCEMENT BEAM HE M	\$	742.00 -	
5	HEADLIGHT MOUNTING - RHS	\$	100.00 ~	
6	FRONT NUMBER PLATE But 5/	N \$	25.00	
7	SUNDRIES NOC.	\$	300.00 ? /	
	TOTAL SPARE PARTS :	\$	4,181.00	
	TOTAL LABOUR CHARGES :	\$	2,252.00	
	GRAND TOTAL :	\$	6,433.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Tel: 6366 2323 Fax: 6841 1183

## Telefax

Name

: Adrian L.

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability

Remarks

: He Anthorsed, 03 Days.

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager

Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

Estimate Workshop Accident Repairs

Workshop Contact No Ubi Road 1 6366 2323

6841 1183

Fax No Reference

PA/TP/0010/2018/JT

Date

3-Jan-18

Vehicle not workshop. Kindly arrange for survey.

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street #19-00 The Octagon Singapore 069534 Hi Adrian 3 days - ok - jb - 15 Mar 18

**Motor Claims Dept** 

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name

Mr. Chiew Chiang Seng

Address

Blk 12 Tampines St 73

#12-01

Singapore 528828 HP +65 9823 9687

Telephone Type of Claim Policy No.

Third Party Claims 5075166527-02

Vehicle No

SDP 722 T

Model Code

Audi A4 1.8 TFSI Mu

Model / Year

Oct-15

Engine No

CJE 106665

Chassis No

WAUZZZ8K3FA154421

Mileage Date In

Date III

•

Liability

<u>\*</u>

Excess Cost Estimated By

Johnny Boo / Allan Wu

**Accident Date** 

31-Dec-17

Place of Accident

Junction of Bishan St 22 & Marymount Road

# Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

## Estimated Labour Charges for Accident Vehicle SDP 722 T.

			Estimated		urveyor's
Nature of Jobs			Charges	Reco	mmendation
To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$	360.00
To dismantle and renew front bumper assy. Reorganize front crash management components. Reinstall all parts removed.		\$	900.00	\$	600.00
To respray front bumper.		\$	800.00	\$	600.00
To carry out diagnostic checks.	S/N	\$	192.00	\$	192.00
TOTAL LABOUR CHARGES	:	\$	2,252.00	\$	1,752.00
	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.  To dismantle and renew front bumper assy. Reorganize front crash management components. Reinstall all parts removed.  To respray front bumper.  To carry out diagnostic checks.	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.  To dismantle and renew front bumper assy. Reorganize front crash management components. Reinstall all parts removed.  To respray front bumper.  To carry out diagnostic checks.  S/N	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.  To dismantle and renew front bumper assy. Reorganize front crash management components. Reinstall all parts removed.  To respray front bumper.  \$ 5/N \$	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.  To dismantle and renew front bumper assy. Reorganize front crash management components. Reinstall all parts removed.  To respray front bumper. \$800.00  To carry out diagnostic checks. S/N \$192.00	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.  To dismantle and renew front bumper assy. Reorganize front crash management components. Reinstall all parts removed.  To respray front bumper. \$800.00 \$  To carry out diagnostic checks. S/N \$ 192.00 \$

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

# Material List for Accident Vehicle Regn No. SDP 722 T.

			Damage Parts & Prices			
S/N	Parts Description		- 8	S/NETT F	REMAR	KS
			_	4.054.00		
1	FRONT BUMPER		\$	1,954.00		
2	RADIATOR GRILLE		\$	899.00	\$	898.50
3	FRONT BUMPER CLOSING ELEMENT		\$	161.00	\$	161.00
4	FRONT REINFORCEMENT BEAM		\$	742.00		
5	HEADLIGHT MOUNTING - RHS		\$	100.00		
6	FRONT NUMBER PLATE	S/N	\$	25.00	\$	25.00
7	SUNDRIES		\$	300.00		
	TOTAL SPARE PARTS	:	\$	4,181.00	\$	1,084.50
	TOTAL LABOUR CHARGES	:	\$	2,252.00	\$	1,752.00
	GRAND TOTAL		\$	6,433.00	\$	2,836.50

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

## Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18000350/AQD3N2

Date:

26/03/2018

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN3004391701

Claimant Vehicle No:

SDP722T

Insured Vehicle SJN4256K

No:

Date of Loss:

31/12/2017

Nature of Claim:

TP

Claim No:

SNM18D00044C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SDP722T

Make & Model:

AUDI A4, 1.8 (A)

27/10/2015 (Man. Year: 2015)

Engine No: Chassis No:

Odometer:

CJE106665

73903 km

WAUZZZ8K3FA154421

Reg. Date: Colour:

Brown

1798 cc

**Engine Capacity:** Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

245/40R18

Rear Tyre Size:

245/40R18

Front Left Side:

Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side:

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 4,181.00 0.00	Adjuster's 1,084.50 0.00	Difference 3,096.50 0.00	Diff % 74.06
Labour	2,252.00	1,752.00	500.00	22.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,433.00	2,836.50	3,596.50	<b>55.91</b> 55.91
+ GST 7.00/7.00% (S\$)	450.31	198.56	251.75	
Nett Amount (S\$)	6,883.31	3,035.06	3,848.25	55.91

INSPECTION

Date of Assignment:

05/01/2018

Date Inspected:

29/01/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Mar 2018)

Parts: 143 AUDI A4 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SDP722T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,954.00 FS	*- FS
2	1		*RADIATOR GRILLE	Cracked	899.00 FS	*898.50 FS
4	1		*RADIATOR GRILLE CLOSING ELEMENT *FRONT REINFORCEMENT BEAM	Cracked Not Necessary	161.00 FS 742.00 FS	*161.00 FS
5	1		*HEADLIGHT MOUNTING-RHS *FRONT NUMBER PLATE	Not Necessary Bent	100.00 FS 25.00 FS	*- FS
r =Fran	1 ichise p	oart. S=SpcNe	*SUNDRIES ett.	Not Necessary	300.00 FS	*- FS
				Total Parts (S\$)	4,181.00	1,084.50

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY.RE- ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	900.00	600.00
3	TO RESPRAY FRONT BUMPER	New	800.00	600.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
	Gross Labour	Cost (S\$)	2,252.00	1,752.00
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >