

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 761K**AAD1801-032***Not Notional**Running B4 perim*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 761K

VF1ABL15AUC283336

RENAULT

LATITUDE

31.12.2017

AXA**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Pr</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Pr</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Pr</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Pr</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Pr</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Pr</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Pr</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Pr</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Pr</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Pr</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	225.95 ?
12	1	BUMPER BEAM BRACKET RH REAR	\$	225.95 ?
13	1	BOOT REAR	\$	<i>Pr</i> 2,872.68 X
14	1	BOOT FINISHER	\$	<i>Pr</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>Pr</i> 323.05 X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Pr</i> 493.35 X
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Pr</i> 493.35 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Pr</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>Pr</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>Pr</i> 276.08 X
21	1	BOOT STRUT RH	\$	<i>Pr</i> 276.08 X
22	1	BOOT HINGE LH	\$	<i>Pr</i> 367.84 X
23	1	BOOT HINGE RH	\$	<i>Pr</i> 367.84 X
24	1	BOOT INNER TRIM	\$	<i>Pr</i> 586.45 X
25	1	BOOT SWITCH	\$	<i>Pr</i> 168.13 X
26	1	BOOT LOCK	\$	<i>Pr</i> 202.67 X
27	1	BOOT LOCK CATCH	\$	<i>Pr</i> 74.40 X
28	2	LICENCE PLATE LAMP	\$	<i>Pr</i> 50.52 X
29	2	BOOT RUBBER PLUG	\$	<i>Pr</i> 221.81 X
30	1	FENDER PANEL REAR LH	\$	<i>Pr</i> 3,299.13 X

Trans-cab Auto Services Pte Ltd

AAD1801-032

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 761K

31	1	WHEELARCH REAR LH	\$	543.47	X
32	1	FENDER PANEL REAR RH	\$	3,299.13	X
33	1	WHEELARCH REAR RH	\$	543.47	X
34	1	TAILLAMP RH	\$	552.55	X
35	1	TAILLAMP PANEL RH	\$	986.70	X
36	1	TAILLAMP LH	\$	552.55	X
37	1	TAILLAMP PANEL LH	\$	986.70	X
38	1	OUTER PANEL REAR (End Panel)	\$	1,471.77	X
39	1	OUTER PANEL REAR (End Panel)TRIM	\$	404.56	X
40	1	EXHAUST REAR	\$	7,489.05	X
41	1	EXHAUST CAP REAR	\$	230.49	X

TOTAL	\$	31,723.96
10%	\$	3,172.40
	\$	28,551.56

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	X
17	1	TAILLAMP CLIP RH	\$	5.00	X
18	1	TAILLAMP CLIP LH	\$	5.00	X
19	2	REAR WINDSCREEN SELANT	\$	80.00	X
20	1	WINDSCREEN MOULDING	\$	100.00	X
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 761K

TOTAL	\$	2,169.02
TOTAL PARTS	\$	30,720.58

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	<i>600</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>300</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nr</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nr</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nr</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>600</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nr</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00	<i>X</i>

TOTAL	\$	7,710.00
Over All Total	\$	38,430.58

(PARTS BY PARTS)

Repair Days

10 Days

4 days

- LKK Auto Consultants henceforth the Repairer of the following
- To resurvey before/after spray painting
- To resurvey the part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: