

INS. CASE OWNER:

CC 3, AIG 18000377, T. 20352

LKK:

IDAC:

Surveyor:

MMH

DOI:

ASSIGNMENT

8/1/18

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJP 4286M

Name of Insured:

G04 HAN TWEE

Insured Tel No.:

HP:

98414168/98484168

Excess Sec II :SS

D.O.A:

5/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJP 8823J



INSRS:

WSP:

Tel:

Liability:

RMKS:

pml



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
10/1/18	SJP 8823J - X: SJP 4286M - X	Non-Reporting ltr (1st):	
10/1/18	PML Submitted 2 claims, AIG 2/1/18.	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI: 11/1/18 - City Hant.	
		After call ltr to OI: 12/1/18 - vic ok	
		Documentation Check List: Handler	Typist
11/1/18 - 2.00	Called OI Mr Goh Han 98414168 no respond. Will sent our letter / tried calling again later.	Notification ltr (if non-pickup)	☐
11/1/18 - 2.17	received a call back from OI Mr Goh Han, 98414168 - agreed to settled on TP claims aware of NED USUR - He mention of selling his car within this week - Will sent our letter.	After call ltr to OI:	☒
12/1/18	98414168 letter to OI.	Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☐
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD:	☐
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:	
FINALIZATION		Date/Time: 12-10-18	Confirm with: CAROLINE	Confirm by: MMH
Repair Cost:	P/R	SS 1,041.75	(6 days) Reduction: 12 %	Email ☒ Call ☐
FINAL SETTLEMENT		Date/Time: 14-3-19	Confirm with: CAROLINE	Email ☒ Call ☐
Final Liability:	100% / %	50	(Agreed / Assessed) BOLA S/N No.: P 2017	If NO or B 28, Ass. Lia:
Repair Cost: W/L	SS	1,588.39	SS 3,794.20	OI REAR ENDED TP
Loss of Rental (LOR):	SS	-	(days)	
Loss of Use (LOU):	SS	400.00	(\$100 x 8 days)	
Loss of Income (LOI):	SS	-	(\$ x days)	
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	SS	2.00		
Medical:	SS	-		
Disbursement:	SS	-	(e.g. Tow/ Independent)	
Legal Cost	SS	-		
Total:	SS	4,196.20	Global Sum SS:	
FINAL PAYMENT		Date/Time: 14-3-19	Confirm with: CAROLINE	Email ☒ Call ☐
Payee 1:	SS	4,196.20	Name 1: PERFORMANCE MOTORS LIMITED	
Payee 2: (Strike if N.A.)	SS	-	Name 2:	
Payee 3: (Strike if N.A.)	SS	-	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18000377/ea3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 08-01-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJP 4286M	Veh. Inspected	SJZ 8823J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	08/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/01/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

106 JAN 2018

Estimate No. : b1 45412
Date Estimated : 06/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Kee Boo Chye (Ji Wucai)
5D Puay Hee Avenue

Singapore 347473

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ8823J	C798951	30/04/2012	640iA/2	0

DESCRIPTION

To replace rear bumper and Remove and install bootlid and attachment include knocking cause by the accident

REAR LH FENDER AND

VALUE

1275 2,550.00
2,550.00

Painting rear bumper, bootlid AND REAR LH FENDER

1868 2,664.00
2,076.00

To supply and rear emboss number plate.

dd 83.00

To check electrical wiring systems and lightings at the rear section for proper function.

152 177.00

Sundries.

new V 80.00

Total Labour 1: 4,966.00

DESCRIPTION

RR BUMPER CARRIER
RR BUMPER ADAPTER
GUIDE CENTER REAR
GUIDE BOTTOM CENTER
MOUNT REAR LH
MOUNT REAR RH
RR BUMPER (PDC)
RR BUMPER TOW HOOK COVER (PRIMED)
BMW EMBLEM
MODEL LETTERING 640I

QTY	PRIC
1	751.70
1	67.10
1	70.25
1	50.05
1	141.65
1	141.65
1	1,690.65
1	25.45
1	67.80
1	61.05

VALUE

751.70
67.10
70.25
50.05
141.65
141.65
1,690.65
25.45
67.80
61.05
1,752.90
69.50
62.95

Total Parts : 3,067.35

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45412
Date Estimated : 06/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ8823J	C798951	30/04/2012	640iA/2	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Claims OD / 3rd Party / ...

Regn No. 5121180.1040

Date/Time 5/2/18 0.1040

Surveyor's Name tanfhn

Surveyor's Tel 97495745

Authorised Yes / No

Time

OTD BY 3 Yes No P/L Yes / No

Recommend tanfhn

Signature: tanfhn

Date: 5/2/18

8666.80

Labour 1	:	4,966.00
Parts	:	3,067.35
Labour 2	:	8033.35 0.00
Excess	:	0.00
Total GST @ 7%	:	562.33
Grand Total	:	8,595.68

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45412
Date Estimated : 06/01/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

- ESTIMATE REPAIR FOR -
Kee Boo Chye (Ji Wucai)
5D Puay Hee Avenue

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 347473

REGN NO	CHASSI S NO	REGN DATE	MODEL	MILEAGE		
SJZ8823J	C798951	30/04/2012	640iA/2	0		
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the boot lid, rear LH fender and knocking out dents caused by the accident			2550.00		2,250.00	
* To spray paint rear bumper, boot lid and rear LH fender			2664.00		2,664.00	
To supply and rear emboss number plate.			83.00		83.00	
To check electrical wiring systems and lightings at the rear section for proper function.			150.00		150.00	
Sundries.			80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR BUMPER (PDC)	1,732.90	1.00		1,732.90
BMW EMBLEM	69.50	1.00		69.50
MODEL LETTERING 640I	62.55	1.00		62.55

SUPPLEMENTARY ITEMS

Total Labour :	5,227.00
Total Parts :	1,864.95
Total Labour & Parts :	7,091.95
Deduction for Excess :	
Total Repair Costs less Excess:	7,091.95
GST @7%:	496.44
Grand Total :	7,588.39

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jan 2018 Edit Reg		05 Feb 2018 00:00 Edit Adj Rpt	S\$7,091.95 Edit Estimates	S\$7,091.95 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GOH HIAN TWEE, ID: S74305051		
Main Claimant:	KEE BOO CHYE, ID: S7224456G		
Vehicle Reg. No.:	SJZ8823J	Date of Loss:	05/01/2018 20:00 - :59 [68 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1338956629SG	Policy/Cover Note No.:	2100277571 (Comprehensive)
Vehicle Reg. No. (Insured):	SJP4286M	Policy No. (Claimant):	-
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ8823J (1338956629SG)**
[SJP4286M]

TP
KEE BOO CHYE
Jan 5 2018 8:00PM
[GOH HIAN TWEE]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/01/18 10:02	AXA's insured dashcam video	1 Load AVI	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	
Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/01/18 15:23	Accident Statement From: OD - Reg. No: SJP4286M, Claimant: GOH HIAN TWEE	1 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/10/18 15:03	Odometer Reading	1 Load JPG	☒
2	12/10/18 15:03	Chassis Number	1 Load JPG	☒
3	12/10/18 15:03	General View	1 Load JPG	☒
4	12/10/18 15:03	General View	1 Load JPG	☒
5	12/10/18 15:03	General View	1 Load JPG	☒
6	12/10/18 15:04	General View	1 Load JPG	☒
7	12/10/18 15:04	General View	1 Load JPG	☒
8	12/10/18 15:04	General View	1 Load JPG	☒
9	12/10/18 15:04	General View	1 Load JPG	☒
10	12/10/18 15:04	General View	1 Load JPG	☒
11	12/10/18 15:04	General View	1 Load JPG	☒
12	12/10/18 15:04	General View	1 Load JPG	☒
13	12/10/18 15:04	General View	1 Load JPG	☒
14	12/10/18 15:04	General View	1 Load JPG	☒
15	12/10/18 15:04	General View	1 Load JPG	☒
16	12/10/18 15:04	General View	1 Load JPG	☒
17	12/10/18 15:04	General View	1 Load JPG	☒
18	12/10/18 15:04	General View	1 Load JPG	☒
19	12/10/18 15:04	General View	1 Load JPG	☒
20	12/10/18 15:04	General View	1 Load JPG	☒
21	12/10/18 15:04	General View	1 Load JPG	☒
22	12/10/18 15:04	General View	1 Load JPG	☒
23	12/10/18 15:04	General View	1 Load JPG	☒
24	12/10/18 15:04	General View	1 Load JPG	☒
25	12/10/18 15:04	General View	1 Load JPG	☒

Video			1 per page ▾	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
26	12/10/18 15:04	General View	 Load JPG	✓
27	12/10/18 15:04	General View	 Load JPG	✓
28	12/10/18 15:04	General View	 Load JPG	✓
29	12/10/18 15:04	General View	 Load JPG	✓
30	12/10/18 15:04	General View	 Load JPG	✓
31	12/10/18 15:04	General View	 Load JPG	✓
Documentation			1 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/01/18 12:14	TP ESTIMATE	 Load TIF	
2	08/01/18 12:14	TP GIA REPORT	 Load PDF	
3	11/01/18 16:22	LETTER TO OI	 Load PDF	
4	07/02/18 13:38	TP ESTIMATE - MARKED	 Load PDF	
5	21/03/19 15:11	AUTHORISATION TO ACT	 Load PDF	
6	21/03/19 15:11	GIA SEARCH	 Load PDF	
7	21/03/19 15:11	RELEASE VOUCHER	 Load PDF	
8	21/03/19 15:11	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJP4286M (Insd veh)	Model:	BMW 640I 3.0 (A)
	SJZ8823J (TP veh)		
Date of Accident:	05/01/2018		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$		9,273.48	
Final Repair Cost	:	\$		3,794.20	
Loss of Use	:	\$		400.00	8.00 days at \$100.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$		2.00	
Others:	:	\$			
	:	\$			
Final Settlement Sum	:	\$		4,196.20	
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u> :			Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> :			BOLA Applicable: Yes/ No BOLA Scenario No:		
			28(F) _____		
BOLA Liability: ____ 50 ____ (%)			Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 4,196.20
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

21 Mar
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18000377/T1EA3S2

Date: 21/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100277571

Claimant Vehicle No : SJZ8823J

Insured Vehicle No : SJP4286M

Date of Loss: 05/01/2018

Nature of Claim: TP

Claim No: 1338956629SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ8823J**

Make & Model: BMW 640i, 3.0 (A)

Reg. Date: 30/04/2012 (Man. Year: 2011)

Colour: Black

Engine Capacity: 2979 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 11117948N55B30A

Chassis No: WBALW320X0C798951

Odometer: 19689 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35R19

Rear Tyre Size:

275/35R19

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,275.80	2,027.95	1,247.85	38.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,391.00	5,064.00	327.00	6.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,666.80	7,091.95	1,574.85	18.17
+ GST 7.00/7.00% (S\$)	606.68	496.44	110.24	18.17
Nett Amount (S\$)	9,273.48	7,588.39	1,685.09	18.17
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
	(S\$)	8,388.39		
Liabe Amount (50.00%) (S\$)		4,194.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,196.20		

INSPECTION

Date of Assignment: 05/02/2018

Date Inspected: 05/02/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER CARRIER	Not Necessary	751.70 FS	*- FS
2	1		*RR BUMPER OUTER	Not Necessary	67.10 FS	*- FS
3	1		*GUIDE CENTER REAR	Not Necessary	70.25 FS	*- FS
4	1		*GUIDE BOTTOM CENTER	Not Necessary	50.05 FS	*- FS
5	1		*MOUNT REAR LH	Not Necessary	141.65 FS	*- FS
6	1		*MOUNT REAR RH	Not Necessary	141.65 FS	*- FS
7	1		*RR BUMPER (PDC)	Deformed	1,732.90 FS	*1,732.90 FS
8	1		*RR BUMPER TOW HOOK COVER (PRIMED)	Not Necessary	25.45 FS	*- FS
9	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
10	1		*MODEL LETTERING 640I	Necessary	62.55 FS	*62.55 FS
11	1		*REAR EMBOSS NUMBER PLATE	Dented	83.00 FS	*83.00 FS
12	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,275.80	2,027.95
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REMOVE AND INSTALL BOOTLID, REAR LH FENDER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT.	New	2,550.00	2,250.00
2	PAINTING REAR BUMPER, BOOTLID AND REAR LH FENDER.	New	2,664.00	2,664.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
Gross Labour Cost (S\$)			5,391.00	5,064.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >