

ASS. REC. BY:

REF: CS/MSG18000379/Gvd3n2 Special Instruction:

SURVIVOR
MENIMEN

ASSIGNMENT (Office)

From (Person): Eliza Ho of MSG Date/Time: 08/01/2017 @ 9.57am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ719R

Insured:

at Workshop m/s

Performance

Tel:

9116 5200

of

303 Alexandra Rd

Policy No:

B27796851 SMP

Claim No:

544463

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A. 05/01/2018

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:23am @ 08/01/17

Person Contacted:

Mr ChuaVehicle ☒ IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/> Estimate
	<u>SKQ719R-X</u>
<u>9/1-</u>	<u>Revert via Menimen</u>
<u>9/1-13:50pm</u>	<u>authorise repair by koh ming shao</u>
<u>9/1-1:54pm</u>	<u>email to chua authorise repair excess \$5001.</u>
<u>7/3/18</u>	<u>Final fig \$13,128.70 confirmed by email (Reel 3434.85, 217)</u>

08/11/13

A&S REC. BY:

xhl.

REF:

MSIG CS/MS918000379/Gvd3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Performance

of

China

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$98K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKQ 719R

Yr Regn:

31 Oct 2014

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 316i

c.c.

1598

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

44284

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA3A16010NS 37233

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

235/40R18

R:

27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

08-01-18

Survey held at

w/s

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 07 MAR 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) B-typist

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

300

Transportation:

S + RS \$

Photos

Others

10

TOTAL

310

Report Format:

merimen

Lump Sum / I.B.I. (\$

13,728.70

Survey Department Check List (Case Handler)

Reference No. : CS/MSG/18000379/GVD3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Veron 7/3/18
 Case Handler Date

*C: Critical *N: Non-Critical


21/05/2014

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18000379/Gvd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-01-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SKQ 719R	
Policy No.	B27796851SMP	Coverage (\$)	0.00	
Claim No.	544463	Excess (\$)	500.00	
Assign From	MERIMEN (ELIZA HO)	Assign Date	08/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/01/2018	Inspection Date	08/01/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	05 Jan 2018		08 Jan 2018 09:57 Assign			

[New Assignment](#)
[Cancel Case](#)

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

[Created by insurer]

CLAIM SUBFOLDER DETAILS

Insured:	CINDY LER HUEY CHING, ID: S7167581E, Tel: +6598756818, Email: NOEMAIL		
Vehicle Reg. No.:	SKQ719R	Date of Loss:	05/01/2018 10:00 - :59
Claim Type:	OD / 544463	Policy/Cover Note No.:	B27796851SMP (Comprehensive) Coverage: 31/10/2017 - 30/10/2018
		Excess:	S\$500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/01/2018]		
Driver/Custodian:	CINDY LER HUEY CHING (46 / Female), NRIC: S7167581E, Tel: +6598756818		
Adj Asg. Remarks:	REVERT		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 09 Jan 2018

Preliminary Advice

Vehicle No	: SKQ719R	Accident Date	: 05/01/2018
Make	: BMW 316I	Policy No.	: B27796851SMP
Assignment Date	: 08/01/2018	Excess	: S\$500.00
Date of Inspection	: 09/01/2018	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,449.45
Revised Amount	:S\$	11,746.40
Check Items (Estimated)	:S\$	2,020.05
Total	:S\$	13,766.45
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	65,604.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,396.00

Remarks

(x) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 March 2018 2:41 PM
To: 'PBSP'; Guo Qiang (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKQ719R

Dear Caroline,

Confirmed finalize \$13,128.70 before excess \$500 and GST

No of days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Friday, 2 March 2018 3:28 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: FINAL REPORT / SKQ719R

Photos 2 of 2.

From: PBSP
Sent: Friday, 2 March 2018 3:26:30 PM
To: Veron Chen (LKKAUTO); Guo Qiang (LKKAUTO); SUR
Subject: Re: FINAL REPORT / SKQ719R

Dear Veron

As requested, please see attached.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Thursday, 22 February 2018 2:26:19 PM
To: PBSP; Guo Qiang (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKQ719R

Dear Caroline,

Kindly forward us check items and supplementary photos.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Wednesday, 21 February 2018 2:25 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SKQ719R

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 7,276.00
Total Parts : 5,852.70
Total Labour & Parts : 13,128.70

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended

View Received Message

This mail is associated with :

***SKQ719R (544463)**

OD

Jan 5 2018 10:00AM

[CINDY LER HUEY CHING]

Performance Motors Limited

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 07/03/2018 11:47 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$13128.70) - SKQ719R - Claim Handler: Eliza Ho Teng Boon

Approved:13128.70:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Eliza Ho Teng Boon	Date: 05 Mar 2018
<u>Preliminary Advice</u>	

Vehicle No	: SKQ719R	Accident Date	: 05/01/2018
Make	: BMW 316I	Policy No.	: B27796851SMP
Assignment Date	: 08/01/2018	Excess	: S\$500.00
Date of Inspection	: 09/01/2018	Est. Duration of Repair	: 6.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,563.55
Revised Amount	:S\$	13,128.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,128.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	65,604.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,396.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 9 January 2018 1:54 PM
To: 'Chua Kee Sin'
Cc: Inthiran Thurasamy; SUR
Subject: SKQ719R OD MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKQ719R (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	05 Jan 2018 14:13	Clim Veh Model Changed	(204780) BMW 316I 1.6 AT D/AB 4DR (A).	[I] Eliza Ho Teng Boon
2	05 Jan 2018 14:13	Clim Created	Reg No: SKQ719R. Policy No: B27796851SMP. Acct Date: 2018/01/05. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Performance Motors Limited (Alexandra). Ins.Status => Incoming Claim. Created from SAS:MPML18002445	[I] Eliza Ho Teng Boon
3	05 Jan 2018 14:46	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):TO AUTHORIZE REPAIR IF DAMAGES ARE CONSISTENT.	[I] Koh Ming Shao
4	05 Jan 2018 14:46	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/06	[I] Koh Ming Shao
5	05 Jan 2018 14:46	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Koh Ming Shao
6	08 Jan 2018 09:51	Assignment 1st Accessed		[A] Ho Pei Fang
7	08 Jan 2018 09:57	Adj Assignment Cancelled		[I] Eliza Ho Teng Boon
8	08 Jan 2018 09:57	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Eliza Ho Teng Boon
9	08 Jan 2018 09:57	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):REVERT	[I] Eliza Ho Teng Boon
10	08 Jan 2018 09:57	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/09	[I] Eliza Ho Teng Boon
11	08 Jan 2018 09:57	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eliza Ho Teng Boon
12	08 Jan 2018 10:16	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
13	08 Jan 2018 12:31	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] Nivitha Govindasamy
14	09 Jan 2018 11:32	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
15	09 Jan 2018 11:37	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/07	[A] DENISE TAY KWEE CHENG
16	09 Jan 2018 11:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07	[A] DENISE TAY KWEE CHENG
17	09 Jan 2018 11:37	Adj Mandate Request	Cur.Req:13766.45:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
18	09 Jan 2018 13:50	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/07. Mandate Remarks: CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao
19	09 Jan 2018 13:50	Adj Mandate Set	Approved:11746.40:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1689716	09/01/2018 11:32	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKQ719R		10.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7581E
Vehicle Details	
Vehicle No.:	SKQ719R
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	316I 1.6 AT D/AB 4DR ABS HID
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	A958J688N13B16A
Chassis No.:	WBA3A16010NS37233
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,709.00
Original Registration Date:	31 Oct 2014
First Registration Date:	31 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$26,393.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2024
PARF Rebate Amount:	\$19,794.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,304.00
COE Rebate Amount:	\$45,810.00
Total Rebate Amount:	\$65,604.00

The information contained herein is correct as at 09 Jan 2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7581E
Vehicle Details	
Vehicle No.:	SKQ719R
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jan 2018
Vehicle Make:	B.M.W.
Vehicle Model:	316I 1.6 AT D/AB 4DR ABS HID
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	A958J688N13B16A
Chassis No.:	WBA3A16010NS37233
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$31,709.00
Original Registration Date:	31 Oct 2014
First Registration Date:	31 Oct 2014
Transfer Count:	0
Actual ARF Paid:	\$26,393.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Oct 2024
PARF Rebate Amount:	\$19,794.00
Intended COE Rebate Details	
COE Expiry Date:	30 Oct 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,304.00
COE Rebate Amount:	\$45,792.00
Total Rebate Amount:	\$65,586.00

The information contained herein is correct as at 10 Jan 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/01/2018 12:23
Date Of Accident	05/01/2018 10:15
Exact Location Of Accident	THOMSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ719R
Insured/Policyholder	
Name Of Registered Owner	CINDY LER HUEY CHING
NRIC No	S7167581E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98756818
Alternative Phone No	OFFICE-98756818

Vehicle Particulars

Manufacturer	BMW
Model	316
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27796851SMP
Cover Note Number	

Driver

Name of Driver	CINDY LER HUEY CHING
NRIC No	S7167581E
Date Of Birth	08/11/1971
Occupation	INDOOR
Date Of Driving Pass	14/07/1999
Driving Experience	18 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98756818
Fax Number	
Contact Number	OFFICE-98756818
Email Address	NOEMAIL

Address	BLK 234 ANG MO KIO AVE 3 #09-1134
Postcode	160234
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU3122J
Vehicle Make/Model/Colour	
Details Of Properties	BLUE
Vehicle Category	PRIVATE CAR
Name of Driver	GOH KOK GUAN
NRIC/Passport Number	S8128074F
Contact Number	90460811
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Sketch Plan


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident

Front car suddenly Jam brake and try to turn left to prevent involve accident unfortune I hit into the car infront on my right front side to his car left side area damage.

Declaration

I/We declare the foregoing particulars are true in every respect.

Linda 5-1-18
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

5/1/2018
Witnessed by Reporting Centre Personnel
1156 hrs

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45395
Date Estimated : 05/01/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Ler Huey Ching
Blk 234 Ang Mo Kio Avenue 3
#09-1134

Singapore 560234

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ719R	NS37233	31/10/2014	316iA/4	0

DESCRIPTION

Replace front bonnet, right front fender, front bumper and remove attachment etc include knock on accident dent

2975 2550 4,250.00

Spray painting front bonnet, bumper front and right front side fender

✓ 2899 3,221.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

✓ 150 177.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

✓ 451 531.00

To carry out body cavity preservation.
(For cut panel).

✓ 200 451 531.00

To replace right headlight including program and conduct tests for proper function.

✓ 451 531.00

Sundries.

ABC. ✓ 8 150.00

Total Labour 1: 9,391.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BONNET — Bue	1	1,189.90	1,189.90
FRT RH SIDE PANEL — Bue	1	665.85	665.85
FRT RH 2 SIDE PANEL BRACKET	1	31.35	31.35
FRT RH 1 SIDE PANEL BRACKET	1	31.35	31.35
FRT RH 3 SIDE PANEL BRACKET	1	31.35	31.35
BONNET LH HINGE	1	71.50	71.50
BONNET RH HINGE	1	71.50	71.50
FRT LH TOP SUPPORT SIDE PANEL	1	17.55	17.55
FRT RH TOP SUPPORT SIDE PANEL	1	17.55	17.55
FRONT SHOCK ABSORBER	1	40.15	40.15
CLOSED GRID RH	1	70.55	70.55
FRT BUMPER TOP MOUNT	1	352.90	352.90

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796602 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081-X

ESTIMATE

Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item to be surveyed and is subject to final approval from Insurance Company

Estimate No. : b1 45395
Date Estimated : 05/01/2018
Prepared By : Chua Kee Sin

Acknowledged by Repairer

Signature:

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ719R	NS37233	31/10/2014	316iA/4	0

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
INSERT AIR INTAKE CENTER	1	97.90	97.90
FRT RH LOWER DEFORMATION ELEMENT	1	80.65	80.65
SUPPORT FOGLAMP RH	1	36.65	36.65
DAMPER FOR CURB DESCENT	1	4.55	4.55
FRT BUMPER TRIM PRIMED (SRA)	1	958.80	958.80
RH COVER SPRAY NOZZLE PRIMED	1	34.35	34.35
FLAP TOWING EYE PRIMED	1	34.00	34.00
SUPPORT CENTRAL	1	10.80	10.80
SUPPORT	2	5.55	11.10
MOUNT FOR SUPPORT	1	6.30	6.30
GROMMET	2	0.75	1.50
STOP BUFFER	2	12.75	25.50
GAS STRUT HOOD	2	101.40	202.80
RH SUPPORT BRAKET HEAD LAMP	1	52.65	52.65
BRACKET AUX RADIATOR UPPER RH	1	33.50	33.50
BRACKET AUX RADIATOR UPPER RH	1	33.50	33.50
BRACKET AUX RADIATOR LOWER RH	1	27.15	27.15
BRACKET AUX RADIATOR LOWER RH	1	27.15	27.15
FRT BUMPER LOWER MOUNT	1	124.90	124.90
LOCK PANEL COVER	1	9.25	9.25
FRT RH WHEEL HOUSING COVER	1	112.75	112.75
RH COVER BOTTOM	1	112.75	112.75
DEFLECTOR LIP RH	1	35.90	35.90
ADJUSTER BONNET	1	6.15	6.15
PLAQUE 82MM	1	67.80	67.80
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	82.75	82.75
TELESCOPING NOZZLE RH	1	152.10	152.10
RH HEADLIGHT (XENON)	1	2,083.75	2,083.75

Total Parts : 7,058.45

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Page No. _____ Claim No. _____
Date & Time 05/1/18 Excess \$
Surveyor's Name Gao Qiang Sign
Surveyor's Tel 82880282 Authorised Yes / No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PSL Yes / No

Surveyor's E-mail Gao Qiang @ lkkauto.com

No. of Working Days Recommend 6-7

before paint photo's.

Labour 1	:	9,391.00
Parts	:	7,058.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,151.46
Grand Total	:	17,600.91

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45395
Date Estimated : 05/01/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Lor Huey Ching
Blk 234 Ang Mo Kio Avenue 3
#09-1134

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 560234

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE		
SKQ719R	NS37233	31/10/2014	316iA/4	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace front bumper and attachments, RH headlight bracket, front RH fender and attachments, bonnet, RH support, RH bottom cover, RH telescoping nozzle include knocking out dents caused by the accident	2975.00		2,975.00			
To spray paint bonnet, front bumper and front RH fender	2899.00		2,899.00			
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00			
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)	451.00		451.00			
To carry out body cavity preservation, (Per panel)	200.00		200.00			
To replace RH xenon headlight include programming and conducting tests for proper function	451.00		451.00			
Sundries.	150.00		150.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT		
BONNET	1,189.90	1.00		1,189.90		
FRT RH SIDE PANEL	665.85	1.00		665.85		
FRT RH 2 SIDE PANEL BRACKET	31.35	1.00		31.35		
FRT RH 1 SIDE PANEL BRACKET	31.35	1.00		31.35		
FRT RH TOP SUPPORT SIDE PANEL	17.55	1.00		17.55		
FRONT SHOCK ABSORBER	40.15	1.00		40.15		
FRT BUMPER TOP MOUNT	352.90	1.00		352.90		
# FRT RH BOTTOM MOUNTING SIDE PANEL *	17.55	1.00		17.55		
FRT BUMPER TRIM PRIMED (SRA)	958.80	1.00		958.80		
RH COVER SPRAY NOZZLE PRIMED	34.35	1.00		34.35		
# RIVET *	0.45	4.00		1.80		
# RH SUPPORT *	52.65	1.00		52.65		
# RH HEADLIGHT BRACKET *	9.25	1.00		9.25		
# COVER FOR BULB REPLACEMENT LH *	9.60	1.00		9.60		
RH COVER BOTTOM	112.75	1.00		112.75		
PLAQUE 82MM	67.80	1.00		67.80		
TELESCOPING NOZZLE RH	152.10	1.00		152.10		
RH HEADLIGHT (XENON)	2,083.75	1.00		2,083.75		
# LABEL COOLANT 550+/-10G *	23.25	1.00		23.25		

SUPPLEMENTARY ITEMS

Total Labour :	7,276.00
Total Parts :	5,852.70
Total Labour & Parts :	13,128.70
Deduction for Excess :	500.00
Total Repair Costs less Excess:	12,628.70
GST @7%:	884.01
Grand Total :	13,512.71

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45395
Date Estimated : 05/01/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Ler Huey Ching
Blk 234 Ang Mo Kio Avenue 3
#09-1134

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 560234

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	ORIGINAL PRICE	DISC. %	NETT
SKQ719R	NS37233	31/10/2014	316iA/4	0			
DESCRIPTION							

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT RH BOTTOM MOUNTING SIDE PANEL * / BT	17.55	1.00		17.55
# RIVET * / MCL	0.45	4.00		1.80
# RH SUPPORT * / SBT	52.65	1.00		52.65
# RH HEADLIGHT BRACKET * / MCL	9.25	1.00		9.25
# COVER FOR BULB REPLACEMENT LH * / MCL	9.60	1.00		9.60
# LABEL COOLANT 550+/-10G * / MCL	23.25	1.00		23.25

Total Labour :	
Total Parts :	114.10
Total Labour & Parts :	114.10

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18000379/GVD3N2

Date: 13/03/2018

REFERENCE

Insured/Claimant: CINDY LER HUEY CHING

Policy No: B27796851SMP

Date of Loss: 05/01/2018

Nature of Claim: OD

Claim No: 544463

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ719R

Make & Model: BMW 316i, 1.6 AT D/AB 4DR (A)

Engine No: A958J688N13B16A

Reg. Date: 31/10/2014 (Man. Year: 2014)

Chassis No: WBA3A16010NS37233

Colour: White

Odometer: 44284 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$98,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40R18

Rear Tyre Size: 235/40R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,322.55	6,002.70	1,319.85	18.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,241.00	7,126.00	2,115.00	22.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,563.55	13,128.70	3,434.85	20.74
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	16,063.55	12,628.70	3,434.85	21.38
+ GST 7.00/7.00% (S\$)	1,124.45	884.01	240.44	21.38
Nett Amount (S\$)	17,188.00	13,512.71	3,675.29	21.38

INSPECTION

Date of Assignment: 08/01/2018

Date Inspected: 08/01/2018 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2018)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ719R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,189.90 FS	*1,189.90 FS
2	1		*FRT RH SIDE PANEL	Buckled	665.85 FS	*665.85 FS
3	1		*FRT RH 2 SIDE PANEL BRACKET	Bent	31.35 FS	*31.35 FS
4	1		*FRT RH 1 SIDE PANEL BRACKET	Bent	31.35 FS	*31.35 FS
5	1		*FRT RH 3 SIDE PANEL BRACKET	Not Necessary	31.35 FS	*- FS
6	1		*BONNET LH HINGE	Not Necessary	71.50 FS	*- FS
7	1		*BONNET RH HINGE	Not Necessary	71.50 FS	*- FS
8	1		*FRT LH TOP SUPPORT SIDE PANEL	Not Necessary	17.55 FS	*- FS
9	1		*FRT RH TOP SUPPORT SIDE PANEL	Bent	17.55 FS	*17.55 FS
10	1		*FRONT SHOCK ABSORBER	Cracked	40.15 FS	*40.15 FS
11	1		*CLOSED GRID RH	Not Necessary	70.55 FS	*- FS
12	1		*FRT BUMPER TOP MOUNT	Bent	352.90 FS	*352.90 FS
13	1		*INSERT AIR INTAKE CENTER	Not Necessary	97.90 FS	*- FS
14	1		*FRT RH LOWER DEFORMATION ELEMENT	Not Necessary	80.65 FS	*- FS
15	1		*SUPPORT FOGLAMP RH	Not Necessary	36.65 FS	*- FS
16	1		*DAMPER FOR CURB DESCENT	Not Necessary	4.55 FS	*- FS
17	1		*FRT BUMPER TRIM PRIMED (SRA)	Deformed	958.80 FS	*958.80 FS
18	1		*RH COVER SPRAY NOZZLE PRIMED	Missing	34.35 FS	*34.35 FS
19	1		*FLAP TOWING EYE PRIMED	Not Necessary	34.00 FS	*- FS
20	1		*SUPPORT CENTRAL	Not Necessary	10.80 FS	*- FS
21	2		*SUPPORT	Not Necessary	11.10 FS	*- FS
22	1		*MOUNT FOR SUPPORT	Not Necessary	6.30 FS	*- FS
23	2		*GROMMET	Not Necessary	1.50 FS	*- FS
24	2		*STOP BUFFER	Not Necessary	25.50 FS	*- FS
25	2		*GAS STRUT HOOD	Not Necessary	202.80 FS	*- FS
26	1		*RH SUPPORT BRACKET HEAD LAMP	Not Necessary	52.65 FS	*- FS
27	1		*BRACKET AUX RADIATOR UPPER RH	Not Necessary	33.50 FS	*- FS
28	1		*BRACKET AUX RADIATOR UPPER RH	Not Necessary	33.50 FS	*- FS
29	1		*BRACKET AUX RADIATOR LOWER RH	Not Necessary	27.15 FS	*- FS
30	1		*BRACKET AUX RADIATOR LOWER RH	Not Necessary	27.15 FS	*- FS
31	1		*FRT BUMPER LOWER MOUNT	Not Necessary	124.90 FS	*- FS
32	1		*LOCK PANEL COVER	Not Necessary	9.25 FS	*- FS
33	1		*FRT RH WHEEL HOUSING COVER	Not Necessary	112.75 FS	*- FS
34	1		*RH COVER BOTTOM	Cracked	112.75 FS	*112.75 FS
35	1		*DEFLECTOR LIP RH	Not Necessary	35.90 FS	*- FS
36	1		*ADJUSTER BONNET	Not Necessary	6.15 FS	*- FS
37	1		*PLAQUE 82MM	Necessary	67.80 FS	*67.80 FS
38	1		*HOSE LINE HEADLIGHT CLEANING SYSTEM	Not Necessary	82.75 FS	*- FS
39	1		*TELESCOPING NOZZLE RH	Damaged	152.10 FS	*152.10 FS
40	1		*RH HEADLIGHT (XENON)	Cracked	2,083.75 FS	*2,083.75 FS
41	1		*FRT RH BOTTOM MOUNTING SIDE PANEL	Bent	17.55 FS	*17.55 FS
42	4		*RIVET	Necessary	1.80 FS	*1.80 FS
43	1		*RH SUPPORT	Bent	52.65 FS	*52.65 FS
44	1		*COVER FOR BULB REPLACEMENT LH	Necessary	9.60 FS	*9.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*RH HEADLIGHT BRACKET	Bent	9.25 FS	*9.25 FS
46	1		*LABEL COOLANT 550+/-10G	Necessary	23.25 FS	*23.25 FS
47	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	7,322.55	6,002.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT BONNET,RIGHT FRONT FENDER,FRONT BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT	New	4,250.00	2,975.00
2	SPRAY PAINTING FRONT BONNET,BUMPER FRONT AND RIGHT FRONT SIDE FENDER	New	3,221.00	2,899.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1X)	New	531.00	451.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	200.00
6	TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
Gross Labour Cost (S\$)			9,241.00	7,126.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >