

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 04/01/2018

TP Veh Reg No: SHC8382J

Estimate No: ES1890009/AMK

Date: 06 Jan 2018

Policy No: 5078379946-01

Veh Reg No: SLA7304E

Make/Model: HONDA VEZEL 1.5 X A

Chassis No: RU11105827

Engine No: L15B4025830

Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No :SLA7304E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	508.50	1 PC	508.50	
2 REAR RH SIDE BUMPER	195.00	1 PC	195.00	
3 REAR BUMPER RH REFLECTOR	135.10	1 PC	135.10	
4 REAR BUMPER CLIP	3.90	4 PC	15.60	
5 REAR TAILGATE	1,100.90	1 PC	1,100.90	
6 TAILGATE INNER LOCK	189.00	1 PC	189.00	
7 TAILGATE INNER RUBBER	96.80	1 PC	96.80	
8 TAILGATE EMBLEM 'VEZEL'	56.20	1 PC	56.20	
9 TAILGATE INNER TRIM BOARD	225.60	1 PC	225.60	
10 TAILGATE WINDSCREEN GLASS MOULDING	158.10	1 PC	158.10	
11 REAR END PANEL	415.60	1 PC	415.60	
12 REAR END PANEL INNER TOP GARNISH	92.30	1 PC	92.30	
13 REAR END PANEL UNDER TRAY	190.00	1 PC	190.00	
14 REAR END PANEL BUZZER SENSOR (INNER)	95.80	1 PC	95.80	
15 REAR END PANEL BUZZER SENSOR (OUTER)	85.00	1 PC	85.00	
16 TOOL SPONGE	225.00	1 PC	225.00	
17 REAR MUFFLER	528.00	1 PC	528.00	
18 REAR RH FENDER WHEEL ARCH GARNISH	150.20	1 PC	150.20	
			4,462.70	
		Less 20%	892.54	3,570.16
Special Net				
19 REVERSE SENSOR	200.00	1 SET	200.00	
20 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	
			240.00	240.00
Labour				
21 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	
22 REMOVE & REFIX REAR BUMPER,RH SIDE BUMPER,TAILGATE & SPOILER & ATTACHMENTS,TAILLAMPS; TO CUT,WELD & RENEW REAR END PANEL;KNOCKING & REPAIR REAR LUGGAGE PANEL & REALIGN THE SAME	950.00	1 LA	950.00	
23 PUTTY & RESPRAY SIDE BUMPER,TAILGATE,FENDER,REAR END PANEL, REAR LUGGAGE PANEL & REALIGN THE SAME	950.00	1 LA	950.00	
24 REMOVE & REFIX REVERSE CAMERA.RESET & REPOSITION	80.00	1 PC	80.00	
25 REMOVE & REFIX REAR MUFFLER & REALIGN THE SAME	80.00	1 LA	80.00	
26 RUSTPROOFING	90.00	1 LA	90.00	
			2,270.00	2,270.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/AMK

Claim Type: Third Party

Accident Date: 04/01/2018

TP Veh Reg No: SHC8382J

Estimate No: ES1890009/AMK

Date: 06 Jan 2018

Policy No: 5078379946-01

Veh Reg No: SLA7304E

Make/Model: HONDA VEZEL 1.5 X A

Chassis No: RU11105827

Engine No: L15B4025830

Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No :SLA7304E

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 6,080.16
			Add GST @ 7%	425.61
			Total Amount Payable	<u><u>S\$ 6,505.77</u></u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be employed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: