

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

05-04-18

TP Direct Asia

Date Of Accident : 05-01-2018

Mr. Adrian

Xiao Tony

OUR REF : SJG 3903U/T/18 (2)

Ms. Usiao Tony

DW LIMO SERVICES

Blk 257A Compassvale Road

#11-505

Singapore 541257

Fax: 67414108

MR053ZEE106108262

ESTIMATE BILL ON VEH. NO. : SJG 3903U**MODEL : TOYOTA ALTIS****CHASSIS NO. : MR053ZEE106108262****LIST ITEM**

Side Mirror Assy - RH

Dend

105.8

987.30

Side Mirror Cover - RH

Missing

793.5

131.20

70.70

1,118.50

Less Discount 25%:

279.63

838.88

LABOUR CHARGE

To Respray Affected Areas.

160

100.00 80

To Renew Damaged Parts.

120.00 80

TOTAL :

1,058.88

GST 7 % :

74.12

AMOUNT DUE :

1,133.00**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 953.50

h/s: 750

02 Apr