



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2017 MERCEDES E220D (SCP3883D)

Date of Loss

30 December 2017

Time of Loss

15.30

Loss Description

SCP3883D (INSD) KNOCK ON THE SIDE ROAD

Comment

Workshop Details

Total Rebate Amount

94073

Nett Loss Amount

\$95,927.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

15/05/2018



Days of work completion *

27



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SCP3883D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

18/08/2017



Mileage

10624

Age of Vehicle

0

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2017

ASSESSMENT INFO...

2017

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

YEO CHAI SONG

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MERCEDES

ASSESSMENT INFO... MERCEDES BENZ

CATEGORY Model

POLICY INFORMAT... E220D

ASSESSMENT INFO... E220D SE AUTO

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO... ▼

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WDD2130042A218803

CATEGORY Date of Birth

FNOL INFORMATI... 22 December 1967

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 50

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI... 31

ASSESSMENT INFO... WDD2130042A218803

CATEGORY Engine No

POLICY INFORMAT... 65492080098249

ASSESSMENT INFO... 65492080098249

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1950

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 190000

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... dd/mm/yyyy

CATEGORY Address

FNOL INFORMATI... BLK 186 TOA PAYOH CENTRAL, 310186, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S1807544Z

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

08/01/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/55R17

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

225/55R17

Front left side

CONTINENTAL9mm

Front right side

CONTINENTAL9mm

Rear left side

CONTINENTAL9mm

Rear right side

CONTINENTAL9mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			BONNET			Buckled	1127				1127	Review
		2	1			BONNET HINGE LH			Repair	0	0	0	0	0	Deny
		3	1			BONNET HINGE RH			Repair	0	0	0	0	0	Deny
		4	1			BONNET DAMPER LH			Serviceable	0	0	0	0	0	Deny
		5	1			BONNET DAMPER RH			Damaged	52				52	Review
		6	1			BONNET STOWAGE LH			Damaged	94				94	Review
		7	1			BONNET STOWAGE RH			Damaged	94				94	Review
		8	1			BONNET STOPPER SPRING LH			Serviceable	0	0	0	0	0	Deny
		9	1			BONNET STOPPER SPRING RH			Serviceable	0	0	0	0	0	Deny
		10	1			HEADLAMP LH WITH ECU			Cracked	1956				1956	Review
		11	1			HEADLAMP BRACKET LH			Damaged	87				87	Review
		12	1			FRONT BUMPER			Buckled	625				625	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		13	1			FRONT BUMPER SIDE RETAINER LH			Serviceable	0	0	0	0	0	Deny
		14	1			FRONT BUMPER SIDE RETAINER RH			Serviceable	0	0	0	0	0	Deny
		15	1			FRONT BUMPER UPPER GRILLE			Serviceable	0	0	0	0	0	Deny
		16	1			FRONT BUMPER GRILLE LINING CHROME			Serviceable	0	0	0	0	0	Deny
		17	1			FRONT BUMPER UPPER GRILLE EMBLEM			Serviceable	0	0	0	0	0	Deny
		18	1			FRONT BUMPER LOWER GRILLE			Serviceable	0	0	0	0	0	Deny
		19	1			FRONT BUMPER SPONGE			Serviceable	0	0	0	0	0	Deny
		20	1			FRONT BUMPER FOG LAMP COVER LH			Serviceable	0	0	0	0	0	Deny
		21	1			FRONT BUMPER SENSOR (NPA)			Serviceable	0	0	0	0	0	Deny
		22	1			FRONT BUMPER SENSOR BRACKET (NPA)			Serviceable	0	0	0	0	0	Deny
		23	1			FRONT BUMPER LOWER LIP			Serviceable	0	0	0	0	0	Deny
		24	1			FRONT BUMPER LOWER LIP CHROME			Serviceable	0	0	0	0	0	Deny
		25	1			FRONT BUMPER PREDESTRIAN SENSOR			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		26	1			FRONT BUMPER UNDER COVER,CENTRE			Cracked	116				116	Review
		27	1			FRONT BUMPER UNDER COVER LH			Cracked	40				40	Review
		28	1			FRONT BUMPER DEFLECTOR BRACKET			Damaged	13				13	Review
		29	1			FRONT BUMPER ENGINE COVER			Serviceable	0	0	0	0	0	Deny
		30	1			FRONT FENDER SHIELD LH			Cracked	153				153	Review
		31	15			FRONT FENDER SHIELD CLIPS			Serviceable	0	0	0	0	0	Deny
		32	1			SIDE UNDER COVER (NPA)			Serviceable	0	0	0	0	0	Deny
		33	1			FRONT ABSORBER LH			Bent	425				425	Review
		34	1			FRONT ABSORBER MOUNTING LH			Serviceable	0	0	0	0	0	Deny
		35	1			FRONT ABSORBER STOPPER LH			Serviceable	0	0	0	0	0	Deny
		36	1			FRONT LOWER ARM LH			Bent	300				300	Review
		37	1			FRONT LOWER ARM BALL JOINT LH			Serviceable	0	0	0	0	0	Deny
		38	1			FRONT KNUCKLE ARM LH			Bent	795				795	Review

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
		39	1			FRONT KNUCKLE ARM BEARING LH			Necessary	260				260	Review
		40	1			FRONT STABILIZER LINK LH			Damaged	42				42	Review
		41	1			FRONT STABILIZER BAR			Serviceable	0	0	0	0	0	Deny
		42	2			FRONT STABILIZER BAR BUSH			Serviceable	0	0	0	0	0	Deny
		43	1			FRONT TIE ROD LH			Serviceable	0	0	0	0	0	Deny
		44	1			FRONT TIE ROD END LH			Serviceable	0	0	0	0	0	Deny
		45	1			FRONT TIE ROD COVER LH			Serviceable	0	0	0	0	0	Deny
		46	2			TIE ROD COVER CLAMP LH			Repair	0	0	0	0	0	Deny
		47	1			FRONT DRIVE SHAFT LH			Serviceable	0	0	0	0	0	Deny
		48	1			FRONT ABS SENSOR LH			Serviceable	0	0	0	0	0	Deny
		49	1			FRONT UPPER ARM LH			Bent	420				420	Review
		50	1			FRONT CONTROL ARM LH			Damaged	285				285	Review
		51	1			FRONT AXLE DIFFERENTIAL ASSY (NPA)			Serviceable	0	0	0	0	0	Deny
		52	1			STEERING RACK			Damaged	4760				4760	Review

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		53	1			ENGINE MOUNTING SET			Serviceable	0	0	0	0	0	Deny
		54	1			ENGINE UNDER STRUT LH			Serviceable	0	0	0	0	0	Deny
		55	1			ENGINE CROSSMEMBER ASSY			Serviceable	0	0	0	0	0	Deny
		56	1			WHEEL RIM			Damaged	465				465	Reviewi
		57	10			FRONT BUMPER CLIPS }			Necessary	7				70	Reviewi
		58	10			FRONT BUMPER UNDER COVER CLIPS }				0				0	Reviewi
		59	10			FRONT SIDE UNDER COVER CLIPS }				0				0	Reviewi

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REA
		1		PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	250	0	0	Reviewing		
		2		PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	450	0	0	Reviewing		
		3		PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	20	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REM
		4		PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	60	0	0	Reviewing		
		5		PROVIDE SKILL LABOUR TO REMOVE AND REPLACE / REFIT UNDERCARRIAGE	250	0	0	Reviewing		
		6		PROVIDE SKILL LABOUR TO RESET ENGINE MANAGMENT SYSTEM WITH ORIGINAL DIAGNOSTIC	200	0	0	Reviewing		
		7		PROVIDE SKILL LABOUR TO RESET ABS MANAGEMENT SYSTEM WITH ORIGINAL DIAGNOSTIC	0	0	0	Deny		
		8		PROVIDE SKILL LABOUR TO RESET UNDERCARRIAGE (AUTO PARKING SENSOR) MANAGEMENT SYSTEM WITH ORIGINAL DIAGNOSTIC	0	0	0	Deny		
		9		PROVIDE SKILL LABOUR TO RESET STEERING WHEEL ANGLE MANAGEMENT SYSTEM WITH ORIGINAL DIAGNOSTIC	0	0	0	Deny		
		10		PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSOR	40	0	0	Reviewing		
		11		PROVIDE SKILL LABOUR TO REMOVE AND RE-BALANCING FRONT TYRE AND RIM	20	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 5 DAYS	Reviewing			
		2	ENGINE UNDER COVER CENTER	Reviewing	30	CRACKED (SUPPLEMENTARY)	
		3	ENGINE UNDER COVER REAR	Reviewing	177	CRACKED (SUPPLEMENTARY)	
		4	ENGINE UNDER COVER SIDE	Reviewing	88	MISSING (SUPPLEMENTARY)	
		5	TYRE - 225/55 R17 CONTINENTAL CPC 5 (SN) (90%)	Reviewing	315	CUT (SUPPLEMENTARY)	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$13,679.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,290.00	\$1,290.00
Spare Parts	\$12,179.00	\$12,179.00
Miscellaneous	\$610.00	\$610.00
Excess	-\$400.00	-\$400.00

Submit for Review